
# ENVIRONMENTAL MANAGEMENT PLAN



# **Giant 999 Steel Manufacturing Factory**

# Prepared by



# GREEN ENVIRONMENTAL, HEALTH, SAFETY & SOCIAL CONSULTANCY COMPANY LTD.

1112/C2 (A), Time Square Condo, Merchant Road, Botahtaung Township, Yangon, Union of Myanmar

Revised (01) Report July 2022



# CONTENT

CONTENT	1
LIST OF FIGURES	8
LIST OF TABLES	. 12
ABBREVIATIONS	. 15
1.0 EXECUTIVE SUMMARY	.17
1.0 အကျဉ်းချုပ်အစီရင်ခံစာ	.50
2.0 INTRODUCTION	. 89
2.1 Project Proponent and Background89	
2.2 Salient Features of the Company89	
2.3 Purposes of the Environmental Management Plan90	
2.3.1 Timeframe of EMP90	
2.4 Process Technology and Environmental Benefit90	
2.5 Consultant Team91	
2.5.1 Personnel Information of Consultant Team	
3.0 ENVIRONMENTAL COMMITMENT	. 93
4.0 LEGAL REQUIREMENT	. 95
4.1 National Laws and Regulations95	
4.2 Environmental Standard and Guideline97	
4.3 Other Acts, Laws101	
5.0 PROJECT DESCRIPTION	102
5.1 Company's Objective102	
5.2 Project Location102	
5.3 Project Timeframe	



5.4 Plant Layout Associated Facilities109	
5.5 Annual raw material requirement	
5.5.1 Chemical Requirement	
5.6 Machineries and Equipment	
5.7 Production Activity117	
5.7.1 Process Flow of Production119	
5.8 Products/ By Product and Production Capacity126	
5.8.1 Sale System	
5.9 Resource Requirement	
5.9.1 Human Resource Requirement	
5.9.2 Working Hours	
5.9.3 Working Days127	
5.10 Water Supply128	
5.11 Electricity	
5.11.1 Fuel Use	
5.12 Waste131	
5.12.1 Solid Waste (Type/ Amount/ Management)	
5.12.2 Effluent/ Waste Water (Type/ Amount/ Management)	
5.12.3 Hazardous waste	
5.13 Drainage	
5.14 Transportation Condition	
BASELINE ENVIRONMENTAL AND SOCIAL QUALITY14	10
6.1 Current Environment and Spatial Boundaries of the Factory140	
6.2 Background History of Hmawbi Township141	

6.0



	6.2.1	Location and Area	142
	6.2.2	Boundaries	142
6.3	Торо	graphy	143
6.4	Drair	nage Condition	143
6.5	Clima	ate	144
	6.5.1	Temperature	144
	6.5.2	Precipitation	145
	6.5.3	Humidity	146
	6.5.4	Wind Direction and Wind Speed	147
6.6	Natu	ral Vegetation and WildLife	147
6.7	Haza	rd Consideration	148
	6.7.1	Earthquake	148
6.8	Land	Use	<b>150</b>
6.9	Soil (	Composition of the plant Area	153
6.1	0 Wate	r Quality of the Factory	155
	6.10.1	Ground Water Quality	155
	6.10.2	Drain Water Quality	157
<b>6.1</b> 1	1 Air Q	Quality	159
	6.11.1	Methodology	159
	6.11.2	Ambient Air Quality Standards	161
	6.11.3	Air Monitoring Points	162
	6.11.4	Air Monitoring and Results	164
6.1	2 Noise	e and Vibration Condition	168
	6.12.1	Noise	168



6.12.2	Vibration	172
6.13 Soil	Quality	175
6.14 Soci	o-Economic Component Near the Factory	176
6.14.1	Social Condition	177
6.14.2	Economic Condition	179
	NMENTAL AND SOCIAL IMPACT ASSESSMENT AN	
7.1 Ove	rview of Impacts	181
7.1.1	Magnitude of the Impact (M)	182
7.1.2	Duration of Impact (D)	182
7.1.3	Geographic or Spatial Extent (E)	183
7.1.4	Probability of Occurrence (O)	183
7.1.5	Significant Level of Risk Consideration	183
7.2 Impa	act Assessment for Construction Phase	185
7.3 Impa	act Assessment for Operation Phase	192
7.4 Impa	act Assessment for Decommission Phase	203
7.5 Sum	mary of Impact	206
7.6 Envi 206	ronmental Impact and Mitigation Measures for Constr	ruction Phase
7.6.1	Water Environment	206
7.6.2	Air Emissions	207
7.6.3	Environmental Noise Impact	207
7.6.4	Solid Waste	207
7.7 Envi	ronmental Impact and Mitigation Measures for Operation	on Phase . 208



GIANT 999 STEEL MANUFACTURING	Green EHSS Con
FACTORY	****

7.7.1	Wastewater	208
7.7.2	Emission to air	210
7.7.3	Existing Dust Collection (De-dusting) Systems	212
7.7.4	Solid Waste	213
7.7.5	Noise Exposure	215
7.7.6	Hazardous Material/Waste	216
7.7.7	Occupational Hazard	223
7.7.8	Emergency and Disaster Situation	228
7.8 Guid	leline and Standard	229
7.9 Envi	ronmental Impact and Mitigation Measures for Decommission	oning
Phase		231
7.9.1	Water Environment	231
7.9.2	Air Emissions	231
7.9.3	Environmental Noise Impact	232
7.9.4	Solid Waste	232
7.9.5	Social Environment	233
	Health and Safety Related with Occupational Accidents, Disaste nunity Hazard	
8.0 STAKEHO	DLDER ENGAGEMENTS AND INFORMATION DISCLOSURI	E234
8.1 Cons	sultation Process	234
8.1.1	Face to Face Meeting	235
8.1.2	Socio-Economic and Opinion Survey	235
8.1.3	Public Meeting	236
8.2 Enga	gement Techniques	240



	nents and Suggestions from the Public Consultations and Socio	
Economic	Survey24	1
8.4 Respo	onses and Implementation Action for Comments24	5
8.5 Future	e Plan For Stakeholder Engagement24	6
9.0 ENVIRON	MENTAL AND SOCIAL MANAGEMENT PLAN	247
9.1 Enviro	onmental Management Team (EMT)24	7
9.2 Roles	and Responsibilities for Environmental Management Team 24	8
9.3 Enviro	onmental and Social Management Plan for Construction Phase25	0
9.4 Enviro	onmental and Social Management Plan for Operation Phase 25	5
9.4.1	Water Management Plans25	5
9.4.2	Air Emission and Dust Management Plans25	7
9.4.3	Noise Management Plans25	8
9.4.4	Solid Waste Management Plans26	0
9.4.5	Traffic Management Plans	2
9.5 Occup	pational and Community Health and Safety26	3
9.5.1	Occupational Health and Safety Plan26	3
9.5.2	Community Health and Safety Plan26	5
9.6 Enviro 266	onmental and Social Management Plan for Decommissioning Phas	e
9.7 Emerg	gency Preparedness and Response Plan27	3
9.7.1	Emergency Response Team (ERT)27	4
9.7.2	Roles and Responsibilities for Emergency Response Team27	4
9.7.3	Fire Prevention Plans	5
9.8 Comn	nunity Involvement and Development Program28	2



9.9 Training, Awareness and Competency2	84
9.10 Commitment2	87
10.0 ENVIRONMENTAL MONITORING PLAN	288
10.1 Objectives2	88
10.2 Regulatory Requirement2	88
10.3 Implementation of Monitoring and Budget2	89
10.4 Report Team and Reporting2	90
10.5 Environmental Monitoring plan for Construction Phase2	91
10.6 Environmental Monitoring plan for Operation Phase2	93
10.7 Environmental Monitoring plan for Decommissioning Phase2	96
11.0 CONCLUSIONS	297
12.0 LIST OF COMMITMENT	299
Appendix (A) Permit and License	304
Appendix (B) Water Quality	307
Appendix (C) Material Safety Data Sheet	309
Appendix (D) ECD Comment Response Table	323
REFERENCES	338



# LIST OF FIGURES

Figure 5.1 Surrounding Condition of the Factory	103
Figure 5.2 Project Location	105
Figure 5.3 Location Map of the Factory	107
Figure 5.4 Production Area	108
Figure 5.5 Layout Plan of the Factory	109
Figure 5.6 Factory Office	110
Figure 5.7 Security Gate	111
Figure 5.8 Factory Dormitory	111
Figure 5.9 Production Building	112
Figure 5.10 Dust Collecting Building	112
Figure 5.11 Photo of Iron Scraps and Storage Area with Roof and Concrete Floor	113
Figure 5.12 Photo of Silicon and Manganese Storage Condition in the Chemical	
Room	115
Figure 5.13 Chemical Storage Area with MSDS, Prevent Unauthorized Individua	ıls
from Entering and Danger Sign	115
Figure 5.14 Photos of Machines	117
Figure 5.15 Process Flow for Finishing	119
Figure 5.16 Process Flow Chart of Production	
Figure 5.17 သံတိုသံစ ကုန်ကြမ်းများ	120
Figure 5.18 သံရည်မကျိုမှီ သံရည်ကျိုအိုး နှင့် မီးခိုးအုပ်ဆောင်း	120
Figure 5.19 သံရည်ကျိုနေစဉ် သံရည်ကျိုအိုး နှင့် မီးခိုးအုပ်ဆောင်း	121
Figure 5.20 ကျိုပြီးသံရည်များကို မီခံခွက် အတွင်းသို့ လောင်းထည့်စဉ်	121
Figure 5.21 နန်းဆွဲ ပထမအဆင့် square တုံး	122
Figure 5.22 နန်းဆွဲ ဒုတိယ အဆင့် square တုံး နန်းဆွဲ ပြေးလမ်းပေါ်ရောက်	122
Figure 5.23 နန်းဆွဲတတိယအဆင့် U Beam စက်သို့ဖြတ်	123
Figure 5.24 U Beam စက်သို့ဖြတ်ပြီး U Beam ချောင်းဖြစ်ပေါ်လာပုံ	123
Figure 5.25 ထွက်လာသော U Beam ချောင်း ပါကင်စက်ပေါ်သို့ရောက်	124
Figure 5.26 ပါကင်စက်ပေါ်မှ U Beam ဖြောင့်စက်သို့ဖြတ်	124
Figure 5.27 ဖြောင့်စက်မှ U Beam ဖြတ်စက်သို့ရောက်	125
Figure 5.28 ဖြတ်စက်မှ ပါကင်စင်ပေါ်သို့ရောက်	125
Figure 5.29 ပါကင်စက်မှ ကုန်ချောစုပုံရာသို့ရောက်	126



Figure 5.30 Photos of Finishing Products and Storage Area	126
Figure 5.31 Photos of Water Storage Condition	128
Figure 5.32 Photos of Tube Wells	128
Figure 5.33 Photos of Transformer and Generator with Extinguisher and D	100
Figure 5.34 Diesel Storage Tank Post with MSDS and No Smoking Sign an Sand	
Figure 5.35 Lubricating Oil Storage Post with MSDS, Safety Signs and Exti	
	131
Figure 5.36 Photo of Factory Garbage Area and Removing Waste	
Figure 5.37 Process Waste Flow Chart	
Figure 5.38 Photos of Fly Ash Solid Waste (သံချော်ပြာ)	
Figure 5.39 Photos of Process Waste (သံဖြတ်စ) and, Broken and Reject Was	
အပယ်) to be Recycled	134
Figure 5.40 Photo Water Storage and Pipe and Water Recycle System	135
Figure 5.41 Photo Records for Sludge Waste Removal from Septic Tanks	
Figure 5.42 Dust Collecting Building	137
Figure 5.43 Dust Collecting System	
Figure 5.44 Internal Drainage	138
Figure 6.1 Surrounding Condition of the Factory	140
Figure 6.2 Factory Location and Myaung Dagar Industrial Zone	141
Figure 6.3 Hmawbi Township Map	142
Figure 6.4 Map Showing Topographic Feature of Surrounding Area	143
Figure 6.5 Average High and Low Temperature	144
Figure 6.6 Daily Chance of Precipitation	145
Figure 6.7 Average Monthly Rainfall	145
Figure 6.8 Humidity Comfort Levels	146
Figure 6.9 Average Wind Speed	147
Figure 6.10 Seismic Zone Map of Myanmar and Plant area	149
Figure 6.11 Nearby Factories	151
Figure 6.12 Surrounding Land Use of the Factory	152
Figure 6.13 Soil Map of Factory	154
Figure 6.14 Water Sample Collections for Ground Water	156
Figure 6.15 Water Sample Collection	158
Figure 6.16 Photos of Air Monitoring Devices	160
Figure 6.17 Haz-Scanner EPAS Device	160
Figure 6.18 Aeroqual Series 500 Air Monitoring Device	160

**FACTORY** 



Figure 6.19 770-1100 HAZ-DUST I, Aerosol Monitoring Device	161
Figure 6.20 Air Quality Monitroing	
Figure 6.21 Photos of Noise Monitoring Device	169
Figure 6.22 Noise Quality Monitoring	
Figure 6.23 Photos of Vibration Monitoring Device	173
Figure 6.24 Vibration Level Monitoring	174
Figure 6.25 Soil Quality Monitroing Places	175
Figure 6.26 Photo Records of Soil Quality Monitroing	175
Figure 6.27 Hmawbi Township	176
Figure 7.1 Internal Drainage of the Factory	210
Figure 7.2 Photo Records for Sludge Waste Removal from Septic Tanks	210
Figure 7.3 Dust Collecting system and Building	212
Figure 7.4 Photo of Factory Garbage Area and Removing Waste	213
Figure 7.5 Process Waste Flow Chart	214
Photos of Fly Ash Solid Waste (သံချော်ပြာ) Sold to Collector	215
Figure 7.6 Photos of Process Waste (သံဖြတ်စ) and, Broken and Reject Waste (အ	ကျိုး၊
အပယ်) to be Recycled	215
Figure 7.7 Hazardous Storage Area with MSDS, Prevent Unauthorized Individ	duals
from Entering and Danger Sign.	
Figure 7.8 Diesel Storage Tank Post with MSDS and No Smoking Sign	
Figure 7.9 Lubricating Oil Storage Post with MSDS, Safety Signs and Extinguis	
	240
Figure 7.10 Samples of Material Safety Data Sheet for Diesel, Silicon and Lubr	_
Oil	
Figure 7.11 Photos of Uniform, Mask, Glove, Caps and First-aid box for Emplo	•
Figure 8.1 Discussion with Village Administrator of Kalar Kone Villages Tract	
Figure 8.2 Socio-Economic Surveys with Household Leaders from Kalar Kone	
Villages Tract	236
Figure 8.3 Photograph of Kalar Kone Villages Tract Administrator Office for F	
Consultation	
Figure 8.4 Public Consultation with Ward Leaders and Local Residents from F	
Kone Villages Tract	
Figure 8.5 Main Concerns Mentioned by Residents during Stakeholder Meetir	_
Figure 9.1 Selection Guidelines for Fire Extinguishers	
Figure 9.2 Photos of Facilities for fire prevention	
Figure 9.3 Photos Record of Fire Drill at the Factory	281



Figure 9.4 Photo Records of Fire Fighting Training	285
Figure 9.5 Photo Records of Training	286

**FACTORY** 



# LIST OF TABLES

Table 4.1 Environmental and Social Parameters	98
Table 4.2 Effluent Levels (NEQEG 2.3.7.3)	
Table 4.3 Air Emission Level (NEQEG 2.3.7.3)	
Table 4.4 Air Quality Standards	
Table 4.5 Noise Level Standard	101
Table 5.1 List of Buildings	110
Table 5.2 Annual Raw Materials	113
Table 5.3 Annual Chemical Requirement	114
Table 5.4 List of Machineries and Equipment	116
Table 5.5 List of Local and Foreign Employee on 1st November 2019	
Table 6.1 Particular Matter of the Township	142
Table 6.2 Yearly Temperature Condition of Hmawbi Township	144
Table 6.3 Yearly Precipitation and Rainy Days Condition of Hmawbi Township	146
Table 6.4 Existing Condition of Ecological Resources	148
Table 6.5 Level of Probable Damage and Destruction	150
Table 6.6 Land Utilization in Hmawbi Township	150
Table 6.7 Geographic Position of Monitoring Points	156
Table 6.8 WHO Drinking Water Quality Standards	156
Table 6.9 Ground Water Quality	157
Table 6.10 Geographic Position of Monitoring Points	158
Table 6.11 Water Quality Standards	158
Table 6.12 Drain Water Quality	159
Table 6.13 Air Quality Standards	161
Table 6.14 Geographic Position of Monitoring Points at Operation Areas	163
Table 6.15 Geographic Position of Ambient Air Quality Monitoring Station	163
Table 6.16 Ambient Air Quality Monitoring Results	164
Table 6.17 Air Quality Monitoring Results	165
Table 6.18 Air Quality Measured at the Operation Areas	167
Table 6.19 Comparison of Air Quality at Operation Areas between Ovserved Fac	tory
Average Value and National Emission Guideline Value	167
Table 6.20 Comparison of Ambient Air Quality between Ovserved Value and	
National Emission Guideline Value	
Table 6.21 Noise Level Standard	
Table 6.22 Geographic Position of Noise Monitoring Points at Operation Areas	
Table 6.23 Geographic Position of Noise Monitoring Station Point near Factory G	ate
	170



Table 6.24 Monitoring Measurements of Noise within the Factory (dBA)	171
Table 6.25 Comparision of Observed Ambient Noise Level with Standard Guide	eline
	171
Table 6.26 Survey Results of Hourly LAeq Value in Noise Monitoring Station	171
Table 6.27 Vibration Intensity Scale	173
Table 6.28 Geographic Position of Monitoring Points	174
Table 6.29 Vibration Intensity Scale	
Table 6.30 Summary of Soil pH	175
Table 6.31 Population by Sex in Hmawbi Township	
Table 6.32 Religious Groups of Ethnic in Hmawbi Township	177
Table 6.33 Population by Foreigner Living in Hmawbi Township	177
Table 6.34 Number of University and Schools in Hmawbi Township	178
Table 6.35 Number of University and Schools in Hmawbi Township	178
Table 6.36 Social Organization in Hmawbi Township	179
Table 6.37 Economic Organization in Hmawbi Township	179
Table 7.1 Evaluation of Magnitude of Impact	182
Table 7.2 Evaluation of Duration of Impact	182
Table 7.3 Evaluation of Spatial Extent of Occurrence	183
Table 7.4 Evaluation of Probability of Occurrence	
Table 7.5 Score Evaluation	184
Table 7.6 Environmental and Social Impact Assessment Matrix for Construction	185
Table 7.7 Environmental Impact Assessment Matrix for Operation	192
Table 7.8 Environmental Impact Assessment Matrix for Decommission	203
Table 7.9 Wastewater, Storm Water Runoff, Effluent and Sanitary Discharges	
(General Application) <sup>3</sup>	229
Table 7.10 Air Quality Standards	230
Table 7.11 Noise Level Standard	230
Table 8.1 List of Participants to the Public Consultation Meeting	238
Table 8.2 Engagement Methods and Techniques	240
Table 8.3 Responses of the Factory for the Comment and Suggestion Received	245
Table 9.1 Roles and Responsibilities of Environmental Management Team	248
Table 9.2 Environmental and Social Management Plan for Construction Phase	250
Table 9.3 Water Management Plan for Operation Phase	255
Table 9.4 Air Emission and Dust Management Plan for Operation Phase	257
Table 9.5 Noise Management Plan for Operation Phase	
Table 9.6 Solid Waste Management Plan for Operation Phase	260
Table 9.7 Traffic Management Plan for Operation Phase	
Table 9.8 Occupational Health and Safety Plan for Operation Phase	263



Table 9.9 Community Health and Safety Plan for Operation Phase	265
Table 9.10 Environmental and Social Management Plan for Decommissioning Pl	nase
	266
Table 9.11 Roles and Responsibilities of Emergency Response Team	275
Table 9.12 Training Program	284
Table 10.1 Environmental and Social Monitoring Parameters	289
Table 10.2 Budget Allocation for Monitoring Plan	289
Table 10.3 Roles and Responsibilities of Report Supported Team	290
Table 10.4 Proposed Environmental Monitoring Programmes – Construction Ph	ase
	291
Table 10.5 Proposed Environmental Monitoring Programmes – Operation Phase	293
Table 10.6 Proposed Environmental Monitoring Programmes – Decommissionir	ıg
Phase	296
Table 12.1 Project Key Commitments	299

# Environmental Management Plan Report





#### **ABBREVIATIONS**

μg/m3 microgram of gaseous pollutant per cubic meter of ambient air

BOD Biochemical Oxygen Demand

CO Carbon Monoxide CO<sub>2</sub> Carbon Dioxide

COD Chemical Oxygen Demand

CSR Corporate Social Responsibility dBA 'A' weighted equivalent decibels

DO Dissolved Oxygen

Dy IC Dy-Incident Controller

ECD Environmental Conservation Department

EHS Environmental, Health and Safety
EIA Environmental Impact Assessment
EMP Environmental Management Plan
EMT Environmental Management Team
EDRP Emergency and Disaster Response

ERT Emergency Response Team

FAO Food and Agriculture Organization

ft Feet gram

Green EHSS Green Environmental, Health, Safety and Social

hr hour

HR Human Resource

HSE Health, Safety and Environmental

i.e. that is

IC Incident Coordinator

IEC Independent Environmental Consultant

IFC International Finance Corporation

Kg kilogram km Kilometer

KVA Kilo (Volt P x Amps)

Kw Kilowatt

LAeq Equivalent Continuous Sound Pressure Level

mg/l miligrams per liter

mg/Nm<sup>3</sup> miligrams per cubic metre

# Environmental Management Plan Report

# GIANT 999 STEEL MANUFACTURING FACTORY



MIC Myanmar Investment Commission

MOECAF Ministry of Environmental Conservation and Forestry

MONREC Ministry of Natural Resources and Environmental Conservation

MSDS Material Safety Data Sheet

N/A Not Applicable

NEQEG National Environmental Quality Emission Guideline

NO<sub>x</sub> Nitrogen Dioxide

O<sub>3</sub> Ozone

OHS Occupational Health and Safety
OIC-AA Officer-in-charge at Assembly Area

pH potential of hydrogen

p.m. Post meridiem (after noon)

PM Particulate Matter

PPE Personal protective equipment

ppm parts per million

Qty. Quantity

RC reinforced concrete

RST Report Supported Team

S.U Standard Unit

SEZ Special Economic Zone

SO<sub>2</sub> Sulphur Dioxide

sq square

TS Total solids

TSS Total suspended solids

UNESCO United Nation Economic Social and Culture Organization

US US Dollar USD US Dollar

US EPA United State Environmental Protection Agency

VECs Valued Environmental/Socioeconomic Component

WHO World Health Organization

YCDC Yangon City Development Committee YESC Yangon Electricity Supply Corporation

°C Celsius

μg Micro gram m³ Cubic meter



#### 1.0 EXECUTIVE SUMMARY

Environmental Management Plan (EMP), which is important in managing the impacts of the factory, is constructed based on the findings of initial assessment. The Environmental Management Plan (EMP) is an integral part of the Health, Safety and Environmental Management System. This is also a tool to ensure the impacts are properly managed.

The EMP started from December 2019 and ended by July 2020 and submission date is in July 2020.

#### 1.1 Project Proponent

The project proponent is Giant 999 Stegel Manufacturing Factory established by Daw Sein Yee. Giant 999 Steel Manufacturing Factory has a license of Hmawbi Township Development Committee on 7<sup>th</sup> October 2019 at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township, Yangon, Myanmar.

The main business is foundry and rolling mills and main products are U Beam and Angle Bar. The factory was built in April 2011 and has been in operation since 2012 in Myanmar.

Environmental Management Plan for operation of Giant 999 Steel Manufacturing Factory is conducted by GREN ENVIRONMENTAL, HEALTH, SAFETY & SOCIAL CONSULTANCY COMPANY LIMITED.

Environmental Department of Yangon Region requested Giant 999 Steel Manufacturing Factory to submit the Environmental Management Plan (EMP). Therefore, Giant 999 Steel Manufacturing Factory needs to submit an EMP to MONREC.

#### 1.2 Legal Requirement

EMP team observed thoroughly the legal requirements that Giant 999 Steel Manufacturing Factory shall comply with are as follows:

- The Conservation of Environment Law (2012) and Rules (2014)
- Myanmar Investment Law (2016)



- Myanmar Investment Rule (2017)
- Minimum Wage Law (March,2013)
- The Myanmar Insurance Law (1993)
- The Social Security Law (2012)
- Factories Acts (1951)
- Workman Compensation Act(1923)
- The Public Health Law
- Underground Water Act ,1930
- The City Development Law and Rules
- The Water Power Act, 1927

#### 1.3 Projection Description

#### 1.3.1 Project Location

Giant 999 Steel Manufacturing Factory is located at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township, Yangon, Myanmar at the coordinates 17° 10′ 25.5″ N and 95° 58' 55.5" E (17.173743, 95.982095). The factory is built on 6.3 acre (274,428 sq ft) land and building area is 5.3 acre.



Figure 1.1 Production Area





Figure 1.2 Map Showing GPS Location of the Factory







Figure 1.3 Location Map of the Factory

# 1.3.2 Project Timeframe

စက်ရုံစီမံကိန်းကာလမှာ ၂၀၁၁ ခုနှစ် ၆.၉.၂၀၁၁ ခုနှစ်မှ လိုင်စင်သက်တမ်းတိုး၍ နှစ်စဥ်ဆောင် ရွက်ပါသည်။ စက်ရုံစီမံကိန်းကာလမှာ နှစ် ၃၀ ဖြစ်ပါသည်။

# 1.3.3 Plant Layout

**Table 1.1 List of Buildings** 

Sr	Building
1	Office Building
2	စက်ရုံဂိတ်
3	ဝန်ထမ်းဆောင်
4	တွင်ခုံ
5	Dust Collection (De-dusting) System
6	သံရည်ကျိုဆောင်
7	သံတို သံစ ကုန်ကြမ်းဆောင်+ စတို
8	သံနန်းဆွဲ + ကုန်ချော
9	အမှိုက်ပုံဟောင်း
10	အဆောင်ဟောင်း






Figure 1.4 Layout Plan of the Factory

#### 1.3.4 Annual Raw Material Requirement

Main raw material for iron and steel fermentation is old iron scraps. Major sources of raw materials are within the country. The factory uses 40 tons of old iron scraps (480 ton/year). They are stored raw material building with roof and concrete floor.

သဘာဝပတ်ဝန်းကျင် ထိခိုက်မှု မရှိစေရန် Chemical ပစ္စည်းများဖြစ်သော Silicon နှင့် Manganese များကို Chemical Room ထဲသို့ ထည့်ပါသည်။ ကားပေါ်မှ ကရိန်းချိတ်များဖြင့် Chemical အိတ်များကို 'မ'ရန် ကရိန်းမောင်းပညာရှင် မှ Chemical Room ထဲသို့ စနစ်တကျ ထည့်ပါသည်။ Chemical Room ထဲသို့ တာဝန်ရှိသူမှလွဲ၍ အပြင်လူများ မဝင်ရပါ။ Chemical ပစ္စည်းလာထုတ်သော သူမှအပ ပေး၍ မဝင်ပါ။



**Table 1.2 Annual Raw Materials** 

Sr	ltem	Photo	Amout (year)
1	Old iron scrap		480 ton
2	Silicon		4.2 ton
3	Magnet		6.2 ton



Figure 1.5 Photo of Iron scraps and Storage Area with Roof and Concrete Floor





Figure 1.6 Photo of Silicon and Manganese Storage Condition in the Chemical Room




Figure 1.7 Chemical Storage Area with MSDS, Prevent Unauthorized Individuals from Entering and Danger Sign

#### 1.3.5 Production Activity

ပြည်တွင်း ကုန်ကြမ်း သံတိုသံစ များကို အရည်ကျိုပြီး သံရည်ကျို ခံအိုး တွင် သွန်ထည့်ပါသည်။ သံရည်ကျိုအိုး မှ တဆင့် လျှောက်လမ်းသို့ သံရည်လောင်းထည့်ပြီး squareတုံး အဆင့် ရောက်ပါသည်။ squareတုံး မှ U Beam စက်သို့ ဖြတ်ပြီး U Beam များထွက်လာပါသည်။ ထွက်လာသော U Beam များ cutter စင်ပေါ်သို့ ရောက်ပြီး ဖြတ်စက်ဖြင့် ဖြတ်ပါသည်။ ဖြတ်ပြီးသော U Beam များကို ပါကင်ထုတ်ပါသည်။ ထုတ်ပြီးသော U Beam များကို ကရိန်းနှင့် သယ်ပြီး ကုန်ချောဂိုဒေါင်သို့ ပို့ပါသည်။





**Figure 1.8 Process Flow for Production** 

#### 1.3.6 Machines and Equipment

လုပ်ငန်းလည်ပတ်စဥ် အတွင်း အသုံးပြုသော စက်ကိရိယာများမှာ သံရည်ကျိုအိုးကြီး ၄ လုံး၊ မီးခိုးမထွက်စေရန်အတွက် အသုံးပြုသော သံရည်ကျိုအုပ်ဆောင်း ကြီး ၄ ခု၊ သံရည်ကျို လျှောက်လမ်း ၁ ခု၊ နန်းဆွဲစက် ၃ စက်၊ ပါကင်စက် ၂ စက်၊ ဖြောင့်စက် ၁ စက်၊ ကတ္တာစက် (ဖြတ်စက်) ၄ စက်၊ ကရိန်း ၆ စင်း ရှိပါသည်။ အခြားကိရိယာများမှ သံရည်ကျိုခံခွက် နှင့် rollar တို့ ဖြစ်ပါသည်။

Machineries and equipment required for production are shown in the following Tables.

Table 1.3 List of Machineries and Equipment

စဥ်	အကြောင်းအရာ	အရေအတွက်
э	သံရည်ကျိုအိုးကြီး	9
J	သံရည်ကျိုအုပ်ဆောင်း	9
9	သံရည်ကျို လျှောက်လမ်း	Э
9	နန်းဆွဲစက်	9
၅	ပါကင်စက်	J
G	ဖြောင့်စက်	Э
9	ကတ္တာစက် (ဖြတ်စက်)	9
၈	ကရိန်း	6



#### 1.3.7 Product and Production Capacity

The annual production capacity for U Beam and Angle Bar is 420 ton/year. Finish products stacked systematically in the finished goods storage area as shown in following figure.



Figure 1.9 Photos of Finishing Products and Storage Area

#### 1.3.8 Resource Requirement

Normally, there are twentysix (26) working days per month and 290 working days in a year. Generally, working hour is 8 hours in a day.

Table 1.4 List of Local and Foreign Employee on 1st November 2019

Sr. No.	Type of Employee	Male	Female	Total
1	Foreign Employees	15	1	15
2	Local Employees	42	8	50
Total		57	8	65



#### 1.3.9 Water Supply

The production water source is from ten on-site tube well. Process water is recycled. The estimated water use for process is 6000 gallons/year.

စက်ရုံအတွင်း တူးဖော်ထားသော အဝိစိတွင်းများမှာ ၆လက်မ ပေ၁၀၀ တွင်း ၆ တွင်းနှင့် ၃လက်မ ပေ၈၀ တွင်း ၄တွင်းရှိပါသည်။ ၆လက်မ ပေ၁၀၀တွင်း ၆တွင်း ၏တည်နေရာမှာ (က)အရည်ကျိုဋ္ဌာန တွင် ၄ တွင်း (ခ) ပါကင်ဋ္ဌာနတွင် ၂ တွင်းရှိပါသည်။ ၃လက်မ ပေ၈၀ တွင်း ၄တွင်း ၏ တည်နေရာမှာ (က) ပါကင်ဖက်၏ အဆုံးနေရာ တွင် ၁ တွင်း (ခ) အမျိုးသားအဆောင် အနီးတွင် ၁ တွင်း (ဂ) တွင်ခုံ အနီးတွင် ၁ တွင်း နှင့် (ဃ) အလယ်ပါကင် တွင် ၁ တွင်း ရှိပါသည်။

#### 1.3.10 Electricity

Giant 999 Steel Manufacturing Factory uses electricity supply from Yangon Electricity Supply Corporation (YESC) by using 7 transformers of 6300 KVA, 6300KVA, 6300KVA, 2000KVA, 2000KVA and 3000KVA. Two generators- 500 KW and 575 KW are installed. Annual fuel requirement for diesel is 1900 gallons. Annual electricity requirement is 152,288 units.

#### **Diesel Storage**

အရန်ဓာတ်အားအဖြစ် ထားရှိသည့် မီးစက်များအတွက် လိုအပ်သော ဒီဧယ် တစ်နှစ်စာ ၁၉၀၀ ဂါလံ (တစ်နေ့ လျှင် ၅ ဂါလံကျော်) ကို သံဆီလှောင်ကန် နှင့်စနစ်တကျသိုလှောင်ထားရှိပါသည်။ ဒီဧယ်ဆီကို ထော်လာဂျီကား အသုံးပြုရာတွင် ထည့်၍မောင်းနှင်ခြင်း၊ ကရိန်းမောင်းရာတွင် လည်း မီးပျက်လျှင် မီးစက်နှိုး၍ မောင်းနှင်ခြင်း တို့အတွက်လည်း အသုံးပြုပါသည်။ သဲအိပ်များ ထားရှိခြင်း၊ MSDS များကပ်ထားခြင်း၊ အန္တရာယ်ဆိုင်းဘုတ်၊ သတိပေးဆိုင်းဘုတ်များ ကပ်ထားပြီး အခြားဖိတ်စင်မှု မရှိအောင် သိမ်းဆည်း ထားပါသည်။



Figure 1.10 Diesel Storage Tank Post with MSDS and No Smoking Sign and Keeping Sand




#### 1.3.11 Waste

Domestic wastes are disposed three times a week and transported by factory own car. The factory produced 1.5 kg of domestic solid waste on average per month (18 kg/year). Some putrid foods are collected by factory workers for animal feed (especially for pig).

စက်ရုံအတွင်းဝန်ထမ်းဆောင်မှ ထွက်ရှိသော အမှိုက်များ နှင့် စားဖိုဆောင်မှ ထွက်သော အမှိုက်များ ကို စက်ရုံမှ ကားဖြင့် မြောင်းတကာ စက်မှုဇုန် အတွင်း သတ်မှတ်ထားသော အမှိုက်ပုံသို့ တစ်ပတ်လျှင် သုံးကြိမ် စွန့်ပစ် ပါသည်။ စက်ရုံမှ ကားအားလပ်မှု မရှိလျှင် စည်ပင်အား အကြောင်းကြား၍ စည်ပင်ကား ဖြင့် စွန့်ပစ်ပါသည်။ စည်ပင်ကားမှ သယ်ဆောင်သွားသော အမှိုက်များအား သက်ဆိုင်ရာ မှ ၄င်းတို့သတ်မှတ်ထားသောနေရာ အားယူဆောင်သွားပါသည်။

Broken pieces, reject products and cut pieces of iron products are re-melting in process of iron melting to be recycled purposes. Factory's dust collecting system generates 4 bags (200 kg) of the fly ash (သံချော်ပြာ) monthly. They are sold to the waste collectors for recycle purpose. ထွက်ရှိလာသော မီးခိုးပြာများကို Carbon တုံးများ ထုတ်လုပ်သော လုပ်ငန်းသို့ အများဆုံး ပြန်လည်ရောင်းချပါသည်။



**Figure 1.11 Process Waste Flow Chart** 





စက်ရုံအမှိုက်ပုံ



Figure 1.2 Photo of Factory Garbage Area and Removing Waste

#### 1.3.12 Dust Collecting System

The furnaces release large amount of light weighted particles. Thus, the factory has already installed the Iron Powder Fume Dust Collecting system.




Figure 1.13 Iron Powder Fume Dust Collecting Building



#### 1.4 Baseline Environmental Quality

#### 1.4.1 Spatial Boundaries of the Project

Giant 999 Steel Manufacturing Factory is located at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township. The factory is surrounded by other factories as shown in following Figure.

South : Garment Factory

North: Electricity Sub-power Station

Weast: Industrial Land Plot

East : Myanmar Sun Bell Factory



Figure 1.14 Surrounding Condition of the Factory

#### 1.4.2 Physical Environment

Climate in Hmawbi Township has a tropical monsoon climate. The hottest day of the year is April 12, with an average high of 36°C and low of 25.5°C. The coldest day of the year is January 10, with an average low of 19.4°C and high of 31.1°C. The most rain falls during the 31 days centered around July 31, with an average total accumulation of 9.1 inches.

Giant 999 Steel Manufacturing Factory is situated in Myaung Dagar Industrial Zone and current land use is industrial land use.



The surrounding terrain is mostly flat land, the elevation approximately ranges from +20 ft to +36 ft.

According to the FAO/UNESCO Soil Classification, the soil compositions around the plant area include Eutric Gleysols.




Figure 1.15 Factory Location and Myaung Dagar Industrial Zone

#### 1.4.3 Socio-economic Environment

Hmawbi Township is situated in Northern District of Yangon Region.

Table 1.5 Particular Matter of the Township

Sr.	Township	Township Sq. Mile	Town	Town Sq. Mile
1	Hmawbi	183.78	Hmawbi	6.09

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"



The population characteristics in Hmawbi Township are as follow.

Table 1.6 Population by Sex in Hmawbi Township

	Male	Female	Total
Urban	13047	13305	26352
Rural	84166	92386	176552
Total	97213	105691	202904

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

Table 1.7 Religious Groups of Ethnic in Hmawbi Township

Sr.	Type of Religion No. of Pers	
1	Buddhist	185700
2	Christian	14247
3	Hindu	656
4	Islam	2301
5	Other	-
Towns	hip Total	202904

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"





Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

Figure 1.16 Hmawbi Township Map

#### 1.5 Environmental and Social Impact and Mitigations

#### 1.5.1 Impact Assessment

Significant Level of the impacts were identified based on the interaction between the project and the VECs. The following considerations were determined to predict the significant effect.

- Magnitude of Impacts;
- Duration of Impact;
- Geographic or Spatial Extent;
- Probability of Occurrence;



During the operation phase, water pollution, air pollution, noise pollution and soil pollution are evaluated as insignificant and low due to the provision of effective control and mitigation measures. The project owner shall use the best available technology for potential impact such as de-dust control measures for the dust emission.

With timely and proper implementation of this EMP and application of appropriate mitigation measures, most if not all the potential negative impacts can be prevented or minimised.

Table 1.8 Environmental and Social Impact Assessment for Construction

Activity	Environmental Impact
Pollution	
-Exhaust gases from diesel generator, vehicles movements - Emission of particulate matters, PM <sub>2.5</sub> and PM <sub>10</sub> from raw materials transportation, handling and storage.	Air Quality
Transportation of construction materials -Operation of heavy machinery -Using diesel generators	Noise and Vibration
<ul> <li>Wastewater generated from site workers</li> <li>Transportation of construction materials and machinery</li> <li>Construction activities during raining season</li> </ul>	Water Quality
<ul> <li>Construction wastes from grading and excavation activities, scrap wood and small concrete spills.</li> <li>Small amount of machinery maintenance materials, used oil,</li> <li>spill clean-up materials</li> </ul>	Solid Waste



Table 1.9 Environmental and Social Impact Assessment for Operation

		Impact Significant <sup>*</sup>	
Activity	Environmental Impact	Before Mitigation	After Mitigation
Pollution			
- Runoff water	Water Quality	Low	Low
-Oil and grease leakage		Low	Low
-Sanitation wastewater		Low	Low
- PM and Ashes emission from the furnace	Air Quality	Low	Low
-Emissions from vehicular movement -Generator		Low	Low
- Operation of machines and equipment -Vehicle / traffic movement	Noise and Vibration	Low	Low
-Using generator		Low	Low
- Domestic wastes Solid Waste - Manufacturing wastes		Low	Low
Health and safety	,		
Occupational Health and Safety	Hazards and	Low	Low
Fire Hazards	Accidents	Low	Low
Emergency situations		Low	Low
Community Health and Safety		Low	Low
Social Environment			



-Social integration	Social Factor	Low	Low
-Ethnic minorities		Low	Low
-Population Influx		Moderate	Low

<sup>\*</sup> The calculated Impact Significant Score are described detail in Table 6.7

Table 1.10 Environmental and Social Impact Assessment for Decommission

Activity	Environmental Impact
Pollution	
- Transportation of materials, transfer of heavy machinery	Air Quality
-Demolition activities	
- Demolition activities	Noise and Vibration
- Unconfined stockpiles of soil and other materials	Water Quality
- Wastewater generated from workers and staff	
- Solid Waste demolition activities.	Solid Waste

#### 1.5.2 Mitigation Measures

**Table 1.11 Mitigation Measures Plan for Operation Phase** 

Purpose	Actions	Time Frame
Wastewater		
Minimizing the amount of pollutants in storm water Sanitation Water	<ul> <li>Regular removal of debris and sediments in the drain is done.</li> <li>Regular cleaning and checking of domestic wastewater.</li> <li>Sludge waste from septic tanks is discharge periodically by contacting Water and Sanitation Department.</li> <li>The maintenance area is provided with concrete floor</li> <li>Leakage and spillage are immediate clean.</li> </ul>	The whole operation period



TACTORT				
Emission of gas	seous substances			
Controlling air born particulates on adjacent areas	ir born and done regular maintenance.  • Metal scraps will be recollected and reused.  • Generators are regularly inspected and maintained.			
Dust Nuisance				
Controlling dusts particulates on adjacent areas	<ul> <li>More comprehensive cleaning should be carried out as often as necessary.</li> <li>Water spraying at the unpaved road during dry season.</li> <li>More effective methods of controlling dust.</li> <li>Provide PPE against dust (i.e. Mask).</li> </ul>	The whole operation period		
Noise and vibr	ation at the territory and beyond the bounds of the enterprise			
Minimizing the noise impact	he noise • Regular maintenance of the machines			
Odor				
Preventing odor impact	<ul> <li>Regular removal of waste accumulation.</li> <li>Proper management for waste disposal.</li> </ul>	The whole operation period		
Formation and	allocation of <b>Solid waste</b>			
Managing solid waste properly Reduction of waste volumes	<ul> <li>Waste should be disposed in bins and segregated by types of waste.</li> <li>Apply 3Rs management (Reduce, Reuse and Recycle).</li> <li>Sold the wastes to recycler regularly.</li> </ul>	The whole operation period		
Littering/ pollu	ting with <b>Solid waste</b>			
To manage and dispose	<ul> <li>Provide sufficient waste bins within the factory premises.</li> <li>Awareness campaign for workers education on the waste segregated system.</li> </ul>	The whole operation period		

# Environmental Management Plan Report



## **GIANT 999 STEEL MANUFACTURING FACTORY**

domestic waste	<ul> <li>Improve notice sign and awareness display board (non-smoking, no-dumping signs).</li> <li>Reuse waste if applicable.</li> <li>Non-reusable wastes will be collected by YCDC department.</li> </ul>	
Hazardous Wa	ste	
To control and mitigate impacts of hazardous wastes	<ul> <li>Hazardous waste like spent oil must be contained to prevent it from blowing away and from leaching into surface or groundwater.</li> <li>Factories must dispose of all hazardous wastes they make by using a qualified hazardous waste contractor, whenever feasible.</li> <li>Warning signage are provided at the chemical and fuel storage areas.</li> <li>Fire Extinguishers shall be provided near to the generator room.</li> </ul>	The whole operation period
Ecological Res	ources	
Minimizing impacts on biodiversity	<ul> <li>Keep the enterprise premises green by planting trees and flowers.</li> <li>In order to avoid the loss of ecological valuable, plant species should be practiced conservation methods as long term conservation.</li> </ul>	The whole operation period
Social Environ	ment	
Minimizing the population influx	he activities.  Informing of local population on existing vacancies	

09 5026245, 09 965026245, 09 425353553



Community an	Community and Occupational Health and Safety				
Preventing safety risk to the community	<ul> <li>All workers will be adequately trained in basic sanitation and health care issues (e.g., how to avoid transmission of sexually transmitted diseases such as HIV / AIDS).</li> <li>Traffic safety should be promoted.</li> <li>The emergency response team including trained fire fighters and first aiders should be formed and emergency response plan should be prepared.</li> </ul>	The whole operation period			
Occupation Health and Safety	<ul> <li>Workers are trained to handle the machine and equipment properly.</li> <li>The relevant Managers and Supervisors closely manage the workers to perform the assigned tasks safely and healthy.</li> <li>Application of personal protective equipment.</li> </ul>	The whole operation period			
Fire Prevention	<ul> <li>Alarms regularly tested by competent person.</li> <li>All the fuel and diesel are to be kept and stored, away from fire prone facilities and equipped with specific fire extinguishers for emergency use.</li> <li>Portable extinguishers should be maintained in a fully charged and operable condition.</li> <li>Conduct fire drill annually.</li> </ul>	The whole operation period			
Electricity	Electrical installation and all equipment are inspected according to a planned schedule and staff report any concerns to shift manager who will take appropriate action	The whole operation period			

#### 1.6 Stakeholder Engagement and Information Disclosure

In the frame of the preparation of this EMP report, Green EHSS has organized meetings with stakeholders with the active support of Giant 999 Steel Manufacturing Factory.

In December 2019, face to face meeting with Kalar Kone Villages Tract Administrator was conducted.

Household interviews were conducted with 6respondents from Kalar Kone Villages Tract.



Public consultation meeting was conducted by Green EHSS Social consultants with representatives of Giant 999 Steel Manufacturing Factory on 15<sup>th</sup> December 2019. It was held at Administrator Office, Kalar Kone Villages Tract with 17 attendees from Kalar Kone Villages Tract and the factory.

Stakeholder consultation revealed that there were no complaints from the surrounding area on Giant 999 Steel Manufacturing Factory.

The main issue raised in public meeting and concerns of residents are as follows:

- To remove the debris from the external drainage channel regularly.
- The factory should be clean.
- To create employment opportunities for local people.
- To manage and implement for fire safety.
- To provide occupational healthcare for employees.

Responses and action plan from Giant 999 Steel Manufacturing Factory are described in section 8.

#### 1.7 Environmental and Social Management Plan

#### 1.7.1 Management Team

Giant 999 Steel Manufacturing Factory establishes the Environmental Management Team (EMT) for implementing environmental and social management and monitoring plan for the operation phase of the project.

#### **Environmental Management Team (EMT)**

EMT shall comprise:

a) Ma Hnin Si – Team Leader

b) Ma Myat Myat Nyein – HSE Representative

c) Ma Mi Mi Kyaw – Team Member

d) Ma Zin Mar Soe – Team Member

e) Ko Thant Zin — Team Member

f) Ko Phoye Wai Aung — Team Member





#### **Emergency Response Team (ERT)**

#### **ERT** shall comprise:

a) Ko Aung San Oo – Incident Coordinator (IC)

b) Ko Thant Zin – Deputy IC

c) Ko Moe Paing Sint – Officer-in-charge at Assembly Area (OIC-AA)

d) Ma Myat Myat Nyein – Supervisors -Warden
e) Ko Wai Phyoe Aung – Supervisors -Warden

f) Ko Kyaw Thiha - First Aiders, Fire Fighters, etc.
 g) Ko Kyar Shin - First Aiders, Fire Fighters, etc.
 h) Ko Kyaw Zin - First Aiders, Fire Fighters, etc.

#### Report Supported Team (RST)

Report supported team is developed as follows:

a) A representative from EMT — Team Leader

b) A representative from Admin – Team Member

c) A representative from HR — Team Member

#### 1.7.2 Environmental and Social Management Plan for Operation Phase

According to the outcomes from the Environmental and Social Impact Analysis, **ENVIRONMENTAL MANAGEMENT PLANS** are addressed to mitigate the potential impacts. Summary of EMP generally takes account of the following crucial management plans.

Table 1.12 Summary of Environmental and Social Management Plans

Water Management Plans					
Performance Indicator(s)	<ul> <li>Monitoring results of ground water quality.</li> <li>pH, Conductivity, Total Dissolved Solid, Total Hardness, Total Alkalinity, Calcium, Magnesium,</li> <li>Monitoring results of drain water Concentration of BOD, COD, TS</li> </ul>				



Impact	Control(s)	Responsibility	Timing
Surface water contamination	<ul> <li>Factories should create a list of the materials that have the potential to come into contact with storm water and pollute it. These may include raw materials, fuels, detergents, finished products and waste materials.</li> <li>Factories should regularly inspect equipment, grounds and areas outside the factory to identify any conditions or practices that might pollute storm water and to assess if best management practices are effective in preventing pollution.</li> <li>Regular removal of debris and sediments.</li> </ul>	Plant Manager  Site Supervisor  HSE  Representative	Throughout processing phase
Sanitation waste water  Training	<ul> <li>Reducing the volume of water used.</li> <li>All sewers should be disposed of through septic tanks.</li> <li>Discharge periodically by contacting Engineering Department (Water and Sanitation) from YCDC.</li> <li>Train employees to minimize water use and on water conservation practices.</li> </ul>		
	Air Emission and Dust Manager	ment Plans	
Performance Indicator(s)	Concentration level of dust, particula CO <sub>2</sub> ,CO, SO <sub>2</sub> , NO <sub>x</sub>	ite matters, PM10 a	nd PM2.5,
Impact	Control(s)	Responsibility	Timing



Control(s)	<ul> <li>Effective dust control system is provided at the furnace.</li> <li>Planting fast growth trees around the factory as a barrier to mitigate the air emission around the factory.</li> <li>Regular maintained and inspection of the furnace and control system.</li> <li>All vehicles are regularly inspected and maintained to reduce the gas emission.</li> <li>Reducing the vehicles use, and collaborated using on same route of vehicles.</li> <li>Providing proper PPE to the employee.</li> </ul>	Plant Manager  Site Supervisor  HSE  Supervisor	Throughout processing phase		
- Haming					
Noise Management Plans					
	Noise Management F	lans			
Performance Indicator(s)	No complaints from adjacent premises or community regardin     Acceptable noise levels (dBA)	residential and	commercial		
	No complaints from adjacent premises or community regarding	residential and	commercial Timing		



Solid Waste Management Plans							
Performance Indicator(s)	<ul> <li>Sludge waste as well as hazardous wastes will be appropriately disposed.</li> <li>Recycling or reuse of all recyclable wastes.</li> <li>Removed from on-site at regular intervals.</li> </ul>						
Impact	Control(s) Responsibility Timing						
Control(s) of Production waste and Hazardous waste	<ul> <li>Provide segregated the waste type and adequate size of waste bins.</li> <li>Dispose wastes regularly and not to allow wastes overflow from bins or accumulate on-site.</li> <li>Apply 3Rs management (Reduce, Reuse and Recycle)</li> <li>Improve notice sign and awareness display board (non-smoking, no-dumping signs).</li> <li>Ensure licensed contractors or YCDC are used to collect hazardous wastes.</li> </ul>	Plant Manager  Site Supervisor  HSE Supervisor	Throughout processing phase				
	<ul> <li>Train employees to store and handle hazardous waste.</li> <li>Hazardous wastes are segregated in the secured bin and disposed by the license collector or YCDC hazardous waste collection department.</li> </ul> Traffic Management Plans						
Performance Indicator(s)	Performance • Public complaint with regards to traffic congestion.						



TACTORT					
Impact	Control(s)	Responsibility	Timing		
Control(s) -Training	<ul> <li>To schedule delivery movements outside of peak vehicle traffic times.</li> <li>Reducing the vehicles use and collaborated using on same route of vehicles.</li> <li>Be sure that trucks and other vehicles are in good working order.</li> <li>Follow the established truck routes in the community.</li> <li>Driver behaviour, awareness and training should be undertaken.</li> </ul>	Plant Manager  Site Supervisor  HSE Supervisor  Truck Operators	Throughout processing phase		
	Occupational Health and Saf	ety Plan			
Performance Indicator(s)	Accident and Incident statistics.				
Impact	Control(s)	Responsibility	Timing		
Control(s) of -Accidents -Drinking -Traffic safety	<ul> <li>The first aid kits and emergency medical boxes are supplied sufficiently.</li> <li>Nearest hospital phone numbers in the factory.</li> <li>Providing purified drinking water for all workers.</li> <li>Improve the driving skills and requiring licensing of drivers.</li> </ul>	Plant Manager  Site Supervisor Factory Doctor/Nurse  HSE Supervisor	Throughout processing phase		
-	Fire extinguishers and facilities.				



45

-Safety measure	<ul> <li>All workers should be provided with proper Personal Protective Equipment.</li> <li>Fire drill will be conducted once per year.</li> <li>Providing competency training</li> </ul>					
	Community Health and Safe	ty Plan				
Performance Indicator(s)	Public complaints.					
Impact	Control(s) Responsibility Tim					
Control(s)	<ul> <li>Sludge wastes from septic tank are removed biannually.</li> <li>Reused and recycled waste.</li> <li>Traffic safety is promoted.</li> </ul>	Plant Manager Site Supervisor	Throughout processing phase			

#### 1.7.3 Management Budglet

Overall budget for the implementation of environmental management and monitoring activities will be kyats 11,000,000/year and described detail in the following tables.

Environmental Management Team will inform about the top management getting more budget allocation if the environmental financial arrangement is insufficient. The top management will ensure to provide necessary financial assistant for EMP.



#### **Table 1.13 Budget Allocation for Monitoring Plan**

Sr.	Description	Annually Estimated Budget (Kyats)	Remark
1	Monitoring Plan for Construction Phase	4,090,000	Section:10.5,
2	Monitoring Plan for Operation Phase	5,120,000	Section:10.6,
3	Monitoring Plan for Decommissioning Phase	1,790,000	Section:10.7,
	Total	11,000,000	

#### 1.7.4 Monitoring Plan

Table 1.14 Proposed Environmental Monitoring Programme- Operation Phase

Environmental Issues	Monitoring Location	Point of Compliance	Monitoring and Reporting Frequency	Annual Budget (Kyats)	Responsibility Party
	Air Pollution				
Env.Standard	National Envir	onmental Quality (	Emission) Guidel	ine for Air E	mission
Parameters	SO2, NO2, CO,	PM2.5, PM10, dus	ts and O3 concent	rations	
Ambient Air Quality	Near Factory Gate	14° 36' 56.3" N 98° 04' 30.2" E	Twice a year	1200000 (600000x 2) (Monito ring fees)	EMT Team  HSE Representative  External Consultant firm
		Noise			
Env.Standard	National Envir	onmental Quality (	Emission) Guidel	ine	
Parameters	Leq (dB(A))				
Noise level dB(A)	Near Factory Gate	14° 36' 56.3" N 98° 04' 30.2" E	Twice a year	100000 (50000x2)	EMT Team  HSE Representative



	I			1	г. 1
					External Consultant firm
					Consultant inin
Water Quality					
Env.Standard	Env.Standard WHO Drinking water Quality Guidelines				
Parameters (Underground Water Quality)	(Underground Total Alkalinity, Sodium, Calcium, Magnesium, Potassium, Iron, Chloride,				
(Drain water Quality)		ygen, Biochemical ( d solids, Oil and Gr	, ,	Chemical O	xygen Demand,
Underground Water Quality	Factory Tube Well (Tap Water)	17° 10.457′N 095° 58.889′ E	Twice a year	360000 (180,000x	EMT Team  HSE  Representative
Wastewater Quality (Drain water)	Drainage outlet	17° 10.409′ N 95° 58.969′E	Twice a year	(labora tory tests fees)	External Laboratory for water quality tests
	Solid W	aste generation fro	m Production Pro	ocess	
Parameters	- Generation of	f waste, storage, rec	ycling, transport	and disposal	
	- Waste recycle	e plan, removed from	m on-site at regul	ar intervals.	
Non- Hazardous Waste	- Cleanliness	The whole factory	Daily	No Extra Cost	Cleaner
	- Inspect waste storage areas ( Visual check)	17° 10′ 27.9′′ N 95° 58′ 53.2′′E	Daily	-	Supervisor
	Remove regularly to final disposal point in Industrial Zone	Designated disposal point in Industrial Zone	Weekly	960,000 (80000x1 2)	Supervisor Township Municipal



Hazardous Waste  (eg. Sludge waste from septic tank, Spent oils)	-Inspect storage area (Visual check) -Disposed sludge waste from septic tank	-	Weekly  Biannually	No Extra Cost 1,000,000	HSE personnel Supervisor
		Health and	Safety		
Parameters	- Medical kit box, fire evacuation, emergency plan, PPE, safe			PPE, safety s	igns.
Safety Measures for Health Status	•	compliance with Health and Safety irst Aid box)	Monthly inspection for health and safety at work place	-	Supervisor
Fire Safety Measures	-Firefighting tr	aining and drill	Annually	500,000	HSE personnel EMT Team
Emergency Safety Measure	First Aid Train	ing	Annually	500,000	HSE personnel EMT Team
	Providing PPE		Monthly	500,000	

#### 1.8 Conclusion

This Environmental Management Plan (EMP) was carried out for the Giant 999 Steel Manufacturing Factory.

Baseline monitoring of ambient air quality, underground water quality, soil pH, noise level demonstrated that all monitoring results are within the National Emission Standards and acceptable levels.

In accordance with the assessment data, the impacts on ambient air quality are generated from the use of furnace, using generator and exhaust gases from the trucks and cars. The furnace is equipped with the effective de-dust controller system.



Generator and all vehicles are regularly inspected and maintained to reduce the exhaust gas emissions.

The provision of effective environmental management and monitoring plans by the factory will mitigate the potential environmental and social impacts. In general, environmental impacts from air and water pollutions are considerably low as the factory has installed dust collecting system.

During public consultation, respondents were positive on the project for the operation of factory and major concern was health care for employees.

During the Project assessment process, over 50 employees are local people. Local employment is the main socio-economic benefit that the factory can directly bring to people living in the community nearest to the factory. The negative impacts on the environment generated by the plant activities can be manageable.



### 1.0 အကျဉ်းချုပ်အစီရင်ခံစာ

စက်ရုံ၏ လုပ်ငန်းဆောင်တာ များကြောင့် ဖြစ်ပေါ်လာမည့် ပတ်ဝန်းကျင်ဆိုင်ရာ သက်ရောက်မှုများ ကို စီမံခန့်ခွဲရာတွင် အရေးပါသည့် ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ် Environmental Management Plans (EMP) ကို ကနဦးလေ့လာတွေ့ ရှိချက်များနှင့် အကဲဖြတ်ချက်များ အရ ရေးဆွဲထားပါသည်။ EMP သည် ကျန်းမာရေး၊ လုပ်ငန်းခွင် အန္တရာယ် ကင်းရှင်းရေး နှင့် ပတ်ဝန်းကျင်ဆိုင်ရာ စီမံခန့်ခွဲမှုစနစ် တွင် အရေးပါသော အစိတ်အပိုင်း တစ်ခုပင်ဖြစ်သည်။ စက်ရုံ လည်ပတ်မှုကြောင့် ဖြစ်ပေါ်လာမည့် ပတ်ဝန်းကျင်ဆိုင်ရာ ဆိုးကျိုးများ ကိုသင့်လျော်စွာ စီမံလုပ်ဆောင်နိုင်ရေးအတွက် EMP ကို အသုံးပြုနိုင်ပါသည်။

ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှုအစီအစဉ် (EMP) ရေးသားခြင်း လုပ်ငန်းအဆင့်ဆင့်ကို ဒီဇင်ဘာလ ၂၀၁၉ ခုနှစ်တွင် ပြုလုပ်ခဲ့ပြီး ဇူလိုင်လ ၂၀၂၀ ခုနှစ်တွင် ပြီးဆုံးခဲပြီး EMP စာအုပ်ကို ဇူလိုင် ၂၀၂၀ နေ့တွင် တင်ပြခဲ့ပါသည်။

## ၁.၁ နိဒါန်း

စက်ရုံမှာ "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" လုပ်ကိုင်သောစက်ရုံဖြစ်ပြီး ပိုင်ရှင်မှာ ဒေါ်စိန်ရီ ဖြစ်ပါသည်။ မှော်ဘီမြို့နယ် စည်ပင်သာယာရေးကော်မတီ ၏ ၇-၁၁-၂၀၁၉ ရက်စွဲပါစာအရ လုပ်ငန်းလိုင်စင်ရရှိထားပြီး စက်ရုံသည် အကွက်အမှတ် (၂၀/၂၁)၊ မြောင်းတကာစက်မှုစုန်၊ မှော်ဘီ မြို့နယ်၊ ရန်ကုန်တိုင်း ဒေသကြီး တွင်တည်ရှိပါသည်။

အဓိကလုပ်ငန်းမှာ သံရည်ကျိုလုပ်ငန်း ဖြစ်ပြီး U Beam and Angle Bar များကို ထုတ်လုပ်ပါသည်။ စက်ရုံသည် ၂၀၁၁ ခုနှစ် ဧပြီလတွင် စတင်တည်ဆောက်ခဲ့ပြီး ၂၀၁၂ ခုနှစ်တွင် လည်ပတ်ခဲ့ပါသည်။ ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" ၏ ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီရင်ခံစာကို Green Environmental, Health, Safety & Social Consultancy Company Limited မှရေးဆွဲပေးပါသည်။

## ၁.၂. ဥပဒေကြောင်းဆိုင်ရာ လိုအပ်ချက်

(EMP) အဖွဲ့သည် "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" ၏ စက်ရုံမှ ဥပဒေဆိုင်ရာလိုက်နာရန် လိုအပ်ချက်များပါ အောက်ဖော်ပြပါ အချက်များအပေါ် လိုက်နာမှု ရှိစေရန် သေချာစွာ စောင့်ကြည့် လေ့လာမှု ပြုထားပါသည်။

• ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး ဥပဒေ (၂၀၁၂) နှင့် ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး နည်းဥပဒေများ (၂၀၁၄)



- မြန်မာရင်းနှီးမြုပ်နှံမှု ဥပဒေ
- အနည်းဆုံး လုပ်ခ လစာ ဥပဒေ (မတ် လ ၊ ၂၀၁၃)
- မြန်မာ့ အာမခံ ဥပဒေ (၁၉၉၃)
- လူမှုဖူလုံရေး ဥပဒေ (၂၀၁၂)
- စက်ရုံများ အက် ဥပဒေများ (၁၉၅၁)
- အလုပ်သမား နစ်နာကြေး အက်ဥပဒေ (၁၉၂၃)
- ပြည်သူ့ ကျန်းမာရေး ဥပဒေ
- မြေအောက်ရေ အက်ဥပဒေ (၁၉၃၀)
- မြို့တော် ဖွံ့ဖြိုးရေး ဥပဒေ နှင့် စည်းမျဉ်းဥပဒေများ
- ရေစွမ်းအားအရင်းအမြစ် အက်ဥပဒေ (၁၉၇၂)

## ၁.၃. စီမံကိန်းအကြောင်းဖော်ပြချက်

## ၁.၃.၁. စီမံကိန်းတည်နေရာ

"ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" ၏ သံရည်ကျိုစက်ရုံသည် အကွက်အမှတ် (၂၀/၂၁)၊ မြောင်းတကာစက်မှုဇုန်၊ မှော်ဘီမြို့နယ်၊ ရန်ကုန်တိုင်း ဒေသကြီး တွင်တည်ရှိပါသည်။ မြောက် လတ္တီ ကျု ၁၇° ၁၀' ၂၅.၅" နှင့် အရှေ့လောင်ဂျီကျု ၉၅° ၅၈' ၅၅.၅" (17.173743, 95.982095) တွင် တည်ရှိပါသည်။ စက်ရုံမြေ အကျယ်အဝန်းမှာ ၆.၃ ဧက နှင့် အဆောက်အဦး အကျယ်အဝန်း ၅.၃ ဧက ရှိပါသည်။ မြန်မာနိုင်ငံသား ရင်းနှီးမြုပ်နုံမှု အမျိုးအစားဖြစ်ပါသည်။



ပုံ ၁.၁ ကုန်ထုတ်လုပ်သည့်ဧရိယာ





ပုံ ၁.၂ စက်ရုံနှင့် ကိုဩဒိနိတ်အမှတ်များ







ပုံ ၁.၃ စက်ရုံတည်နေရာပြပုံ

## ၁.၃.၂ စီမံကိန်းကာလ


စက်ရုံစီမံကိန်းကာလမှာ ၂၀၁၁ ခုနှစ် ၆.၉.၂၀၁၁ ခုနှစ်မှ လိုင်စင်သက်တမ်းတိုး၍ နှစ်စဥ်ဆောင် ရွက် ပါ သည်။ စက်ရုံစီမံကိန်းကာလမှာ နှစ် ၃၀ ဖြစ်ပါသည်။

## ၁.၃.၃ လုပ်ငန်းခွင် နေရာချထားမှုပုံစံ

**ဖယား ၁.၁ အဆောက်အဦးစာရင်း** 

Sr	Building
1	Office Building
2	စက်ရုံဂိတ်
3	ဝန်ထမ်းဆောင်
4	တွင်ခုံ
5	Dust Collection (De-dusting) System
6	သံရည်ကျိုဆောင်
7	သံတို သံစ ကုန်ကြမ်းဆောင်+ စတို
8	သံနန်းဆွဲ + ကုန်ချော
9	အမှိုက်ပုံဟောင်း
10	အဆောင်ဟောင်း





ပုံ ၁.၄ စက်ရုံ အနေအထားအပြင်အဆင်

## ၁.၃.၄ တစ်နှစ်ကုန်ကြမ်းလိုအပ်ချက်

အဓိကကုန်ကြမ်းများ မှာ အသုံးပြုပြီးသော သံအပိုင်းအစများ သံတိုသံစများ ဖြစ်ပါသည်။ မြန်မာ နိုင်ငံ အနှံ့မှ သံတိုသံစများကို လာရောက်ရောင်းချကြပါသည်။ အဆိုပါ ကုန်ကြမ်း များကို စက်ရုံ၏ သိုလှောင်ရုံတွင် ထားရှိ ပါသည်။ တစ်လလျှင် ၄၀ တန် (တစ်နှစ်လျှင် သံတိုသံစကုန်ကြမ်း ၄၈၀ တန်ခန့်) ရှိပါသည်။ သံတိုသံစ ကုန်ကြမ်းများကို စက်ရုံဝင်းအတွင်းရှိ ကွန်ကရစ်ခင်း နှင့် အမိုးမိုးထား သော အဆောက်အဦးအတွင်း တွင်ထားရှိပါသည်။

သဘာဝပတ်ဝန်းကျင် ထိခိုက်မှု မရှိစေရန် Chemical ပစ္စည်းများဖြစ်သော Silicon နှင့် Manganese များကို Chemical Room ထဲသို့ ထည့်ပါသည်။ ကားပေါ် မှ ကရိန်းချိတ်များဖြင့် Chemical အိတ်များကို မရန် ကရိန်းမောင်းပညာရှင် မှ Chemical Room ထဲသို့ စနစ်တကျ ထည့်ပါသည်။ Chemical Room ထဲသို့ တာဝန်ရှိသူမှလွဲ၍ အပြင်လူများ မဝင်ရပါ။ Chemical ပစ္စည်းလာထုတ်သော သူမှအပ ပေး၍ မဝင်ပါ။



## **ယေား ၁.၂ တစ်နှစ်ကုန်ကြမ်းလိုအပ်ချက်များ**ပြယေား

စ်၌	အမျိုးအစား	ဓာတ်ပုံ	ပမာဏ (နှစ်)
Э	သံတိုသံစဟောင်း		၄၈၀ တန်
J	စီလီကွန်		၄.၂ တန်
3	မဂ္ဂနစ်		၆.၂ တန်



ပုံ ၁.၅ သံတိုသံစ ကုန်ကြမ်းများ သိုလှောင်ရာ နေရာ





ပုံ ၁.၆ ဓာတုပစ္စည်းသိုလှောင်ခန်းအတွင်း စီလီကွန် နှင့် မဂ္ဂနစ် တို သိမ်းဆည်းထားပုံ



ပုံ ၁.၇ ဓာတုပစ္စည်းသိုလှောင်ခန်းတွင် သတိပေးဆိုင်းဘုတ်များ နှင့် MSDS ထားရှိပုံ

## ၁.၃.၅ ကုန်ထုတ်လုပ်မှုလုပ်ငန်းစဉ်

ပြည်တွင်း ကုန်ကြမ်း သံတိုသံစ များကို အရည်ကျိုပြီး သံရည်ကျို ခံအိုး တွင် သွန်ထည့်ပါသည်။ သံရည်ကျိုအိုးမှ တဆင့် လျှောက်လမ်းသို့ သံရည်လောင်းထည့်ပြီး squareတုံး အဆင့် ရောက်ပါသည်။ squareတုံး မှ U Beam စက်သို့ ဖြတ်ပြီး U Beam များထွက်လာပါသည်။ ထွက်လာသော U Beam များ cutter စင်ပေါ်သို့ ရောက်ပြီး ဖြတ်စက်ဖြင့် ဖြတ်ပါသည်။ ဖြတ်ပြီးသော U Beam များကို ပါကင်ထုတ်ပါသည်။ ထုတ်ပြီးသော U Beam များကို ကရိန်းနှင့် သယ်ပြီး ကုန်ချောဂိုဒေါင်သို့ ပို့ပါသည်။





ပုံ ၁.၈ ထုတ်လုပ်ပုံလုပ်ငန်းအဆင့်ဆင့်

၁.၃.၆ စက်ပစ္စည်း ကိရိယာများ

**ဖေား ၁.၃ စက်ပစ္စည်း ကိရိယာများစာရင်း** 

စဥ်	အကြောင်းအရာ	အရေအတွက်
Э	သံရည်ကျိုအိုးကြီး	9
J	သံရည်ကျိုအုပ်ဆောင်း	9
5	သံရည်ကျို လျှောက်လမ်း	0
9	နန်းဆွဲစက်	2
၅	ပါကင်စက်	J
G	ဖြောင့်စက်	0
9	ကတ္တာစက် (ဖြတ်စက်)	9
െ	ကရိန်း	G

## ၁.၃.၇ ထုတ်ကုန်အမျိုးအစား နှင့် ထုတ်လုပ်မှုပမာဏ

အဓိကထုတ်ကုန်ဖြစ်သည့် U Beam and Angle Bar တို့သည် တစ်နှစ်လျှင် ၄၂၀ တန်ခန့် ထုတ်လုပ် ပါသည်။ စက်ရုံ၏ ကုန်ချောများကို ကုန်ချောသိုလှောင် နေရာတွင် ပုံပါအတိုင်းစနစ်တကျ ထားပါ သည်။





ပုံ ၁.၉ ကုန်ချောပစ္စည်း နှင့် ထားရှိပုံ

## ၁.၃.၈ လူစွမ်းအားအရင်းအမြစ်လိုအပ်ချက်

စက်ရုံသည် ပုံမှန်အားဖြင့် တစ်လလျှင် အလုပ်တက်ရက် ၂၆ ရက်ဖြစ်ပြီး တစ်နှစ်လျှင် ၂၉၀ ရက် ဖြစ်ပါသည်။ အလုပ်လုပ်ချိန်မှာ ယေဘူယျ အားဖြင့် တစ်နေ့ လျှင် ၈ နာရီဖြစ်ပါသည်။

## eယား ၁.၄၂၀၁၉ ခုနှစ်၊ နိုဝင်ဘာလ ၁ ရက်နေ့ ရှိဝန်ထမ်းအင်အားeယား

စဉ်	ဂန်ထမ်းအမျိုးအစား	ကျား	မ	စုစုပေါင်း
၁	နိုင်ငံခြားသား	၁၅	-	၁၅
J	ပြည်တွင်း	<b>9</b> J	ଚ	၅၀
Total		99	ଚ	၆၅

## ၁.၃.၉ ရေလိုအပ်ချက်

ကုန်ထုတ်လုပ်မှု အတွက် အသုံးပြုသည့် ရေကို အဝီစိတွင်း ၁၀ တွင်းမှရရှိပါသည်။ အသုံပြုသောရေကို recycled လုပ်၍ ပြန်လည်အသုံးပြုပါသည်။ အသုံးပြုသော ရေပမာဏမှာ ခန့်မှန်းခြေ တစ်နှစ်လျှင် ၆၀၀၀ ဂါလန် ဖြစ်ပါသည်။

စက်ရုံအတွင်း တူးဖော်ထားသော အဝိစိတွင်းများမှာ ၆လက်မ ပေ၁ဂ၀ တွင်း ၆ တွင်းနှင့် ၃လက်မ ပေ၈၀ တွင်း ၄တွင်းရှိပါသည်။ ၆လက်မ ပေ၁၀၀တွင်း ၆တွင်း ၏တည်နေရာမှာ (က)အရည်ကျိုဋ္ဌာန တွင် ၄ တွင်း (ခ) ပါကင်ဋ္ဌာနတွင် ၂ တွင်းရှိပါသည်။ ၃လက်မ ပေ၈၀ တွင်း ၄တွင်း ၏ တည်နေရာမှာ (က) ပါကင်ဖက်၏ အဆုံးနေရာ တွင် ၁ တွင်း (ခ) အမျိုးသားအဆောင် အနီးတွင် ၁ တွင်း (ဂ) တွင်ခုံ အနီးတွင် ၁ တွင်း နှင့် (ဃ) အလယ်ပါကင် တွင် ၁ တွင်း ရှိပါသည်။



### ၁.၃.၁၀ လျှပ်စစ်ဓာတ်အား

စက်ရုံသည် ရန်ကုန်မြို့တော် မီးပေးဝေရေးမှ လျှပ်စစ်ကိုရရှိပြီး 6300 KVA, 6300KVA, 6300KVA, 2000KVA, 2000KVA and 3000KVA ထရန်စဖော်မာ ၅၀၀ KVA နှင့် ၅၇၅ KVA လျှပ်စစ်ထုတ်စက် နှစ်လုံးရှိပါသည်။ တစ်နှစ် ဒီဇယ်လိုအပ်ချက် ၁၉၀၀ ဂါလံ ဖြစ်ပါသည်။ လစဉ် လျှပ်စစ်မီးလိုအပ်ချက်မှာ ၁၅၂,၂၈၈ ယူနှစ်ဖြစ်ပါသည်။

## ဒီဇယ်သိုလှောင်ခြင်း

အရန်ဓာတ်အားအဖြစ် ထားရှိသည့် မီးစက်များအတွက် လိုအပ်သော ဒီဇယ် တစ်နှစ်စာ ၁၉၀၀ ဂါလံ (တစ်နေ့လျှင် ၅ ဂါလံကျော်) ကို သံဆီလှောင်ကန် နှင့်စနစ်တကျသိုလှောင်ထားရှိပါသည်။ ဒီဇယ်ဆီကို ထော်လာဂျီကား အသုံးပြုရာတွင် ထည့်၍မောင်းနှင်ခြင်း၊ ကရိန်းမောင်းရာတွင် လည်း မီးပျက်လျှင် မီးစက်နှိုး ၍မောင်းနှင်ခြင်း တို့အတွက်လည်း အသုံးပြုပါသည်။ သဲအိပ်များ ထားရှိခြင်း၊ MSDS များကပ်ထားခြင်း၊ အန္တရာယ်ဆိုင်းဘုတ်၊ သတိပေးဆိုင်းဘုတ်များ ကပ်ထားပြီး အခြားဖိတ်စင်မှု မရှိအောင် သိမ်းဆည်း ထား ပါသည်။





ပုံ ၁.၁၀ သံဆီလှောင်ကန်ပုံ နှင့်MSDS များကပ်ထားခြင်း၊ အန္တရာယ်ဆိုင်းဘုတ်၊ သတိပေးဆိုင်းဘုတ်များ ကပ်ထားခြင်း သဲအိပ်များ ထားရှိပုံ




## ၁.၃.၁၁ စွန့်ပစ်ပစ္စည်း

မီးဖိုချောင်သုံး နှင့် ပုံမှန်အမှိုက်များကို အမှိုက်ပုံသို့ စက်ရုံမှ ကားဖြင့် တစ်ပတ်လျှင် ၃ ကြိမ်ခန့် သွားရောက်စွန့်ပစ်ပါသည်။ စက်ရုံသည် တစ်လလျှင် ပျှမ်းမျှ အမှိုက် ၁.၅ ကီလိုဂရမ် (၁၈ ကီလိုဂရမ်/ တစ်နှစ်) စွန့်ပစ်ပါသည်။ အချို့သော စားကြွင်း စားကျန် အမှိုက်များကို စက်ရုံဝန်ထမ်းအချို့မှ တိရိစ္ဆာန်စာ (ဝက်စာ) အဖြစ် သိမ်းဆည်းယူဆောင်သွားပါသည်။

စက်ရုံအတွင်းဝန်ထမ်းဆောင်မှ ထွက်ရှိသော အမှိုက်များ နှင့် စားဖိုဆောင်မှ ထွက်သော အမှိုက်များ ကို စက်ရုံမှ ကားဖြင့် မြောင်းတကာ စက်မှုစုန် အတွင်း သတ်မှတ်ထားသော အမှိုက်ပုံသို့ တစ်ပတ်လျှင် သုံးကြိမ် စွန့်ပစ်ပါသည်။ စက်ရုံမှ ကားအားလပ်မှု မရှိလျှင် စည်ပင်အား အကြောင်းကြား၍ စည်ပင်ကား ဖြင့် စွန့်ပစ်ပါသည်။ စည်ပင်ကားမှ သယ်ဆောင်သွားသော အမှိုက်များအား သက်ဆိုင်ရာ မှ ၄င်းတို့သတ်မှတ်ထားသောနေရာ အားယူဆောင်သွားပါသည်။

သံထုတ်ကုန်များ၏ အကျိုးအပဲ့များ၊ ထုတ်ကုန်အပယ်များ၊ ဖြတ်စအပိုများ ကို သံရည်ကျိုသည့် အခါ ပြန်လည်ကျိုပြီး ရီဆိုင်ကယ်ပြုလုပ်ပါသည်။ စက်ရုံ၏ dust collecting system မှလည်း သံချော်ပြာ များကို တစ်လလျှင် ၂၀၀ ကီလိုဂရမ် ခန့် ရရှိပြီး ၄င်းတို့ကို ရီဆိုင်ကယ်ရည်ရွယ်ချက်အရ ဝယ်ယူသူသို့ ပြန်လည် ရောင်းချပါသည်။ ထွက်ရှိလာသော မီးခိုးပြာများကို Carbon တုံးများ ထုတ်လုပ်သော လုပ်ငန်းသို့ အများဆုံး ပြန်လည်ရောင်းချပါသည်။





ပုံ ၁.၁၁ ကုန်ထုတ်လုပ်မှု နှင့် စွန့်ပစ်ပစ္စည်းထွက်ရှိမှုအဆင့်ဆင့်




ပုံ ၁.၁၂ စက်ရုံ စွန့်ပစ်ပစ္စည်း စွန့်ပစ်နေရာ နှင့်စွန့်ပစ်ပစ္စည်း ရှင်းလင်းနေပုံ



## ၁.၃.၁၂ အမှုန် နှင့် အနံ့ ဖမ်းစနစ်

စက်ရုံ၏ မီးပြင်းဖိုဖြင့် သံရည်ကျို ခြင်း မှ လေထုအတွင်းသို့ အမှုန်များ ထုတ်လွှတ်မှုများရှိပါသည်။ ထို့ကြောင့် စက်ရုံသည် Iron Powder Fume Dust Collecting system ကို အောက်ဖော်ပြပါ ပုံအတိုင်း တည်ဆောက်တပ်ဆင် အသုံးပြုလျက်ရှိပါသည်။



ပုံ ၁.၁၃ Iron Powder Fume Dust Collecting အဆောက်အဦး

၁.၄. ပတ်ဝန်းကျင်ဆိုင်ရာ အခြေခံ အရည်အသွေးများ

၁.၄.၁ စက်ရုံပတ်ဝန်းကျင် ဖော်ပြချက်

Giant 999 Steel Manufacturing Factory သည် အကွက်အမှတ် (၂၀/၂၁)၊ မြောင်းတကာစက်မှုဇုန်၊ မှော်ဘီမြို့နယ်၊ ရန်ကုန်တိုင်း ဒေသကြီး အတွင်းတွင်တည်ရှိပါသည်။ စက်ရုံ ၏ ဘေးပတ်လည်တွင် အခြား သော စက်မှုလုပ်ငန်းများ၊ စက်ရုံများ တည်ရှိမှုအနေအထားမှာ ပုံပါအတိုင်း ဖြစ်ပါသည်။

အရှေ့ : မြန်မာ ဆန်းဘဲလ် စက်ရုံ

အနောက်: စက်မှုမြေကွက်လပ်

တောင် : အထည်ချုပ်စက်ရုံ

မြောက် : လျှပ်စစ်ဓာတ်အားခွဲရုံ






ပုံ ၁.၁၄ စက်ရုံတည်နေရာ နှင့် ပတ်ဝန်းကျင် ဧရိယာပြပုံ

## ၁.၄.၂ ရုပ်ပိုင်းဆိုင်ရာပတ်ဝန်းကျင်

မှော်ဘီမြို့နယ်၏ ရာသီဥတုသည် အပူပိုင်းရာသီဥတု ဖြစ်ပါသည်။ အပူဆုံးရက်သည် ဧပြီလ ၁၂ ရက် ဖြစ်ပြီး အမြင့်ဆုံးအပူချိန် ၃၆ ဒီဂရီ စင်တီဂရိတ် နှင့် အနိမ့်ဆုံးအပူချိန် ၂၅.၅ ဒီဂရီ စင်တီဂရိတ် တို့ဖြစ်ပါသည်။ အအေးဆုံးရက်သည် ဇန်နဝါရီလ ၁၀ ရက်ဖြစ်ပြီး အမြင့်ဆုံးအပူချိန် ၁၉.၄ ဒီဂရီ စင်တီဂရိတ် နှင့် အနိမ့်ဆုံးအပူချိန် ၃၁.၁ ဒီဂရီ စင်တီဂရိတ် တို့ဖြစ်ပါသည်။ မိုးအများဆုံးရွာသွန်းသည့် လမှာ ဇူလိုင်လဖြစ်ပြီး ပျမ်းမျှမိုးရေချိန်သည် ၉.၁ လက်မ ဖြစ်ပါသည်။

စက်ရုံပတ်ဝန်းကျင် မြေမျက်နှာပြင်သည် မြေမျက်နှာပြင်သည် မြေပြန့်ဒေသဖြစ်ပြီး ခန့်မှန်း ချေ အားဖြင့် အမြင့်ပေ ၂၀ပေ မှ ၃၆ပေ အထိ မြင့်ပါသည်။ Giant 999 Steel Manufacturing Factory သည် မြောင်းတကာစက်မှုဇုန် အတွင်း တည်ရှိပြီး ပတ်ဝန်းကျင်ရှိ မြေအသုံးချမှုမှာ စက်မှုဇုန် မြေအသုံးချခြင်း ဖြစ်ပြီး ဒေသအတွင်း စက်ရုံများ များစွာ တည်ရှိနေပါသည်။ FAO / UNESCO Soil Classification အရ စက်ရုံပတ်ဝန်းကျင် ရှိ မြေဆီလွှာ မြေအမျိုးအစားမှာ Eutric Gleysols ဖြစ်ပါသည်။





ပုံ ၁.၁၅ မြောင်းတကာစက်မှုဇုန် နှင့် စက်ရုံတည်နေရာပြပုံ

၁.၄.၃ လူမှုစီးပွားဆိုင်ရာပတ်ဝန်းကျင်

မှော်ဘီမြို့နယ်သည် ရန်ကုန်တိုင်းဒေသကြီး၏ မြောက်ပိုင်းခရိုင်တွင် ပါဝင်ပါသည်။

## **ဖောား ၁.၅ မြို့နယ်စာရင်းအချက်အလက်များ**

စဥ်	မြို့	မြို့ဧရိယာ (Sq. Mile)	ကျေးရွာအုပ်စုဧရိယာ (Sq. Mile)
0	မှော်ဘီမြို့နယ်	ල.ට	၁၈၃.၇၈

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

မှော်ဘီမြို့နယ်၏ လူမှုရေးဆိုင်ရာ အချက်အလက်များမှာ အောက်ပါအတိုင်း ဖြစ်ပါသည်။

## eယား ၁.၆ မှော်ဘီမြို့နယ်၏လူဦးရေ စာရင်းပြယေား

	ကျား	<sub>\text{\ti}\text{\texi{\text{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}}\tint{\text{\text{\text{\text{\text{\text{\text{\text{\text{\tin}}\\ \text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}\tint{\text{\text{\text{\text{\text{\text{\text{\text{\text{\ti}}\tint{\text{\text{\text{\text{\text{\tin}}\tint{\text{\text{\tin}}\tint{\text{\text{\text{\text{\tin}}\tint{\text{\text{\text{\text{\text{\text{\text{\text{\texi}\tint{\tiin}\tint{\tiin}\tint{\text{\tin}\tint{\tiin}\tint{\text{\text{\text{\texi}\ti</sub>	စုစုပေါင်း
မြို့	၁၃၀၄၇	၁၃၃၀၅	၂၆၃၅၂
ကျေးရွာ	၈၄၁၆၆	၉၂၃၈၆	၁၇၆၅၅၂
စုစုပေါင်း	<sub>6</sub> ഗിാട	၁၀၅၆၉၁	ეიეციς

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"



## eယား ၁.၇ မှော်ဘီမြို့နယ်၏ ကိုးကွယ်သည့် ဘာသာအလိုက် လူဦးရေ

စဥ်	ဘာသာ	လူဦးရေ
၁	ရ်ဒီသာဘာ	၁၈၅၇၀၀
J	ခရစ်ယာန်	૦ <b>૬</b> ၂૬૧
5	ဟိန္ဒူ	ઉગુઉ
9	အစ်စလာမ်	၂၃၀၁
၅	အခြား	-
မြို့နယ်	<b>ာ</b> စုပေါင်း	ეიეციς



Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

ပုံ ၁.၁၆ မှော်ဘီမြို့နယ်မြေပုံ



၁.၅. ပတ်ဝန်းကျင် နှင့် လူမှုရေးဆိုင်ရာ သက်ရောက်မှုများ နှင့် လျော့ပါးစေရေးနည်းလမ်းများ ၁.၅.၁ သက်ရာက်မှုများကို အကဲဖြတ်ခြင်း

စီမံကိန်း နှင့် ပတ်ဝန်းကျင်ဆိုင်ရာ ထည့်သွင်းစဥ်းစားရမည့် တန်ဘိုးများအကြား အပြန်အလှန် ဆက်စပ်မှုကို အခြေခံ၍ အကျိုးသက်ရောက်မှု၏ သိသာထင်ရှား သည့် အဆင့်အတန်းကို သတ်မှတ် ဖော်ထုတ်ပါသည်။ သိသာထင်ရှားသည့် အကျိုးသက်ရောက်မှုကို ကြိုတင် ခန့်မှန်း ဆုံးဖြတ် ရန်အတွက် အောက်ဖော်ပြပါအချက်များထည့်သွင်းစဥ်းစားပါသည်။

- အကျိုးသက်ရောက်မှု ၏ ပြင်းထန်မှု
- အကျိုးသက်ရောက်မှု ၏ ကာလ
- ပထဝီဝင်ဆိုင်ရာ (သို့) ပတ်ဝန်းကျင်အတိုင်းအတာ
- ဖြစ်ပွားနိုင်ခြေ

လုပ်ငန်းလည်ပတ်သည့် ကာအတွင်း ရေထုညစ်ညမ်းခြင်း၊ လေထုညစ်ညမ်းခြင်း၊ ဆူညံသံ နှင့် မြေထု ညစ်ညမ်းခြင်း များ၏ သက်ရောက်မှုသည် သက်ရောက်မှုမရှိ (သို့) အနည်းငယ် သာ သက်ရောက်သည် ဟု မှတ်ယူနိုင်ပါသည်။ အဘယ့်ကြောင့်ဆိုသော် ထိရောက်မှု ရှိသော ထိန်းချုပ်မှု များ နှင့် သက်ရာက်မှုများ လျော့နည်းအောင်ပြုလုပ်မှုတို့ကြောင့် ဖြစ်ပါသည်။ စီမံကိန်းပိုင်ရှင်သည် လေထုအတွင်း ထုတ်လွှတ်မှုများ ၏ အလားအလာကိုလျော့နည်းအောင် ထိန်းချုပ်နိုင်ရန် de-dust control measures ကဲ့သို့သော အဆင့်မြင့်နည်းပညာ ကို အသုံးပြုမည်ဖြစ်ပါသည်။

ဤ EMP စာအုပ်အား အချိန်မှီ နှင့် သင့်တော်စွာ အကောင်အထည်ဖော်ခြင်းဖြင့် လည်းကောင်း၊ mitigation measures များကို ကောင်းမွန်စွာ အသုံးပြုခြင်းဖြင့် လည်းကောင်း၊ ဖြစ်ပေါ်လာနိုင်သည့် ဆိုးကျိုးကိုဖြစ်ပေါ်နိုင်စေသည့် သက်ရောက်မှုများ အများစုကို မဖြစ်ပေါ်စေရန် ကာကွယ်တားဆီးခြင်း (သို့) နည်းပါးစေမည် ဖြစ်ပါသည်။



eယား ၁.၈ တည်ဆောက်ဆဲကာလအတွက် ပတ်ဝန်းကျင် နှင့် လူမှုရေးဆိုင်ရာ သက်ရောက်မှုများ အကဲဖြတ်ခြင်း

ဆောင်ရွက်မှု	သက်ရာက်မှုများ
ညစ်ညမ်းမှုများ	
- အရန်မီးစက် မှ အမှုန် နှင့် အခိုးအငွေ့ ထုတ်လွှတ်ခြင်း၊ - မော်တော်ယာဉ်များသွားလာခြင်း	လေထုညစ်ညမ်းခြင်း
- ဆောက်လုပ်ရေးပစ္စည်းများသယ်ဆောင်ခြင်း၊ ကိုင်တွယ်ခြင်း၊ သိုလှောင်ခြင်းတို့မှ PM <sub>2.5</sub> and PM <sub>10</sub> အမှုန်များထွက်ရှိမှု	
- ဆောက်လုပ်ရေးပစ္စည်းများပို့ဆောင်ခြင်း၊	ဆူညံသံ နှင့် တုန်ခါမှု
- စက်ယန္တယားများကို မောင်းနှင်အသုံးပြုခြင်း	
- အရန်မီးစက်အသုံးပြုခြင်း	
- ဆိုဒ်အလုပ်သမားများ မှ အသုံးပြု၍ ဖြစ်ပေါ်လာသည့် စွန့်ပစ်ရေ	ရေထုညစ်ညမ်းခြင်း
- ဆောက်လုပ်ရေးပစ္စည်းများ နှင့် စက်ယန္တရားများ သယ် ဆောင်ခြင်း နှင့်	
- မိုးရာသီအတွင်း ဆောက်လုပ်ရေးလုပ်ငန်းများကို လုပ်ကိုင်ခြင်း	
-မြေသားပြုပြင်ခြင်း၊ မြေသားတူးဖော်ခြင်း စသည့် ဆောက်လုပ် ရေးဆိုင်ရာ လုပ်ငန်းများ လုပ်ကိုင်ခြင်း၊ သစ်သား အပိုင်းအစ များ၊ကွန်ကရစ် ဖိတ်စင်မှုများ	စွန့်ပစ်အစိုင်အခဲ
- စက်ပစ္စည်းမျာထိန်းသိမ်း ပြုပြင်သည့် အခါတွင် အသုံး ပြုသည့် အရာများ၊ အသုံးပြုပြီး စက်ဆီများ	
- ဖိတ်စင်သည့် ဆီများ	



ဧယား ၁.၉ စက်ရုံလည်ပတ်သည့် ကာလအတွက် ပတ်ဝန်းကျင် နှင့် လူမှုရေးဆိုင်ရာ သက်ရောက်မှု များ အကဲဖြတ်ခြင်း

	ပတ်ဝန်းကျင်အ ပေါ်ထိခိုက်မှု	သက်ရောက်မှု အဆင့် <sup>*</sup>	
ဆောင်ရွက်မှု		လျော့ပါးစေရန် မပြုလုပ်မှီ	လျော့ပါးစေရေး လုပ်ဆောင်ပြီး
ညစ်ညမ်းမှုများ			
-စီးဆင်းရေ	ရေထုညစ်ညမ်း	အနည်းငယ်	အနည်းငယ်
-ဆီ နှင့် ချောဆီများ ယိုစိမ့်မှု	්	အနည်းငယ်	အနည်းငယ်
-သန့်စင်ခန်း နှင့် မိလ္လာစွန့်ပစ်အရည်		အနည်းငယ်	အနည်းငယ်
- လေထုအတွင်း PM ထုတ်လွှတ်မှုနှင့် မီးဖိုမှ ပြာလွင့်စင်ခြင်း	လေထုညစ်ညမ်း ခြင်း	အနည်းငယ်	အနည်းငယ်
- မော်တော်ယာဉ်များသွားလာမှု - အရန်မီးစက် မှ အမှုန် နှင့် အခိုးအငွေ့ ထုတ် လွှတ် ခြင်း		အနည်းငယ်	အနည်းငယ်
-ကုန်ထုတ်လုပ်မှုလုပ်ငန်းစဉ်တွင် စက် ကိရိယာ များ အသုံးပြုခြင်း - ယာဉ်များ သွားလာခြင်း	ဆူညံသံ နှင့် တုန်ခါမှု	အနည်းငယ်	အနည်းငယ်
- အရန်မီးစက် မှဆူညံသံ ထွက်ရှိခြင်း		အနည်းငယ်	အနည်းငယ်
- မီးဖိုချောင်သုံး ထွက်ရှိသောစွန့်ပစ်အမှိုက်များ -ကုန်ထုတ်လုပ်ငန်းမှ ထွက်ရှိသော ပစ္စည်းများ	စွန့်ပစ်အစိုင်အခဲ	အနည်းငယ်	အနည်းငယ်
ကျန်းမာရေး နှင့် ဘေးအန္တရာယ်			
လုပ်ငန်းခွင်ကျန်းမာရေး နှင့် ဘေးအန္တရာယ်		အနည်းငယ်	အနည်းငယ်
မီးဘေးအန္တရာယ်		အနည်းငယ်	အနည်းငယ်



အရေးပေါ် အခြေအနေ	ဘေးအန္တရာယ်	အနည်းငယ်	အနည်းငယ်
ပြည်သူလူထုကျန်းမာရေး နှင့် ဘေးအန္တရာယ်	နှင့် မတော်တဆ မှုများ	အနည်းငယ်	အနည်းငယ်
လူမှုဝန်းကျင်			
- လူမှုရေးပေါင်းစည်းမှု	လူမှုရေးဆိုင်ရာ	အနည်းငယ်	အနည်းငယ်
-တိုင်းရင်းသားလူနည်းစု	အချက်အလက် များ	အနည်းငယ်	အနည်းငယ်
-လူဦးရေဝင်ရောက်မှု		အသင့်အတင့်	အနည်းငယ်

<sup>\*</sup> သက်ရောက်မှု အဆင့် တွက်ချက်ခြင်းကို ဧယား ၆.၇ တွင် အသေးစိတ် ဖော်ပြထားပါသည်။

# ဧယား ၁.၁၀ စက်ရုံပိတ်သိမ်းသည့် ကာလအတွက် ပတ်ဝန်းကျင် နှင့် လူမှုရေးဆိုင်ရာ သက်ရောက်မှု များ အကဲဖြတ်ခြင်း

ဆောင်ရွက်မှု	သက်ရာက်မှုများ
ညစ်ညမ်းမှုများ	
- ဆောက်လုပ်ရေးပစ္စည်းများသယ်ဆောင်ခြင်း၊ စက်ယန္တရားများ လည်ပတ်ခြင်း	လေထုညစ်ညမ်းခြင်း
-ဖြိုဖျက်သည့်လုပ်ငန်းများ ဆောင်ရွက်ခြင်း	
- ဖြိုဖျက်သည့်လုပ်ငန်းများ ဆောင်ရွက်ခြင်း	ဆူညံသံ နှင့် တုန်ခါမှု
- ပစ္စည်းများ၊ မြေသားများကို စနစ်တကျ စုပုံထားမှု မရှိခြင်း	ရေထုညစ်ညမ်းခြင်း
- ဆိုဒ်အလုပ်သမားများ ဝန်ထမ်းမျာ မှ အသုံးပြု၍ ဖြစ်ပေါ်လာသည့် စွန့်ပစ်ရေ	
- ဖြိုဖျက်သည့်လုပ်ငန်းများ ဆောင်ရွက်ခြင်းမှ ထွက်ပေါ်လာသည့် စွန့်ပစ်အစိုင်အခဲများ	စွန့်ပစ်အစိုင်အခဲ



## ၁.၅.၂ လျော့ပါးစေအောင်ပြုလုပ်သည့်နည်းလမ်းများ

## eယား ၁.၁၁ စက်ရုံလည်ပတ်သည့် ကာလအတွက် လျော့ပါးစေရေး နည်းလမ်းစီမံ ခန့်ခွဲမှု

ရည်ရွယ်ချက်	လုပ်ဆောင်ချက်	အချိန်ကာလ	
စီးဆင်းရေ/ သန့်ရှင်းရေးသုံး စွန့်ပစ်ရေ			
စီးဆင်းရေ ညစ်ညမ်းမှု ပမာဏ လျှော့ချခြင်း	<ul> <li>ရေဆင်းမြောင်းများ အတွင်း အမှိုက်များ အနည် အနစ်များကို ပုံမှန် ရှင်းလင်းဖယ်ရှားရန်</li> <li>စက်ရုံအတွင်း domestic wastewater ကို ပုံမှန် စစ်ဆေးခြင်း သန့်ရှင်းရေးပြုလုပ် ခြင်း</li> <li>ရေနှင့်သန်ရှင်းရေးဌာန သို့ ဆက်သွယ်ပြီး မိလ္လာကန်မှ စွန့်ထုတ်မှု များကို အခါ အား လျှော်စွာ ဆောင်ရွက်ရန်</li> <li>ပြုပြင်ထိန်းသိမ်းသည့် နေရာအား ကွန်ကရစ်ခင်း ဖြင့်ထားရှိရန်</li> <li>ဖိတ်ကျမှုများ ယိုစိမ့်မှုများ ဖြစ်ပေါ်ပါက ချက်ချင်း ရှင်းလင်းရန်</li> </ul>	လုပ်ဆောင်	
ဖန်လုံအိမ် ဓာတ်ငွေ့ ထုတ်လွှတ်ခြင်း			
နီးကပ်သော ဧရိယာတွင် ဖန်လုံအိမ် ဓာတ်ငွေ့ ကို ထိန်းချုပ်ခြင်း	<ul> <li>ထွက်ရှိလာသောပြာကို ထိရောက်စွာ ထိန်းချုပ် နိုင်သည့် စနစ်ရှိသည့် မီးပြင်းဖို ကိုတပ်ဆင် အသုံး ပြုရန်</li> <li>ကုန်ပစ္စည်းထုတ်လုပ်မှုများ နှင့် စက်ရုံတွင် အသုံးပြု သော စက်ပစ္စည်း နှင့် ယာဉ်များအား ပုံမှန် စစ်ဆေး ခြင်းများ နှင့် ပြင်ဆင်ခြင်းများကို ပုံမှန် ပြုလုပ် ပေးရန်</li> <li>သတ္တုအပိုင်းအစများကို ပြန်လည် စုစည်း ၍ ပြန်လည် အသုံးပြုရန်</li> <li>လျှပ်စစ် ထုတ်စက် ကို ပုံမှန် စစ်ဆေး၍ ပြုပြင် ထိန်းသိမ်းရန်</li> <li>စက်ပစ္စည်းများ အတွက် သင့်တော်သည့် လေဝင် လေထွက်စနစ် ထားရှိရန်</li> </ul>		



အမှုန်ညစ်ညမ်းခြင်း			
နီးကပ်သော ဧရိယာတွင် ဖုန်မှုန့် အမှုန်များ ကို ထိန်းချုပ်ခြင်း	<ul> <li>ပိုမိုပြီးပြည့်စုံသည့် သန့်ရှင်းရေး လုပ်ဆောင်မှု များ ကို လိုအပ်သည့်အခါတိုင်း မကြာခဏ ပြုလုပ် ပေးရန်၊</li> <li>ခြောက်သွေ့ရာသီအတွင်း မြေသားလမ်းတွင် ရေဖြန်း ခြင်း ပြုလုပ်ပေးရန်</li> <li>အမှုန်အမွှားများ ထိန်းချုပ်ရန်အတွက် ပိုမိုထိ ရောက် သည့် နည်းလမ်းများ ကို အသုံးပြုရန်</li> <li>နှာခေါင်းစည်းများ အသုံးပြုတပ်ဆင်ရန်</li> </ul>	နေစဉ်ကာလ	
စက်ရုံ အဝန်းအဝိုင်း နှင့် စက်ရုံပတ်လည် ပြင်ပတို့တွင် <b>ဆူညံသံ နှင့် တုန်ခါမှုများ</b>			
ဆူညံသံ၏ သက်ရောက်မှုကို လျော့ချခြင်း	<ul> <li>မီးစက်ကို ပုံမှန် ပြုပြင်ထိန်းသိမ်း မှုများပြုလုပ်ရန်</li> <li>စက်များကို အသံထွက်ရှိမှု လျော့နည်းစေရန် ပုံမှန်</li> <li>စစ်ဆေးပြင်ဆင်ခြင်း</li> <li>ဆူညံသံမြင့်မားသော လုပ်ငန်းခွင်ရှိ လုပ်သားများ</li> <li>အား နားကာ ကိရိယာများ ပေးအပ် တပ်ဆင်</li> <li>စေခြင်း</li> </ul>	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက်လုံး	
အနံ့			
အနံ့ဆိုးများ မထွက်စေရန် ကာကွယ်ခြင်း	<ul> <li>အမှိုက်များကို ကြာရှည်စုံပုံထားခြင်းမရှိစေရန် ပုံမှန် ရှင်းလင်း ဖယ်ရှားခြင်း</li> <li>စွန့်ပစ်ပစ္စည်းများကို သင့်တော်စွာ စွန့်ပစ်ခြင်း</li> </ul>	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက်လုံး	
<b>စွန့်ပစ်အစိုင်အခဲ များ</b> ဖြစ်ပေါ်မှု နှင့် ထားရှိမှု			
စွန့်ပစ်အစိုင် အခဲကို သင့် လျော်စွာ စီမံခြင်း	<ul> <li>ထွက်ရှိသည့်စွန့်ပစ် ပစ္စည်းများ ကို စွန့်ပစ်ပစ္စည်း များ ခွဲခြားခြင်း ကို ပြုလုပ် ၍ အမှိုက်ပုံးများ အတွင်းစွန့်ပစ်ရန်</li> <li>3Rs စီမံခန့်ခွဲမှုကို လုပ်ဆောင်ရန် (စွန့်ပစ်ပစ္စည်း ထွက်ရှိမှု လျှော့ချခြင်း၊ ပြန်လည် သုံးစွဲခြင်း ၊ ပြန် လည်ပြုပြင် သုံးစွဲခြင်း)</li> </ul>	နေစဉ်ကာလ	



စွန့်ပစ်ပမာဏ လျှော့ချခြင်း	• ပြန်လည်ပြုပြင်၍ ရသော ပစ္စည်းများကို recycler ထံသို့ ရောင်းချရန်	
စွန့်ပစ်အစိုင်အခဲ စွန့်ပ	စ်ခြင်း/ ညစ်ညမ်းခြင်း	
domestic waste ကို စီမံခန့်ခွဲ ခြင်း နှင့် စွန့်ပစ်ခြင်း	<ul> <li>စက်ရုံအတွင်း လုံလောက်သော အမှိုက်ပုံးများ ထားရှိရန်</li> <li>စက်ရုံဝန်ထမ်းများအား အမှိုက်အမျိုးအစားများ ခွဲခြားစွန့်ပစ်ခြင်းနှင့် ပက်သက်၍ အသိပညာ ပေး ရန်</li> <li>ဆေးလိပ်မသောက်ရ၊ အမှိုက်မပစ်ရ စသည်ဖြင့် သတိ ပေးဆိုင်းဘုတ်များကပ်ထားရန်</li> <li>စွန့်ပစ်ပစ္စည်းများအား ပြန်လည်အသုံးပြုရန်</li> <li>ပြန်လည်အသုံးမပြုနိုင်သော စွန့်ပစ်ပစ္စည်းများ ကို စည်ပင်ဌာနမှ စွန့်ပစ်ရန်</li> </ul>	
ဘေးအန္တရာယ် ဖြစ်စေ	သော စွန့်ပစ် ပစ္စည်း များ	
ဘေးအန္တရာယ် ဖြစ်စေသော စွန့်ပစ် ပစ္စည်း များ ကို ထိန်းချုပ်ခြင်း နှင့် သက်ရောက်မှုများကို လျော့နည်းအောင် ပြုလုပ်ခြင်း	<ul> <li>အသုံးပြုပြီး စက်ဆီ များကဲ့သို့သော ဘေးအန္တရာယ် ဖြစ်စေသော စွန့်ပစ် ပစ္စည်း များ ကို မြေသား အတွင်းစိမ့်ဝင်ခြင်း (သို့) မြေအောက်ရေ အတွင်း စိမ့်ဝင်ခြင်း မရှိစေရန် ကောင်းမွန်သော ထားသိုရန် ပစ္စည်းအတွင်း ထားရှိရန်၊</li> <li>စက်ရုံသည် ဖြစ်နိုင်လျှင် ဘေးအန္တရာယ် ဖြစ်စေ သော စွန့်ပစ် ပစ္စည်းများ ကို လိုင်စင်ရဘေးအန္တရာယ် ဖြစ်စေသော စွန့်ပစ် ပစ္စည်း များ ပြန်လည်သန့်စင်သည့် waste contractor များနှင့် ဆက်သွယ်ပြုလုပ်ရန်</li> <li>ဓာတုပစ္စည်း (သို့) လောင်စာဆီ သိုလှောင်သည့် နေရာများတွင် သတိပေးဆိုင်းဘုတ်များ တပ်ဆင် ထားရှိရန်</li> <li>မီးစက် အနီး တွင် မီးသတ်ဆေးဗူးများကို ထားရှိထား ရန်</li> </ul>	နေစဉ်ကာလ



## သက်ရှိဇီဝသယံဧာတ

<b>ီဝမျိုးကွဲများ</b> အပေ	r
သက် ရောက်ခြင်း	

- စက်ရုံ အဝန်းအဝိုင်းကို စိမ်းလန်းသာယာ နေစေရန် အတွက် ပန်းပင်များ၊ အပင်များ ကိုစိုက်ပျိုးသွားရန်။
- ဇီဝတန်ဘိုးများ ပျောက်ကွယ်ခြင်းများ မဖြစ်ပေါ် နေစဉ်ကာလ စေရန် အပင်များ ကိုထိန်းသိမ်းခြင်း နှင့် ရေရှည် တစ်လျောက် ထိန်းသိမ်း နိုင်မည့် နည်းလမ်း များ ဖြင့် ဆောင်ရွက် ရန်

လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက်လုံး

## လူမှုပတ်ဝန်းကျင်

## လူမှုရေး ဆိုင်ရာ အချက်များ

- ဒေသခံများကို အလုပ်အကိုင်ခန့်ထားခြင်း
- အခြားဒေသတွင် နေထိုင်သော ဝန်ထမ်းများအား ပန်ထမ်း ကြိုပို့ ကားများစီစဉ်ရန်
- စက်ရုံလုပ်ငန်းစဉ်များနှင့် ပက်သက်၍ ပြည်သူ လူထု ပါဝင်နိုင်ရေး ဆောင်ရွက်ရန်
- စက်ရုံရှိ လပ်လစ်ဝန်ထမ်းနေရာများကို ဒေသ ဆိုင်ရာ ပြည်သူများ သိရှိနိုင်ရေး ဆောင်ရွက်ရန်
- လိုအပ်သည့် အရည်အချင်းပြည့်မှီသည့် ဒေသခံ များအား အလုပ် ခန့်ထားပေးနိုင်ရေး စီမံရန်
- လုပ်ငန်းကျွမ်းကျင်မှု သင်တန်းများ ပြုလုပ်ပေးရန်
- စွန့်ပစ်ပစ္စည်းစီမံခန့်ခွဲမှု၊ ကုန်ပစ္စည်းများ ကိုင်တွယ် ခြင်း၊ ပတ်ဝန်းကျင်ဆိုင်ရာ ကျန်းမာရေး နှင့် လူမှုရေး ဆိုင်ရာ ပြဿနာများ မဖြစ်ပေါ်စေရေး အတွက် ပန်ထမ်း များအား အသိပညာပေးရန်
- ဒေသခံဝန်ထမ်းများ အလားတူအလုပ်များ လွယ်ကူ စွာ ရရှိနိုင်ရေး လုပ်ငန်းကျွမ်း ကျင်မှု ရှိစေရန် စီမံရန်

လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက်လုံး



ရပ်ရွာနှင့် လုပ်ငန်းခွင်	ကျမ်းမာရေး နှင့် ဘေးအန္တရာယ် ကင်းရှင်းရေး	
ပြည်သူလူထု ဘေး အန္တရာယ် ဖြစ်ပေါ် မှုမှကာကွယ် ခြင်း	<ul> <li>ပန်ထမ်းများ အားလုံး အခြေခံ ကျမ်းမာရေး ဗဟု သုတ ရှိစေရန် (ကူးစက်ရောဂါများ မဖြစ်ပေါ် စေရေး ၊ ရှောင်ရှားစေနိုင်ရန်) ပညာပေးရေး လုပ် ဆောင်ရန်</li> <li>ယာဉ်အန္တရာယ် ကင်းရှင်းရေး စီမံထားရှိရန်</li> <li>အရေးပေါ် ကာကွယ်ရေးစီမံချက်ကို ပြုလုပ်၍ အရေး ပေါ် ကာကွယ်ရေးဖွဲ့စည်းခြင်း၊ မီးသတ် ခြင်း၊ ရှေးဦးသူနာပြုစုခြင်း များအတွက် လေ့ကျင့် သင်တန်းပေးရန်</li> </ul>	L .
လုပ်ငန်းခွင် ကျမ်းမာရေး နှင့် ဘေးအန္တရာယ် ကင်းရှင်းရေး	<ul> <li>ပန်ထမ်းများကို သက်ဆိုင်ရာ စက်ပစ္စည်း များ ၊ ကိရိယာများ ကောင်းမွန်စွာ ကိုင်တွယ် အသုံးပြု နိုင်ရန်အတွက် သင်တန်းများ ပြုလုပ်ပေးရန်</li> <li>သက်ဆိုင်ရာ မန်နေဂျာ ၊ ကြီးကြပ်ရေးမှုးများမှ အလုပ်သမားများ သည် လုပ်ငန်းခွင်တာဝန် များကို ကျမ်းမာစွာနင့် ဘေးကင်းလုံခြုံစွာ လုပ်ကိုင်နိုင်ရေး အတွက် အနီးကပ်ကြီးကြပ် ကွပ်ကဲရန်</li> <li>အကာအကွယ်ပစ္စည်းများ PPE ပေးရန်</li> </ul>	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက်လုံး
မီးဘေးကာကွယ် ရေး	<ul> <li>မီးလန့်အချက်ပေးစနစ် အရေးပေါ်မီးများကို တာဝန် ရှိ သူများမှ ပုံမှန်စစ် ဆေးရန်</li> <li>လောင်စာဆီ၊ ဓာတ်ဆီ များကို မီးလောင်လွယ်သည့် ပစ္စည်းများနှင့် ဝေးရာတွင်သာ သိုလှောင် ထားရှိ ရန်နှင့် လောင်စာဆီများ ငြိမ်းသတ်နိုင်သည့် မှန်ကန်သည့် မီးသတ် ဆေးဘူး အမျိုးအစားကို အနီးတွင်တပ်ဆင်ထားရှိရန်။</li> <li>မီးသတ်ဆေးဘူးများကို လိုအပ်သည့် အချိန်တွင် အသုံး ပြုနိုင်ရေး အတွက် အဆင် သင့် ဖြည့်ဆည်း ထားရန်</li> <li>မီးငြိမ်းသတ် သရုပ်ပြကို နှစ်စဥ်ပြုလုပ်ရန်</li> </ul>	လုပ်ဆောင် နေစဉ်ကာလ
လျှပ်စစ်	• သွယ်တန်းတပ်ဆင်ထား သောလျှပ်စစ် နှင့် စက် ပစ္စည်း များအား သတ်မှတ် ထားသည့် အစီအစဉ်	



ဖြင့်စစ်ဆေးကာ ပြင်ဆင်ရန် စစ်ဆေး တွေ့ရှိ နေစဉ်ကာလ
ချက်များ ကိုသက်ဆိုင်ရာ တာဝန်ရှိမန်နေဂျာသို့ တစ်လျောက်လုံး တင်ပြရန်

## ၁.၆ အများပြည်သူနှင့် တိုင်ပင်ဆွေးနွေးခြင်းနှင့် သတင်းအချက်အလက်များ ထုတ်ဖော် တင်ပြခြင်း

ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ် ကိုပြင်ဆင် ရေးဆွဲရာတွင် Green EHSS အကြံပေးအဖွဲ့သည် "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံရှိ တာဝန်ရှိသူများ ၏ကူညီ ထောက်ပံ့မှု များဖြင့် ဒေသ ခံများနှင့် တိုင်ပင်ဆွေးနွေးခြင်း များကို ပြုလုပ် ခဲ့ပါသည်။

၂၀၁၉ ခုနှစ်၊ ဒီဇင်ဘာလ အတွင်း ကုလားကုန်းကျေးရွာအုပ်စု အုပ်ချုပ်ရေးမှူး နှင့် Face to face meeting ပြုလုပ်ခဲ့ပါသည်။

Household interviews ကိုပြုလုပ်ခဲ့ရာ ကုလားကုန်းကျေးရွာအုပ်စုမှ ၆ ဦးတို့က သဘောထား မှတ်ချက်များကို ပေးခဲ့ပါသည်။

၂၀၁၉ ခုနှစ်၊ ဒီဇင်ဘာလ ၁၅ ရက်နေ့တွင်ဒေသခံ ပြည်သူလူထုနှင့် တွေ့ဆုံဆွေးနွေး ညှိနှိုင်းမှုများကို Green EHSS အကြံပေးအဖွဲ့သည် "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံ မှ ကိုယ်စား လှယ်များနှင့် ညှိနှိုင်း၍ ကျင်းပခဲ့ပါသည်။ အဆိုပါ အစည်းအဝေးကို ကုလားကုန်းကျေးရွာ အုပ်ချုပ်ရေးမှူးရုံးတွင် ကျင်းပခဲ့ပြီး တက်ရောက်သူ ၁၇ ဦးရှိခဲ့ပါသည်။

အများပြည်သူနှင့် တိုင်ပင်ဆွေးနွေးခြင်း အစည်းအဝေး ရလာဒ်အရ မကျေနပ်ချက်များ ရရှိခဲ့ခြင်းမရှိဘဲ "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံ ၏ ပတ်ဝန်းကျင်အနီး မှ လည်း တစ်စုံတစ်ရာ ကန့်ကွက်ခြင်းများ လည်းမရှိပါ။

အများပြည်သူနှင့် တိုင်ပင်ဆွေးနွေးခြင်း အစည်းအဝေး တွင် အဓိက တင်ပြကြသော အကြံပြုချက် များမှာ အောက်ပါအတိုင်း ဖြစ်ပါသည်။

- စက်ရုံပတ်ဝန်းကျင် ရေစီးရေလာ ကောင်းမွန်အောင် ပြုလုပ်ပါက ကောင်းမွန်ကြောင်း
- စက်ရုံအားသန့်ရှင်းရေးပြုလုပ်ပါက ကောင်းမွန်ကြောင်း
- စက်ရုံရှိ လစ်လပ်လုပ်သား နေရာများခန့်ထားရာတွင် ပတ်ဝန်းကျင်အနီးရှိ ဒေသခံများကို ဦးစားပေး ခန့်ထားရန်
- မိမိတို့ စက်ရုံအတွင်း မီးဘေးအန္တရာယ် မဖြစ်ပွားစေရန် အတွက် အထူးကြပ်မတ် ဆောင်ရွက်သင့် ကြောင်း
- စက်ရုံရှိ အလုပ်သမားများ အလုပ်လုပ်ရင်း တစ်စုံတစ်ခု ထိခိုက်မှုများရှိလာပါက အထူးဂရုစိုက် ပြုလုပ်ပေးစေလိုကြောင်း



စက်ရုံ မှ ပြန်ကြားချက်များ နှင့် ဆောင်ရွက်မည့် လုပ်ငန်းများကို အခန်း (၈) တွင်ဖော်ပြ ပေးထား ပါသည်။

၁.၇. သဘာဝပတ်ဝန်းကျင် နှင့် လူမှုရေးဆိုင်ရာ စီမံခန့်ခွဲမှု အစီအစဉ့်

## ၁.၇.၁ စီမံခန့်ခွဲမှုအဖွဲ့

စက်ရုံသည် စက်ရုံလည်ပတ်ခြင်းအဆင့်တွင် ပတ်ဝန်းကျင် နှင့် လူမှုရေး စီမံခန့်ခွဲမှုများကို အကောင် အထည်ဖော်ရန် နှင့် စောင့်ကြပ်ကြည့်ရှုရန် တို့အတွက် ပတ်ဂန်း ကျင်စီမံခန့်ခွဲမှုအဖွဲ့ (EMT) နှင့် အရေးပေါ် ကယ်ဆယ်ရေး အဖွဲ့ (ERT) တို့ကို ဖွဲ့စည်း ထားပါသည်။

## <u>ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှုအဖွဲ့ (EMT)</u>

EMT တွင်အောက်ပါ အတိုင်း ဖြင့်ဖွဲ့ စည်းထားပါသည်။

က) မနှင်းဆီ –အဖွဲ့ ခေါင်းဆောင်

ခ) မမြတ်မြတ်ငြိမ်း – ကျမ်းမာရေး၊ လုံခြုံရေး နှင့် ပတ်ဂန်းကျင် ထိန်းသိမ်းရေး ကိုယ်စားလှယ်

ဂ) မမီမီကျော် – အဖွဲ့ ဝင် ဃ) မဇင်မာစိုး – အဖွဲ့ ဝင်

c) ကိုသန့်ဇင် – အဖွဲ့ဝင်

စ) ကိုဖြိုးဝေအောင် – အဖွဲ့ ဝင်

## <u>အရေးပေါ်ကယ်ဆယ်ရေးအဖွဲ့ (ERT)</u>

ERT တွင်အောက်ပါ အတိုင်း ဖြင့်ဖွဲ့ စည်းထားပါသည်။

\_ – အဖွဲ့ခေါင်းဆောင် – အမွဲ့ ခေါင်းဆောင် –ဒုအဖွဲ့ ခေါင်းဆောင် က) ဦးအောင်ဆန်းဦး

ခ) ဦးသန့်ဇင်

ဂ) ဦးမိုးပိုင်ဆင့် – စုရပ် တာဝန်

– ကြီးကြပ် ဃ) မမြတ်မြတ်ငြိမ်း

c) ဦးဝေဖြိုးအောင် – ကြီးကြပ်

စ) ဦးကျော်သီဟ – ကြက်ခြေနီ၊ မီးသတ်

- ကြက်ခြေနီ၊ မီးသတ် ဆ) ဦးကျားရင်

e) ဦးကျော်ဇင် – ကြက်ခြေနီ၊ မီးသတ်



## <u>အစီရင်ခံစာ ထောက်ပံ့ရေးအဖွဲ့ (RST)</u>

(RST)တွင်အောက်ပါ အတိုင်း ဖြင့်ဖွဲ့ စည်းထားပါသည်။:

က) ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှုအဖွဲ့ဝင်တစ်ဦး –အဖွဲ့ခေါင်းဆောင်

ခ) စီမံဌာန ကိုယ်စားလှယ်

-အဖွဲ့ ဝင်

ဂ) လူ့စွမ်းအားအရင်းအမြစ်ဌာနကိုယ်စားလှယ်–အဖွဲ့ ဝင်

## ၁.ဂု.၂ စက်ရုံလည်ပတ်သည့် ကာလအတွက်သဘာဝပတ်ဝန်းကျင် နှင့် လူမှုပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ်

သဘာဝပတ်ဝန်းကျင် နှင့် လူမှုပတ်ဝန်းကျင် များကို ဆန်းစစ်မှုများအရ ဖြစ်ပေါ်လာ နိုင်သည့် သက်ရောက်မှုများ ကို လျော့ပါးအောင်ပြုလုပ်နိုင်ရန်အတွက် ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ် (ENVIRONMENTAL MANAGEMENT PLANS) ကိုရေးဆွဲပြုစုပါသည်။ EMP ၏အဓိက စီမံခန့်ခွဲမှု အစီအစဉ် အကျဉ်းချုပ်မှာ အောက်ပါအတိုင်းဖြစ်ပါသည်။

## eယား ၁.၁၂ သဘာဝပတ်ဝန်းကျင် နှင့် လူမှုပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ် အကျဉ်းချုပ်

စွန့်ပစ်ရေ စီမံခန့်ခွဲရေး အစီအစဥ်များ			
လုပ်ဆောင် ချက် ပြ အညွှန်း (များ)	<ul> <li>စက်ရုံ မြေအောက်ရေ အရည်အသွေးကို စောင့်ကြည့် တိုင်းတာရန်</li> <li>pH, Conductivity, Total Dissolved Solid, Total Hardness, Total Alkalinity, Calcium, Magnesium,</li> <li>စက်ရုံရေမြောင်းရေ တိုင်းတာမှုတွင် BOD, COD,TS တို့ကိုတိုင်းတာရန်</li> </ul>		
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာဝန်ဝတ္တရား	အချိန်
မျက်နှာပြင်ရေ ညစ်ညမ်းမှု	<ul> <li>စက်ရုံသည် စီးဆင်းရေ ထိတွေ့ နိုင်သည့် အရာ များကို သိရှိအောင် ပြုလုပ်ထား ရန် (၄င်းတို့တွင် ကုန် ကြမ်းများ၊ လောင်စာဆီ၊ ဆပ်ပြာ မှုန့်များ၊ ကုန်ချောများ၊ စွန့်ပစ်ပစ္စည်း များပါဝင်ပါသည်။)</li> <li>စက်ရုံသည် စက်ပစ္စည်းများ၊ မြေပြင် များ၊ စက်ရုံပြင်ပ နေရာများတို့ရှိ</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ HSE ကြီးကြပ်သူ	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး



စက်ရုံသန့်စင် ခန်းသုံး မိလ္လာရေများ	စီးဆင်းရေကို ညစ်ညမ်းစေနိုင်သည့် အကြောင်းအရာ များကို ပုံမှန် စစ်ဆေးကြည့်ရှုရန် နှင့် ညစ်ညမ်းမှုမှ ကာကွယ်နိုင်ရေး စီမံခန့်ခွဲရန် • အမှိုက် နှင့် အနည်အနစ် များကို ပုံမှန် ရှင်းလင်းပေးခြင်း • ရေကိုချွေတာသုံးစွဲရန်. • သန့်စင်ခန်းသုံး ရေများအား မိလ္လာကန် သို့သာ စွန့်ပစ်ရန် • စည်ပင် သာယာရေး ကော်မတီ ရေနှင့် သန့်ရှင်းရေး ဌာန သို့ ဆက် သွယ်ပြီး မိလ္လာကန်မှ စွန့်ထုတ်မှုများကို အခါအား လျော်စွာ ဆောင်ရွက်ရန်.		
သင်တန်း	ရေကိုချွေတာသုံးစွဲရေး စက်ရုံဝန်ထမ်း များ အား အသိပညာပေးရန်		
	လေထုတ်လွှတ်မှု နှင့် အမှုန်အမွှား စီမံခန့်ခွဲဖ	ရေး အစီအစဥ်များ	
လုပ်ဆောင် ချက် ပြ အညွှန်း (များ)	ဖုန်သိပ်သည်းသည့် အဆင့်၊ အမှုန်အမွှား PM	M <sub>10</sub> and PM <sub>2.5</sub> , CO <sub>2</sub> ,C	CO, SO <sub>2</sub> , NO <sub>x</sub>
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာ၀န်၀တ္တရား	အချိန်
	<ul> <li>မီးပြင်းဖိုတွင် လေထုအတွင်းသို့ ထုတ်လွှတ်မှုများအား ထိန်းချုပ်နိုင် သည့် စနစ်ပါရှိသော စနစ်တပ်ဆင်ရန်</li> <li>လေထုအတွင်းသို့ ထုတ်လွှတ် မှုများ အား လျော့ချရေး အဖြစ် စက်ရုံ ပတ်</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး
	1	1	1



	FACTORY				
သင်တန်း	လည် တွင်ကြီမြန်သစ်ပင် များအား အတားအဆီးတစ်ခုသဖွယ် စိုက်ပျိုးရန် • ဓာတ်ငွေ့ထုတ်လွှတ်မှု လျော့ချရန် အ တွက် ယာဉ်များ၊ အားလုံးကို ပုံမှန် စစ် ဆေးခြင်း နှင့် ထိန်းသိမ်း ပြုပြင် ခြင်း ပြုလုပ်ရန် • ယာဉ်အသုံးပြုမှုလျော့ချခြင်းနှင့် လမ်း ကြောင်း တူယာဉ်များကို ပူးပေါင်း၍ အသုံးပြုခြင်း • ဝန်ထမ်းများကို နှာခေါင်းစည်း များ တပ်ဆင် စေရေး အသိပညာပေးရန်	HSE ကြီးကြပ်သူ			
	ဆူညံမှု စီမံခန့်ခွဲရေး အစီအစဥ်များ				
လုပ်ဆောင်ချက် ပြအညွှန်း (များ)	<ul> <li>ဘေးချင်းကပ် လူနေအိမ်ယာ၊ စီးပွားရေ</li> <li>လူထု မှ ဆူညံမှု နှင့် ပက်သက်သည့် စေ</li> <li>လက်ခံနိုင်သော ဆူညံမှု အဆင့် (dBA)</li> </ul>	ာဒကတက် တိုင်တန်			
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာ၀န်၀တ္တရား	အချိန်		
ဆူညံမှု	<ul> <li>ဆူညံမှုများကို ကန့်သတ်ရန် အတွက် စက်ကိရိယာများ ကို ပုံမှန် ထိန်းသိမ်း ပြုပြင်ခြင်း</li> <li>ဆူညံသံမြင့်မားသော လုပ်ငန်းခွင်ရှိ အလုပ်သ မားများကို နားကာ ကိရိယာ များ လုံလောက် စွာ ပံ့ပိုးပေးရန်</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ HSE ကြီးကြပ်သူ	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး		



စွန့်ပစ်ပစ္စည်း စီမံခန့်ခွဲရေး အစီအစဥ်များ			
လုပ်ဆောင် ချက် ပြ အညွှန်း (များ)	<ul> <li>မိလ္လာ နှင့် ဘေးအန္တရာယ် ဖြစ်စေသော စွန့်ပစ်ပစ္စည်း များကို သင့်တော် သော နည်းလမ်းဖြင့် စွန့်ပစ်ခြင်း</li> <li>ရီဆိုင်ကယ် ပြန်လည် လုပ်ဆောင်နိုင်သည့် စွန့်ပစ်ပစ္စည်းအားလုံးကို ရီဆိုင်ကယ် လုပ်ဆောင်ခြင်း နှင့် ပြန်လည်အသုံးပြုခြင်း ပြုလုပ်ရန်</li> <li>စွန့်ပစ်ပစ္စည်းများ၊ အမှိုက်များ ကို စက်ရုံမှ ပုံမှန် ဖယ်ရှား ရှင်းလင်းရန်</li> </ul>		
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာဝန်ဝတ္တရား	အချိန်
ကုန်ထုတ် စွန့်ပစ် ပစ္စည်း ဘေး အန္တ ရာယ်ရှိ စွန့် ပစ်ပစ္စည်း	<ul> <li>စွန့်ပစ်ပစ္စည်းများကို အမျိုးအစား အလိုက် ခွဲ ခြားထားပြီး လုံလောက်စွာ ထည့်သွင်းထား နိုင်သော စွန့်ပစ် ပစ္စည်း ထည့် ပုံးများကို ပံ့ပိုး ပေးရန်</li> <li>စွန့်ပစ်ပစ္စည်းပုံးများမှ အမှိုက်များ ပြည့် လျှံခြင်း (သို့) လုပ်ငန်းခွင် အတွင်း စုပုံလာခြင်းကို ခွင့်မ ပြုရန် နှင့် စွန့်ပစ်ပစ္စည်း များကို ပုံမှန် စွန့်ပစ်ရန်</li> <li>အနေ စီမံခန့်ခွဲမှုကို လုပ်ဆောင်ရန် (စွန့်ပစ် ပစ္စည်း ထွက်ရှိမှု လျှော့ချခြင်း၊ ပြန်လည် သုံးစွဲ ခြင်း၊ ပြန်လည်ပြုပြင် သုံးစွဲခြင်း</li> <li>အမှိုက်မပစ်ရ၊ ဆေးလိပ်မသောက်ရ စသည့် သတိပေးဆိုင်းဘုတ် များကို တပ်ဆင်ရန်</li> <li>စာသည့် သတိပေးဆိုင်းဘုတ် များကို လုင်စင်ရကန်</li> <li>ဘေး အန္တရာယ်ရှိ စွန့်ပစ်ပစ္စည်း များကို လိုင်စင်ရကန်ထရိုက်တာ (သို့) စည်ပင် မှ သိမ်းဆည်း ဆောင်ရွက်ရန်</li> <li>စက်ရုံဝန်ထမ်းများအား ဘေးအန္တရာယ် ဖြစ်စေ သော စွန့်ပစ်ပစ္စည်းများ</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ HSE ကြီးကြပ်သူ	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး



	သိုလှောင်ခြင်း၊ ကိုင်တွယ်ခြင်း များနှင့် ပက်သက်၍ အသိပညာ ပေးရန် • ဘေး အန္တရာယ်ရှိ စွန့်ပစ်ပစ္စည်း များကို မြေသားအတွင်း စိမ့်ပင်ခြင်း (သို့) မြေအောက် ရေအတွင်း စိမ့်ပင်ခြင်း မရှိစေရန် ကောင်းမွန် သော ထားသို၍ စည်ပင်သာယာမှ ချမှတ်ထားသော လမ်းညွှန်ချက်များအတိုင်း ဌာနနှင့် ပူးပေါင်းစွန့်ပစ်ရန်		
	ယာဉ်ကြော ကြပ်မှု စီမံခန့်ခွဲရေး အင်္ဂ	ဒီအစဥ္ပဲများ	
လုပ်ဆောင် ချက် ပြ အညွှန်း (များ)	<ul> <li>ယာဉ်ကြောကြပ်မှု နှင့် ဆိုင်သည့် အများ</li> <li>ယာဉ်မတော်တဆဖြစ်မှုများ</li> </ul>	း ပြည်သူ တိုင်တန်းမှု	
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာဝန်ဝတ္တရား	အချိန်
ယာဉ်ကြောကြပ် မှု	<ul> <li>ယာဉ်အသွားအလာ များသည့် ယာဉ် ကြောကြပ်ချိန်ပြင်ပတွင် ပို့ဆောင် ရေး ကားများ ကို အချိန် ဧယား ဆွဲပေး ရန်</li> <li>ယာဉ်အသုံးပြုမှု လျော့ချခြင်းနှင့်လမ်း ကြောင်း တူယာဉ်များကို ပူးပေါင်း၍ အသုံး ပြုခြင်း</li> <li>Trucks နှင့် အခြားယာဉ်များ အား ကောင်းမွန်စွာ အသုံးပြုနိုင် ရန် ဆောင်ရွက် ထားရန်</li> <li>နယ်မြေမှ သတ်မှတ်ထားသော ကား လမ်း ကြောင်း ဆိုင်ရာများကို လိုက် နာရန်</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ HSE ကြီးကြပ်သူ ယာဥ်မောင်းများ	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး



- သင်တန်း	• ယာဉ်မောင်းများ ဆိုင်ရာ အပြုအမူ များ၊ အသိ ပညာများ ကို သင်တန်း များပေးရန်		
O	ပုပ်ငန်းခွင် ကျမ်းမာရေး နှင့် ဘေးအန္တရာယ် ဂ	ာင်းရှင်းရေး စီမံချက်	
လုပ်ဆောင် ချက် ပြ အညွှန်း (များ)	• -မတော်တဆ ဖြစ်သည့် စာရင်းဇယားမ	ရှား	
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာ၀န်၀တ္တရား	အချိန်
မတော်တ ဆမှုများ - သောက် သုံးရေ -ယာဉ်စည်း ကမ်း လိုက်နာမှု	<ul> <li>အရေးပေါ် သူနာပြုဆေးသတ္တာများကို လုံ လောက်စွာ ထားရှိခြင်း</li> <li>စက်ရုံတွင်း ကြက်ခြေနီသူနာပြု သင် တန်း စသည်ဖြင့် ပေးခြင်း</li> <li>အနီးဆုံးရှိ ဆေးရုံ ဖုန်းနံပါတ် များကို စက်ရုံ အတွင်း ကပ်ထား ပေးခြင်း</li> <li>သောက်ရေသန့်ကို ဝန်ထမ်းများ အား လုံး အတွက် စီစဉ်ပေးခြင်း</li> <li>လိုအပ်သော ယာဉ်မောင်းလိုင်စင် ရှိ ရေး နှင့် ယာဉ်မောင်းနှင်မှု ကျမ်းကျင် မှုကို မြှင့်တင် ပေးရန်</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ HSE ကြီးကြပ်သူ	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး
-ဘေးအန္တ ရာယ်ကင်း ရှင်းရေး	<ul> <li>မီးသတ်ဆေးဗူး အပါအဝင် ထောက်ပံ့ ရေး ပစ္စည်း များ ထားရှိရန်</li> <li>ယာဉ်မောင်းများအား လိုအပ်သော အကာအကွယ်ပစ္စည်းများ ပေးအပ် ရန်</li> <li>မီးသတ် သရုပ်ပြခြင်းကို တနှစ် တခါ ပြုလုပ်ရန်</li> </ul>		



သင်တန်း	လုပ်ငန်းခွင် စွမ်းဆောင်ရည် မြင့်မားရေး သင်တန်းများ ပြုလုပ်ရန်		
	ရပ်ရွာ ကျမ်းမာရေး နှင့် ဘေးအန္တရာယ် ကင်	းရှင်းရေး စီမံချက်	
လုပ်ဆောင် ချက် ပြ အညွှန်း (များ)	• အများပြည်သူတိုင်တန်းမှုများ		
သက်ရောက်မှု	ထိန်းချုပ်မှုများ	တာ၀န်၀တ္တရား	အချိန်
ဘေးအန္တရာယ်	<ul> <li>မိလ္လာများကို တစ်နှစ်လျှင် ၂ ကြိမ် ပုံမှန်စုပ်ထုပ် ဖယ်ရှားရန်.</li> <li>စွန့်ပစ်ပစ္စည်းများကို ပြန်လည်အသုံး ပြုခြင်း နှင့် ရီဆိုင်ကယ်ပြုလုပ်ခြင်း</li> <li>ယာဉ် အန္တရာယ် ကင်းရှင်းရေး မြှင့် တင်ရန်</li> <li>မီးငြိမ်းသတ်သူများ နှင့် ရှေးဦး သူနာပြုသူများ ပါဝင်သော အရေးပေါ် ကယ်ဆယ်ရေး အဖွဲ့ ဖွဲ့စည်းခြင်း</li> <li>မီးသတ် သရုပ်ပြခြင်းကို တနှစ်တခါ ပြုလုပ် ရန်</li> </ul>	စက်ရုံမန်နေဂျာ ကြီးကြပ်သူ HSE ကြီးကြပ်သူ အရေးပေါ် ကယ်ဆယ်ရေး အဖွဲ့	လုပ်ငန်း လုပ်ဆောင် နေစဉ်ကာလ တစ်လျောက် လုံး

## ၁.၇.၃ စီမံခန့်ခွဲမှု အသုံးစရိတ်

ပတ်ဝန်းကျင် နှင့် လူမှုရေး စီမံခန့်ခွဲမှုများကို အကောင်အထည်ဖော်ရန် နှင့် စောင့်ကြပ်ကြည့်ရှုရန် တို့ကို အကောင်အထည်ဖော်ရန် ယေဘူယျအသုံးစရိတ်ကို တစ်နှစ်လျှင် ၁၁,၀၀၀,၀၀၀ ကျပ် လျာထားပြီး ၄င်းတို့ကို အောက်ပါဇယားများတွင် အသေးစိတ် ဖော်ပြထားပါသည်။



အသုံးစရိတ် လုံလောက်မှု မရှိပါက ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှုအဖွဲ့သည် ဘတ်ဂျတ်ပိုမိုရရှိရေးအတွက် စက်ရုံတာဝန်ရှိသူများအား တင်ပြမည်ဖြစ်သည်။ စက်ရုံတာဝန် ရှိသူများ မှလည်း EMP အတွက် လိုအပ်သော ငွေကြေးဆိုင်ရာ ထောက်ပံ့မှုများကို ပြုလုပ်မည် ဖြစ်သည်။

## eယား ၁.၁၃ ပတ်ဝန်းကျင် နှင့် လူမှုရေး စီမံခန့်ခွဲမှုများကို အကောင်အထည်ဖော်ရန် နှင့် စောင့်ကြပ်ကြည့်ရှုရန် လျာထားရံပုံငွေပြဇယား

စဥ်.	အကြောင်းအရာ	တစ်နှစ်ခန့်မှန်း ကုန်ကျစရိတ် (Kyats)
э	တည်ဆောက်ဆဲကာလအတွက် စောင့်ကြပ် ကြည့်ရှုမှု	5,060,000
J	စက်ရုံလည်ပတ်မှု ကာလအတွက် စောင့်ကြပ် ကြည့်ရှုမှု	၅,၁၂၀,၀၀၀
5	ပိတ်သိမ်းမည့် ကာလအတွက် စောင့်ကြပ် ကြည့်ရှုမှု	၁,၇၉၀,၀၀၀
	စုစုပေါင်း	၁၁,000,000

## ၁.၇.၄ ပတ်ဝန်းကျင် စောင့်ကြပ်ကြည့်ရှုမှု

## eယား ၁.၁၄ ပတ်ဝန်းကျင် စောင့်ကြပ်ကြည့်ရှုမှုအစီအစဉ် - စက်ရုံလည်ပတ်သည့်ကာလ

က်ရောက်မှု အကြောင်းအ ရာ	စောင့်ကြပ်ကြည့် ရှုသည့်နေရာ	လိုက်နာမှတ်	အကြိမ်အရေ အတွက်	ခန့်မှန်း ကုန်ကျ စရိတ် (ကျပ်)	တာဝန်ရှိ အဖွဲ့အစည်း
	လေထုညစ်ညမ်းခြင်း				
Standards စံနှုန်းများ	အမျိုးသား ထုတ်လွှတ်မှုဆိုင်ရာ အရည်အသွေး - လေထုအတွင်းထုတ်လွှတ်မှု Guideline				
Parameters ပါရာမီတာ	SO <sub>2</sub> , NO <sub>2</sub> , CO, PM <sub>2.5</sub> , PM <sub>10</sub> , dusts and O <sub>3</sub>				
ဝန်းကျင်လေထု	စက်ရုံဝင်ပေါက် အနီး	95° 58.876'N 17° 10.443'E	တစ်နှစ် နှစ်ကြိမ်	o, Joo,ooo (Gooooox J) (Monito ring fees)	EMT အဖွဲ့ HSE ကြီးကြပ်သူ



					ပြင်ပ တတိယ အဖွဲ့ အစည်း
		ဆူညံသံ			
Standards စံနှုန်းများ	အမျိုးသား ထုတ်င	အမျိုးသား ထုတ်လွှတ်မှုဆိုင်ရာ အရည်အသွေး			
Parameters ပါရာမီတာ	ဆူညံသံ အဆင့်(d	ဆူညံသံ အဆင့်(dB)			
အသံဆူညံမှု dB(A)	စက်ရုံဝင်ပေါက် အနီး	95° 58.876'N 17° 10.443'E	တစ်နှစ် နှစ်ကြိမ်	ooo,ooo (goooo xj) (Sound meter device cost)	EMT အဖွဲ့ HSE ကြီးကြပ်သူ ပြင်ပ တတိယ အဖွဲ့အစည်း
		ရေအရည်အ	သွေး		
Standards စံနှုန်းများ	WHO ရေအရည်အသွေး guideline				
Parameters ပါရာမီတာ (မြေအောက်ရေ အရည်အသွေး)	-Temperature, pH, Colour, Conductivity, Total Dissolved Solid, Total Hardness, Total Alkalinity, Sodium, Calcium, Magnesium, Potassium, Iron, Chloride, Sulphate, Bicarbonate, Carbonate, Hydroxide,				
(ရေဆင်း မြောင်းရေ)		gen, Biochemical O solids, Oil and Gre		Chemical Oxy	gen Demand,
မြေအောက်ရေ အရည်အသွေး	စက်ရုံ အဝီစိတွင်း (ဘုံဘိုင်ရေ)	17° 10.457'N 095° 58.889' E	တစ်နှစ် နှစ်ကြိမ်	२,600,00 0	EMT အဖွဲ့



		1	1	1	1
စွန့်ပစ်ရေ (ရေဆင်း မြောင်းရေ)	ရေဆင်းမြောင်း အထွက်	17° 10.409' N 95° 58.969'E	တစ်နှစ် နှစ်ကြိမ်	(၁၈၀၀၀၀x ၂) ဓာတ်ခွဲခန်း စစ်ဆေးမှု ကုန်ကျ စရိတ်	HSE ကြီးကြပ်သူ ရေအရည်အ သွေးစစ်ဆေး မည့် ပြင်ပ ဓာတ်ခွဲခန်း
		စွန့်ပစ်ပစ္စဥ			
Parameters ပါရာမီတာ		န်လည်အသုံးပြုခြင်း : ား စက်ရုံမှ ပုံမှန် စွန့်ပ			
ဘေးအန္တရာယ် မဖြစ်စေသော စွန့်ပစ်ပစ္စည်း	- သန့်ရှင်းရေးပြု လုပ် ခြင်း	စက်ရုံတစ်ခုလုံး	နေ့စဉ်	ကုန်ကျစ ရိတ်မရှိ	သန့်ရှင်းရေး ဝန်ထမ်း
များ	- စွန့်ပစ်ပစ္စည်း ထား သိုရာ နေရာကို စစ် ဆေးခြင်း (အမြင်ဖြင့် စစ်ဆေး ခြင်း)	17° 10' 27.9'' N 95° 58' 53.2''E	နေ့စဉ်	-	ကြီးကြပ်ရေး မှူး
	- စွန့်ပစ်ပစ္စည်း များကို စက်မှုဇုန်ရှိ အမှိုက်ပုံသို့ ပုံမှန် စွန့်ပစ် ဖယ်ရှားခြင်း	စက်မှုဇုန် အတွင်းရှိ သတ်မှတ်ထား သော အမှိုက်ပုံ	အပတ်စဉ်	၉၆၀,၀၀၀ (၈၀၀၀၀ x ၁၂)	ကြီးကြပ်ရေး မှူး မြို့နယ် စည်ပင်
ဘေးအန္တရာယ် ဖြစ်စေသော စွန့်ပစ်ပစ္စည်း များ (ဥပမာ-	- ထား သိုရာ နေရာ ကို စစ် ဆေးခြင်း (အမြင်ဖြင့် စစ်ဆေး ခြင်း)	-	အပတ်စဉ်	ကုန်ကျစ ရိတ်မရှိ	HSE ကြီးကြပ်သူ ကြီးကြပ်ရေး
အသုံးပြုပြီး စက်ဆီ ချောဆီများ၊ မိလ္လာများ)	-မိလ္လာများကို စုပ် ထုတ်ခြင်း	-	တစ်နှစ် နှစ်ကြိမ်	2,000,000	쉬ᆙ



	ကျန်းမာရေးနှင့် ဘေးအန္တရာယ်ကင်းရှင်းရေး				
Parameters ပါရာမီတာ	-ကြက်ခြေနီဆေးသေတ္တာ၊ မီးဘေးစီမံချက်၊ အကာအကွယ်ကိရိယာ၊ ဘေးအန္တရာယ်ကင်းရှင်းရေး အချက်ပြဆိုင်းဘုတ်များ				
ကျမ်းမာ ရေး အခြေအနေ ဆိုင်ရာ အန္တရာယ်ကင်း ရှင်းရေး နည်းလမ်းများ	-လုပ်ငန်းခွင် ကျန်းမာရေးနှင့် ဘေးအန္တရာယ်ကင်းရှင်းရေး နည်းလမ်းများ (ဥပမာ- ကြက်ခြေနီဆေးသေတ္တာ)	လုပ်ငန်းခွင် နေရာအား ကျန်းမာရေးနှင့် ဘေးအန္တရာယ် ကင်းရှင်းရေး အတွက် လစဥ်စစ်ဆေး ခြင်း	-	ကြီးကြပ် ရေး မှူး	
မီးဘေးလုံခြုံ ရေး နည်းလမ်းများ	-မီးသတ်သင်တန်း နှင့် မီးသတ်သရုပ်ပြလေ့ ကျင့်ခြင်း	နှစ်စဉ်	၅၀၀,၀၀၀	HSE personnel EMT Team	
အရေးပေါ် အခြေ အနေ ဘေးအန္တ ရာယ် ကင်းရှင်းရေး	ရှေးဦးသူနာပြု သင်တန်း	နှစ်စဉ်	900,000	HSE ကြီးကြပ်ရေး မှူး EMT အဖွဲ့	
	အကာအကွယ် ဝတ်စုံ	လစဥ်	၅၀၀,၀၀၀		

## ၁.၈. နိဂုံး

Giant 999 Steel Manufacturing Factory စက်ရုံနှင့် ပက်သက်၍ ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှု အစီရင်ခံစာတင်ပြ နိုင်ရန် ဆောင်ရွက် လျက်ရှိပါသည်။

ပန်းကျင်လေထု အရည်အသွေး၊ မြေအောက်ရေ အရည်အသွေး၊ မြေဆီလွှာ ချဉ်ဖန်ကိန်း၊ ဆူညံသံ စသည်တို့ကို အခြေခံစောင့်ကြည့်တိုင်းတာမှုများ၏ ရလာဒ်များသည် အမျိုးသား ထုတ်လွှတ်မှုဆိုင်ရာ စံနှုန်းများအတွင်းကျရောက်ပြီး လက်ခံနိုင်သည့် အဆင့်ရှိပါသည်။



လုပ်ငန်းလည်ပတ်ခြင်းကြောင့် ဖြစ်ပေါ်နိုင်သည့် သက်ရောက်မှုများကို လွှမ်းခြုံ အကဲဖြတ်ခြင်းအရ လေထုအတွင်းသို့ ထုတ်လွှတ်မှုများသည် စက်ရုံမှ မီးပြင်းဖိုများမှထုတ်လွှတ်မှုများ၊ မီးစက် အသုံးပြုခြင်း နှင့် ထရပ်များ ကားများ အသုံးပြုခြင်းတို့မှ ထွက်ရှိပါသည်။ မီးပြင်းဖို အား ထိရောက်မှုရှိသည့် de-dust controller system တပ်ဆင်ထားပါသည်။ မီးစက်များ မော်တော်ယာဥ်များ အား ပုံမှန်စစ်ဆေးပြီး ပြုပြင်ထိန်းသိမ်းပါသောကြောင့် ဓာတ်ငွေ့ထုတ်လွှတ် မှုများအားလျော့နည်းစေပါသည်။

ထိရောက်မှု ရှိသည့် ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု နှင့် ပတ်ဝန်းကျင်စောင့်ကြပ် ကြည့်ရှုခြင်း တို့သည် ပတ်ဝန်းကျင် နှင့် လူမှုရေးဆိုင်ရာ သက်ရောက်မှုများ ဖြစ်ပေါ်လာနိုင်သည့် အလားအလာကို လျော့နည်း စေပါမည်။ စက်ရုံသည် dust collecting system တပ်ဆင်အသုံးပြုထားသောကြောင့် ယေဘူယျအားဖြင့် လေထု ထုတ်လွှတ်မှုများ၊ စွန့်ပစ်ရေ အရည်အသွေး ညစ်ညမ်းမှုတို့ကြောင့် ပတ်ဝန်းကျင်အပေါ် သက်ရောက်မှုများသည် နည်းပါးသည် ဟု ယူဆ နိုင် ပါသည်။

အများပြည်သူနှင့် တိုင်ပင်ဆွေးနွေးခြင်း အစည်းအဝေး ရလာဒ်အရ မကျေနပ်ချက်များ ရရှိခဲ့ခြင်းမရှိဘဲ စက်ရုံ ၏ လည်ပတ်ခြင်းအတွက် ဝန်ထမ်းများ၏ ဘေးအန္တရာယ်ကင်းရှင်းရေးအတွက် အကြံပြု ချက်များ ရှိပါသည်။

လုပ်ငန်းလည်ပတ်ခြင်းကြောင့် ဖြစ်ပေါ်နိုင်သည့် သက်ရောက်မှုများကို လွှမ်းခြုံ အကဲဖြတ်ခြင်းအရ စက်ရုံသည် ဒေသခံ အလုပ်သမား ၅၀ ကျော် ကိုခန့်ထားပြီးဖြစ်၍ ဒေသဆိုင်ရာ အလုပ်အကိုင် အခွင့် အလမ်းများ အတွက် ကောင်းကျိုး သက်ရောက်မှု များဖြစ်ပေါ် စေပါသည်။ စက်ရုံ၏ လည်ပတ် မှုကြောင့် ဖြစ်ပေါ် လာနိုင်သည့် ဆိုးကျိုးသက် ရောက်မှုများ ကိုလည်း လျော့နည်းစေရန် စီမံ နိုင်ပါ သည်။



#### 2.0 INTRODUCTION

## 2.1 PROJECT PROPONENT AND BACKGROUND

The project proponent is Giant 999 Steel Manufacturing Factory established by Daw Sein Yee. Giant 999 Steel Manufacturing Factory has a license of Hmawbi Township Development Committee on 15<sup>th</sup> October 2018 at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township, Yangon, Myanmar. The main business is foundry and rolling mills and main products are U Beam and Angle Bar.

The factory was built in April 2011 and has been in operation since 2012 in Myanmar.

#### 2.2 SALIENT FEATURES OF THE COMPANY

The salient features of the company are mentioned below.

Name of Factory : Giant 999 Steel Manufacturing Factory

Established by : Daw Sein Yee

Address : Plot No. 20/21, Myaung Dagar Industrial Zone,

Hmawbi Township, Yangon, Myanmar

Type of Business : Refinery Plant (iron)

Type of Investment : 100% Local Investment

Total amount of Capital : 200 Million kyats

System of Sales : 100% Local

Total Land Area : 6.3 acre (274,428 sq ft)

Building Area : 5.3 acre

Type of Land : Industrial Land

Business Permit : Hmawbi Township Development Committee

on 16th January 2019

Commence date of Construction: 2010-11

Commence date of Operation : 2012

Contact Ph. : 09960307778 (Ma Hnin Si, Admin)



#### 2.3 PURPOSES OF THE ENVIRONMENTAL MANAGEMENT PLAN

This report is the Environmental Management Plan (EMP) for Giant 999 Steel Manufacturing Factory. The purpose of this EMP is to assist Giant 999 Steel Manufacturing Factory, in managing steel manufacturing factory. It is to develop an effective environmental management plan (EMP) or to improve programs, which may already be in place. Implementing an effective environment plan requires a continuous commitment by a wide range of the personnel from Giant 999 Steel Manufacturing Factory.

The environmental management plan will help the factory to assess its present performance in protection of environment and identify opportunities for additional environmental protection measures.

This document, which identifies possible environmental compliance problems in the general regulatory categories of air, water, land use, solid waste and hazardous materials, helps the factory in the area comply with local and environmental regulations. It contains information for management of operation activities, and for the existing factory that has never examined the environmental impact of its operations.

#### 2.3.1 TIMEFRAME OF EMP

The EMP started from December 2019 and ended by July 2020. Revised EMP report is ended by July 2022.

#### 2.4 PROCESS TECHNOLOGY AND ENVIRONMENTAL BENEFIT

လက်ရှိလည်ပတ်ဆောင်ရွက်နေသည့် နည်းပညာမှာ Chinese Technology နည်းပညာ ဖြစ်ပါသည်။ မြောင်းတကာစက်မှုဇုန်အတွင်း "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံ လည်ပတ် လုပ်ကိုင်ခြင်း ကြောင့် ဒေသအတွင်းရှိ သံတို သံစ metal wastes များကို စက်ရုံမှကုန်ကြမ်းအဖြစ် အသုံးပြုသည့် အတွက် recycle အဖြစ်ပြန်လည်အသုံးပြုနိုင်သည့် အခွင့်အလမ်းဖြစ်ပေါ်စေပါသည်။ Chinese Technology နည်းပညာ ကို အသုံးပြုလုပ်ကိုင် သည့် အတွက် ထွက်ကုန်များကို အရည်အသွေးပြည့်ဝ စွာ ထုတ်လုပ်နိုင်ပြီး ကုန်ချော ပစ္စည်းများ ဖြစ်သည့် သံချောင်းများ၊ U Beam and Angle Bar တို့ကို ဆောက်လုပ်ရေး လုပ်ငန်းများတွင် သုံးစွဲရန် သွင်းကုန် အစားထိုးအဖြစ် ဝယ်ယူသုံးစွဲနိုင်သဖြင့် နိုင်ငံတော်အနေနှင့် ဆောက်လုပ်ရေးပစ္စည်းများ တင်သွင်းမှု လျော့ချနိုင်သည့် အကျိုးကျေးဇူးကို ဖြစ်ပေါ်စေမည် ဖြစ်ပါသည်။ ထို့အပြင် နိုင်ငံတစ်ဝှန်း ဆောက်လုပ်ရေး ကဏ္ဍ ဖွံဖြိုးပြီး ဆက်စပ် လိုအပ်သော လုပ်သားအင်အားများအတွက်လည်း အလုပ်အကိုင်



အခွင့်အလမ်းများဖြစ်ပေါ်စေသည့် အတွက် ဒေသဆိုင်ရာ အလုပ်လက်မဲ့နှုန်းကို လည်း လျှော့ချ ပေးနိုင်မည် ဖြစ်ပါသည်။

မြောင်းတကာ စက်မှုဇုန်အတွင်း အများစုမှာ သံ၊သံမဏိ နှင့် သံရည်ကျိုစက်ရုံများ ဖြစ်ပါသည်။ "ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံသည် Dust Collection (DE-Dusting) System ကို အသုံးပြု ထားသဖြင့် ပတ်ဝန်းကျင်ညစ်ညမ်းမှု မဖြစ်ပေါ်စေသည့်အပြင် စက်မှုဇုန် အတွင်း အခြားသော အလားတူ သံရည်ကျိုစက်ရုံများသည် အဆိုပါ နည်းပညာအား စံပြုအသုံးပြု နိုင်မည်ဖြစ်ကာ ambient air quality အား ညစ်ညမ်းမှု နည်းပါးစေမည် ဖြစ်သောကြောင့် ပတ်ဝန်းကျင် ဒေသခံများ၏ complains များ၊ လူမှုရေး ပဋိပက္ခ များ လည်း လျော့နည်းသွားမည် ဖြစ်ပါသည်။

စက်ရုံလည်ပတ် ခြင်းကြောင့် ဒေသခံ များအား အလုပ်အကိုင်အခွင့်အလမ်းများ ဖြစ်ပေါ်စေပြီး ဒေသအတွင်း ငွေကြေးလည်ပတ်သုံးစွဲမှုဖြစ်ပေါ်စေကာ အခြားစီးပွားရေးလုပ်ငန်းများလည်း တိုက်ရိုက်ဖြစ်စေ သွယ်ဝိုက်၍ ဖြစ်စေ ဖွံဖြိုးတိုးတက်လာပြီး လူနေမှုဘဝကို မြှင့်တင်ပေးနိုင်မည် ဖြစ်ပါသည်။

#### 2.5 CONSULTANT TEAM

Environmental Management Plan for operation of Giant 999 Steel Manufacturing Factory is conducted by **GREEN ENVIRONMENTAL**, **HEALTH**, **SAFETY & SOCIAL CONSULTANCY COMPANY LIMITED**. GREEN EHSS COMPANY LIMITED is established in Myanmar under Incorporate Registration No: 4289/2011-12.

Green EHSS Consultancy firm has been providing Environmental, Health, Safety and Social related services for local and international organizations. EMP consultant team includes competent professionals with more than 20 years of local and international experience in Environment, Health, Safety and Social domain.

#### 2.5.1 PERSONNEL INFORMATION OF CONSULTANT TEAM

No.	Name	Designation	Academic and Professional Qualifications	Years of Experience
1	Catherine Soe Soe	Team Leader,	Master in Environmental	25
	Aung	Sr. Environmentalist	Engineering, National	
		Certified Environmental	University of Singapore	
		Professional, Canada	Master in Zoology, YU	
		Approved Risk	Bachelor in Zoology, YU	
		Consultant, MOM,		
		Singapore		



	1	Г <u>-</u>		I		
		ADB's Consultant				
		Management				
	Contact	catherine@greenehss.com				
		09 42 5353553		T		
2	Dr. Theingi Ye	Waste Management and	Ph.D(YU)	5		
	Myint	Water Quality Specialist	Master in Environmental			
			Engineering, NUS			
			Master in Industrial			
			Chemistry, YU			
			Bachelor in Industrial			
			Chemistry, YTU			
	Contact	095095555		T		
3	Dr. Esther	Biodiversity	Master in Zoology, YU	Biodive		
	Kumar	Specialist, Fauna	Bachelor in Zoology,	rsity		
		Team Leader	YU			
	Contact	info@greenehss.com				
4	Dr. May Thin	Department Head	M.B.B.S(Yangon)	30		
	Swe	Jivitadana Sangha				
		Hospital				
	Contact	marketing@greenehss.com				
5	U San Aye	Mapping and GIS	Bachelor in Maths, Diploma	40		
		Specialist	in Mapping, Japan			
	Contact	info@greenehss.com				
6	Daw Swe Swe	Social Impact	Master in Geography, YU	18		
	Aung	Assessment Specialist	Bachelor in Geography, YU			
			Diploma in GIS,			
			Communication Skill for			
			Business, Singapore			
			Polytechnic			
	Contact	green.sweaung@gmail.com	<u>1</u>			
		095026245		T		
7	Daw Mi Mi Soe	Social Impact	Master in Public	24		
		Assessment Specialist	Administration			
			Bachelor in Chemistry			
			Diploma in Computer			
			Science			
			Post-Graduate Diploma In			
		0040040===	Applied Psychology			
	Contact	09420135551				
8	U Aung Ze Ya	Project Manager	B.Sc ( Math)	Oversee		
			, ,	project		
	Contact	09787874674		<u> </u>		
<u> </u>		1				



#### 3.0 ENVIRONMENTAL COMMITMENT

#### Commitment by Project Proponent

#### Giant 999 Iron Mill

အမှတ် ( 19,20,21) မြောင်းတကာ စက်မှု့ ဇုံ ၊မှော်ဘီမြို့ နယ်၊ ရန်ကုန်တိုင်းဒေသကြီး။ ဖုန်း - 09-421061999 ၊ 09-772021999 ၊ 09-955021999

## "ဧရာမ သံရည်ကျိုနင့် သံနန်းဆွဲ လုပ်ငန်း"

ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီရင်ခံစာကို Green Environmental, Health, Safely & Social Consultancy Company Limited မှ ရေးဆွဲထားပြီး အစီရင်ခံစာတွင် ပါရှိသော အကြောင်းအရာများသည် မှန်ကန်တိကျခိုင်မာပြီး ပြည့်စုံပါသည်။ သဘာဝသယ်ဇာတ နှင့် ပတ်ဝန်းကျင် ထိန်းသိမ်းရေးဝန်ကြီး ဌာန နှင့် ဒေသဆိုင်ရာ အစိုးရများမှာ ရမှတ်ထားသော ဥပဒေ၊ နည်းဥပဒေ၊ လုပ်ထုံးလုပ်နည်းများကို တိကျစွာ လိုက်နာမည် ဖြစ်ကြောင်း ကတ်ကဝတ်ပြပါသည်။ ပတ်ဝန်းကျင် ထိခိုက်မှု ဆန်းစစ်ခြင်းဆိုင်ရာ လုပ်ထုံး လုပ်နည်း အပါအဝင် သက်ဆိုင်ရာ ဥပဒေများကို တိကျစွာ လိုက်နာ၍ ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအဝဉ် ကို ရေးဆွဲထားပါသည်။ Giant 999 Steel Manufacturing Factory သည် ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီ ရင်ခံစာပါ ကတ်ကဝတ်များ ပတ်ဝန်းကျင် ထိခိုက်မှု လျော့ချရေး လုပ်ငန်းများနှင့် အစီအစဉ်များကို အပြည့်အဝ အစဉ်အမြဲ လိုက်နာဆောင်ရွက်မည် ဖြစ်ပါသည်။

လုပ်ငန်းလည်ပတ် ဆောင်ရွက်နေသည့် ကာလအတွင်း အတည်ပြုထားသည့် ပတ်ပန်းကျင် စီမဲ့စန့်ခွဲမှ အစီအစဉ်အား တိုးတက်နေသည့် နည်းပညာများ စနစ်များနှင့် လုပ်ငန်းလိုအပ်ချက် ပေါ်မူတည် ၍ ပိုဝိုကောင်းမွန်သည့် ပတ်ဂန်းကျင် စီမံစန့်ခွဲမှ အစီအစဉ် ဖြစ်စေရန်အတွက် ပြင်ဆင်ဖြည့်စွက်ရန် ညွှန် ကြားချက်များ ရှိလာပါက တင်ပြအတည်ပြုချက် ရယူ၍ ပြင်ဆင်ဆောင်ရွက်မည် ဖြစ်ပါသည်။

စက်ရုံလုပ်ငန်း ပြီးစီး၍ စီမံကိန်းပိတ်သိမ်းချိန်တွင် လူမှုဝန်းကျင်အား ထိနိက်မှ မဖြစ်စေရန် နှင့် ထိနိက်မှုများ ရှိလာပါက ထိနိက်မှု အနည်းဆုံး ဖြစ်စေရေး အစီအမံများ ရမှတ်ဆောင်ရွက်မည်

ဖြစ်ပါသည်။

Signature

Managing Director
Henr Stool Manufacturio



#### Commitment by Third Party



#### GREEN ENVIRONMENTAL, HEALTH, SAFETY & SOCIAL CONSULTANCY CO., LTD

ရန်ကုန်တိုင်းဒေသကြီး၊ မှော်ဘီမြို့နယ်၊ မြောင်းတကာစက်မှုဇုန်ရှိ Giant 999 Steel Manufacturing Factory သံရည်ကျိုစက်ရုံ၏ ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ် Environmental Management Plan (EMP) အား သယံဧာတ နှင့် သဘာဝ ပတ်ဝန်းကျင် ထိန်းသိမ်းရေးဝန်ကြီးဌာန မှ ထုတ်ပြန်ထားသော ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး ဥပဒေ၊ နည်းဥပဒေများ နှင့် ကိုက်ညီအောင်ရေးဆွဲထားပါသည်။ ပတ်ဝန်းကျင်ဆိုင်ရာ အရည်အသွေး (ထုတ်လွှတ်မှု) လမ်းညွှန်ချက်များ (၂၀၁၅) ကို အဓိက အခြေခံပြီး အခြားလိုက်နာ ဆောင်ရွက် ရမည့် သက်ဆိုင်ရာ ဥပဒေ၊ နည်းဥပဒေများ နှင့် ဆက်စပ်ကျင့်သုံးနိုင်ရေး ရေးသားပြုစု တင်ပြ ထားပါသည်။

ဤပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဉ်တွင် စီမံကိန်းနှင့် ပတ်သက်သော အချက်အလက်များ နှင့် စီမံကိန်းအကောင်အထည် ဖော်ဆောင် ရွက်မည့်ဒေသ၏ လက်ရှိ ပတ်ဝန်း ကျင် အခြေအနေများကို စီမံခန့်ခွဲမှုအစီအစဉ် ရေးဆွဲသော အဖွဲ့၏ အတွေ့အကြုံအပေါ် အခြေခံ သော သုံးသပ်ချက်များနှင့် ပေါင်းစပ်ပြီး ပတ်ဝန်းကျင်အပေါ် သက်ရောက်မှုဖြစ်ပေါ် စေနိုင်သော အကြောင်းအရာများ နှင့် ကုစားနိုင်မည့် နည်းလမ်းများကို ရေးဆွဲဖော်ပြထားပါ သည်။

အစီရင်ခံစာပါ အချက်အလက်များမှာ အဖွဲ့တွင်ပါဝင်သော ပညာရှင်များမှ မြေပြင်တွင် ကွင်းဆင်းလေ့လာပြီး ပတ်ဝန်းကျင် ဆန်းစစ်ခြင်း ပြုလုပ်ရေးဆွဲထားခြင်း ဖြစ်ပါ၍ အစီရင်ခံစာတွင် ပါဝင်သော အချက်အလက်များမှာ တိကျမှန်ကန်၍ ပြည့်စုံမှန်ကန် မှု ရှိပါသည်။

Signature :

Catherine Soe Soe Aung Managing Director Green EHSS Consultancy Co.,Ltd.





#### 4.0 LEGAL REQUIREMENT

#### 4.1 NATIONAL LAWS AND REGULATIONS

The National laws and regulations for the environmental protection applicable to the project are compiled and presented. Giant 999 Steel Factory will follow strictly the applicable legislation, rules and guidelines laid down by MONREC, and the local and international relevant laws, guidelines, and procedure while implementing environmental and social management plans.

The Constitution of the Republic of the Union of Myanmar (2008) is the main concern for the environment conservation in Myanmar. The others are as follows:

- i. Environmental Conservation Law (2012)
   (Section 3, Section 7, Section 10, Section 13, Section 14, Section 15 and Section 16)
- ii. Environmental Conservation Rules (2014) (Rule 58, 60 and 61)
- iii. The Conservation of Water Resources and River Law, 2<sup>nd</sup> October (2006) (Section 8)
- iv. Myanmar Investment Law (2016) (Section 36, 50, 51, 56)
- v. Myanmar Investment Rule (2017) (section 41, 67)
- vi. The Import Export Law (2012) (Section 5,6,7)
- vii. Myanmar Fire Brigade Law (2015) (Section: 17, 25)
- viii. Environmental Impact Assessment Procedure (Ministry of Natural Resources and Environmental Conservation No. 616/2015) (29 Dec, 2015)
  - ix. National Environmental Quality (Emission) Guidelines (No. 615/2015)(29 Dec, 2015)
  - x. The Boiler Law (2015) (Section: 5,6,7,12,13,14,15,16,17,18,19,20)
  - xi. Land Acquisition Law (2015)
- xii. The Payment of Wages Law 2016 (Jan 2016) (Section 3,4,5,6,7,8,9,10,11,14)

## Environmental Management Plan Report

## GIANT 999 STEEL MANUFACTURING FACTORY



- xiii. The Minimum Wages Law (2013) (Section 12,13,14,15)
- xiv. Minimum Wage Notification 1/2018
- xv. The Social Security Law (2012) (Section 11,16)
- xvi. The Social Security Rules, Notification, No. 41/2014
- xvii. The Public Health Law
- xviii. Prevention and Control of Communicable Diseases Law (1995) (Section 8,9,10,11)
- xix. Pollution Control and Cleansing Rules, Order No.10/99 (YCDC, Order No. 10/99 of 24 Dec, 1999)
- xx. The Water Power Act (1927) (Section 6)
- xxi. The Labour Organization Law (2011) (Section 29,30,31)
- xxii. Vehicle Law (2015) (Section 4,5,11,12,13)
- xxiii. ဘေးအန္တရာယ်ကင်းရှင်းရေးနှင့် ကျမ်းမာရေးဆိုင်ရာဥပဒေ ၂၀၁၉ (12,13,26,27,28,29)
- xxiv. ပြည်သူ့ကျမ်းမာရေးဥပဒေ ၁၉၇၂ (6,7,8,9)
- xxv. ပုဂ္ဂလိကစက်မှုလုပ်ငန်းဥပဒေ ၁၉၉၀ (3,4,13,14,15,21)
- xxvi. အမျိုးသားပတ်ဝန်းကျင်ရေးရာမှုဝါဒ (၂၀၁၉)
- xxvii. ရန်ကုန်မြို့တော်စည်ပင်သာယာရေးဥပဒေ (၂၀၁၈)
- xxviii. မြေအသုံးချမှုဥပဒေ (၂၀၁၉)
  - xxix. လူမှဖူလုံရေးဥပဒေများ (၂၀၁၄)
  - xxx. အလုပ်သမားအဖွဲ့ အစည်းဥပဒေ (၂၀၁၁)
  - xxxi. အလုပ်သမားအဖွဲ့ အစည်းနည်းဥပဒေ (၂၀၁၂)
- xxxii. အနည်းဆုံးအခကြေးငွေနည်းဥပဒေများကို ပြင်ဆင်သည့်နည်းဥပဒေများ (၂၀၁၅)
- xxxiii. ခွင့်ရက်နှင့် ပိတ်ရက်ဥပဒေ(၁၉၅၁)
- xxxiv. အလုပ်ရုံအက်ဥပဒေများ(၁၉၅၁)
- xxxv. အလုပ်ရုံအက်ဥပဒေများကို ပြင်ဆင်သည့်ဥပဒေ(၂၀၁၆)



xxxvi. အခကြေးငွေပေးချေရေဥပဒေ (၂၀၁၆)

xxxvii. အလုပ်သမားရေးရာ အငြင်းပွားမှု ဖြေရှင်းရေးဥပဒေကို ဒုတိယအကြိမ်ပြင်ဆင်သည့်ဥပဒေ (၂၀၁၉)

xxxviii. အလုပ်သမားရေးရာ အငြင်းပွားမှုဖြေရှင်းရေးနည်းဥပဒေများ (၂၀၁၂)

xxxix. လုပ်ငန်းခွင်ဘေးအန္တရာယ်ကင်းရှင်းရေးနှင့် ကျမ်းမာရေးဆိုင်ရာဥပဒေ (၂၀၁၉)

xl. မြန်မာနိုင်ငံ မီးသတ်တပ်ဖွဲ့ နည်းဥပဒေများ (၂၀၁၅)

xli. ဓာတုပစ္စည်းနှင့် ဆက်စပ်ပစ္စည်းများ အန္တရာယ်မှတားဆီးကာကွယ်ရေးဥပဒေ (၂၀၁၃)

xlii. ဓာတုပစ္စည်းနှင့် ဆက်စပ်ပစ္စည်းများ အန္တရာယ်မှတားဆီးကာကွယ်ရေးနည်းဥပဒေ (၂၀၁၆)

xliii. မြန်မာနိုင်ငံရင်းနှီးမြုပ်နှံမှုဥပဒေကိုပြင်ဆင်သည့်ဥပဒေ (၂၀၁၉)

xliv. မြန်မာနိုင်ငံရင်းနှီးမြုပ်နှံမှုဥပဒေကိုပြင်ဆင်သည့်နည်းဥပဒေ (၂၀၁၈)

xlv. ဖွဲ့စည်းပုံအခြေခံဥပဒေ(၂၀၁၈)

xlvi. မြေအောက်ရေကြီးကြပ်မှုအက်ဥပဒေ (၁၉၃၀)

xlvii. အလုပ်သမားလျော်ကြေးငွေအက်ဥပဒေ(၁၉၅၁)

xlviii. ကုန်သွယ်လုပ်ငန်းခွန်ဥပဒေ (၂၀၁၅)

xlix. ပြည်ထောင်စု၏အခွန်အကောက်ဥပဒေ (၂၀၁၈)

1. မြန်မာနိုင်ငံကုမ္ပဏီများဥပဒေ(၂၀၁၇)

#### 4.2 ENVIRONMENTAL STANDARD AND GUIDELINE

#### Water Quality:

- WHO Water Quality Standard, World Bank Standards,
- Yangon City Development Committee Standards
- Wastewater, Storm Water Runoff, Effluent and Sanitary Discharges (General Application) National Environmental Quality Guidelines

#### Air Quality:

• Air Emission Level of National Environmental Quality (Emission) Guidelines

#### **Noise Level:**

Noise Level of National Environmental Quality (Emission) Guidelines



#### Safety, Health and Environment

- Factory Acts, Myanmar
- Occupational Health and Safety Acts, Ministry of Labour, Myanmar
- Environmental, Health and Safety Guidelines, IFC

#### **Governing Parameters**

**Table 4.1 Environmental and Social Parameters** 

Sr.	Items	Parameters
1	Air Quality	SO <sub>2</sub> , NO <sub>2</sub> , CO, PM <sub>2.5</sub> , PM <sub>10</sub> , dusts and O <sub>3</sub> concentrations of National Emission guidelines, 2015 December
2	Noise	Acceptable noise levels of National Emission guidelines, 2015 December
3	Water Quality	WHO Drinking water Quality Guidelines pH, Colour, Turbidity, Hardness, Iron, Chloride, Conductivity, Salinity, Concentration of BOD, COD
4	Waste	Waste recycle plan, removed from on-site at regular intervals.
5	Health and Safety	Medical kit box, fire evacuation, emergency plan, PPE.
6	Socio-economic situation	Job availability, providing skill enhancement training, CSR



#### Table 4.2 Effluent Levels (NEQEG 2.3.7.3)

Table 1.2 Elliacit bevels (14EQEG 2.5.7.5)				
Parameter	Unit	Guideline Value		
Aluminum	kg/ton	0.02a		
Ammonia	mg/l (as Nitrogen)	5		
Cadmium	mg/l	0.01		
Chemical Oxygen Demand	mg/l	125		
Chromium (Total)	mg/l	0.5		
Copper	mg/l	0.5		
Fluoride	mg/l	5		
Iron	mg/l	5		
Lead	mg/l	0.2		
Nickel	mg/l	0.5		
Oil and Grease	mg/l	10		
рН	S.U <sup>b</sup>	6~9		
Phenols	mg/l	1		
Temperature Increase	.C	<3c		
Tin	mg/l	2		
Total Suspended Solids	mg/l	35		
Zinc	mg/l	0.5		

<sup>&</sup>lt;sup>a</sup> Aluminum smelting and casting

Table 4.3 Air Emission Level (NEQEG 2.3.7.3)

Parameter	Unit	Guideline Value
Amines	mg/Nm <sup>3a</sup>	5 <sup>b</sup>
Carbon Monoxide	ma/Nim3	200°
Carbon Monoxide	mg/Nm <sup>3</sup>	150 <sup>d</sup>
Chloride	mg/Nm³	5 <sup>e</sup>
Chlorine	mg/Nm³	$5^{\rm f}$
Copper and compounds	mg/Nm³	5-20 <sup>g</sup>
Fluoride	mg/Nm³	5 <sup>h</sup>
Hydrogen sulfide	mg/Nm³	5
Lead, cadmium and their compounds	mg/Nm³	1-2 <sup>i</sup>

<sup>&</sup>lt;sup>b</sup> standard unit

<sup>&</sup>lt;sup>c</sup> At the edge of a scientifically established mixing zone which takes into account ambient water quality, receiving water use, potential receptors and assimilative capacity: when the zone is not defined, use 100 meters form the point of discharge

**FACTORY** 



Nickel, Cobalt, Chromium, Tin and their compounds	mg/Nm³	5
	mg/Nm³	400 <sup>j</sup>
Nitrogen oxides		120°
		150 <sup>k</sup>
Oil Aerosol/ mist	mg/Nm³	5
	/A.T. 2	20 <sup>m</sup>
Particulate mather PM <sub>10</sub> <sup>1</sup>	mg/Nm <sup>3</sup>	50 <sup>n</sup>
		400°
Sulfer dioxide	mg/Nm³	50p
		120 <sup>q</sup>
		20°
Volatile organic compounds	mg/Nm³	30
		15 <sup>r</sup>

- a Milligrams per normal cubic meter at specified temperature and pressure
- b Non-ferrous metal melting (aluminum)
- c Non-ferrous metal melting (shaft furnaces)
- d Cold box molding and core making shop
- e Furnace emissions where chloride flux is used
- f Thermal sand reclamation systems and solvent based investment foundry coating, shelling, and setting operation
- g Higher value applicable to copper and its alloy producing processes
- h Furnace emissions where fluoride flux is used
- i Higher value applicable to non-ferrous metal foundries from scrap
- j Ferrous metal melting (maximum emissions level considered on best available technology base and based on cokeless cupola furnaces)
- k From thermal sand reclamation systems / regeneration units
- 1 Particulate matter 10 micrometers or less in diameter
- m Particulate matter emissions when toxic metals are present
- n Particulate matter emissions when toxic metals are not present
- o Ferrous metal melting (cupola furnaces)
- p Toxicity equivalence factor
- ${\bf q}$  Maximum emissions level considered on best available technology base and based on cold blast cupola furnaces
- r Ferrous metal melting (electric arc furnaces); cupola furnaces may have higher emissions levels (up to 1,000 mg/Nm3)



Table 4.4 Air Quality Standards

Parameter	Averaging Period	Guidelines Value µg/m³
Nitrogen Dioxide	1-year	40
	1-hour	200
Ozone	8-hours daily	100
	maximum	100
Particular matter PM10a	1-year	20
	24-hour	50
Particular matter PM <sub>2.5</sub> b	1-year	10
	24-hour	25
Sulphur Dioxide	1-hour	20
	10-minute	500

<sup>&</sup>lt;sup>a</sup> Particular matter 10 micrometer or less in diameter

Source: National Environmental Quality (Emission) Guideline for Myanmar, 2015 Dec 29

Table 4.5 Noise Level Standard

	One Hour LAeq ( dBA) <sup>a</sup>		
	Daytime	Nighttime	
Receptor	07:00-22:00	22:00-07:00	
	(10:00-22:00 for Public	(22:00-10:00 for Public	
	holidays)	holidays)	
Residential, Institutional,	FF	45	
educational	55	45	
Industrial, commercial	70	70	

<sup>&</sup>lt;sup>a</sup> Equivalent continuous sound level in decibels

#### 4.3 OTHER ACTS, LAWS

The project proponent shall comply with the disciplines described in the permit and licences required.

In addition, project proponent shall comply with the law, rules and regulations which related with the project activities and the regulations issued by the Industrial Zone Management.

<sup>&</sup>lt;sup>b</sup> Particular matter 2.5 micrometer or less in diameter



#### 5.0 PROJECT DESCRIPTION

#### 5.1 COMPANY'S OBJECTIVE

Giant 999 Steel Manufacturing Factory intends to produce the high quality of U Beam and Angle Bar with customers 'satisfaction is our main purpose.

## 5.2 PROJECT LOCATION

Giant 999 Steel Manufacturing Factory is located at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township, Yangon, Myanmar at the coordinates 17° 10′ 25.5″ N and 95° 58' 55.5" E (17.173743, 95.982095). The factory is built on 6.3 acre (274,428 sq ft) land and building area is 5.3 acre.

The surrounding conditions of the project site are as follows:

South : Garment Factory

North: Electricity Sub-power Station

Weast: Industrial Land Plot

East : Myanmar Sun Bell Factory





Figure 5.1 Surrounding Condition of the Factory









**Figure 5.2 Project Location** 










Figure 5.3 Location Map of the Factory





**Figure 5.4 Production Area** 



#### 5.3 PROJECT TIMEFRAME

The factory was built in April 2011 and has been in operation since 2012 in Myanmar. စက်ရုံစီမံကိန်းကာလမှာ ၂၀၁၁ ခုနှစ် ၆.၉.၂၀၁၁ ခုနှစ်မှ လိုင်စင်သက်တမ်းတိုး၍ နှစ်စဥ်ဆောင် ရွက်ပါသည်။ စက်ရုံစီမံကိန်းကာလမှာ နှစ် ၃၀ ဖြစ်ပါသည်။

#### 5.4 PLANT LAYOUT ASSOCIATED FACILITIES

စက်ရုံဝင်း အတွင်းဆောက်လုပ်ထားပြီး ဖြစ်သည့် အဆောက်အဦး အမျိုးအစားများမှာ အုတ်ကာသွပ်မိုး နှင့် streel structure ဖြစ်ပါသည်။




Figure 5.5 Layout Plan of the Factory



**Table 5.1 List of Buildings** 

Sr	Building	Туре	
1	Office Building	Brick and Tin Roof	
2	စက်ရုံဂိတ်	Brick and Tin Roof	
3	ဝန်ထမ်းဆောင်	Brick and Tin Roof	
4	တွင်ခုံ	Streel Structure	
5	Dust Collection (De-dusting) System	Streel Structure	
6	သံရည်ကျိုဆောင်	Streel Structure	
7	သံတို သံစ ကုန်ကြမ်းဆောင်+ စတို	Streel Structure	
8	သံနန်းဆွဲ + ကုန်ချော	Streel Structure	
9	အမှိုက်ပုံဟောင်း	-	
10	အဆောင်ဟောင်း	-	



**Figure 5.6 Factory Office** 






Figure 5.7 Security Gate



**Figure 5.8 Factory Dormitory** 





Figure 5.9 Production Building




Figure 5.10 Dust Collecting Building



#### 5.5 ANNUAL RAW MATERIAL REQUIREMENT

Main raw material for iron and steel fermentation is old iron scraps. Scrap consists of recyclable materials left over from product manufacturing and consumption, such as parts of vehicles, building supplies, and surplus materials. They are stored raw material building with roof and concrete floor. Major sources of raw materials are within the country. Raw materials are stored in the building of the factory.

The factory uses 40 tons/month of old iron scraps (480 ton/year).

**Table 5.2 Annual Raw Materials** 

Sr	ltem	Photo	Amout (year)
1	Old iron scrap		480 ton



Figure 5.11 Photo of Iron Scraps and Storage Area with Roof and Concrete Floor



#### 5.5.1 CHEMICAL REQUIREMENT

သုံးစွဲသည့် ဓာတုပစ္စည်းမှာ Silicon နှင့် Magnet နှစ်မျိုးဖြစ်ပါသည်။ Silicon တစ်လအသုံးပြုနှုန်းမှာ 0.35 ton ဖြစ်ပြီး Magnet တစ်လအသုံးပြုနှုန်းမှာ 0.516 ton ဖြစ်ပါသည်။

သဘာဝပတ်ဝန်းကျင် ထိခိုက်မှု မရှိစေရန် Chemical ပစ္စည်းများဖြစ်သော Silicon နှင့် Manganese များကို Chemical Room ထဲသို့ ထည့်ပါသည်။ ကားပေါ်မှ ကရိန်းချိတ်များဖြင့် Chemical အိတ်များကို မ၍ ကရိန်း မောင်းပညာရှင် မှ Chemical Room ထဲသို့ စနစ်တကျ ထည့်ပါသည်။ Chemical Room ထဲသို့ တာဝန်ရှိသူ မှလွဲ၍ အပြင်လူများ မဝင်ရပါ။ Chemical ပစ္စည်းလာထုတ်သော သူမှအပ ပေး၍ မဝင်ပါ။

#### Storage Condition

- Store in the proper container/bag in the storage room.
- o Marked prominently as "Chemical Storage Area".
- Obtaining material safety data sheet (MSDS)
- o Provide fire extinguisher at storage area.
- o Display warning signage at storage area.

**Table 5.3 Annual Chemical Requirement** 

	Table 5.5 Amitual Chemical Requirement				
Sr	Item	Photo	Amout (year)		
1	Silicon		4.2 ton		
2	Magnet		6.2 ton		





Figure 5.12 Photo of Silicon and Manganese Storage Condition in the Chemical Room



Figure 5.13 Chemical Storage Area with MSDS, Prevent Unauthorized Individuals from Entering and Danger Sign.



#### 5.6 MACHINERIES AND EQUIPMENT

လုပ်ငန်းလည်ပတ်စဥ် အတွင်း အသုံးပြုသော စက်ကိရိယာများမှာ သံရည်ကျိုအိုးကြီး ၄ လုံး၊ မီးခိုး မထွက် စေ ရန်အတွက် အသုံးပြုသော သံရည်ကျိုအုပ်ဆောင်း ကြီး ၄ ခု၊ သံရည်ကျို လျှောက်လမ်း ၁ ခု၊ နန်းဆွဲစက် ၃ စက်၊ ပါကင်စက် ၂ စက်၊ ဖြောင့်စက် ၁ စက်၊ ကတ္တာစက် (ဖြတ်စက်) ၄ စက်၊ ကရိန်း ၆ စင်း ရှိပါသည်။ အခြား ကိရိယာ များမှာ သံရည်ကျိုခံခွက် နှင့် rollar တို့ ဖြစ်ပါသည်။

Machineries and equipment required for production are shown in the following Tables.

Table 5.4 List of Machineries and Equipment

စဥ်	အကြောင်းအရာ	အရေအတွက်
Э	သံရည်ကျိုအိုးကြီး	9
J	သံရည်ကျိုအုပ်ဆောင်း	9
5	သံရည်ကျို လျှောက်လမ်း	0
9	နန်းဆွဲစက်	9
၅	ပါကင်စက်	J
G	ဖြောင့်စက်	0
9	ကတ္တာစက် (ဖြတ်စက်)	9
၈	ကရိန်း	G











ကရိန်း

Rollar



Figure 5.14 Photos of Machines

#### 5.7 PRODUCTION ACTIVITY

ပြည်တွင်း ကုန်ကြမ်း သံတိုသံစ များကို အရည်ကျိုပြီး သံရည်ကျို ခံအိုး တွင် သွန်ထည့်ပါသည်။ သံရည်ကျိုအိုးမှ တဆင့် လျှောက်လမ်းသို့ သံရည်လောင်းထည့်ပြီး squareတုံး အဆင့် ရောက်ပါသည်။ squareတုံး မှ U Beam စက်သို့ ဖြတ်ပြီး U Beam များထွက်လာပါသည်။ ထွက်လာသော U Beam များ cutter စင်ပေါ်သို့ ရောက်ပြီး ဖြတ်စက်ဖြင့် ဖြတ်ပါသည်။ ဖြတ်ပြီးသော U Beam များကို ပါကင်ထုတ်ပါသည်။ ထုတ်ပြီးသော U Beam များကို ကရိန်းနှင့် သယ်ပြီး ကုန်ချောဂိုဒေါင်သို့ ပို့ပါသည်။



# ထုတ်လုပ်မှုလုပ်ငန်းအဆင့်ဆင့်မှာ-

# (၁) ကုန်ကြမ်း သံတို/သံစ ဝယ်ယူခြင်း

ပြည်တွင်းမှ ကုန်ကြမ်းသံတို/သံစ များကို ဝယ်ယူပါသည်။ အရည်အသွေးညံ့သော သံတို/သံစ များကို ဝယ်ယူခြင်းမပြုပါ။ သံတို/သံစ များကို supplier များထံမှ အရောက်ပို့စနစ် ဖြင့် ဝယ်ယူပါသည်။ ဝယ်ယူ ပြီးသော သံတို/သံစ များကို ကရိန်းဖြင့် မောင်း၍ သံလိုက်အုံကြီးနှင့် ကပ်၍ သံတို/သံစ ဂိုဒေါင်ထဲသို့ စနစ်တကျ သိုလှောင်ထားရှိပါသည်။

# (၂) သံအရည်ကျိုခြင်း

ဝယ်ယူရရှိသော ကုန်ကြမ်းသံတို/သံစများကို သံရည်ကျိုအိုး တွင် အရည်ကျိုပါသည်။ ထိုသို့ သံရည်ကျို ခြင်းကို လျှပ်စစ်စွမ်းအင် တစ်မျိုးထဲသာ အသုံးပြုပါသည်။ Silicon နှင့် Manganese ကို သံရည်ကျို ပထမ အဆင့်တွင်ထည့်သုံးပါသည်။ သံရည်ကျိုရာတွင် Silicon နှင့် Manganese ကို သံများ အရည်ပျော်ချိန်၊ သံရည်များ ရရှိချိန်တွင် ထည့်ပါသည်။ အရည်ကျို၍ ရလာသော သံရည်ကို စံနှုန်းမှီ/မမှီ စမ်းသပ် စစ်ဆေး ပါသည်။ စစ်ဆေးချက် result ပေါ်မှ ရရှိသော သံအရည်အသွေး ပေါ်မူတည်၍ Silicon နှင့် Manganese ကို ထည့်ပါသည်။ သံအရည် အသွေးကောင်းလျင် ထည့်ရန်မလိုပါ။

# (၃) သံရည်ကျို ခံခွက်အတွင်းလောင်းထည့်ခြင်း

အရည်ကျိုပြီးသွားသော သံရည်များကို သံရည်ကျိုခံခွက် အတွင်းသို့ လောင်းထည့်ပါသည်။ ထည့်ပြီး သွား သော သံရည်ကျိုခံခွက်ကို ကရိန်းနှင့်မ၍ သံရည်ကျိုလောင်းစင်သို့ သယ်ဆောင်ပြီး Square တုံး ဘက်သို့ လောင်းထည့်ပါသည်။

# (၄) U Beam များထွက်ရှိလာခြင်း

ထွက်ရှိလာသော Square တုံးများမှ လျှောက်လမ်းပေါ်သို့ ရောက်၍ နန်းဆွဲစက်ကို ဖြတ်ကာ နန်းဆွဲ ပြီးလျှင် U Beamစက်ကို ဖြတ်၍ U Beam များဖြစ်ပေါ်လာပါသည်။ ထွက်ရှိလာသော U Beam များကို ဖြတ်စက်ဖြင့် ဖြတ်ပါသည်။ ဖြတ်ပြီးသော U Beam များကို ပါကင်စက် ပေါ်သို့ ရောက်ရှိလျင် ပါကင် ထုတ်ပါသည်။

# (၅) Angle များထွက်လာခြင်း

U Beam နှင့် Angle ကို Rollar များလဲပြီး တစ်မျိုးပြီးမှ တစ်မျိုးထုတ်၍ ရပါသည်။ ပါကင်ထုတ်ပြီး ထွက်လာသော ကုန်ချောများကို ကရိန်းဖြင့်သယ်ယူ၍ ကုန်ချောဂိုဒေါင်သို့ ပို့ပါသည်။

အထက်တွင် ဖော်ပြထားသော Production Activity တွင် Silicon နှင့် Manganese များကို သံရည်ကျို ပထမ အဆင့်တွင်ထည့်၍သုံးရပါသည်။ သံရည်ကျို အရည်အသွေးစစ်ဆေးပြီး သံရည်ကျို အရည်အသွေး ပေါ်မူတည်၍ ထပ်ထည့်ပါသည်။ သံအရည်အသွေး ကောင်း၍ မလိုအပ်လျင် ထည့်ရန် မလိုပါ။



ထိုသို့ သံရည်ကျို ခြင်းကို လျှပ်စစ်စွမ်းအင် တစ်မျိုးထဲသာ အသုံးပြုပါပြီး အခြားလောင်စာစွမ်းအင် များသုံးစွဲ ခြင်းမရှိပါ။

#### 5.7.1 PROCESS FLOW OF PRODUCTION

The process flow chart is dexcribed follows:



Figure 5.15 Process Flow for Finishing




Figure 5.16 Process Flow Chart of Production





Figure 5.17 သံတိုသံစ ကုန်ကြမ်းများ




Figure 5.18 သံရည်မကျိုမှီ သံရည်ကျိုအိုး နှင့် မီးခိုးအုပ်ဆောင်း



သံရည်ကျို ကျိုနေစဉ် သံရည်ကျိုအိုး + မီးခိုးအုပ်ဆောင်း



Figure 5.19 သံရည်ကျိုနေစဉ် သံရည်ကျိုအိုး နှင့် မီးခိုးအုပ်ဆောင်း

# ကျိုပြီး သံရည်များကို ခံခွက်အတွင်းသို့ လောင်းထည့် စဉ်



Figure 5.20 ကျိုပြီးသံရည်များကို မီခံခွက် အတွင်းသို့ လောင်းထည့်စဉ်





Figure 5.21 နန်းဆွဲ ပထမအဆင့် square တုံး





Figure 5.22 နန်းဆွဲ ဒုတိယ အဆင့် square တုံး နန်းဆွဲ ပြေးလမ်းပေါ်ရောက်



နန်းဆွဲ တတိယ အဆင့် U Beam စက်သို့ ဖြတ်



Figure 5.23 နန်းဆွဲတတိယအဆင့် U Beam စက်သို့ဖြတ်



Figure 5.24 U Beam စက်သို့ဖြတ်ပြီး U Beam ချောင်းဖြစ်ပေါ်လာပုံ



ထွက်လာသော U Beam ချောင်း ပါကင်စင်ပေါ် သို့ ရောက်



Figure 5.25 ထွက်လာသော U Beam ချောင်း ပါကင်စက်ပေါ်သို့ရောက်



Figure 5.26 ပါကင်စက်ပေါ်မှ U Beam ဖြောင့်စက်သို့ဖြတ်





Figure 5.27 ဖြောင့်စက်မှ U Beam ဖြတ်စက်သို့ရောက်

# ဖြတ်စက်မှ ပါကင်သို့



Figure 5.28 ဖြတ်စက်မှ ပါကင်စင်ပေါ်သို့ရောက်





ပါကင်စင်

Figure 5.29 ပါကင်စက်မှ ကုန်ချောစုပုံရာသို့ရောက်

#### 5.8 PRODUCTS/ BY PRODUCT AND PRODUCTION CAPACITY

The main products are U Beam. Most of by products generated from the factory's manufacturing activities are reject product and process wastes. They are reused in the fermentation process for recycle purposes.

The annual production capacity for U Beam and Angle Bar is 420 ton/year.

#### **Storage**

Finish products stacked systematically in the finished goods storage area as shown in following figure.



Figure 5.30 Photos of Finishing Products and Storage Area



#### 5.8.1 SALE SYSTEM

Sale system is 100% local.

#### 5.9 RESOURCE REQUIREMENT

#### 5.9.1 HUMAN RESOURCE REQUIREMENT

Giant 999 Steel Manufacturing Factory composes of well-trained staffs, local people from nearby Hmawbi Township as well as foreign experts. The production is managed by 15 foreign managers and technicians. During the Project assessment process, 50 employees are local people. Local employment is the main socio-economic benefit that the Project can directly bring to people living in the community nearest to the Plant.

Table 5.5 List of Local and Foreign Employee on 1st November 2019

Sr. No.	Type of Employee	Male	Female	Total
1	Foreign Employees	15	-	15
2	Local Employees	42	8	50
Total		57	8	65

#### 5.9.2 WORKING HOURS

Generally, working hour is 8 hours in a day. Employee on the working duty on public holiday is paid overtime fees according to the labour law.

 Working time
 7:00 a.m. to 11:30 a.m.

 Lunch time
 11:30 a.m. to 12:30 p.m.

 Working time
 12:30 p.m. to 3:00 p.m.

 Over time (if required)
 3:15 p.m. to 5:15 p.m.

#### 5.9.3 WORKING DAYS

Working hour is 8 hours in a day. Normally, there are twenty six (26) working days per month and 290 working days in a year (Public holidays are assumed 22 days in a year). Basic pay for monthly salary is 144,000 kyats. Overtime fee is paid according to the labour law.



#### 5.10 WATER SUPPLY

The production water source is from ten on-site tube wells. The water is stored in 10 storage tanks and pumped to 6 overhead tanks. Process water is recycled. The estimated water use for process is 6000 gallons/year.

စက်ရုံအတွင်း တူးဖော်ထားသော အဝိစိတွင်းများမှာ ၆လက်မ ပေ၁၀၀ တွင်း ၆ တွင်းနှင့် ၃လက်မ ပေ၈၀ တွင်း ၄တွင်းရှိပါသည်။ ၆လက်မ ပေ၁၀၀တွင်း ၆တွင်း ၏တည်နေရာမှာ (က)အရည်ကျိုဌာန တွင် ၄ တွင်း (ခ) ပါကင် ဌာနတွင် ၂ တွင်းရှိပါသည်။ ၃လက်မ ပေ၈၀ တွင်း ၄တွင်း ၏ တည်နေရာမှာ (က) ပါကင်ဖက်၏ အဆုံးနေရာ တွင် ၁ တွင်း (ခ) အမျိုးသားအဆောင် အနီးတွင် ၁ တွင်း (ဂ) တွင်ခုံ အနီးတွင် ၁ တွင်း နှင့် (ဃ) အလယ်ပါကင် တွင် ၁ တွင်း ရှိပါသည်။



**Figure 5.31 Photos of Water Storage Condition** 



Figure 5.32 Photos of Tube Wells



#### 5.11 ELECTRICITY

The project use electricity supply from Yangon Electricity Supply Corporation (YESC) by using 7 transformers of 6300 KVA, 6300KVA, 6300KVA, 2000KVA, 2000KVA and 3000KVA.

Two generators- 500 KW and 575 KW are installed to ensure continuous power supply to the factory during the power supply outage. Annual fuel requirement for diesel is 1900 gallons. Annual electricity requirement is 152,288 units.



Transformer



Generators

Figure 5.33 Photos of Transformer and Generator with Extinguisher and Danger Sign



#### **5.11.1 FUEL USE**

စက်ရုံ၏ ကုန်ထုတ်လုပ်ငန်း တွင် လျှပ်စစ်မီးကို အသုံးပြုပြီး မီးပြတ် ချိန်တွင် မီးစက် အတွက်သာ ဒီဇယ်ဆီကို အသုံးပြုပါသည်။

အရန်ဓာတ်အားအဖြစ် ထားရှိသည့် မီးစက်များအတွက် လိုအပ်သော ဒီဇယ် တစ်နှစ်စာ ၁၉၀၀ ဂါလံ (တစ်နေ့လျှင် ၅ ဂါလံကျော်) ကို သံဆီလှောင်ကန် နှင့်စနစ်တကျသိုလှောင်ထားရှိပါသည်။ ဒီဇယ်ဆီကို ထော်လာဂျီကား အသုံးပြုရာတွင် ထည့်၍မောင်းနှင်ခြင်း၊ ကရိန်းမောင်းရာတွင် လည်း မီးပျက်လျှင် မီးစက်နှိုး၍မောင်းနှင်ခြင်း တို့အတွက်လည်း အသုံးပြုပါသည်။ သဲအိပ်များ ထားရှိခြင်း၊ MSDS များကပ်ထားခြင်း၊ အန္တရာယ်ဆိုင်းဘုတ်၊ သတိပေးဆိုင်းဘုတ်များ ကပ်ထားပြီး အခြားဖိတ်စင်မှု မရှိအောင် သိမ်းဆည်းထားပါသည်။

စက်ဆီ ချောဆီ အနေနှင့် Hydraulic ဆီ၊ Grease ၊ Engine Oil ၊ Gear Oil များကို အသုံးပြုပါသည်။ Hydraulic ဆီမှာ ၁လ လျင် ၂၅ဂါလံ၊ Grease ၅ဂါလံ၊ Engin Oil ၂ဂါလံ နှင့် Gear Oil ၂ဂါလံ အသုံးပြုပါသည်။ ၄င်းတို့ကို ဆီပီပါ အတွင်းလုံခြုံစွာထည့်ပြီး သီးသန့် နေရာတွင် ထားရှိပါသည်။ အနီးတွင် မီးသတ်ဆေးဗူး ထားရှိပါသည်။





Figure 5.34 Diesel Storage Tank Post with MSDS and No Smoking Sign and Keeping Sand







Figure 5.35 Lubricating Oil Storage Post with MSDS, Safety Signs and Extinguishers

#### 5.12 WASTE

#### 5.12.1 SOLID WASTE (TYPE/ AMOUNT/ MANAGEMENT)

#### **Domestic Waste**

The domestic waste and waste from office, canteen and dormitory are collected first at the garbage space for normal waste.

Factory practises reducing and recycling of waste management. For domestic waste, factory has waste storage area (Figure 5.36) in the factory premises. Some putrid foods are collected by factory workers for animal feed (especially for pig).

For disposing waste are disposed to the designated place in industrial zone three times a week and transported by factory own car. The factory produced 1.5 kg of domestic waste on average per month.

စက်ရုံအတွင်းဝန်ထမ်းဆောင်မှ ထွက်ရှိသော အမှိုက်များ နှင့် စားဖိုဆောင်မှ ထွက်သော အမှိုက်များ ကို စက်ရုံမှ ကားဖြင့် မြောင်းတကာ စက်မှုဇုန် အတွင်း သတ်မှတ်ထားသော အမှိုက်ပုံသို့ တစ်ပတ်လျှင် သုံးကြိမ် စွန့်ပစ် ပါသည်။ စက်ရုံမှ ကားအားလပ်မှု မရှိလျှင် စည်ပင်အား အကြောင်းကြား၍ စည်ပင်ကား ဖြင့် စွန့်ပစ် ပါသည်။ စည်ပင်ကားမှ သယ်ဆောင်သွားသော အမှိုက်များအား သက်ဆိုင်ရာ မှ ၄င်းတို့သတ်မှတ်ထားသောနေရာ အား ယူဆောင် သွားပါသည်။









Figure 5.36 Photo of Factory Garbage Area and Removing Waste

#### **Process Waste**

Systematic management of solid waste is of importance as mismanagement of the waste will lead critical occupational hazard including fire hazard. Waste generation from the whole production process and waste management is as follows:






Figure 5.37 Process Waste Flow Chart

The main types of wastes generated by the production activities are broken pieces of iron, reject products and cut pieces of iron. Broken pieces, reject products and cut pieces of iron products are re-melting in process of iron melting to be recycled purposes.

Another solid waste is ironish fly ash. Dust is collected through the dust collecting system. The collected dust is normally called fly ash, visually, it is a very fine powder, gray in colour, account for the foundry solid waste. Factory's dust collecting system generates 4 bags (200 kg) of the fly ash (သံရော်ပြာ/မီခိုးပြာ) monthly. They are sold to the waste collectors for recycle purpose. Fly ash can be recycled and reused in a variety of engineering applications, including cement production, paving material, flowable fill and in structural fills and embankments. ထွက်ရှိလာသော မီးခိုးပြာများကို Carbon တုံးများ ထုတ်လုပ်သော လုပ်ငန်းသို့ အများဆုံး ပြန်လည်ရောင်းချပါသည်။





Figure 5.38 Photos of Fly Ash Solid Waste (သံချော်ပြာ)



Figure 5.39 Photos of Process Waste (သံဖြတ်စ) and, Broken and Reject Waste (အကျိုး၊ အပယ်) to be Recycled

#### 5.12.2 EFFLUENT/ WASTE WATER (TYPE/ AMOUNT/ MANAGEMENT)

The production water sources are from on- site tube well.

Water use of employees and staff, domestic wastewater, oil/fuel leakage from vehicles and diesel generator, cleaning of machines and tanks are sources of waste water.

Domestic wastewater from the toilets is disposed to the septic tanks located in the factory compound. In order to prevent contamination to the underground water, frequent cleaning and pumping out of septic tank are done by contacting Engineering Department (Water and Sanitation) from YCDC.

The factory use water to spray the hot iron product. The water is recycled for this process. Staff is giving knowledge to turn on water taps only when needed and not to waste water comsumption.



စက်ရုံ၏ ကုန်ထုတ်လုပ်ငန်းလည်ပတ်ခြင်းမှ စွန့်ပစ်ရေ (effluent wastewater) မရှိပါ။ ထုတ်လုပ်မှု အဆင့်ဆင့် မှ နန်းဆွဲစက် သို့ရောက်ပြီး ထိုမှ U Beam စက်သို့ဖြတ်၍ U Beam စက်သို့ ရောက်လျှင် ရေသို လှောင်ကန်မှ ရေများကို စက်ဖြင့်မောင်း၍ U Beam စက်များတွင် ရေဖျန်းပါသည်။ အဆိုပါ ဖျန်းပြီးသော ရေများသည် U Beam စက်အောက်မြောင်း မှတဆင့် မူလရေသိုလှောင်ကန်သို့ ပြန်လည် ရောက်ရှိ သွားပါသည်။ ဤနည်းဖြင့် ရေကို ပြန်လည်အသုံးပြု recycle ပြုလုပ်ပါသည်။ စက်ရုံပြင်ပသို့ စွန့်ထုတ်ခြင်းမရှိပါ။

The managements for waste water are as follows:

- All factory staff is giving knowledge to turn on water taps only when needed and any leakage should be promptly reported to engineering department as soon as possible.
- Recycle the water which spray the hot iron.
- Regularly pumping out of sludge waste from septic tank.
- Related employees are trained to use minimize water for cleaning of machines.

#### Management for leakage and spillage

- Names and telephone numbers of ERT to be contacted in the event of a spill.
- Clean the leakage and spillage of oil/fuel immediately.
- Acquire spill control materials and spill clean-up kits.
- Spill control materials and spill kits will be restocked after used.
- Training in its proper use (when needed).



Figure 5.40 Photo Water Storage and Pipe and Water Recycle System





Figure 5.41 Photo Records for Sludge Waste Removal from Septic Tanks

#### **5.12.3 HAZARDOUS WASTE**

**Hazardous waste** includes small amount of machinery maintenance materials, such as oily rags, used oil, batteries, machine oil containers.

Silicon နှင့် Manganese များကို Chemical Room မှထုတ်ယူလျင် လုပ်သားများ နှင့် ထုတ်ပေးသူ Store Men မှ လက်အိတ်၊ Mask တပ်ဆင်ပြီးလျှင် သေချာစွာ ကိုင်တွယ်၍ ကတ္တားသေး နှင့်ချိန်တွယ်ပြီး ပီနံအိတ်ထဲသို့ သေချာထည့်၍ ထုတ်ယူပါသည်။

Used oil is sold to third party collector for recycling purpose. Sometime, the factory reuses the used lubricating oil for factory machine. For disposing, hazardous wastes are packed with plastic bag and disposed by YCDC as hazardous waste.

#### 5.12.3.1 EXISTING DUST COLLECTION (DE-DUSTING) SYSTEMS

The furnaces release large amount of light weighted particles. Released dust particles can produce hazardous air pollution. Air pollution and their treatments are one of the major issues. Thus, the factory has already installed the Iron Powder Fume Dust Collecting system /https://www.alibaba.com/product-detail/Iron-Powder-Bag-Type-Fume-Dust 60804611390.html?spm=a2700.7724857.normalList.35.14ed799foTLWSu.







**Figure 5.42 Dust Collecting Building** 

လေထုညစ်ညမ်းမှု မဖြစ်စေရန် သံရည်ကျိုရာမှ ထွက်ရှိသော မီးခိုးများကို Iron Powder Fume Dust Collection System ကို တည်ဆောက်တပ်ဆင် အသုံးပြုလျက်ရှိပါသည်။ Iron Powder Fume Dust Collection အဆောက်အဦး၏ အကျယ်အဝန်းမှာ ၅၀ပေx၇၀ ပေဖြစ်ပါသည်။ 380KW ရှိ Blower ကြီး နှင့် မီးခိုးများ စုပ်ယူပြီး Filter နှင့် စစ်ယူကာ အမှုန်စစ်ဧကာတွင် ကပ်နေသော မီးခိုးပြာ များကို Vibrate နှင့် ခါချပြီး ထွက်ရှိလာသော ချော်ပြာများကို စနစ်တကျ နေ့စဥ် ထုတ်ပိုးပါသည်။ သံချော်ပြာ ထွက်ပေါက်မှာ ၁၆ ပေါက်ရှိပါသည်။ မီးခိုးပြာများ တစ်လလျင် ၂၀၀ ကီလိုဂရမ် ခန့်ရှိပြီး ၄င်းတို့ကို ရီဆိုင်ကယ် ရည်ရွယ်ချက်အရ ဝယ်ယူသူသို့ ပြန်လည်ရောင်းချပါသည်။ ထွက်ရှိလာသော မီးခိုးပြာများကို carbon တုံးများထုတ်လုပ်သော လုပ်ငန်းသို့ အများဆုံး ပြန်လည်ရောင်းချပါသည်။









Figure 5.43 Dust Collecting System

#### 5.13 DRAINAGE

In the factory compound, there are drainage systems for storm water and domestic waste water. The existing drainage system includes internal and external drainage system. Both drainage systems are provided with proper concrete gutters.



Figure 5.44 Internal Drainage



#### 5.14 TRANSPORTATION CONDITION

The project site is located in Myaung Dagar Industrial Zone which situated at west side of Yangon-Pyay Road. It runs north and south direction and connects the Yangon to the south and Pyay to the north. Vehicles used for procuring goods, material and manpower to the plant and the subsequent transportation of product will use these Road.

The rawmaterials of old iron scarps are received by many types of motorcars from the whole country to the factory. The finished products are colleted by the customers with their cars.

ကုန်ကြမ်းပစ္စည်းများ သယ်ယူရာတွင် ကုန်သည်များမှ ၄င်းတို့၏ ကားများနှင့် စက်ရုံအရောက် လာရောက် ရောင်းချကြပါသည်။

ကုန်ချောမျာကို ရောင်းချရာတွင်လည်း ကုန်သည်များက ၄င်းတို့၏ ကားများနှင့် စက်ရုံအရောက် လာရောက် ဝယ်ယူကြပါသည်။

စက်ရုံအတွင်းရှိ လုပ်သားများကို ကြိုပို့ပေးရန်မလိုပါ။ စက်ရုံပြင်ပမှ လာရောက်ကြသော လုပ်သားများ သည် မိမိတို့၏ အစီအစဉ့်ဖြင့် လာရောက် အလုပ်ဆင်းကြပါသည်။



#### 6.0 BASELINE ENVIRONMENTAL AND SOCIAL QUALITY

# 6.1 CURRENT ENVIRONMENT AND SPATIAL BOUNDARIES OF THE FACTORY

Giant 999 Steel Manufacturing Factory is located at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township. The factory is surrounded by other factories as shown in following Figure.

Being situated in industry zone, the surrounding land use is industrial land use and factories are situated in the area with high density. The nearby land use comprises other factories and industries.

The surrounding conditions of the project site are as follows:

South: Garment Factory

North: Electricity Sub-power Station

Weast: Industrial Land Plot

East : Myanmar Sun Bell Factory



Figure 6.1 Surrounding Condition of the Factory






Figure 6.2 Factory Location and Myaung Dagar Industrial Zone

#### 6.2 BACKGROUND HISTORY OF HMAWBI TOWNSHIP

မှော်ဘီမြို့နယ်သည် လွန်ခဲ့သော နှစ်ပေါင်း (၄၀၀) ကျော်ခန့်က မွန်၊ ကရင် များ အခြေချ နေထိုင်ခဲ့ ကြရာမှ စတင်ဖြစ်ပေါ် လာသည့် မွန်စကား"မောတပီ" မှ "မှော်ဘီ" ၄င်းမှတဆင့် မှော်ဘီ ဟု ခေါ်လာခြင်း ဖြစ်သည်။ မြန်မာ သက္ကရာဇ် (၆၃၆) ခုနှစ်တွင် သောက္ကတံမင်း မြန်မာ အခေါ် မင်းရင်ခင်းသည် မှော်ဘီထီးနန်းအား တင်ထားခဲ့သည်။ မှော်ဘီ မြို့သည် စစ်မဖြစ်မှီ ကာလအထိ ကျေးရွာ တစ်ခုအဖြစ်သာ တည်ရှိခဲ့ပြီး (၈.၁၁.၁၉၀၀) ရက်နေ့တွင် အခွန်ဌာန၏ကြေငြာချက် (၄၃၇) အရ မီးရထားမြို့ အဖြစ်သတ်မှတ်ခဲ့သည်။ (၈.၄.၁၉၅၅) ရက်နေ့တွင် မှော်ဘီမြို့ကို အင်းစိန်ခရိုင် အောက်တွင်ထည့်သွင်းခဲ့သည်။ (၂၉.၅.၁၉၆၅) ရက်စွဲပါ အမိန့် (၆၆၀) အရ အင်းစိန်ခရိုင်အား မှော်ဘီခရိုင်ဟုပြင်ဆင်ဖွဲ့စည်းလျက် မှော်ဘီကို မြို့နယ် အဖြစ်သတ်မှတ် ရာတွင် ထန်းတပင်မှ ကျေးရွာအုပ်စု (၁၀)စု၊ အင်းစိန်မှ (၂၄)စု၊ တိုက်ကြီးမှ (၉)စု၊ စုစုပေါင်း (၄၃) အုပ်စုအဖြစ် ဖွဲ့စည်းခဲ့ ပါသည်။ ယခုအခါတွင် မြို့ပေါ် (၄)ဂုပ်ကွက်၊ ကျေးရွာအုပ်စု (၃၉) အုပ်စုနှင့် ကျေးရွာပေါင်း (၁၉၅) ရွာ ဖြင့်ဖွဲ့စည်းခဲ့ပါသည်။



#### 6.2.1 LOCATION AND AREA

Hmawbi Township is situated in Northern District of Yangon Region.

**Table 6.1 Particular Matter of the Township** 

Sr.	Township	Township Sq. Mile	Town	Town Sq. Mile
1	Hmawbi	183.78	Hmawbi	6.09

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

#### 6.2.2 BOUNDARIES

The township shares borders with Hlegu Township in the east, Htatabin Township in the west, Mingaladon Township in the south and Taik Kyi Township in the north.



Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

Figure 6.3 Hmawbi Township Map



#### 6.3 TOPOGRAPHY

Hmawbi township is southwest of the Bago Yoma. There is uneven elevation in the north and south of the Township and down to the western section in which Yangon-Pyay Highway Road passes through.

The surrounding terrain is mostly flat land, the elevation approximately ranges from +20 ft to +36 ft. The ground elevation around the factory approximately ranges from + 23 ft to +30 ft. The contour map of the area shows most gentle relief.




Figure 6.4 Map Showing Topographic Feature of Surrounding Area

#### 6.4 DRAINAGE CONDITION

Hlaing River is flow in the township from east to west. Hlaing River is used for irrigation. The channel is navigable by boats.

Hlaing River is well beyond the project vicinity of 2.574 km (1.6 mile) radius.




#### 6.5 CLIMATE

The plant is situated in the Hmawbi Township. Hmawbi Township has HOT HUMID CLIMATE. Climate of Hmawbi Township can be considered as climate of Yangon. Statistical analysis for climate data is based on the period from January 1, 1980 to December 31, 2016.

#### 6.5.1 TEMPERATURE

The hot season lasts for 2.0 months, from March 3 to May 4, with an average daily high temperature above 35°C. The hottest day of the year is April 12, with an average high of 36°C and low of 25.5°C.

The cool season lasts for 3.9 months, from June 3 to September 30, with an average daily high temperature below 30.5°C. The coldest day of the year is January 10, with an average low of 19.4°C and high of 31.1°C.



https://weatherspark.com

Figure 6.5 Average High and Low Temperature

Table 6.2 Yearly Temperature Condition of Hmawbi Township

		Tempe	erature
Sr	Year	Summer (°C)	Winter (°C)
		Maximum	Minimum
1	2018	39.3	10
2	2019	41.6	13.4

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"



#### 6.5.2 PRECIPITATION

A wet day is one with at least 0.04 inches of liquid or liquid-equivatent precipitation. The chance of wet days in Yangon varies very significantly throughout the year.

The wetter season lasts 5.0 months, from May 13 to October 12, with a greater than 28% chance of a given day being a wet day. The drier season lasts 7.0 months, from October 12 to May 13. The smallest chance of a wet day is 1% on January 25.




Figure 6.6 Daily Chance of Precipitation

The rainy period of the year lasts for 7.7 months, from April 6 to November 29, with a sliding 31-day rainfall of at least 0.5 inches. The most rain falls during the 31 days centered around July 31, with an average total accumulation of 9.1 inches.

The rainless period of the year lasts for 4.3 months, from November 29 to April 6. The least rain falls around February 1, with an average total accumulation of 0.1 inches.



Figure 6.7 Average Monthly Rainfall



Table 6.3 Yearly Precipitation and Rainy Days Condition of Hmawbi Township

		Precipitation	
Sr	Year	Rainy Day	Total Rainfall
1	2018	11	12.26
2	2019	103	87.95

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

#### 6.5.3 HUMIDITY

The comfort level humidity is based on the dew point. Lower dew points feel drier and higher dew points feel more humid. Dew point tends to change slowly and muggy day is typically followed by a muggy night. Yangon experiences extreme seasonal variation in the perceived humidity. The muggier period of the year lasts for 10 months, from February 22 to December 24, during which time the comfort level is muggy, oppressive, or miserable at least 61% of the time. The muggiest day of the year is August 6, with muggy conditions 100% of the time. The least muggy day of the year is January 11, with muggy conditions 48% of the time.




Figure 6.8 Humidity Comfort Levels



#### 6.5.4 WIND DIRECTION AND WIND SPEED

The average hourly wind speed in Yangon experiences significant seasonal variation over the course of the year.

The windier part of the year lasts for 4.1 months, from May 2 to September 5, with average wind speeds of more than 8.2 miles per hour. The windiest day of the year is July 25, with an average hourly wind speed of 10.6 miles per hour.

The calmer time of year lasts for 7.9 months, from September 5 to May 2. The calmest day of the year is January 9, with an average hourly wind speed of 5.8 miles per hour.

The wind is most often from the south for 2.1 months, from January 6 to January 21 and for 2.6 months, from May 14 to August 3, and for 1.1 months, from September 17 to October 20, with a peak percentage of 60% on June 12. The wind is most often from the west for 2.8 months, from January 21 to May 14 and for 1.5 months, from August 3 to September 17, with a peak percentage of 56% on August 31. The wind is most often from the east for 2.5 months, from October 20 to January 6, with a peak percentage of 35% on January 1.




Figure 6.9 Average Wind Speed

#### 6.6 NATURAL VEGETATION AND WILDLIFE

There is no apparent data about natural vegetation and wildlife for Hmawbi Township. (Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ" 2019, မြို့နယ်အထွေထွေအုပ်ချုပ်ရေးဦးစီးဌာန, ရန်ကုန်မြောက်ပိုင်းခရိုင်)

Therefore, there is no anticipated impact on wildlife and protected area.



**Table 6.4 Existing Condition of Ecological Resources** 

Ecological Resources	Existing condition
Fisheries, aquatic biology	The nearest river is Hlaing River 2.574 km (1.6 mile) west of the factory. Fresh water fish species are residing in the river.
Wildlife	Non existence
Forests	Non existence
Rare or endangered species	Non existence
Protect areas	The nearest protected areas is Hlaw Gar Park which is located 12 miles south east of the factory.

#### 6.7 HAZARD CONSIDERATION

#### 6.7.1 EARTHQUAKE

By the global scope of geology, Myanmar lies in one of the great earthquake provinces called the Alpine Earthquake Belt. Therefore, minor to catastrophic earthquakes has occurred many times in the territory of Myanmar since long ago.

The buildings and structures where they are constructed at or near seismic distribution zone are possible to experience some destruction due to ground shaking effect during earthquake event. Hence, the building or structures has to be considered possible of destruction due to earthquake. Due to this unstable activity of ground earthquake occurrences can expect at any time in Myanmar.

#### 6.7.1.1 EARTHQUAKE INTENSITY OF MYANMAR

Earthquake intensity in the area can be seen in Figure 6.10. The map is an earthquake probable intensity zoning map. The approach is mainly empirical and historical in the sense that it makes use of past seismic event and history to make educated guesses about region wide intensities in the future. It is hoped that a probabilistic seismic risk (or earthquake hazard map) on horizontal ground acceleration should be taken into account in the design.



According to the seismic zone map of Myanmar (after Dr. Maung Thein et.al, 2005 Dec), the Plant area is shown in Figures 6.10, the probable ground peak acceleration when earthquake occur will be 0.15 g.




Figure 6.10 Seismic Zone Map of Myanmar and Plant area



Table 6.5 Level of Probable Damage and Destruction

Zone	MM Class	Probable Damage	Examples of Damage
V	IX	Major damage	Considerable damage in specially
			designed structures
			Major damage in good RC buildings
IV	VIII-IX	Considerable	Considerable damage in good RC
		damage	buildings Major damage in ordinary
			brick buildings
III	VII	Moderate damage	Moderate damage in good RC buildings
			Considerable damage in ordinary brick
			buildings
II	VII	Minor damage	Minor damage in good RC buildings
			Moderate damage in ordinary brick
			buildings
I	VI	Slight damage	Minor damage in ordinary brick
			buildings

#### 6.8 LAND USE

Hmawbi Township is 1193 acres. Urban settlement land use is 6.09 acres. Rural settlement land use is 3450 acres and industrial land use is 4115 acres in the township.

The project is located in the Myaung Dakar Industrial Zone. The nearby land use and properties adjacent to the project site of the Giant 999 Steel Manufacturing Factory are mixed landuse with agricultural landuse, rural settlement and industrial land use. Adjacent to the project area is surrounded by factories.

Table 6.6 Land Utilization in Hmawbi Township

No.	Type of Land	Area (Acre)	Remark
1	Le Land (Paddy Land)	1544	
2	Ya Land	-	
3	Kaing Land (Alluvial Farming)	-	
4	Garden Land	-	
5	Dahni (Nipa Palm)	-	
6	Fallow Land	-	
7	Pastureland	5695	
8	Industrial Land	4115	



9	Urban Settlement	1193	
10	Rural Settlement	3450	
11	Other	-	
12	Reserved Forest	630	
13	Forest (Jungle)	-	
14	Cultivable Waste Land	4621	
15	Bare Land	33099	

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ, 2019"





Figure 6.11 Nearby Factories





Figure 6.12 Surrounding Land Use of the Factory



#### 6.9 SOIL COMPOSITION OF THE PLANT AREA

According to the FAO/UNESCO Soil Classification, the soil compositions around the plant area include Eutric Gleysols (Figure 6.13).

Gleysols holds wetland soils that unless drained, are saturated with groundwater for long enough periods to develop a characteristic 'gleyic colour pattern'. This pattern is essentially made up of reddish, brounish or yellowish colours at ped surfaces and/or in the upper soil layer(s), in combinateion with greyish/bluish colours inside the peds and/or deeper in the soil.

#### Parent material and environment

**Parent material**: a wide range of unconsolidated materials, mainly fluvial, marine and lacustrine sediments of Pleistocene or Holocene age, with basic to acidic mineralogy.

**Environment**: depression areas and low landscape positions with shallow groundwater.

#### **Characteristics**

#### a. Reductomorphic properties

• Signify permanently wet conditions and reflect the redox gradient between the ground water and the capillary fringe. They are expressed by neutral whitish/greyish or bluish to greenish "gley colours" in more than 95 prcent of the soil matrix. Near the capillary fringe, the (subsoil) layer with reductomorphic properties may include up to 5 percent oxidation colours e.g. as mottles (around air pockets) of "root prints".

#### b. Oximorphic properties

Indicate alternating reducing and oxidizing conditions, as occur near the capillary fringe and in the surface layers of soils with fluctuating groundwater depth. Oximorphic properties feflect the redox gradient between the reduced soil matrix and air inclusions in the soil matrix such as root holes. They are expressed by reddish brown or bright yellowish brown mottles on aggregate surfaces and on walls of pores. Acid sulphate soils feature bright yellow mottles of jarosite (at pH <3.5) or schwertmannite (at pH 3.0-4.5).



## **Suitable Crops**

The soils of rice paddies may be true Gleysols but are often anthrequic units of some other Reference Soil Group. "Paddy Soils" developed stagnic soil properties after long continued irrigation of in-undation. By and large, there are two broad categories of "Paddy soil".




Figure 6.13 Soil Map of Factory



#### 6.10 WATER QUALITY OF THE FACTORY

Water supply during operation is extracted from the tube well water.

Sanitation wastewater from toilets is disposed in the septic tank.

Survey team collected the tube well water from the tap of the factory and drain water from the drainage channel and sent them to the Labs for water analysis.

#### 6.10.1 GROUND WATER QUALITY

In order to analyze the ground water quality, the water sample was gathered from the tube well located within the plant. Table 6.9 shows the baseline data of ground water quality during October.

#### 6.10.1.1 METHODOLOGY

Ground water sampling was collected form the tap of the factory on 4-11-19 and transporting to the laboratory. Water samples have been sent to laboratory of **MYANMAR WATER ENGINEETING AND PRODUCTS CO., LTD**. All of the test items are listed below as:

- 1) Turbidity
- 2) pH
- 3) Total Dissolved Solid
- 4) Total Alkalinity
- 5) Total Hardness
- 6) Iron
- 7) Conductivity
- 8) Chloride
- 9) Colour





Figure 6.14 Water Sample Collections for Ground Water

**Table 6.7 Geographic Position of Monitoring Points** 

No.	Location	North	East
1	Tap Water	17° 10.457′	095° 58.889′

#### 6.10.1.2 WATER QUALITY STANDARD

Table 6.8 WHO Drinking Water Quality Standards

Parameters	WHO Standard
рН	6.5-8.5
Colour	Clear
Total Dissolved Solid	<250
Total Hardness	<16
Total Alkalinity	<250
Calcium	<8
Magnesium	<8
Iron	<0.3
Chloride	<250
Bicarbonate	<250
Carbonate	<250
Hydroxide	<100



#### 6.10.1.3 WATER QUALITY ASSESSMENT RESULTS

The ground water quality can provide some indications of water quality of the factory (Lab certificate is shown in Appendix B). According to the result, water condition is chemically potable.

**Table 6.9 Ground Water Quality** 

ъ .		1 D 1	
Parameters	Sam	ple Result	WHO Standard
рН	7		6.5-8.5
Colour	Clear		Clear
Conductivity	78.13 r	nicro mho/cm	-
Total Dissolved Solid	50	mg/l	<250
Total Hardness	16	mg/l	<16
Total Alkalinity	38	mg/l	<250
Sodium	-		-
Calcium	4.01	mg/l	<8
Magnesium	1.44	mg/l	<8
Potassium	-		
Iron	0.02	mg/l	<0.3
Chloride	17	mg/l	<250
Sulphate	-		
Bicarbonate	38	mg/l	<250
Carbonate	ND	mg/l	<250
Hydroxide	-		<100

#### 6.10.2 DRAIN WATER QUALITY

In order to monitor the drain water quality, drain water sample from drainage line of the factory was taken in November. The analysis results of the physico-chemical parameters are presented in Table 6.12.

#### 6.10.2.1 METHODOLOGY

Drain water sampling was collected on 4-11-19 and transporting to the laboratory. Water samples have been sent to laboratory and tested at Advanced Medical & Diagnostics laboratory. All of the test parameters items are listed below as:



- 1) Dissolved Oxygen (DO)
- 2) Biochemical Oxygen Demand
- 3) Chemical Oxygen Demand
- 4) pH effluent water
- 5) Total suspended solids (TSS)
- 6) Nitrate

**Table 6.10 Geographic Position of Monitoring Points** 

No.	Location	North	East
1	Drainage	17° 10.409′	95° 58.969′



Figure 6.15 Water Sample Collection

#### 6.10.2.2 WATER QUALITY STANDARD

**Table 6.11 Water Quality Standards** 

Parameters	YCDC Target range	WHO Standard
Dissolved Oxygen (DO)	>1 ppm	-
Biochemical Oxygen Demand	20-60 ppm	<200 ppm
Chemical Oxygen Demand	<200 ppm	20-60 ppm
pH effluent water	6 <ph<9.6< td=""><td>6.5-8.5</td></ph<9.6<>	6.5-8.5
Total suspended solids (TSS)	<500	<1500 mg/l
Nitrate	N/A	-



#### 6.10.2.3 WATER QUALITY ASSESSMENT RESULTS

Following table shows the results of the physico-chemical parameters.

According to the baseline data, COD and BOD values are within the guideline (Lab certificate is shown in Appendix B). All parameters are good within the acceptable range and it is suitable to discharge to the public drainage.

Table 6.12 Drain Water Quality

Parameters	Waste Water Drainage	YCDC Target range
Dissolved Oxygen (DO)	3.6	>1 ppm
Biochemical Oxygen Demand	31.8	20-60 ppm
Chemical Oxygen Demand	54	<200 ppm
pH effluent water	6.97	6 <ph<9.6< td=""></ph<9.6<>
Total suspended solids (TSS)	16	<500
Nitrate	1.3	N/A

#### 6.11 AIR QUALITY

#### 6.11.1 METHODOLOGY

Haz-Scanner EPAS Wireless Environmental Perimeter Air Station was used for ambient air quality. Ambient air quality samples were collected for Particulate Maters (PM10 and PM2.5) and gases parameter Carbon monoxide (CO), Carbon dioxide (CO2), Sulfur dioxide (SO2) and Nitrogen dioxide (NO2). The averaging period adopted is 24 hours.

The air quality monitoring at operation points is performed by using Aeroqual Series 500 Air monitoring device from New Zealand and 770-1100 HAZ-DUST I, Aerosol Monitor, 110-240V from USA. The Aerosol Sensor heads for Carbon Monoxide, Nitrogen Oxide and Sulphur Dioxide and H<sub>2</sub>S. Carbon dioxide concentration was measured with Carbon Dioxide sensor meter M0198132S 81. Aerosol monitor is used to monitor dusts. PM2.5 and PM10 were monitored by using HOLDPEAK 5800D PM<sub>2.5</sub>/PM<sub>10</sub> Monitor Detector for 1 hour at operation areas within the plant.





Figure 6.16 Photos of Air Monitoring Devices



Figure 6.17 Haz-Scanner EPAS Device



Figure 6.18 Aeroqual Series 500 Air Monitoring Device





Figure 6.19 770-1100 HAZ-DUST I, Aerosol Monitoring Device

## 6.11.2 AMBIENT AIR QUALITY STANDARDS

Ministry of Environemntal Conservation and Forestry legislate general air emission guidelines for general industry to reduce air pollution form the industrial activities. Standard parameters of general air emission includes Sulphur Dioxide (SO<sub>2</sub>), Nitrogen Dioxide (NO<sub>x</sub>), Particular matter PM<sub>10</sub>, Particular matter PM<sub>2.5</sub> and Ozone (O<sub>3</sub>). National Air Emission standards and US EPA standards are shown in the following table. National Air Emission standards values shall be applied to ensure that air emission conform to good practice.

Table 6.13 Air Quality Standards

Parameter	Averaging Period	Guidelines Value µg/m³	US-EPA Standards	WHO
Nitrogen	1-year	40	-	40 μg/m3
Dioxide	1-hour	200		200 μg/m3
Ozone	8-hours daily maximum	100		100 μg/m3
Particular matter PM <sub>10</sub> <sup>a</sup>	1-year	20	150 μg/m3	20 μg/m3
	24-hour	50	(24-hour)	50 μg/m3
Particular matter PM <sub>2.5</sub> <sup>b</sup>	1-year	10	35 μg/m3 (24-	10 μg/m3
	24-hour	25	hour)	25 μg/m3
Sulphur Dioxide	24-hour 10-minute	20 500	75 ppm (1-hour)	20 μg/m3 500 μg/m3

<sup>&</sup>lt;sup>a</sup> Particular matter 10 micrometer or less in diameter

Source: National Environmental Quality (Emission) Guideline for Myanmar, 2015 Dec 29

<sup>&</sup>lt;sup>b</sup> Particular matter 2.5 micrometer or less in diameter



#### **6.11.3 AIR MONITORING POINTS**

In order to get the baseline ambient air quality parameters such as PM10, PM 2.5, and gases parameter CO, CO2, SO2, NO<sub>2</sub>, EMP team selected a monitoring point which was situated near factory gate at North Latitude 17° 10.443′N and East Longitude 95° 58.876′E (Table 6.15). Ambient air quality monitoring was measured by using the HAZ SCANNER on 10<sup>th</sup> to 11<sup>th</sup> May 2022 for 24 hours continuously (Figure 6.20).

Additional 6 points in and around the factory were measured about one hour period for evaluation and comparison the with emission standard values on 1st November 2019.









Figure 6.20 Air Quality Monitroing

**Table 6.14 Geographic Position of Monitoring Points at Operation Areas** 

No.	Location	North	East
1	သံရည်ကြို	17° 10.446′	95° 58.941′
2	Square ကုန်ကြမ်းလောင်းစက်	17° 10.417′	95° 58.963′
3	ကုန်ချောကြိတ်လုံး	17° 10.383′	95° 58.891′
4	ကုန်ကြမ်းသိုလှောင်ရုံ	17° 10.439′	95° 58.927′
5	Generator	17° 10.471′	95° 58.908′
6	Exhaust system အနီး	17° 10.443′	95° 58.881′

Table 6.15 Geographic Position of Ambient Air Quality Monitoring Station

No.	Location	North	East
1	Near Factory Gate	17° 10.443′	95° 58.876′



#### 6.11.4 AIR MONITORING AND RESULTS

Records of ambient air quality monitoring results are described in Table 6.16. Comparing with the National Environmental Quality (Emission) Guideline for baseline ambient air quality is presented in Table 6.20. Comparing the ambient air quality with the NEQEG, the measured values of SO<sub>2</sub>, NO<sub>2</sub>, O<sub>3</sub>, PM<sub>10</sub> and PM<sub>2.5</sub> lie within the range of Air Quality Guidelines.

To reveal the existing status of air quality at the operation areas, observed values are mentioned in Table 6.18 and the average air qualities measured were compared with National Environmental Quality (Emission) Guideline in Table 6.19. The average concentrations of air quality at operation areas are within the permissible value of National Environmental Quality (emission) Guideline.

## 1) Ambient Air Monitoring Station

**Table 6.16 Ambient Air Quality Monitoring Results** 

Location	Date & Time	Item	Average Period	Unit	Observed Value
Near Factory	10-5-22 (9:00) to	NO <sub>2</sub>	24 hrs	μg/m³	21.73
Gate			24 hrs	μg/m³	0.01
		CO	24 hrs	ppm	0.0002
		CO <sub>2</sub>	24 hrs	ppm	382
		PM <sub>2.5</sub>	24 hrs	μg/m³	17.31
		PM <sub>10</sub>	24 hrs	μg/m³	18.26



# 2) Operation Areas

**Table 6.17 Air Quality Monitoring Results** 

No	Place	H <sub>2</sub> S ppm	SO <sub>2</sub> ppm	NO <sub>2</sub>	CO ppm	CO <sub>2</sub>	O <sub>3</sub> ppm	PM(2.5) μg/m³	PM(10) μg/m³
1	သံရည်ကြို	0.0	0.00	0.004	0.00	443	0.000	17.3	32.3
	(9:00-10:00)	0.0	0.00	0.004	0.00	443	0.000	16.4	29.2
		0.0	0.00	0.004	0.00	443	0.000	17.7	28.6
		0.0	0.00	0.003	0.00	444	0.000	16.5	31.5
		0.0	0.00	0.003	0.00	444	0.000	15.1	28.9
	Average	0.0	0.00	0.0036	0.00	443.4	0.000	16.6	30.1

No	Place	H <sub>2</sub> S ppm	SO <sub>2</sub> ppm	NO <sub>2</sub> ppm	CO ppm	CO <sub>2</sub> ppm	O <sub>3</sub> ppm	PM(2.5) μg/m³	PM(10) μg/m³
2	Square	0.0	0.00	0.021	0.00	434	0.000	10.0	24.7
	ကုန်ကြမ်းလောင်းစက်	0.0	0.00	0.021	0.00	434	0.000	8.5	14.2
	(10:30-11:30)	0.0	0.00	0.020	0.00	433	0.000	9.0	11.4
		0.0	0.00	0.022	0.00	433	0.000	8.9	13.4
		0.0	0.00	0.022	0.00	432	0.000	9.7	14.0
	Average	0.0	0.00	0.0212	0.00	433.2	0.000	9.22	15.54

No	Place	H <sub>2</sub> S ppm	SO <sub>2</sub> ppm	NO <sub>2</sub>	CO ppm	CO <sub>2</sub> ppm	O <sub>3</sub> ppm	PM(2.5) μg/m <sup>3</sup>	PM(10) μg/m³
3	ကုန်ချောကြိတ်လုံး	0.0	0.00	0.016	0.00	436	0.000	23.1	48.9
	(12:00-13:00)	0.0	0.00	0.016	0.00	436	0.000	24.0	47.4
		0.0	0.00	0.016	0.00	441	0.000	12.7	17.1
		0.0	0.00	0.021	0.00	442	0.000	15.0	28.5
		0.0	0.00	0.021	0.00	442	0.000	12.2	24.1



Average	0.0	0.00	0.018	0.00	439.4	0.000	17.4	33.2

No	Place	H <sub>2</sub> S ppm	SO <sub>2</sub>	NO <sub>2</sub>	CO ppm	CO <sub>2</sub>	O <sub>3</sub>	PM(2.5) μg/m³	<b>PM(10)</b> μg/m³
4	ကုန်ကြမ်းသိုလှောင်ရုံ	0.0	0.00	0.036	0.29	436	0.000	10.2	15.0
	(13:30-14:30)	0.0	0.00	0.036	0.29	436	0.000	9.9	13.9
		0.0	0.00	0.035	0.32	435	0.000	10.9	19.8
		0.0	0.00	0.035	0.32	435	0.000	10.1	16.1
		0.0	0.00	0.037	0.00	435	0.000	10.4	13.8
	Average	0.0	0.00	0.0358	0.244	435.4	0.000	10.3	15.72

No	Place	H <sub>2</sub> S ppm	SO <sub>2</sub> ppm	NO <sub>2</sub>	CO ppm	CO <sub>2</sub>	O <sub>3</sub> ppm	PM(2.5) μg/m³	<b>PM(10)</b> μ <b>g/m</b> <sup>3</sup>
5	Generator	0.0	0.00	0.029	0.00	429	0.014	9.6	15.8
	(15:00-16:00)	0.0	0.00	0.029	0.00	430	0.014	8.4	16.4
		0.0	0.00	0.034	0.00	430	0.014	8.6	12.1
		0.0	0.00	0.033	0.00	430	0.014	8.4	15.8
		0.0	0.00	0.033	0.00	430	0.014	8.0	14.7
	Average	0.0	0.00	0.0316	0.00	429.8	0.014	8.6	14.96

No	Place	H <sub>2</sub> S ppm	SO <sub>2</sub> ppm	NO <sub>2</sub>	CO ppm	CO <sub>2</sub>	O <sub>3</sub> ppm	PM(2.5) μg/m³	<b>PM(10)</b> μg/m³
6	Exhaust	0.0	0.00	0.028	0.00	430	0.016	6.1	15.6
	system အနီး	0.0	0.00	0.028	0.00	430	0.016	5.7	11.1
	(16:30-17:30)	0.0	0.00	0.028	0.00	431	0.016	5.4	9.0
		0.0	0.00	0.021	0.00	434	0.016	5.7	10.9
		0.0	0.00	0.021	0.00	434	0.016	5.6	11.0
	Average	0.0	0.00	0.0252	0.00	431.8	0.016	5.7	11.52



Table 6.18 Air Quality Measured at the Operation Areas

Area	Date & Time	H <sub>2</sub> S ppm	SO <sub>2</sub>	NO <sub>2</sub>	CO ppm	CO <sub>2</sub>	O <sub>3</sub>	PM <sub>(2.5)</sub> μg/m <sup>3</sup>	PM <sub>(10)</sub> μg/m <sup>3</sup>
သံရည်ကြို	1-11- 2019	0.0	0.00	0.0036	0.00	443.4	0.000	16.6	30.1
Square ကုန်ကြမ်း လောင်းစက်	(09:00- 17:30)	0.0	0.00	0.0212	0.00	433.2	0.000	9.22	15.54
ကုန်ချော ကြိတ်လုံး		0.0	0.00	0.018	0.00	439.4	0.000	17.4	33.2
ကုန်ကြမ်း သိုလှောင်ရုံ		0.0	0.00	0.0358	0.244	435.4	0.000	10.3	15.72
Generator		0.0	0.00	0.0316	0.00	429.8	0.014	8.6	14.96
Exhaust system အနီး		0.0	0.00	0.0252	0.00	431.8	0.016	5.7	11.52
Factory Average		0.00	0.00	0.0225 (42.34 μg/m3)	0.040	435.5	0.005 (9.82 μg/m3)	11.30 (μg/m3)	20.17 (μg/m3)

Table 6.19 Comparison of Air Quality at Operation Areas between Ovserved Factory Average Value and National Emission Guideline Value

Location	Item	Average Period	Unit	Observed Value	Guideline	Organization
Factory	NO <sub>2</sub>	1 hr	μg/m³	42.34	200 (1 hr)	NEQEG
Average	O3	1 hr	μg/m³	9.82	100 (8 hr)	NEQEG
(Operation	SO <sub>2</sub>	1 hr	μg/m³	0.00	20 (24 hr)	NEQEG
Areas)	CO	1 hr	ppm	0.040	-	-
	CO <sub>2</sub>	1 hr	ppm	435.5	-	-
	PM <sub>2.5</sub>	1 hr	μg/m³	11.30	25 (24 hrs)	NEQEG
	PM <sub>10</sub>	1 hr	μg/m³	20.17	50 (24 hrs.)	NEQEG



Table 6.20 Comparison of Ambient Air Quality between Ovserved Value and National Emission Guideline Value

Location	Item	Average Period	Unit	Observed Value	Guideline	Organization
Near Factory	NO <sub>2</sub>	24 hrs	μg/m³	21.73	200 μg/m³ (1 hr)	NEQEG
Gate	SO <sub>2</sub>	24 hrs	μg/m³	0.01	20 μg/m³ (24 hrs)	NEQEG
	CO	24 hrs	ppm	0.0002	25 ppm (1 hr)	WHO
	CO <sub>2</sub>	24 hrs	ppm	382	-	-
	PM2.5	24 hrs	μg/m³	17.31	25 μg/m³ (24 hrs)	NEQEG
	PM <sub>10</sub>	24 hrs	μg/m³	18.26	50 μg/m³ (24 hrs.)	NEQEG

#### 6.12 NOISE AND VIBRATION CONDITION

#### **6.12.1 NOISE**

#### 6.12.1.1 METHODOLOGY

EMP Team conducted the noise measurement inside and outside of the building. In order to assess the noise levels from the potential noise sources, the noise levels are measured about one hour at potential sources of 6 points (Table 6.22) by using a digital noise level meter, ST 435355 (Figure 6.21) on 1st November 2019.

Measurement of environmental sound level for 24 hours duration was conducted on 10<sup>th</sup> to 11<sup>th</sup> May 2022 (Table 6.23).

MONREC has issued National Environmental Quality (Emission) Guidelines to provide the basis for regulation and control of noise level. Noise impact should not exceed the levels presented in Table 6.21. The average noise levels in the project site area are compared with NEQE guideline.





Figure 6.21 Photos of Noise Monitoring Device

Table 6.21 Noise Level Standard

	One Hour LAeq (dBA) <sup>a</sup>		
Receptor	Daytime 07:00-22:00 (10:00-22:00 for Public holidays)	Nighttime 22:00-07:00 (22:00-10:00 for Public holidays)	
Residential, Institutional, educational	55	45	
Industrial, commercial	70	70	

<sup>&</sup>lt;sup>a</sup> Equivalent continuous sound level in decibels

#### 6.12.1.2 MONITORING POINTS AND RESULTS

Geographic position at potential sources of 6 points are mentioned in Table 6.22 and the results compared with NEQEG are described in Table 6.24. All values of noise are below the level of National Emission guidelines.

Geographic position of Noise Monitoring Station for 24 hours is presented in Table 6.23. Observed value results of ambient noise level are detailed in Table 6.26. The data is divided into daytime and night-time period. The summarise dresults are compared against the Myanmar NEQ Guideline for commercial activities in Table 6.25. The observed values of daytime and night-time are below the stipulated limits of 70 dBA in industrial area.

However, in Table 6.26, the observed value of some noise level are little higher than National Environmental Quality Emission Guideline for industrial sector because there are cumulative effect of noise sources from the renovation activities of factory gate entrance road and moment of moving trucks that delivered the old iron scrap to the factory during noise level measuring at project site.



Table 6.22 Geographic Position of Noise Monitoring Points at Operation Areas

No.	Location	North	East
1	သံရည်ကြို	17° 10.446′	95° 58.941′
2	Square ကုန်ကြမ်းလောင်းစက်	17° 10.417′	95° 58.963′
3	ကုန်ချောကြိတ်လုံး	17° 10.383′	95° 58.891′
4	ကုန်ကြမ်းသိုလှောင်ရုံ	17° 10.439′	95° 58.927′
5	Generator	17° 10.471′	95° 58.908′
6	Exhaust system အနီး	17° 10.443′	95° 58.881′

Table 6.23 Geographic Position of Noise Monitoring Station Point near Factory Gate

No.	Location	North	East
1	Near Factory Gate	17° 10.443′	95° 58.876′







Figure 6.22 Noise Quality Monitoring



Table 6.24 Monitoring Measurements of Noise within the Factory (dBA)

No.	Location	Date & Time	Measured Mean Value (dBA)	Standard Value
1	သံရည်ကြို	1-11-2019	68.0	70
2	Square ကုန်ကြမ်းလောင်းစက်	One Hour	67.2	70
3	ကုန်ချောကြိတ်လုံး		57.0	70
4	ကုန်ကြမ်းသိုလှောင်ရုံ		60.2	70
5	Generator		55.5	70
6	Exhaust system အနီး		51.3	70

Table 6.25 Comparision of Observed Ambient Noise Level with Standard Guideline

Monitoring	LAeq		D-1- 8			EQ ne Value
Station	Date & Time	Measured Mean Value (dBA)		Industrial, Commercial	Residential, Institutional, Educational	
Near Factory	May 10 <sup>th</sup> – 11 <sup>th</sup> 22	LAeq- Daytime	55.7	70	55	
Gate	24 Hours	LAeq-Nigh time	39.2	70	45	

Table 6.26 Survey Results of Hourly LAeq Value in Noise Monitoring Station

Date	Time	Mean Value	Day/Night
10/5/2022	09:05:00-10:05:00	59.9	Day
10/5/2022	10:05:00-11:05:00	72.1	Day
10/5/2022	11:05:00-12:05:00	61.9	Day
10/5/2022	12:05:00-13:05:00	62.7	Day
10/5/2022	13:05:00-14:05:00	63.4	Day
10/5/2022	14:05:00-15:05:00	72.7	Day



	,		
10/5/2022	15:05:00-16:05:00	62.7	Day
10/5/2022	16:05:00-17:05:00	63.1	Day
10/5/2022	17:05:00-18:05:00	60.4	Day
10/5/2022	18:05:00-19:05:00	57.2	Day
10/5/2022	19:05:00-20:05:00	54.7	Day
10/5/2022	20:05:00-21:05:00	53.4	Day
10/5/2022	21:05:00-22:05:00	51.3	Day
10/5/2022	22:05:00-23:05:00	47.3	Night
10/5/2022	23:05:00-00:05:00	43.1	Night
11/5/2022	00:05:00-01:05:00	38.6	Night
11/5/2022	01:05:00-02:05:00	34.4	Night
11/5/2022	02:05:00-03:05:00	32.6	Night
11/5/2022	03:03:00-04:05:00	34.7	Night
11/5/2022	04:05:00-05:05:00	38.5	Night
11/5/2022	05:05:00-06:05:00	44.5	Night
11/5/2022	06:005:00-07:05:00	51.4	Night
11/5/2022	07:05:00-08:05:00	53.2	Day
11/5/2022	08:05:00-09:00:05	58.3	Day
LAeq-I	Daytime	55.7	
LAeq-N	igh time	39.2	

#### 6.12.2 VIBRATION

Vibration levels within the project area was monitored on 10 May 2022. Tivolii digital vibration meter gm63a portable digital vibration meter handheld vibrometer tester device with vibration analyzer gauge is use along with VIBROMETER software to analyze the vibration levels.

Total 4 points are selected based on the use of machines and the vehicle movements that can probably emit vibration (Table 6.28).



EMP Team will compare the vibration assessment results to the Vibration analysis scale develoed by United State Geological Survey.



Figure 6.23 Photos of Vibration Monitoring Device

**Table 6.27 Vibration Intensity Scale** 

Intensity Category	Acceleration (m/s)	Description	Potential Damage
I	<0.0167	Detectable only by instruments	None
II-III	0.0167- 0.13734	Very slight vibration felt by only some people	None
IV-V	0.13734- 0. 9025	Feeling moderate shaking	None- Very light
VI-VII	0.9025- 3.3354	Strong and very strong shock. Explicit destruction	Light- Moderate
VIII	3.3354- 12.1644	Sudden shocks. Widespread destruction	Moderate to Heavy
IX-X	>12.1644	Change the configuration of land, landslide and cracks	Very Heavy

(Ref: United State Geological Survey)

## 6.12.2.1 MONITORING POINTS AND RESULT

Geographic position at potential sources of 4 points are mentioned in Table 6.28 and the results are described in Table 6.29.

In accrodance with vibration assessment results (Table 6.29) that compared to the Vibration analysis scale develoed by United State Geological Survey, the vibration levels in and around the factory were considered as None to Very Light. It can be concluded that the vibration impact is insignificant to the environment and the workplace.





Figure 6.24 Vibration Level Monitoring

**Table 6.28 Geographic Position of Monitoring Points** 

No.	Location	North	East
1	သံရည်ကြို	17° 10.446′	95° 58.941′
2	ကုန်ကြမ်းသိုလှောင်ရုံ	17° 10.439′	95° 58.927′
3	ကုန်ချောကြိတ်လုံး	17° 10.383′	95° 58.891′
4	Square ကုန်ကြမ်းလောင်းစက်	17° 10.417′	95° 58.963′

**Table 6.29 Vibration Intensity Scale** 

	Location	Within Factory Vibration Level (m/s)	Guideline Value
1	သံရည်ကြို	0.016	0.0167-0.13734 None
2	ကုန်ကြမ်းသိုလှောင်ရုံ	0.024	ii
3	ကုန်ချောကြိတ်လုံး	0.11	0.13734-0. 9025 None- Very Light
4	Square ကုန်ကြမ်းလောင်းစက်	0.07	0.0167-0.13734 None



## 6.13 SOIL QUALITY

Soil pH within the Plant and around the Plant was measured by using Soil pH meter, Dr. Meter Soil Moisture Meter S30. Summary of Soil pH results showed pH at the monitoring points lies within 6 to 7 (Table 6.30). It can be considered that soil quality around the factory is neutral.

Table 6.30 Summary of Soil pH

Location	North	East	Soil pH	Moisture
Within the factory	17° 10.445′	95° 58.882′	7.0	1
Within the factory	17° 10.388′	95° 58.902′	6.8	1

17 10.445, 95 58.882

17 10.388, 95 58.902




Figure 6.25 Soil Quality Monitroing Places



Figure 6.26 Photo Records of Soil Quality Monitroing



## 6.14 SOCIO-ECONOMIC COMPONENT NEAR THE FACTORY

Giant 999 Steel Manufacturing Factory is located at Plot No. 20/21, Myaung Dagar Industrial Zone, Hmawbi Township, Yangon, Myanmar.




Figure 6.27 Hmawbi Township



#### 6.14.1 SOCIAL CONDITION

Hmawbi Township is 183.78 square miles. The township is made up of 4 wards in the urban area and 39 village tracts including 195 villages in the rural area. The township has a total population of 202,904 with 43,987 households.

The population characteristics in Hmawbi Township are as follow.

## a) Population By Sex

Table 6.31 Population by Sex in Hmawbi Township

	Male	Female	Total
Urban	13047	13305	26352
Rural	84166	92386	176552
Total	97213	105691	202904

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

## b) Religion

Table 6.32 Religious Groups of Ethnic in Hmawbi Township

Sr.	Type of Religion	No. of Person
1	Buddhist	185700
2	Christian	14247
3	Hindu	656
4	Islam	2301
5	Other	-
Township Total		202904

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

#### c) Population by Foreigner Living

Table 6.33 Population by Foreigner Living in Hmawbi Township

Sr.	Ethnic Race	No. of Person	% of Tsp. Population
1	Chinese	307	0.15
2	Indian	2221	1.09
3	Pakistan	30	0.01
4	Bangaladesh	535	0.26
5	Other	30	0.01
Towns	hip Total	3123	1.53



## d) Education

Table 6.34 Number of University and Schools in Hmawbi Township

Sr.	Uni/School	Quantity		
Higher	Higher Education			
1	Technological University	1		
Basic E	Basic Educatin			
2	High School	10		
3	State high school (branch)	4		
4	State Middle School	2		
5	State middle school (branch)	4		
6	Post-Primary School	28		
7	Primary	95		
8	Monestric Education	8		

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"

There are 27 libraries in the township.

#### e) Health

The main diseases in Hmawbi Township are tuberculosis, diarrhoea-related illnesses, dysentery and hepatitis.

Table 6.35 Number of University and Schools in Hmawbi Township

Sr.	Туре	Quantity	Remark
1	Government Hospital	3	82 beds
2	Department of Health (Rural)	5	
3	Sub Department of Health (Rural)	30	



## f) Status of Social Organization

Table 6.36 Social Organization in Hmawbi Township

Sr.	Description	Quantity
1	Pagoda	2
2	Monastery	456
3	Nun dwelling	10
3	Religious Hall	20

#### 6.14.2 ECONOMIC CONDITION

Hmawbi Township is located in Yangon Region and the economic development is slow compare with other townships. Hmawbi Township is predominately rural with living in a rural area. Hmawbi, located outside Yangon City, reflects the rural economic conditions. Crop production and agricultural trade play an important role in Hmawbi Township. Hmawbi Township has Nayung Hnapin agricultural and livestock farm zone, which concentrates on growing vegetables and raising livestock to be sent to Yangon City.

#### a) Status of Economic Organization

Table 6.37 Economic Organization in Hmawbi Township

Sr.	Туре	Quantity
1	Industrial Zone	1
2	Lifestock Farm Zone	1
3	Government Factory	-
4	Private factory	80
5	Industry and Craft of Domestic	175
6	Private Petroleum Station	8
7	Hotel/ Motel/ Inn/ Guest house	14
8	Government Major market	3



9	Government Bank	2
10	Private Bank	4
11	Shop house and stores	278

Source: "မှော်ဘီမြို့နယ် ဒေသဆိုင်ရာ အချက်အလက်များ"



## 7.0 ENVIRONMENTAL AND SOCIAL IMPACT ASSESSMENT AND MITIGATION MEASURES

#### 7.1 OVERVIEW OF IMPACTS

Giant 999 Steel Manufacturing Factory's production activity is unlikely to cause any major negative environmental and social impacts. The project operation would create potential environmental issues and proper management is pertinent to minimize the environmental impacts.

The impact specific to the project operation phase will be Solid Waste. With timely and proper implementation of this EMP and application of appropriate mitigation measures, most if not all the potential negative impacts can be prevented or minimised.

In brief, environmental and social impact assessment involves the processes as follows:

Monitoring, field survey, remote sensing, collecting current and historical data, etc. are mainly used for the investigation of the environmental background/ baseline data.

Levels of a Risk Matrix (5x5 risk matrix) is used to determain the significance of the impact. Qualitative and risk metrix approach methods are used for different environmental aspects depending on their characteristics, variation extent, as well as the features and regularities of the impacts of the Project.

By comparing the predicted results with relevant standards or threshold values, the features, magnitude, and significance of the impacts were analyzed and assessed. The significance of each impact is classified into 5 cathegories in overall.

Details of the approach and methodology are discussed below.



#### 7.1.1 MAGNITUDE OF THE IMPACT (M)

Magnitude of impact is the amount of change in a measurable parameter or variable relative to existing (baseline) conditions. Table 7.1 explained evaluation and prediction of Magnitude of an impact.

Table 7.1 Evaluation of Magnitude of Impact

Severity or	1	Insignificant							
Magnitude of	2	Minor Impact (Small and will have no effect on working							
Impact		environment/ Minor local impact)							
_	3	Moderate Impact (Moderate and will result in minor							
	changes on working environment/ Moderate local impa								
	4	High Impact (High and will result in significant changes on							
		working environment/ Major impact on local and							
		neighborhood)							
	5	Very High (Very high and will result in permanent changes							
		on working environment/ Major impact on region)							

#### 7.1.2 DURATION OF IMPACT (D)

Duration refers to the length of time over which an environmental impact may occur: i.e. transient (less than 1 year), short-term (0 to 5 years [construction]), medium term (5 to 15 years), long-term (greater than 15 years[operational]), permanent (impact ceasing after closure of the project).

Table 7.2 Evaluation of Duration of Impact

		<u> </u>
Duration of	1	Temporary (0-1 year)
Impact	2	Short (0 to 5 years)
•	3	Medium ( 5 to 15 years)
	4	Long term (<15 years to project end)
	5	Permanent (Post Closure)



#### 7.1.3 GEOGRAPHIC OR SPATIAL EXTENT (E)

Geographic extent refers to the area that could be affected by the impact and is classified as site; local; the regional; beyond regional and effect extends to international.

**Table 7.3 Evaluation of Spatial Extent of Occurrence** 

Spatial Extent	1	Site (Site - specific)
•	2	Local (Community to municipal)
	3	Regional (Municipal to regional)
	4	National (Beyond regional)
	5	International (Global)

#### 7.1.4 PROBABILITY OF OCCURRENCE (O)

Probability of occurrence how likely is it that the impact may occur

This criterion is corresponding to the frequency of the impact occurrence.

**Table 7.4 Evaluation of Probability of Occurrence** 

Probability of Occurrence	1	Occur in very unlikely condition/extreme condition (Never Happen)
	2	Occur in unlikely condition (Remote)
	3	Occur in unlikely condition (Occasionally)
	4	Occur in likely condition (Frequently)
	5	Occur in very likely condition (Definite)

#### 7.1.5 SIGNIFICANT LEVEL OF RISK CONSIDERATION

An important step in environmental and social assessment is the determination of the significance level of environmental risks. The World Bank's EIA Guidelines, Asia Development Banks' EIA guidelines and other applicable guidelines are used to determine whether the project is likely to cause significant adverse environmental effects.

The significant level is calculated by following formula.

Significant Level = (Magnitude + Duration + Extant) x Occurrence



#### **Table 7.5 Score Evaluation**

Risk Score	Risk Level	Impact Level	Remark
<15	Very Low	No significant impact	No additional Risk Control
15-29	Low	Light impact, try to improve	No additional Risk Control, however, require regular monitoring and review.
30-44	Moderate	Significant impact,	Require additional risk control measures and regular review.
45-59	High	Highly Significant impact, need to improve	Must provide appropriate risk control measures and continuous monitoring the effectiveness of improvement
60	Very High	Unsustainable situation	Require alternative for the impact defined.



#### 7.2 IMPACT ASSESSMENT FOR CONSTRUCTION PHASE

All impacts for construction phase of the Giant 999 Steel Manufacturing Factory are assessed and tabulated in the Table 7.6 below.

Table 7.6 Environmental and Social Impact Assessment Matrix for Construction

		Existing Control	Significance of potential impacts							act
Potential Impact			le	1		ce c	evel	ıtion	Signif	icant
	Project Activities		Magnitude	Duration	Extent	Occurrence	Significant Level	Score Evaluation	Before Mitigation	After Mitigation
		Wa	stewater							
-Sanitation Waste Water	- Wastewater generated from sewers	- Temporary Toilets are provided -Sludge waste from septic tank are removed periodically.	+3 Modera te	+2 Short	+1 Site	X2 Remote	12	Low	Low	Low

# Green EHSS Consultancy

## GIANT 999 STEEL MANUFACTURING FACTORY

Oil and grease leakage from machines and vehicles used	-Oil and grease from maintenance of machinery and vehicles	- Spillage are cleared immediatelyKeeping the impervious floors of oil and grease handling areas -Vehicles are regularly inspecte	+3 Modera te	+2 Short	+1 Site	x2 Remote	12	Low	Low	Low
Runoff water during raining season	-Runoff water from soil piles	-All waste water is collected via drainage system and sedimented in the collection pond.	+3 Modera te	+1 Tempo rary	+2 Local	x12 Remote	12	Low	Low	Low
		Air	Pollution							
-Exhaust gases	-Exhaust gases from diesel generator, vehicles movements	- The factory uses the generator only when the power supply outage -Vehicle maintenance	+4 High	+1 Tempo rary	+2 Local	x2 Remote	14	Low	Low	Low

## GIANT 999 STEEL MANUFACTURING FACTORY



- Dust emissions	- Emission of particulate matters, PM <sub>2.5</sub> and PM <sub>10</sub> from construction activites and vehicle movements on unpaved roads	- Regular water spraying and covered the soil piles and at the unpaved roads	+4 High	+1 Tempo rary	+2 Local	x2 Remote	14	Low	Low	Low
		Noice a	and Vibrat	ion						
Noise exposure	-Transportation of construction materials -Operation of heavy machinery such as excavators and loaders -Using diesel generators	<ul> <li>Noisy activities are conducted during day time.</li> <li>-Factory site is far from residential area.</li> <li>- Built Noise barriers for diesel generator</li> </ul>	+4 High	+1 Tempo rary	+2 Local	X2 Remote	14	Low	Low	Low

## GIANT 999 STEEL MANUFACTURING FACTORY



			Waste							
Disposal of Solid Wastes	- Construction wastes from grading and excavation activities, scrap wood and small concrete spills.	- Unable wastes such as timbers and metal scraps will be recycled.	+3 Modera te	+1 Tempo rary	+2 Local	X2 Remote	12	Low	Low	Low
Disposal of Hazardous Wastes	- Small amount of machinery maintenance materials, used oil, - spill clean-up materials	- All hazardous wastes are disposed in accordance with Township Committee's guideline.	+4 High	+2 Short	+1 Site	x2 Remote	14	Low	Low	Low
		Soi	il Quality							
Soil Contaminatio n	-Spillage of diesel and chemicals on the land -Construction materials delivery trucks movement	<ul><li>Spillage are cleared immediately.</li><li>Washing bay is provided.</li></ul>	+3 Modera te	+3 Mediu m	+2 Local	x2 Remote	16	Low	Low	Low



## **GIANT 999 STEEL MANUFACTURING FACTORY**

		H	Iazards							
Occupational Health and Safety	- All construction activities can expose minor to major occupational health and safety hazards.	-Relevant workers are trained to educate occupational health and safety.	+4 High	+1 Tempo rary	+1 Site	x4 Freque ntly	24	Low	Low	Low
	- Some construction activities can cause minor to major injuries to public.	-Warning signages are provided around the project area.	+5 Very High	+2 Short	+2 Local	+2 Remote	18	Low	Low	Low
	- Emergency situations such as fire, explosion, and collapse of structure and malfunction of heavy vehicles during construction phase.	-All machine and heavy vehicles are operated by trained operatorNo on-site fuels storages.	+5 Very High	+1 Tempo rary	+2 Local	+2 Remote	16	Low	Low	Low

# Green EHSS Consultancy

## GIANT 999 STEEL MANUFACTURING FACTORY

Community Health and Safety	- Increase vehicular movements associated with construction activities	<ul><li>-All truck drivers are trained and licensed.</li><li>- Construction trucks movements will be reduced during peak hours.</li></ul>	+4 High	+1 Tempo rary	+2 Local	+3 Occatio nally	21	Low	Low	Low
		Soc	ial Factor							
Cultural heritage	- There are no historical and cultural monuments located nearby the project site.	The plant is located in the designated industrial zones.	-	-		-	-	-	-	NA
-In voluntary Resettlement	- No physical resettlement is necessary.	- The plant is located in the designated industrial zones.	-	-		-	-	-	1	NA
-Social integration	-Potential for conflict between people of different	The plant is located in the designated industrial zones.	-	-		-	-	-	-	NA

## GIANT 999 STEEL MANUFACTURING FACTORY



	backgrounds and cultural beliefs.	- The plant complies with laws and relevant internal guidelines.								
-Ethnic minorities and indigenous peoples	- There are no indigenous people in the project area.	-The plant is located in the designated industrial zones.	-	-		-	-	-	-	NA
Risks for infectious disease such as AIDS/HIV	-Influx of people may cause negative impact on local people.	- Construction warkers are provided health knowledge	+4 High	+4 Long term	+3 Region al	+2 Remote	22	+Low	+Low	+Low
		Communi	ty Develo <sub>l</sub>	pment						
Employment	Positive impact. It is expected to accept and to be employed in the project's activities with high hopes for improvement in neighborhood	-Employment creation to the locals	+3 Modera te	+1 Tempo rary	+2 Local	x5 Definite	30	+ Moderate	+ Moderate	+ Moderate



### 7.3 IMPACT ASSESSMENT FOR OPERATION PHASE

All impacts for operation phase of the Giant 999 Steel Manufacturing Factory are assessed and tabulated in the Table 7.7 below.

Table 7.7 Environmental Impact Assessment Matrix for Operation

			Significance of potential impacts							act
Potential	D : .		e			e	evel	tion	Signif	icant
Impact	Project Activities	Existing Control	Magnitude	Duration	Extent	Occurrence	Significant L	Score Evaluation	Before Mitigation	After Mitigation
		Wa	stewater							
Storm Water	-Surface water quality impact by discharge of water	-proper drainage system is provided -Drained water is collected and metal scraps are removed and reused	+3 Moder ate	+4 Long term	+2 Short	x3 Occation ally	27	Low	Low	Low



-Sanitation Waste Water	- Wastewater generated from workers and staff	- Sludge waste from septic tanks is removed periodically -Sewage system is securely constructed.	+3 Moder ate	+2 Short term	+1 Site	x2 Remote	12	Low	Low	Low
- Wastewater generated by oil and grease leakage	-Oil and grease leakage from machines, vehicles and generator	<ul> <li>- Process areas are provided with the secured concrete floor</li> <li>-Regularly checking</li> <li>- Providing spill tray</li> </ul>	+4 High	+4 Long term	+1 Site	x2 Remote	18	Low	Low	Low
		Air	Pollution							
-Exhaust gases	-Exhaust gases from diesel generator and vehicles movements	- The factory uses the generator only when the power supply outage -The generator is equipped with emission control device -Vehicle maintenance	+4 High	+4 Long term	+2 Local	x2 Remote	20	Low	Low	Low

# Green EHSS Consultancy

## GIANT 999 STEEL MANUFACTURING **FACTORY**

- Dust emissions	- Emission of particulate matters from the furnace and from operation	-Regular maintenance and inspection of furnace  - Effective dust control system is provided at the furnace  -Regular water spraying at the unpaved roads  - Metal scrap materials must be cleaned up daily or often enough to prevent them from collecting on floors, tabletops, in aisle ways, or other area.	+4 High	+4 Long term	+2 Local	x2 Remote	27	Low	Low	Low
		Noice a	nd Vibrat	ion						
Noise exposure	-Vehicle movement, ventilators, pumps, motors, compressors processed machines	<ul> <li>Regular maintenance of vehicle, ventilator and generator.</li> <li>Oily and regular maintenance of the machines to reduce noise emission.</li> </ul>	+4 High	+4 Long term	+1 Site	x3 Occasio nal	27	Low	Low	Low



	-Using diesel generators	- Built noise barriers for diesel generator or install a silencer at the generator -Provide hearing protector like ear plug to to the workers who involve the noisy operation (generator man) or work near to the noise sources.	+4 High	+2 Short	+1 Site	x2 Remote	14	Low	Low	Low
		7	Vaste							
Disposal of Solid Wastes	- Solid Waste from production activities	- The factory applies reducing, reusing and recycling management for factory's solid wasteMetal scraps are reused or sold	+3 Moder ate	+4 Long term	+2 Local	X2 Remote	18	Low	Low	Low
Disposal of Hazardous Wastes	- Diesel, machine oil, lubricant -Batteries	<ul> <li>- All hazardous wastes are disposed in accordance with Township and Zone Committee guideline.</li> <li>-Used oil are sold to recycler.</li> </ul>	+4 High	+4 Long term	+2 Local	x2 Remote	20	Low	Low	Low

## GIANT 999 STEEL MANUFACTURING FACTORY



		Soil	Quality							
Soil Contaminatio n	- Solid wastes from the processing activities - Domestic wastewater	- The factory applies 3R management for factory's solid waste.  -Most of the process wastes are recycled in manufacturing activities and sold the fly ash to collector  - Sludge waste from septic tanks is removed by third party contractor periodically.	+3 Moder ate	+4 Long term	+2 Local	x2 Remote	18	Low	Low	Low
		Н	azards							
Occupational Health and Safety (Accidents)	Minor to serious injuries due to workplace hazards	- Workers are trained to use and operated machine, equipment and devices safely	+4 High	+4 Long term	+1 Site	x2 Remote	18	Low	Low	Low



- Provide appropriate safety devices and barriers and control measures at high risk operations				
-Develop Hazardous indentification and risk assessments for high risk activities and communicate the documents with workers -Provide OHS training to the wokers - Display warning signage at high risk areas -Regular inspection and supervison by OHS personnel and supervisors -Workers are provided				
sufficient PPE.				



Fire Hazards	- Emergency situations	<ul> <li>- Emergency Response team is organized.</li> <li>- Fire fighting equipment are provided.</li> <li>- Workers are provided with basic fire fighting</li> </ul>	+4 High	+2 Short	+2 Local	x2 Remote	16	Low	Low	Low
		<ul> <li>knowledge.</li> <li>Fire drill is conducted once per year.</li> <li>An assembly area is assigned in the factory premise.</li> <li>"Fire Prevention Plan" has developed (section 9.7.3).</li> </ul>								
	-Fire hazards posed by storage of diesel	-Sufficient firefighting equipment is provided within the factory premises -Workers are provided fundamental firefighting training.								



999	STEEL MANUF	1
	<b>FACTORY</b>	

Emergency	Natural disaster, explosion, and collapse of structure and malfunction of processing machine	<ul> <li>- Emergency team is formed to tackle the potential emergency situation.</li> <li>- The machines and equipment are regularly maintained and inspected.</li> <li>- Trained operators are assigned at the processing areas.</li> <li>- Operators watch and inspect regularly the processed machines.</li> </ul>	+4 High	+2 Short	+1 Site	x2 Remote	14	Low	Low	Low
Community Health and Safety	-Traffic accident by delivery activities.	<ul><li>-All truck drivers are trained and licensed.</li><li>- Fuel and machine oil are properly stored.</li></ul>	+4 High	+4 Long term	+2 Local	x2 Remote	20	Low	Low	Low
		Soci	al Factor							
Cultural heritage	- There are no historical and cultural monuments	The plant is located in the designated industrial zones.	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil



## **GIANT 999 STEEL MANUFACTURING FACTORY**

	located nearby the project site.									
-In voluntary Resettlement	- No physical resettlement is necessary.	- The plant is located in the designated industrial zones.	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
-Social integration	-Potential for conflict between people of different backgrounds and cultural beliefs.	<ul><li> The plant is located in the designated industrial zones.</li><li>- The plant complies with laws and relevant internal guidelines.</li></ul>	+4 High	+4 Long term	+2 Local	x2 Remote	20	Low	Low	Low
-Ethnic minorities and indigenous peoples	- There are no indigenous people in the project area.	-The plant is located in the designated industrial zones.	+4 High	+4 Long term	+3 Regio nal	x1 very unlikely	11	Low	Low	Low



Population Influx	-Permitting employees for factory operation -Influx of people may cause negative impact on health condition of local peopleRisks for infectious disease such as AIDS/HIV	- Maximum possible involvement of local labour force in view of qualifying requirements Providing own health care facilities - Additional knowledge in waste management, material handling, and general application of environmental, health and social precautionary measuresThis impact for the operation phase is considered to be low with mitigation by knowledge and health care support.	+4 High	+4 Long term	+2 Local	x3 Occation ally	30	* Moderate	Moderate	Low



Community Development											
Employment	Positive impact for operation phase. It is expected to accept and to be employed in the project's activities with high hopes for improvement in neighborhood	-Employment creation to the locals (more than 1500 factory workers to be recruited from the local areas) - Employment creation would bring higher living standard and education status.	+4 High	+4 Long term	+2 Local	x4 Frequen tly	40	+ Moderate	+ Moderate	+ Moderate	
Corporate Social Responsibilit y	-CSR activities	-CSR budget is allotted as 2% of the annual profit.	+2 Minor	+4 Long term	+2 Local	x3 Occation ally	30	+ Moderate	+ Moderate	+ Moderate	

<sup>\*</sup>Current workforce for local people is about 50. Impact assessment at the table is based on proposed workforce of 1500 for the project business become grow and expand.

202



#### 7.4 IMPACT ASSESSMENT FOR DECOMMISSION PHASE

All impacts for decommission phase of the Giant 999 Steel Manufacturing Factory are assessed and tabulated in the Table 7.8 below.

Table 7.8 Environmental Impact Assessment Matrix for Decommission

Potential Impact	Project Activities	Existing Control	Significance of potential impacts						Impact	
			Je	Duration	Extent	Occurrence	Significant Level	Score Evaluation	Significant	
			Magnitude						Before Mitigation	After Mitigation
	Wastewater									
Sedimentatio n/ siltation of drainage or waterway	- Unconfined stockpiles of soil and other materials	- Avoiding earth work in rainy season	+3 Moder ate	+2 Short	+2 Local	x2 Remot e	14	Low	Low	Low



#### I 999 STEEL MANUF FACTORY

-Sanitation Wastewater	- Wastewater from temporary facilities	- Suitable facilities or portable toilets	+4 High	+2 Short	+1 Site	x2 Remot e	14	Low	Low	Low
		Air l	Pollution							
- Dust emissions	- Transportation of materials, transfer of heavy machinery -Demolition activities	- Water sprinkling should be carried in case of extreme dry and windy condition prevails,	+4 High	+1 Tempo rary	+2 Local	x2 Remot e	14	Low	Low	Low
		Noice a	nd Vibrat	ion						
Noise exposure	- Demolition activities	<ul> <li>Noise barriers should be built</li> <li>Decommissioning activities are during daytime.</li> <li>Provide hearing protector like ear plug to the workers with high noise exposure.</li> </ul>	+3 Moder ate	+1 Tempo rary	+2 Local	x2 Remot e	12	Low	Low	Low

## GIANT 999 STEEL MANUFACTURING FACTORY



Waste										
Disposal of Solid Wastes	- Solid Waste demolition activities.	- All unused or surplus building materials can be sold to other who needs it.	+3 Moder ate	+1 Tempo rary	+2 Local	x2 Remot e	12	Low	Low	Low
	Hazards									
Occupational Health and Safety (Accident)	<ul> <li>- Working at height</li> <li>- Ergonomic</li> <li>- High noise exposure</li> <li>- Electric and physical hazards</li> </ul>	- Site fencing and safety signatures should be done in this phase -Workers are provided sufficient PPETrained and experienced workers are employed	+4 High	+1 Tempo rary	+2 Local	x2 Remot e	14	Low	Low	Low



#### 7.5 SUMMARY OF IMPACT

According to the environmental impact assessments for the construction phase, operation phase and demolition phase, it is unlikely to have significant impacts on surface and ground waterair quality, ambient air quality, the environmental and occupational noise level and the soil quality caused by solid and liquid waste accumulations. During the operation phase, water pollution, air pollution, noise pollution and soil pollution are evaluated as insignificant and low due to the provision of effective control and mitigation measures. The project owner has provided best available technology for potential impact such as de-dust control measures for the dust emission. The moderate impacts can be reduced to low level with the effective mitigation measures. In addition, the project site is situated in the designated industrial zone and is far from the residential areas.

Thereforre, it can be assumed that the potential environmental and social impacts associated with the manufacturing activities of 999 Steel Mill are controllable with proper measures.

## 7.6 ENVIRONMENTAL IMPACT AND MITIGATION MEASURES FOR CONSTRUCTION PHASE

#### 7.6.1 WATER ENVIRONMENT

#### a) Potential Impacts

Surface and ground water contamination may result from various activities during construction phase. These activities can include

- Wastewater generated from temporary facilities
- Oil and grease leakage from machines and vehicles used for transportation of construction materials and machinery
- Potential leakage of oil, greases, fuels and paints can percolate through the soil and can cause soil contamination and eventually ground water pollution.

#### b) Mitigation Measures

- Provide proper drainage system and treated the drained water before discharge
- Storage area is provided with secured concrete floor and spill tray and spill kits



Ensure not to overflow of wastewater from the temporary facilities at the site

#### 7.6.2 AIR EMISSIONS

#### a) Potential Impacts

 During construction phase, transportation of construction materials, transfer of heavy machinery and construction activities may give rise to dust emissions.

#### b) Mitigation Measures

- Exposed sand and earth piles are covered
- Unpaved roads are watered regularly during dry season

#### 7.6.3 ENVIRONMENTAL NOISE IMPACT

#### a) Potential Impacts

- Operation of heavy machinery such as excavators and loaders and trucks
- Construction activities and using diesel generators will cause high noise level

#### b) Mitigation Measures

- Occupational preventive measures should be applied in this phase.
- Construction activities are implemented during day time and avoid later than 8 p.m.
- Provision of silence or noise barriers for the generator.
- Working employing in high noise area should be worked on shifts and hearing protective wear such as earplugs, earmuffs, etc. should be provided.
- Impose the speed limit within and around the site to reduce the noise levels from the vehicle movements

#### 7.6.4 SOLID WASTE

#### a) Potential Impacts

- None-hazardous solid waste generated at construction site includes excess fill
  materials from grading and excavation activities, scrap wood and small
  concrete spills.
- Other non-hazardous solid waste includes office and pantry wastes
- Hazardous solid waste like spillage eof paints, thinner, diseal, oily rags, used oil filters, and used oils,



#### b) Mitigation Measures

- Provide adequate size bins with label e.g. metal waste, general waste, hazardous or toxic waste.
- Separate recyclable materials from waste and keep covered.
- Dispose wastes regularly and not to allow wastes overflow from bins or accumulate on-site.
- Collect concrete and wash water in concrete washout facilities.
- Choose smaller, covered containers and more frequent collection.
- Conduct visual inspections of dumpsters and recycling bins, removing contaminants and keeping containers covered.

## 7.7 ENVIRONMENTAL IMPACT AND MITIGATION MEASURES FOR OPERATION PHASE

#### 7.7.1 WASTEWATER

#### 7.7.1.1 POTENTIAL IMPACTS

Potential surface water and ground water contamination may result from various activities during operation phase. These activities can include following:

- Runoff water from the plant during heavy rain
- Wastewater generated from sewer system and cleaning activities at kitchen/pantry
- Oil and grease leakage from machines, vehicles and oil storage tanks

#### > Runoff water from the plant during heavy rain

Rain / storm water flow movement from the factory can lead the storm water runoff to nearby areas during heavy rain. Flooding and stagnant water (which could lead to mosquito breeding and silted water) discharge into public water course. Debris in the runoff water can block waterways that may lead to flooding in and around the plant.

## > Wastewater generated from sewer system and cleaning activities at kitchen/pantry

Domestic waste water from sanitation and kitchen/pantry cleaning can release through septic tank and drainage channel. They can pollute the water environment.



#### > Oil and grease leakage from machines, vehicles and oil storage tanks

Oil and grease leakage from machines, vehicles and oil storage tanks may result water pollution.

Thay may release to the water body through the factory drainage system.

#### 7.7.1.2 MITIGATION MEASURES FOR WASTE WATER

#### > Runoff water from the plant during heavy rain

- The proper drainage system is provided.
- Regular removal of debris and sediments in the drain is done.

## > Wastewater Generated from sewer system and cleaning activities at kitchen/pantry

- Domestic wastewater from the toilets is disposed to the concerte septic tanks located in the factory compound and breakup naturally.
- Sludge waste from septic tanks is discharge periodically by contacting Water and Sanitation Department.
- Washing and cleaning waste water will be disposed to the septic tank via pipeline.

#### > Oil and Grease Leakage from Machines, Vehicles and Oil Storage Tanks

- The maintenance area is provided with concrete floor to avoid the surface water contamination by oil/fuel leakage from vehicles and diesel generator.
- Staffs are clean and check regularly for surface water contamination by oil/fuel leakage from vehicles and diesel generator.
- Leakage and spillage are immediate clean.

#### > Drainage System

- Proper drainage system is provided.
- The drainage systems are provided with concrete flooring to prevent the impacts on water quality.
- Conduct regular inspection at the drainage system.
- Monitor water quality before discharge it to the public water course.
- Leakage and spills of engine oils and greases from the maintenance activities must be cleaned immediately.





Figure 7.1 Internal Drainage of the Factory



Figure 7.2 Photo Records for Sludge Waste Removal from Septic Tanks

#### 7.7.2 EMISSION TO AIR

#### 7.7.2.1 POTENTIAL IMPACTS

Various identified sources, in production activities that can cause potential impacts on air quality are emissions from:

- PM and Ashes emission from the furnace
- Emissions from vehicular movement
- Generator

#### > PM and Ashes emission from the furnace

Molding of irons by using furnace generates PM particles and ashes.



#### > Emissions from vehicular movement

The factory uses the vehicles for transportation of raw materials as well as finished goods and for staff ferry.

#### Generator

Burning diesel of other fuels creates exhaust gasses. Diesel generators mainly produce carbon dioxide (CO2), nitrogen oxide (NOx), and particulate matter.

#### 7.7.2.2 MITIGATION MEASURES FOR EMISSIONS TO AIR

#### > Particulate Matter and Ashes emission from the furnace

- The factory has installed a new furnace with effective ash control system to control ashes and PM emission.
- Metal scraps will be recollected and reused daily to reduce small particiles dispersions.
- The factory planted trees and vegetation along the roadside to mitigate the air emission.

#### > Emissions from vehicular movement

#### **Exhaust gas emission**

- All vehicles are regularly inspected and maintained to reduce the gas emission.
- The factory applies systematic management for vehicles use (eg. Reducing the vehicles use, collaborated using on same route of vehicles).
- Using the high grade of diesel fuel quality for reducing SO<sub>2</sub> emission.

#### **≻** Generator

- Using the high grade of diesel fuel quality for reducing SO<sub>2</sub> emission.
- Regular checking and changing of lubricating oil and engine oil to prolong engine life and reduce CO emission.
- Generators are regularly inspected and maintained to reduce the particulate matter emission.



#### 7.7.3 EXISTING DUST COLLECTION (DE-DUSTING) SYSTEMS

The furnaces release large amount of light weighted particles. Released dust particles can produce hazardous air pollution. Air pollution and their treatments are one of the major issues. Thus, the factory has already installed the Iron Powder Fume Dust Collecting system /https://www.alibaba.com/product-detail/Iron-Powder-Bag-Type-Fume-Dust 60804611390.html?spm=a2700.7724857.normalList.35.14ed799foTLWSu.







Figure 7.3 Dust Collecting system and Building



#### 7.7.4 SOLID WASTE

#### 7.7.4.1 POTENTIAL IMPACTS

#### **Domestic Waste**

Domestic wastes are organic and inorganic wastes from kitchen/pantry and office.

#### Manufacturing Waste

Manufacturing wastes are mainly metal scraps released from the processes.

#### 7.7.4.2 MITIGATION MEASURE FOR SOLID WASTE

#### **Domestic Waste**

- Provision of adequate waste bins to avoid loss to the floor inside the factory as well as outside the building.
- Domestic wastes like plastic bags, plastic water bottles and papers are separated and collected by recycler.
- Some organic wastes are collected by workers for animal feed.
- Non-reusable domestic wastes will be collected by outside waste collector or relevant municipal department.



Figure 7.4 Photo of Factory Garbage Area and Removing Waste



#### **Process Waste**

Giant 999 Steel Manufacturing Factory establishs and implements waste management plan.




Figure 7.5 Process Waste Flow Chart

#### Reduce:

The factory pays careful attention during planning to reduce rejected parts.

#### Reuse:

Some reject iron scraps are reused.

#### Recycle:

- Fly ash collected by de-dusting system are sold to the waste collectors for recycle purpose.
- Plastic, paper, cartoon boxes and metal waste are also sold out to the local merchants from the company for recycle purpose.





Photos of Fly Ash Solid Waste (သံချော်ပြာ) Sold to Collector




Figure 7.6 Photos of Process Waste (ചിയ്യര്ക്ക) and, Broken and Reject Waste (ചെസ്സില ചാധി) to be Recycled

#### 7.7.5 NOISE EXPOSURE

#### 7.7.5.1 POTENTIAL IMPACTS

In terms of environmental noise pollution, the factory is located in the industrial zone as well as far from residential area. No environmental noise is created from this small sacle production.

However, use of machines and noisy processes from the production can emit high level of noise at the operation areas. The potential noise impact is considered as occupational health hazard for workers working near to the noisy machines or processes.

Following activities would result high noise exposure.

• Operation of machines and equipment as well as ventilators



- Operation of generator
- Vehicle / traffic movement

#### 7.7.5.2 MITIGATION MEASURE FOR NOISE EXPOSURE

- Proper maintenance of generator and install sound barrier for generator.
- Vehicles used in delivery are regularly inspected and maintained the engine and exhaust system to minimize the noise exposure to public area.
- Regular maintenance of the machines to reduce noise emission.
- Employees working in high noise generating areas are provided with proper hearing protecting equipment such as ear muffs and ear plugs

#### 7.7.6 HAZARDOUS MATERIAL/WASTE

#### 7.7.6.1 POTENTIAL IMPACTS

Hazardous materials /wastes generated from the production activities are as follow:

- Grease
- Machine oil
- Fuel leakage
- Silicon
- Manganese

#### Diesel

Diesel is used for motor vehicles and generator.

Hazard statements: Flammable liquid and vapour

May be fatal if swallowed and enters airways

Causes skin irritation Harmful if inhaled

May cause dowsiness or dissiness

Suspected of causing cancer

May cause damage to organs (liver, thymus, bone)

through prolonged or repeated exposure.

Flash Point : 125°F

➤ Machine oil, lubricating oil are used for generators and machines.



Hazard statements: liquid (only liquid)

May cause eye and skin irritation. Avoid contact with

eyes, skin and clothing.

Wash thoroughly after handling

Respiratory tract irritation and possible long-term effects.

#### > Silicon

Silicon is used in melting process as additive to iron foundry products.

Hazard statements : Sieve fractions, fine.

In contact with water releases flammable gas. Toxic if

swallowed. Toxic if inhaled.

Wash skin with water and/or a mild detergent. Rinse eyes with water/saline solution. Remove the person affected from dust-exposed area. See a physician on persistent

feeling of discomfort.

Melting Point (°C): 1240 -1350

#### > Manganese

Cast iron products are alloyed with small quantities of manganese.

Hazard statements: Manganese metal

Product may cause irritation to the eyes, skin

and respiratory system.

Prolonged skin contact may cause mild irritation. Eye Contact: Rinse opened eye for at least 15 minutes under running water. Assure adequate flushing by

separating the eyelids with fingers.

Swallowing: If conscious, rinse mouth out with water and

seek medical attention.

Melting Point: Approx 1244 °C

7.7.6.2 MITIGATION MEASURE FOR HAZARDOUS MATERIAL/WASTE

**Hazardous solid waste** includes small amount of machinery maintenance materials, such as oily rags, used oil, damaged tube light and bulb, batteries, machine oil containers.



- Spill tray is kept near the fuel filling area.
- Warning signage are provided at the chemical and fuel storage areas.
- Fire Extinguishers shall be provided near to the generator room.
- Spent oils, batteries, electric tubes and other hazardous waste are contained to prevent it from blowing away and from leaching into surface or groundwater.
- Keeping hazardous waste container with clearly marked "Hazardous Waste".
- Workers who handle hazardous wastes are trained to avoid personal injury, prevent spills and releases, and to make sure these wastes are disposed of safely.

Giant 999 Steel Manufacturing Factory uses silicon and magnet as additive to iron foundry products.

## Hazardous Material like Silicon, Magnet

- Excessive purchase and receipt.
  - o Avoid purchase of excessive quantity.
  - Supervisor checks right type and quantity receipt.
- Loading and unloading of raw chemicals
  - Storage, handling and mixing areas are provided with concrete floor.

#### Storage

- o Store in the proper container/bag in the storage room.
- o Marked prominently as "Chemical Storage Area".
- Obtaining material safety data sheet (MSDS)
- o Regularly check and maintain the suitable temperature of the storage area.
- o Provide fire extinguisher at storage area.
- Display warning signage at storage area.

#### Handling, Mixing

- Providing information and training to employees. Workers who handle hazardous wastes are trained to avoid personal injury, prevent spills and releases, and to make sure these wastes are disposed of safely.
- Proper PPE such as mask, goggle, apron and glove are provided for employees.
- o Display warning signage and MSDS at the working area.





Figure 7.7 Hazardous Storage Area with MSDS, Prevent Unauthorized Individuals from Entering and Danger Sign.



Figure 7.8 Diesel Storage Tank Post with MSDS and No Smoking Sign



Figure 7.9 Lubricating Oil Storage Post with MSDS, Safety Signs and Extinguishers



### కేంట్ MSDS

၁ အချက် - ဓါတုပစ္စည်းအကျဉ်းချပ် မြန်မာအခေါ် အဝေါ် ဒီဇယ်ဆီ အင်္ဂလိပ်အခေါ် အဝေါ် Diesel fuel အဓိပ္ပါယ်တူ အင်္ဂလိပ်စာလုံးများ Diesel Fuel Diesel Oil ၂ အချက် - ပါဝင်သည့်အရာများ

အန္တာရာယ်ရှိ ဓါတုလျှပ်စစ်ပစ္စည်း သံလိုက်စွမ်းအား ပါဝင်မှုအနည်းငယ်

Cas No: 68334-30-5

၃ အချက် - အန္တာရာယ်ရှိနိုင်သည့် အကြောင်းအရင်း

ကျန်းမာရေးထိခိုက်နိုင်ခြင်း

အဓိကအားဖြင့် အရေပြားမှ တိုက်ရိုက်ထိတွေပြီး ဒီဇယ်အား ဆုပ်ယူနိုင်သောကြောင့် ကျောက်ကပ်

အသည်းအသန် ဖြစ်၍ ပျက်စီးသည်။

ထို့ အပြင် ဒီဇယ်ကြောင့် အရေပြားရောဂါ၊ အဆီအကျိတ်ပေါက်ခြင်း ဖြစ်နိုင်သည်။ ဓါတ်ငွေ့ နှင့် အရည်ကို ဖိအားပေးသွင်း ထားသောဘူး စသည်မှပန်းထွက်လာသော အမှုန်အမွှားများကို ရှုသွင်းမိပါက အသည်းရောင်အသားဝါ ဖြစ်တတ်သည်။ မိခင်ဗိုက်အချင်းမှ တစ်ဆင့် သန္ဓေသား၏ သွေးထဲသို့ ဝင်ရောက်နိုင်သည်။ ထို့ပြင်လည်း ဒီဇယ်အငွေ့ အသက်သည် လူနှင့်ထိတွေ့ ခဲ့ပါက မျက်လုံး၊ နှာခေါင်း စူးခြင်းနှင့် ခေါင်းမူး ခေါင်း ကိုက်ခြင်း ဖြစ်စာတ်ပါသည်။ ပတ်ဝန်းကျင်ထိခိုက်မှ

သဘာဝပတ်ဝန်းကျင်ကို အန္တာရာယ်ဖြစ်စေသည်၊ ရေနှင့်လေထုသည် ညစ်ညမ်းမှုကို ဖြစ်ပေါ် စေသည်။ ပေါက်ကွဲမှုဘေးအန္တာရာယ်

လောင်ကျွမ်း ပေါက်ကွဲလွယ်သော ပစ္စည်းဖြစ်သည်။ စူးရှပြင်းထန်မှု ရှိသည်။

၄ အချက် - အရေးပေါ် ကယ်ဆယ်မှု

အရေပြားနှင့်ထိသောအခါ

ဒီဇယ်အစွန်းအထင်း ထိမိသော အထည်အား ချက်ခြင်းချွတ်ပစ်ရမည်၊ ဆပ်ပြာရည် (သို့မဟုတ်) ရေသန့်ဖြင့် ဒီဇယ်ထိတွေ့ မိသောအရေပြားအား စင်ကြယ်စွာဆေးကြောပါ။ လိုအပ်လျှင် ဆရာဝန်နှင့် ပြပါ။ မျက်လုံးထဲသို့ဝင်သောအခါ

ဒီဇယ်ဝင်သော မျက်လုံး၏ မျက်ခွံအား အပေါ် သို့ ဆွဲတင်ပါ။ ရေသန့် (သို့ မဟုတ်) ဓာတ်ဆားနှင့် လောင်းဆေးပေးပါရန်။ လိုအပ်ပါက ဆရာဝန်နှင့်ပြပါ။

နှာခေါင်းထဲသို့ ရှုသွင်းမိသောအခါ

လေကောင်းလေသန့် ရှိရာသို့ လျှင်မြန်စွာသွားပါ။ အသက်ရှူလမ်းကြောင်း မပိတ်မိစေရန် နေထိုင်ပါ။



## အန္တရာယ်ကင်းရှင်းမှု အဆင့်မှတ်တမ်း/ MSDS

### **Ferrosilicon**

စာမျက်နှာ 1/5

### ၁. ထုတ်ကုန်ပစ္စည်းအမျိုးအမည် နှင့် ပေးသွင်းသူ၏ အချက်အလက်ဖော်ပြချက်

ထုတ်ကုန်အမည် Ferrosilicon ဓာတုမိသားစု သတ္တု၊ အလွိုင်း

အဓိပ္ပါယ်တူ/ကုန်သွယ်မှုအမည်များ Ferro Silicon၊ Fesi (Fesi %75)

UN Number: 1408 CAS နံပါတ်: 8049-17-0

ထုတ်ကုန်အသုံးပြုမှု သံမဏိအတွက်၊ သံမဏိနှင့် သံရည်ကျိုပစ္စည်းများအတွက်

ပေါင်းထည့်ခြင်း

လိပ်စာ/ဖုန်းနံပါတ် Iran Ferroalloy Industries (IFI), P.O. အကွက် ၁၅၁၇၈/၃၁၆၉

φδ: (+98 21) 88 77 93 30 – 88 78 70 33-88 77 42 71, Fax:

(+98 21) 88 88 20 43, www.Iranferroalloys.com

ဆက်သွယ်ရန်ပုဂ္ဂိုလ် Alaleh Shahani၊ အီးမေးလ်- shahani@iranferroallovs.com

#### ၂. ပါဝင်သောပစ္စည်းများ

<u> ခြ</u> ပ်စင်	သင်္ကေတ	CAS နံပါတ်	အလေးချိန် %
Silicon	Si	7440-21-3	72-80
ကာဗွန်	С	7440-44-0	<0.20
ဆာလဖာ	S	7704-34-9	<0.04
Phosphorus	Р	7723-14-0	<0.05
အလူမီနီယမ်	အယ်လ်	7429-90-5	0-3
Calcium	Ca	7440-70-2	<0.08
မန်းဂနိစ်	Mn	7439-96-5	<0.50
Chromium	Cr	7440-47-3	<0.30
တိုက်တေနီယမ်	Ti	7440-32-6	<0.20
Iron	Fe	7439-89-6	လက်ကျန်

## ၃. ဘေးအန္တရာယ်ဖော်ပြချက်

အမျိုးအစားခွဲခြားခြင်း

ရုပ်ပိုင်းဆိုင်ရာအန္တရာယ် - ရေနှင့်ထိတွေ့သည့်အရာများသည် မီးလောင်လွယ်သော ဓာတ်ငွေ့

အမျိုးအစား 3 ကိုထုတ်လွှတ်သည်။ ကျန်းမာရေးအန္တရာယ် - အဆိပ်သင့်မှု အမျိုးအစား 3 (ပါးစပ်၊ ရှူရှိုက်မိခြင်း)

ကျနးမာရေးအန္တရာယ Label Elements သင်္ကေတ





#### MATERIAL SAFETY DATA SHEET

အမည် Trade Name : Engine Oil စက်ဆီ

အန္တရာယ်သင့်စေသည့်အကြောင်း Hazard Rating: ကျမ်းမာရေးနှင့် မသင့်လျော် Health

အမျိုးအစား Form : အရည် Liquid

ထင်ရှားသည့် အသွင်အပြင်/အရောင် Appearance/Colour: အဝါနုရောင် Light Yellow

အနံ Odor: အနံမရှိ Odorless

မီးငြိမ်းသတ်ရမည့် ပစ္စည်း Extinguishing Media: မီးသတ်ဆေးဗူး Dry chemical

- အရည်ပြားထိခိုက်နိုင်မှု Skin contact: အရည်ပြားနှင့် အချိန်ကြာကြာ ထိတွေ့မိပါက ပူ လောင်ယားယ့နိုင်ပါသည်။ Prolonged or repeated contact can cause moderate irritation, defatting, and dermatitis.
- မျက်လုံးထဲဝင်ပါက Eye contact: မျက်လုံးယားယံခြင်း၊ ပူလောင်ခြင်း၊ နီခြင်း၊ အမြင်အာရုံ မှုန်ဝါးခြင်း can cause severe irritation, redness, tearing, and blurred vision.
- ခန္တာကိုယ်အတွင်းဝင်ပါက Ingestion : အစာအိမ်နှင့် အူလမ်းကြောင်းထိခိုက်နိုင်ခြင်း ဖြစ်ပွားနိုင်ပါသည်။ can cause gastrointestinal irritation, nausea, vomiting, and the lungs can cause chemical pneumonitis which can be fatal.
- အရေးပေါ်နှင့် ရှေးဦးသူနာပြုဆိုင်ရာ လုပ်ထုံးလုပ်နည်းများ Emergency and first aid procedures: မျက်လုံးထဲဝင်ပါက ၁၅ မိနစ်ကြာသည်အထိ ရေနှင့် ဆက်တိုက် ဖြန်း ပေးရမည်။ eyes flush thoroughly with running water for 15 minutes, including under eyelids. Get medical attention.
- အရည်ပြားထိခိုက်မိပါက Skin: အရည်ပြားထိခိုက်မိပါက ရေဖြင့်ဆေးပါ၊ ဆေးကုသမှုခံယူပါ။ promptly remove contaminated clothing and wash affected areas thoroughly with soap and water. If irritation occurs get medical attention. Wash contaminated clothing thoroughly before re-use.
- ရှုရှိုက်မိပါက Inhalation: အနံ့ရှိသောနေရာမှ ချက်ခြင်းဖယ်ရှားပြီး လေဝင်လေထွက် ကောင်းမွန်သော နေရာသို့ ခေါ်ဆောင်၍ နွေးထွေးအောင်ထားပြီးဆေးကုသမှုခံယူပါ။

Figure 7.10 Samples of Material Safety Data Sheet for Diesel, Silicon and Lubricating Oil



#### 7.7.7 OCCUPATIONAL HAZARD

#### 7.7.7.1 POTENTIAL IMPACTS

Primary OHS issues related to Giant 999 Steel Manufacturing Factory are:

- Physical hazards
- Ergonomic Hazards
- Exposure to chemicals
- Exposure to heat
- Exposure to noise and vibration
- Fire Hazards
- Traffic Movement

#### 7.7.7.2 MITIGATION MEASURE FOR OCCUPATIONAL HAZARDOUS

As with any manufacturing facility, worker safety should be an important consideration. A safe workplace is important to the factory and the employees.

Giant 999 Steel Manufacturing Factory has established the **Environmental Management Team**, and Emergency Response Team. These teams will identify and evaluate health and safety trends, investigate accidents and other health and safety events at the factory, and use health and safety resources within the factory. They will review accidents or event reports to make sure actions are taken to correct hazards and to avoid a similar event in the future.

Factroy Manager oversees and ensure the production processes to control or mitigate the potential occupational health and safety hazards and associated risks. The relevant Managers and Supervisors closely manage the workers to perform the assigned tasks safely and healthy.

Workers are trained to handle the machine and equipment properly. Occupational Health and Safety training were provided to all levels accordingly.

The factory management including the Factory Manager shall conduct regular environmental, health and safety inspections within the factory to maintain and improve environmental, health and safety performances.



#### a. Physical Hazards

The common risks for accidents in the factory are bodily injuries due to working at height, trips and falls caused by slippery floors, stairs, and elevated platforms, manual handling, lifting and carrying the heavy items, the incorrect use of equipment, contact with pinch point of machines, accidents involving delivery and manufacturing. Workers are provided with occupational health and safety training to understand the potential physical hazards. Risk Assessments are developed and communicated with workers to mitigate the hazards. Warning signage are provided accordingly.

#### b. Ergonomic Hazards

Lifting, carrying, and manual handling of heavy items and repetitive works can expose ergonomic hazards during manufacturing. Workers are provided with occupational health and safety training including ergonomic hazard. Risk Assessments are developed and communicated with workers to mitigate ergonomic hazards.

#### c. Exposure to chemicals

Workers are exposed to chemicals such as cement dusts during manufacturing activities. The factory use some chemicals that can cause chemical exposure to the staff and nearby people. Workers are provided with occupational health and safety training including chemical hazard. Risk Assessments are developed and communicated with workers to mitigate the associated hazards.

#### d. Exposure to heat

The exposures to heat occur during operation and maintenance of furnace and melting areas. Workers are provided with proper PPE and air supply during maintenances at the high heat areas. Warning signage are provided to prevent accidental touch and exposure of heat. The hot surfaces are shielded where workers' proximity and close contact.

#### e. Noise and Vibration

Noise may result from a variety of sources such as mills, crushing, grinding, exhaust fans, blowers and extractions of raw materials. The Plant provides enclosure rooms, noise barriers for noisy operations. Workers are provided with hearing protectors during working at the noisy areas.



#### f. Electrical Hazards

Use of faulty or damaged electrical devices and ground fault can create a serious risk to workers. Overhead wires can also be struck by overhead lifting machines or ladder.

Only trained electricians are allowed to operate, inspect and repair the electrical appliances and equipment. Workers are provided with proper PPE. Warning signage are provided at potential electrical hazard areas.

#### g. Fire Hazards

The factory has provided sufficient numbers of extinguishers throughout the factory's areas. Fire drill is conducted annually together with the personnel from township Fire Department.

#### h. Traffic Movement

Vehicular movements within the factory compound are controlled with warning signge, speed limits and supervision. Only trained and competent vehicle operators are employed.

မတော်တဆ ထိခိုက်မှုများအတွက် စက်ရုံတွင် first-aid box ဆေးပုံးထားရှိပေးပါသည်။ ဆေးဝါးများလည်း အစုံအလင် ထားရှိပေးပါသည်။ စက်ရုံဆေးဝါးနှင့် မရလောက်သော ဒဏ်ရာများရရှိပါက စက်ရုံ လမ်းထိပ်ရှိ ဆေးခန်းသို့ ပို့ဆောင်ပေးပါသည်။ ဆေးခန်း နှင့် မရပါက သက်ဆိုင်ရာ ဆေးခန်းမှ ညွှန်ကြားပေးသော ဆေးရုံသို့ ပို့ဆောင်ပေးမည် ဖြစ်ပါသည်။ အရေးပေါ် အခြေအနေ ဖြစ်ပွားလာပါက ကယ်ဆယ်ရေးနည်းလမ်းအား အောက်ပါတွင် ဖော်ပြထားပါသည်။

## In the event of Fire & Explosion (Fire Emergency Procedures)

#### a) If you discover a fire

- Activate the nearest fire alarm (or) shout loudly.
- Otherwise, he shall evacuate and alert all personnel in the area and notify the IC/ Dy IC/ Supervisor
- The person who discover can attempt to extinguish any incipient fire with the available firefighting equipment and without personal risk.

#### b) Fight the fire ONLY if:

- The fire department has been notified of the fire, and
- The fire is small and confined to its area of origin, and
- You have a way out and can fight the fire with your back to the exit, and



- You have the proper extinguisher, in good working order, and have been trained and know how to use it.
- If you are not sure of your ability or the fire extinguisher's capacity to contain the fire, leave the area.

#### c) If you hear a fire alarm:

- Evacuate the area, and close doors as you leave.
- Leave the building and move away from exits and out of the way of emergency operations.
- Assemble in an assigned area, outside the building.
- Supervisors and Coordinators should account for all workers in their area to determine that all personnel have evacuated.
- All workers should remain outside until given the signal or announcement that it is safe to re-enter.

#### d) Evacuation Routes:

- Learn at least two escape routes and emergency exits from your area.
- Learn to activate a fire alarm.
- Learn to recognize alarm sounds.
- Take an active part in fire evacuation drills.

#### e) Evacuation

- When the alarm sounds, all personnel not assigned to emergency duties will immediately proceed to the nearest SAFE exit. Leave the building, and move directly to the nearest assembly area.
- Do not stop to pick up personal items.
- All personnel should refrain from smoking during the evacuation.
- All personnel should be at least sixty meters (60mm) or two hundred feet (200 ft) away from the building.
- Be familiar with exit routes, assembly areas, and evacuation maps.
- Report to assembly area coordinator if evacuating from other than your normally assigned location, also report to assembly area coordinator if coworker is missing.
- Treat all alarms as if there is an emergency situation. Factory will evacuate for all alarms.

### f) Power Failure

• In the event of a power failure, remain in your work area. Wait for instruction from your coordinator, Supervisor, or shift leader.



• Stop and park all moving equipment immediately for the duration of the power failure.









Figure 7.11 Photos of Uniform, Mask, Glove, Caps and First-aid box for Employees



#### 7.7.8 EMERGENCY AND DISASTER SITUATION

#### 7.7.8.1 POTENTIAL IMPACTS

Myanmar is prone to various natural hazards that include earthquakes, floods, cyclones, droughts, fires, tsunamis, some of which have the potential to impact large numbers of people. During operation phase, chemical spill, machine failure, collapse of structure and malfunction of processing machine may occur in many factories.

# 7.7.8.2 MITIGATION MEASURE FOR EMERGENCY AND DISASTER SITUATION

For 999 factory, emergency situation such as fire is assessed, and the factory established "Emergency Preparedness and Response Plan".

The overall goal of the **ERP Plan** is to mitigate the impact of fire and disasters and save as many lives as possible from preventable causes.

Giant 999 Steel Manufacturing Factory has planned, designed and constructed with fixed firefighting installations systematically. Giant 999 Steel Manufacturing Factory has prepared an **Emergency Preparedness and Response Plan** in order to prevent consequences of natural disasters such as fire, floods and earthquakes and man-made errors (e.g. electricity shock, fire hazards).

**Emergency Preparedness and Response Plan** describes the requirements for planning and preparing to protect workers in the event of an emergency. Emergency and disaster response plan describes the requirements for planning and preparing to protect workers in the event of an emergency.

- Emergency Response team is organized.
- Fire fighting equipment are provided.
- Workers are provided with basic fire fighting knowledge.
- Fire drill is conducted once per year.
- An assembly area is assigned in the factory premise.
- "Fire Prevention Plan" has developed (section 9.7.3).
- Sufficient firefighting equipment is provided within the factory premises.
- Workers are provided fundamental firefighting training.
- Emergency team is formed to tackle the potential emergency situation.



- The machines and equipment are regularly maintained and inspected.
- Trained operators are assigned at the processing areas.
- Operators watch and inspect regularly the processed machines.

Project proponent commits to apply and implement the safety methods above mentioned and to provide the safety preventive measure such as first-aid box, fire extinguishers and PPE for employees.

#### 7.8 GUIDELINE AND STANDARD

Ministry of Natural Resources and Environmental Conservation - MONREC (former Ministry of Environmental Conservation and Forestry - MOECAF) issued National Environmental Quality (Emission) Guidelines, NEQEGs, in December 2015 according to the provision of Paragraph (42), Sub-paragraph (b) of the Environmental Conservation Law (2012).

Table 7.9 Wastewater, Storm Water Runoff, Effluent and Sanitary Discharges (General Application)<sup>3</sup>

Parameter	Unit	Guideline Value
5-day Biochemical Oxygen Demand	mg/l	50
Ammonia	mg/l	10
Arsenic	mg/l	0.1
Cadmium	mg/l	0.1
Chemical Oxygen Demand	mg/l	250
Chlorine (Total residual)	mg/l	0.2
Chromium (Hexavalent)	mg/l	0.1
Chromium (Total)	mg/l	0.5
Copper	mg/l	0.5
Cyanide (Free)	mg/l	0.1
Cyanide (Total)	mg/l	1
Fluoride	mg/l	20
Heavy Metals (Total)	mg/l	10
Iron	mg/l	3.5
Lead	mg/l	0.1
Mercury	mg/l	0.01
Nickel	mg/l	0.5
Oil and Grease	mg/l	10
рН	S.Uª	6~9
Phenols	mg/l	0.5



Selenium	mg/l	0.1
Silver	mg/l	0.5
Sulfide	mg/l	1
Temperature Increase	.C	<3b
Total Coliform Bacteria	100ml	400
Total Phosphorous	mg/l	2
Total Suspended Solids	mg/l	50
Zinc	mg/l	2

<sup>&</sup>lt;sup>a</sup> Standard Unit

**Table 7.10 Air Quality Standards** 

Parameter	Averaging Period	Guidelines Value μg/m³
Nitrogen Dioxide	1-year	400
	1-hour	200
Ozone	8-hours daily	100
	maximum	100
Particular matter PM <sub>10</sub> <sup>a</sup>	1-year	20
	24-hour	50
Particular matter PM <sub>2.5</sub> <sup>b</sup>	1-year	10
	24-hour	25
Sulphur Dioxide	1-hour	20
	10-minute	500

<sup>&</sup>lt;sup>a</sup> Particular matter 10 micrometer or less in diameter

Source: National Environmental Quality (Emission) Guideline for Myanmar, 2015 Dec 29

Table 7.11 Noise Level Standard

	One Hour LAeq ( dBA)a			
	Daytime	Nighttime		
Receptor	07:00-22:00 (10:00-22:00 for Public	22:00-07:00		
	holidays)	(22:00-10:00 for Public holidays)		
Residential, Institutional,	55	45		
educational Industrial, commercial	70	70		

<sup>&</sup>lt;sup>a</sup> Equivalent continuous sound level in decibels

<sup>&</sup>lt;sup>b</sup> At the edge of a scientifically established mixing zone which takes into account ambient water quality, receiving water use, potential receptors and assimilative capacity; when the zone is not defiend, use 100 meters from the point of discharge

<sup>&</sup>lt;sup>b</sup> Particular matter 2.5 micrometer or less in diameter



## 7.9 ENVIRONMENTAL IMPACT AND MITIGATION MEASURES FOR DECOMMISSIONING PHASE

#### 7.9.1 WATER ENVIRONMENT

### a) Potential Impacts

Surface water and ground water contamination may result from various activities during decommission phase. These activities can include wastewater generated from workers and staff and oil and grease leakage from machines and vehicles. Sedimentation/siltation of drainage or waterway may also result from unconfined stockpiles of soil and other materials.

### b) Mitigation Measures

These activities shall be reduced by avoiding earth work in rainy season and discharging wastewater into existing sewage line. Suitable facilities or portable toilets must be provided to prevent discharging sanitary waste to the ground.

#### 7.9.2 AIR EMISSIONS

#### a) Potential Impacts

Negative impact on ambient air quality such as dust particles emissions could be expected due to demolition works during the decommission phase of the factory after the lifespan of the project. During decommissioning phase, transportation of materials, transfer of heavy machinery and demolition activities may give rise to dust emissions.

#### b) Mitigation Measures

In case of extreme dry and windy condition prevails, water sprinkling should be carried out by means of a dedicated water bowser so as to suppress windborne dust emissions. This nuisance will be temporary in nature and is not expected to affect the surrounding environment since the factory is located far from the residential area.



#### 7.9.3 ENVIRONMENTAL NOISE IMPACT

#### a) Potential Impacts

After the lifespan of the project, decommissioning of the factory can also affect noise level. Temporary noise barriers and properly controlled system of equipment and occupational preventive measures should be applied in this phase.

#### b) Mitigation Measures

Noise barriers should be built for diesel generator. Decommissioning activities are implemented during daytime and avoid later than 8 p.m. Occupational preventive measure should be applied in this phase. Workers employing in high noise areas should be worked on shifts and hearing protective wear such as earplugs, earmuffs, etc. should be provided. Sensitization of truck drivers to switch off vehicle engines while loading materials avoid running of vehicle engines or hooting especially.

#### 7.9.4 SOLID WASTE

#### a) Potential Impacts

Contamination and degradation of soil can be caused during the decommissioning phase.

#### b) Mitigation Measures

All unused or surplus building materials can be sold to other who needs it. Solid waste can be also used in the land level adjustments in the landfill area. Organic waste and construction debris should be properly collected at a dedicated storage area and suitably disposed of at designated place.

#### **Hazardous Waste**

#### a) Potential Impacts

Decommissioning activities may pose the potential for release of petroleum based products such as lubricants, hydraulic fluids, of fuels during their storage, transfer, of use in equipment. These materials may also be encountered during decommissioning activities in building components or industrial process equipment.



#### b) Mitigation Measures

Techniques for prevention or control of these impacts include:

- Provide adequate secondary containment for fuel storage tanks and for the temporary storage of other fluids such as lubricating oils and hydraulic fluids.
- Using impervious surfaces for refuelling areas and other fluid transfer areas
- Isolated storage for hazardous wastes release from the site should be provided and installation of fire extinguisher shall be done near storage of hazardous wastes.

#### 7.9.5 SOCIAL ENVIRONMENT

Loss of jobs of the employees may occur during decommissioning phase and it may reduce by taking responsibility on gradual reducing or transferring of work force.

## 7.9.6 HEALTH AND SAFETY RELATED WITH OCCUPATIONAL ACCIDENTS, DISASTER AND COMMUNITY HAZARD

#### 7.9.6.1 POTENTIAL IMPACTS

During decommissioning phase, health and safety impacts can result from working at height and electric shock hazards. Workers can face safety hazards related to manual handling and carrying heavy materials, working at height and use of electrical and hand tools.

#### 7.9.6.2 MITIGATION MEASURES

Site fencing and safety signatures should be done in this phase. Personal protective equipment (PPE) such as safety harness for working at height, safety gloves, helmet, goggles, earmuffs, etc. will be provided. Mechanical aids should be used to carry and handle heavy materials. Trained and competent workers are hire for demolition activities.



## 8.0 STAKEHOLDER ENGAGEMENTS AND INFORMATION DISCLOSURE

Public consultation and information disclosure ensures that communities and stakeholders are part and parcel of the proposed developments and in so doing assure the sustainable use of resources. Public consultations form a useful component for gathering, understanding and establishing likely impacts of projects determining community and individual preferences and selecting alternatives.

Green EHSS has organized meetings with Giant 999 Steel Manufacturing Factory. The objectives of the meeting was to collect up-to-date and precise information on the project activities. The outcome of the meeting will help in the assessment of the anticipated impacts.

Giant 999 Steel Manufacturing Factory is situated in Myaung Dagar Industrial Zone, near Kalar Kone Villages Tract, Hmawbi Township. Green EHSS and factory authorities had conducted stakeholder engagement with local residents near Industrial Zone to inform the local administration on the project, to collect the views, and to obtain the input into the impact and mitigation measures to be included in the EMPs.

#### 8.1 CONSULTATION PROCESS

Key issues and concerns were identified through:

#### Face to face meeting

The key stakeholder (Village Tract Administrator) was interviewed through holding **face to face meeting** and administration of questionnaires. One of the strategies was to collect the perceptions of authority persons.

#### • Socio-economic and opinion surveys

Detailed socio economic, and opinion surveys were also conducted in December 2019.

#### Public Meeting

Public Consultation was conducted in December 2019.



#### 8.1.1 FACE TO FACE MEETING

In December 2019, Village Tract Administrator of Kalar Kone Villages Tract was informed of the Project activities and there was face to face meeting for the commencement of baseline studies and household survey. Face to face meeting was conducted by GREEN EHSS social consultant.



Figure 8.1 Discussion with Village Administrator of Kalar Kone Villages Tract

#### 8.1.2 SOCIO-ECONOMIC AND OPINION SURVEY

The purpose of the socio economic and opinion questionnaire was to collect general socio economic and opinion information in this area and to obtain opinions and understanding of the activities of Giant 999 Steel Manufacturing Factory in Industrial Zone.

The household interviews were conducted inform of **socio-economic survey** through the use of predefined questionnaires targeting the PAP. The interviewers targeted the general public residing in the vicinity of the Giant 999 Steel Manufacturing Factory (Figure 8.2).

During December 2019, household surveys were conducted with 6 respondents in total from Kalar Kone Villages Tract. The household leaders were consulted with the objective of understanding the existing socio-economic conditions of the area of influence and the immediate surroundings of the project. Data collected during the



survey included data on the particulars of the community members and their opinion on the project.



Figure 8.2 Socio-Economic Surveys with Household Leaders from Kalar Kone Villages Tract

#### 8.1.3 PUBLIC MEETING

On 15<sup>th</sup> December 2019, public consultation and participation was conducted by Green EHSS Social consultant with three representatives of Giant 999 Steel Manufacturing Factory. It was held at Administrator Office, Kalar Kone Villages Tract with 17 attendees from Kalar Kone Villages Tract and the factory. Public meeting conducted to collect the ideas and opinions of village leaders, village elders and local residents with questionnaires to give their perceptions and the potential impacts in order to influence project design, implementation and follow-up (Figure 8.4).

In an open-ended question, the respondents were asked to identify the negative and positive impacts they expect this project to have on the local community. Moreover,



respondents were given an opportunity at the end of the questionnaire to provide any additional comments they wanted recorded.



Figure 8.3 Photograph of Kalar Kone Villages Tract Administrator Office for Public Consultation





Figure 8.4 Public Consultation with Ward Leaders and Local Residents from Kalar Kone Villages Tract

## **Environmental Management Plan Report**





## Table 8.1 List of Participants to the Public Consultation Meeting



GREEN ENVIRONMENTAL, HEALTH, SAFETY & SOCIAL CONSULTANCY CO., LTD 1112/C2 (A), Time Square Home, Merchant Road, Botataung Township, Yangon Ph: 095026245, 09425353553, Email: <a href="mailto:catherine@greenehss.com">catherine@greenehss.com</a>, <a href="mailto:green-sweaung@gmail.com">green.sweaung@gmail.com</a>

"ရောမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း"(မြောင်းတကာစက်မှုဇုန်၊ မှော်ဘီမြို့နယ်)နှင့်စပ်လျဥ်း၍ အကြံပြုဆွေးနွေးမှုများ ဆွေးနွေးပွဲသို့တက်ရောက်သူဒေသခံစာရင်း

### **Public Consultation Meeting**

Date of Meeting : \_\_\_\_\_\_\_ 15 . 12 - 2019 . Venue for Meeting: <u>ကုဃးကုန်းကျေးဥာ ကုပ်ချုပ်ကို</u>မျူးကွဲး Meeting Time : 10:00 a·m

Sr. •§	Name အမည်	Position ရာထူး	Address နေရဝ်လိဝ်စာ	Tel. Number థ§:ఫిరిరు	Signature လက်မှတ်
1	Erashie d.	भ्रेत्र शिवब्यः श्रीः	was: M. shop	9 974058878	2
2	g: 6300 / 29:0mc	٤٠٠٠ :	ч	4.420126202	28%
3	98 G25 F:	<i>જ</i> છે	h.	<sup>9</sup> 9:779650813	الم محمدون
4	ర్థీ:తాలుడ్:	h	h	<sup>Qq</sup> -450042256	Squart
5	Er 3 F Orals	ь,	fa	<sup>Q9,</sup> 777450720	fort
6	€:0E:68nE	3-	h	<sup>વ્ય</sup>	Com
7	3,000 30 E	L.	<b>h</b>	4.778457695	Meg
8	Z: 4564nE	ಎ೧೭ <b>ಸ</b> ್ಪೀಡ್ರೆ.	h	<sup>Q</sup> q :7150167∞	کسسی
9	ર્રેંજિં મેંજી	ь	h	aq.454846171	00.00
10	કું. ગ્રદ્યોં લ્બ	h.		29.898622062	Som





GREEN ENVIRONMENTAL, HEALTH, SAFETY & SOCIAL CONSULTANCY CO., LTD 1112/C2 (A), Time Square Home, Merchant Road, Botataung Township, Yangon Ph: 095026245, 09425353553, Email: <a href="mailto:catherine@greenehss.com">catherine@greenehss.com</a>, <a href="mailto:greenehss.com">green.sweaung@gmail.com</a>

Sr.	Name အမည်	Position	Address နေရဝ်လိဝ်စာ	Tel. Number థ§ఃఫిరిలు	Signature လက်မှတ်
11	ટું: કે (હદ	ปกลเปกด	dansoll the	29-69-4413790	<b>A</b>
12	\$1656 8nE	h	4	<sup>Qq</sup> · 7779434 <u>7</u> 9.	0
13	Fieningt	h	•	09.289323350	Omres
14	శ్రీ:61నార్యయ	h	h	09.250168308	:M
15				-	:



GREEN ENVIRONMENTAL, HEALTH, SAFETY & SOCIAL CONSULTANCY CO., LTD 1112/C2 (A), Time Square Home, Merchant Road, Botataung Township, Yangon Ph: 095026245, 09425353553, Email: <a href="mailto:catherine@greenehss.com">catherine@greenehss.com</a>, green.sweaung@gmail.com

ဖရာမ သံရည်ကိုုနှင့် သံနန်းဆွဲ လုပ်ငန်း"(မြောင်းတကာစက်မှုစုန်) နှင့်စပ်လျဉ်း၍ အကြံပြုဆွေးနွေးမှုများ ဆွေးနွေးပွဲသို့တက်ရောက်သူဝန်ထမ်းများစာရင်း

### **Public Consultation Meeting**

Date of Meeting	:_	15.	12 .	201	9.		
Venue for Meeti	ng: _	no.	:mf:	6m)	30 th	25/192	BUT
Meeting Time	:.	1765311	10	00	a.m		

Sr. •§	Name ఇంచ్ర	Position	Address နေရစ်လိစ်စာ	Tel. Number ఇశ్చితురు	Signature യനിഴുത്
1	Mother of to	Pipp	ונת בקיננטוףם	09 920017060	Jack .
2	છ્યું કેલ્સ્ટ્રેટ	<del>ଔ</del> ମେମ	840e030FE	09960361778	0.00
3	<b>ය</b> ලාදලදාද දැ	<b>အ</b> ကောင်း	6	08 9JOJ 00 9 99	
4					
5					



## 8.2 ENGAGEMENT TECHNIQUES

Giant 999 Steel Manufacturing Factory has implemented a comprehensive range of engagement activities using varied techniques to ensure that the project effectively involves stakeholders. The using techniques for aforementioned discussions, meetings and survey are showed in following table.

**Table 8.2 Engagement Methods and Techniques** 

<b>Engagement Technique</b>	Description Description				
Company address,	Giant 999 Steel Manufacturing Factory provides				
Factory address,	company location and factory location in Yangon.				
Plant location map	Using location map makes the interested stakeholders				
	and community clarified.				
	These are relevant tactics in easily way of accessibility				
	for all kinds of stakeholders.				
Hot line number,	Giant 999 Steel Manufacturing Factory operates a hot				
	line number which is available during business hours.				
Pamphlet	Giant 999 Steel Manufacturing Factory has produced				
	pamphlet available in community meetings for general				
	information related with plant activities, environmental				
	management, safety, community development and				
	public involvement.				
Face to face meeting	Giant 999 Steel Manufacturing Factory engages directly				
	with a range of stakeholders as required. In particular,				
	Giant 999 Steel Manufacturing Factory has an ongoing				
	engagement with local authority persons, and				
	community organizations.				
Questionnaires and	Giant 999 Steel Manufacturing Factory conducted				
Surveys	household survey in the vicinity of the plant location, to				
	evaluate the effectiveness of engagement mechanisms				
	and gain an understanding of community perception,				
	interests and issues.				
Public Meeting	Giant 999 Steel Manufacturing Factory has conducted				
	public meeting to generate more in-depth information				
	around issues and concerns raised by stakeholders.				
	These were giving stakeholders an opportunity to				



directly obtain information and ask questions concerned
with the project.

## 8.3 COMMENTS AND SUGGESTIONS FROM THE PUBLIC CONSULTATIONS AND SOCIO-ECONOMIC SURVEY

Stakeholder consultation revealed that there were no complaints from the surrounding area on Giant 999 Steel Manufacturing Factory.

The main issue raised in public meeting and concerns of residents are as follows:

- To remove the debris from the external drainage channel regularly.
- The factory should be clean.
- To create employment opportunities for local people.
- To manage and implement for fire safety.
- To provide occupational healthcare for employees.

Thu, the results of public consultation and socio-economic survey show that respondents were positive on the project for the operation of Giant 999 Steel Manufacturing Factory.



'ရောမ သံရည်ကျို့နှင့် သံနနိုးဆွဲ လုပ်ငန်း' (မြောင်းဘကာစက်မှုခုန်၊ မှော်ဘီမြို့နယ်) လည်ပတ်ခြင်းနှင့်စပ်လျှင်း၍ အကြံပြုသွေးမွေးမှုများ

#### အကြံပြုချက်များ

- နတ်ရဲလျှဉ်သတ်သောင်ရွက်ရာတွင် သဘဝ ပတ်ခန်းတွင်လီရိုက်စေရိုင် သော နည်းပညာ ဖြင့် မူနစ်းလမ်း များ စာခိုးပြုလာသနှစ် စတွက် လောင်းလျှင်ကြောင်း
- ် မက်ရွိ ရှိ လန်လပ်ရပ် ဘာသနာ ရာ ဈားများ ဆုပြလေး ရာတွင် ပတစ်ချီးများ - ဘန်နိန် ဗဒ္ဓဘစ်များလုံး ဦးအား မေး ဆုပ်ထားရန်
- නම්බල නෙදියදුර නම් නිද්යෙනු ගන්නෙදාග් මොසිය

దీస్తార్వలు కాడా చేస్తానిని కి. అబ్దర్లు <u>చాలువార్యము</u>త్తున్నారికి ఆయి <u>మానిక్షాలలో ఇక్</u> అయ్లు <del>మానిక్షాలకోనికి</del> అయ్లు <del>మానిక్షాలకోనికిక్క</del>

"ဧရာမ သံရည်ကျို့နှင့် သံနှန်းဆွဲ လုပ်ငန်း" (မြောင်းတကာစက်မှုစုန်၊ မှော်တီမြို့နှယ်) လည်ပတ်ခြင်းနှင့်စပ်လျဉ့်၍ အကြံပြုဆွေးရွေးမှုများ

#### အကြံပြုချက်များ

- sweet shratecond os tecon rator come of core
- etvol e@ dout sursh + vhady or fe as oloceung; \$100.15
- 33: @s. esestions reg delesti

(000000) J. 1944 25-510.

## Environmental Management Plan Report

## GIANT 999 STEEL MANUFACTURING FACTORY



"ရောမ သံရည်ကျို့နှင့် သံနနီးဆွဲ လုပ်ငန်း" (မြောင်းတကာစက်မှုစုန်၊ မှော်ဘီမြို့နယ်) လည်ပတ်ခြင်းနှင့်စပ်လှဉ်း၍ ဘကြံပြုဆွေးခွေးမှုများ

#### အကြံပြုရက်များ

- ශිශ්රේ, නැත්ති හතු දිද සිදුලාද හා උදුලාර ගැලීම පුරා කෙලෙද හතු  $\kappa$ හතුද ලිගි මෙර ගෙන උතුරු කළ සුලාදි .
- -- అయ్లాల్లో కాయాలులు? ఆధికు కాయాలులో ఇద్దులు వర్గలుకు కాయాలు తో కాయా కారా కార్యాలులు? ఆధికు కాయాలులో ఇద్దులు వర్గలు ప్రాంతి ప్రాంతి చేసిన కాయాలు
- Sienesheliowsiggeen

dereglos of researches a

"ဧရာမ သံရည်ကျို့နှင့် သံနုန်းဆွဲ လုပ်ငန်း" (မြောင်းတကာစက်ဖူဇုန်၊ မှော်ဘီမြို့နယ်) လည်ပတ်ပြင်းနှင့်စပ်လျှဉ်း၍ အကြံပြဆွေးနွေးမှုများ

#### အကြံပြုချက်များ

- song sons sol 32 1 @ 600 0 000 8 1 8 4 6 60 6 1
- 38,0000 816 8:0(0 of d = 600E:



**FACTORY** "ရောမ သံရည်ကျိုနှင့် သံနနိုးဆွဲ လုပ်ငန်း" (မြောင်းတကာဝက်မှုစုနဲ၊ မှော်ဘီခြုံနယ်) လည်ပတ်ခြင်းနှင့်စပ်လျင်း၍ အကြံပြုဆွေးနွေးမှုများ အကြံပြုရက်များ - سي روي و ميلاده کې د هې د ۱۹۵۰ د ۲۰ (000 ( လက်မှတ် ) జించ్ ్ట్రైల్ ఆర్మిక్ చా ಲಿಯೇ *-ಚಾನ್ಯಪ್ರಸ್*ಚಾರಿಸಿ ్యులు చక్కుడుకు ولايلونان عصد محود ٢٠٠٤ و ١ "ရောမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" (မြောင်းတကာစက်မှုဇုန်၊ မှော်ဘီမြို့နယ်) လည်ပတ်ခြင်းနှင့်စပ်လျဥ်း၍ အကြံပြုဆွေးနွေးမှုများ အကြံပြုချက်များ - alleand 1922. & All : hart: Angy wagne extent of so : so es of e@ 18: - poes tengelound ome groone: - B. B. : ext. ext. odo o & ye @v &)

Figure 8.5 Main Concerns Mentioned by Residents during Stakeholder Meeting



## 8.4 RESPONSES AND IMPLEMENTATION ACTION FOR COMMENTS

During the discussion process the issues raised are reviewed, and actions for resolution are agreed by the parties. Some issues were agreed at the time of consultation meeting. Responses and action plan from the Factory are shown in Table 8.3.

Table 8.3 Responses of the Factory for the Comment and Suggestion Received

"ရောမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" အနေဖြင့် အများပြည်သူနှင့် တိုင်ပင်ဆွေးနွေးခြင်း နှင့် သတင်းအချက်အလက်များ ထုတ်ဖော် တင်ပြခြင်း အစည်းအဝေးတွင် ရပ်ဗိရပ်ဖ ပြည်သူများ နှင့် တွေ့ဆုံဆွေးနွေး အကြံပြုချက်များ နှင့် ပက်သက်၍ ဆောင်ရွက်ပေးမည့် အစီအစဉ်

စဉ်	သဘောထား အကြံပြုချက်များ	ရှင်းလင်း ဆောင်ရွက်ချက်
э	- စက်ရုံပတ်ဝန်းကျင် ရေစီးရေလာ ကောင်းမွန်အောင် ပြုလုပ်ပါက ကောင်းမွန်မည်	- စက်ရုံပတ်ဝန်းကျင် ရေစီးရေလာ ကောင်းမွန်အောင် စက်ရုံမှ နေ့စားဝန်ထမ်းများ နှင့် သန့်ရှင်းရေးပြုလုပ်ပါသည်။
J	-စက်ရုံပတ်ဝန်းကျင် သန့်ရှင်းရေးပြုလုပ်ပါက ကောင်းမွန် မည်	-စက်ရုံပတ်ဝန်းကျင် သန့်ရှင်းရေးကိုလည်း နေစားဝန်ထမ်းများ နှင့် နေ့စဉ် သန့်ရှင်းရေး ပြုလုပ်ပေးပါသည်။
9	-စက်ရုံရှိ လစ်လပ်လုပ်သားနေရာများအား ခန့်ထားရာတွင် ပတ်ဝန်းကျင် အနီးရှိ ဒေသခံ များကို ဦးစားပေးခန့် ထားရန်	-ဝန်ထမ်းများခန့်ရာ တွင် အရည်အချင်းတူပါက ဒေသခံများအား ဦးစားပေး ခန့်ထားမည် ဖြစ်သည်
9	-မိမိတို့ စက်ရုံအတွင်း မီးဘေးအန္တရာယ် မဖြစ်ပွားစေရေး အတွက် အထူးကြပ်မတ် ဆောင်ရွက်ရန်	-စက်ရုံအတွင်း မီးဘေးအန္တရာယ် မဖြစ်ပွားစေရန် တာဝန်ရှိမီးသတ်တပ်ဖွဲ့ မှ ၆လ တစ်ကြိမ် စက်ရုံ အတွင်း လိုအပ်ချက်များကို လာရောက်စစ်ဆေးပြီး စက်ရုံမှ စစ်ဆေးချက်များကို စနစ်တကျ လိုက်နာ ဆောင်ရွက်ပါသည်။
9	-စက်ရုံရှိ အလုပ်သမားများ အလုပ်လုပ်ရင်းတစ်စုံ တစ်ရာ ထိခိုက်ဒဏ်ရာများ ရရှိပါက ဂရုစိုက်ပြုစုပေးစေလို	-စက်ရုံရှိ အလုပ်သမားများ အလုပ်လုပ်ရင်းတစ်စုံ တစ်ရာ ထိခိုက်မှုရှိခဲ့ပါက ဒဏ်ရာ နည်းလျင် နီးစပ်ရာ ဆေးခန်းများသို့ သွားရောက် ပြသကုသမှု ခံယူပြီး၊ ဒဏ်ရာ ကြီးမား ပြင်းထန်ပါက အထူးကုဆေးခန်းများ၊ ပြည်သူ့ဆေးရုံများသို့ သွားရောက်ပြသ ကုသပေးပါသည်။



#### 8.5 FUTURE PLAN FOR STAKEHOLDER ENGAGEMENT

Giant 999 Steel Manufacturing Factory commit to provide an opportunity to all the stakeholders and communities in the surrounding area as well as all employees to raise issues and concerns pertaining to the factory.

The ongoing consultation process will handle through mechanisms as follows:

- a) Neighbouring community/stakeholders can directly inform their perception to the Giant 999 Steel Manufacturing Factory Office.
- b) They can give their suggestions to the factory through the village administration office or industrial zone office.
- c) Giant 999 Steel Manufacturing Factory will continue to engage the relevant government departments annually for receiving required permit and license.
- d) Conduct discussions with village leaders both informally through phone conversation and formally through face to face meetings whenever necessary.

The required contact information from both sides Giant 999 Steel Manufacturing Factory as well as community contacts had been already disclosure. The ongoing consultation process will be handed by plant manager associated with government affair officer.



#### 9.0 ENVIRONMENTAL AND SOCIAL MANAGEMENT PLAN

Environmental and social management plan is intended to develop a management framework for the factory. The environmental practices, procedures and responsibilities are defined to get full compliance with the existing environmental policy, law, rules and regulation of the Environmental Department.

The environmental management plans for Giant 999 Steel Manufacturing Factory have been developed due to the significant environmental impacts associated with the Plant activities.

#### 9.1 ENVIRONMENTAL MANAGEMENT TEAM (EMT)

Giant 999 Steel Manufacturing Factory establishes the Environmental Management Team (EMT) for implementing environmental and social management and monitoring plan for the operation phase of the project.

#### **Environmental Management Team (EMT)**

EMT shall comprise:

a) Ma Hnin Si – Team Leader

b) Ma Myat Myat Nyein – HSE Representative

c) Ma Mi Mi Kyaw — Team Member d) Ma Zin Mar Soe — Team Member e) Ko Thant Zin — Team Member

f) Ko Phoye Wai Aung — Team Member



# 9.2 ROLES AND RESPONSIBILITIES FOR ENVIRONMENTAL MANAGEMENT TEAM

Table 9.1 Roles and Responsibilities of Environmental Management Team

Table 9.1 Roles and Responsibilities of Environmental Management Team				
POSITION	RESPONSIBILITIES	CONTACT DETAILS		
Team Leader	<ul> <li>Evaluate and supervise corrective and preventive actions taken and the management of identified environmental impacts and OHS hazards and issues.</li> <li>Monitor the environmental and social management plans implementation. Make sure that the plans are effectively followed and the results are discussed and evaluated for effectiveness and continual improvement.</li> <li>Guide the relevant personnel to effectively implement the environmental and social monitoring programme and supervise immediate actions taken in emergency situations.</li> <li>Represent the company in handling environmental and social issues / program with the media or regulatory agencies</li> <li>Conduct Management Review on a regular basis. Reporting to top management on the key performances and monitoring of environmental and social issues for review, including recommendation for improvements.</li> </ul>			
Team Member	• Ensure the risk assessments and environmental and social management plans are implemented.			



	<ul> <li>Ensure compliance with applicable legal requirements and other requirements that the company subscribes.</li> <li>Ensure that all employees, contractors and visitors under their control are instructed regarding the company's environmental health and safety rules &amp; regulations and there is good level of compliance.</li> <li>Ensure to monitor and review the environmental and OHS impacts and risks.</li> </ul>	
HSE Representative	<ul> <li>Conduct environment, safety and health inspections at once a month.</li> <li>Participate in incident investigations.</li> <li>Conduct environmental, health and safety talks and in-house trainings.</li> <li>Assist the managers in communicating to the employees under their control and ensure employees follow accordingly.</li> <li>Assist in implementing environmental, health and safety &amp; social management plans, monitoring plans.</li> </ul>	
Electrician / Mechanic	<ul> <li>Conduct of regular EHS inspection with maintenance of relevant EHS inspection records.</li> <li>Performs random verification of Tool Box Meeting conducted by foremen or subcontractor representatives for work groups.</li> <li>Supports the Plant Manager on other assigned tasks.</li> <li>Monitors the works carried out by respective workgroups in terms of schedule and adopted environmental and social management plans.</li> </ul>	



# 9.3 ENVIRONMENTAL AND SOCIAL MANAGEMENT PLAN FOR CONSTRUCTION PHASE

Table 9.2 Environmental and Social Management Plan for Construction Phase

Table 9.2 Environmental and Social Management Plan for Construction Phase					
Objectives	To control or mitigate significant impacts, hazards and risks associated with demolition activities during construction phase.				
Management Strategy	Providing awareness about potential OHS hazards and risks and community safety for Contractors for construction phase.  Provide necessary resources to control potential hazards and risks and to maintain a healthy and safe working environment.				
Impact	Control(s)	Responsibility	Timing		
Noise					
(Long/short term noise nuisance and hearing loss)					
Performance Indicator(s)	<ul> <li>No complaints from adjacent residential and commercial premises or community regarding noise exposure.</li> <li>Acceptable noise levels (dBA)</li> </ul>				
Controls	<ul> <li>Temporary noise barriers,</li> <li>Properly controlled system of equipment,</li> <li>Occupational preventive measures should be applied in this phase.</li> <li>Construction activities are implemented during daytime and avoid later than 8 p.m.</li> <li>Noise barriers should be built for diesel generator.</li> <li>Working employing in high noise area should be worked on shifts and hearing protective wear such as earplugs, earmuffs, etc. should be provided.</li> </ul>	Through-out construction phase	Contractor Site Supervisor OHS Supervisor		



Air/ Dust					
(Chronic respiratory disease and eye complication)					
Performance Indicator(s)	Concentration level of dust, particulate matters, PM10 and PM2.5, CO2, CO, SO2, NOx				
Controls	<ul> <li>This nuisance will be temporary in nature and is not expected to affect the surrounding environment since the project is located within an industrial zone.</li> <li>All vehicles used are inspected and done regular maintenance.</li> <li>Restriction of transport speed on roads.</li> <li>Installation of temporary cover.</li> <li>Practice dust management techniques, including watering down dust.</li> <li>Provide PPE against dust (i.e. mask)</li> </ul>	Through-out construction phase	Contractor Site Supervisor OHS Supervisor		
Water Pollution  (Contamination of surface and underground water sources)					
Performance Indicator(s)	<ul> <li>Monitoring results of tube well water quality.</li> <li>Concentration of BOD, COD, TSS</li> </ul>				
Controls	<ul> <li>Discharging wastewater into existing sewer line,</li> <li>Provision of oil and grease, and keeping the impervious floors of oil and grease handling areas,</li> <li>Water demand can be reduced by avoiding wastage of water and efficient water use for construction.</li> </ul>	Through-out construction phase	Contractor Site Supervisor OHS Supervisor		



	T		1
	Soil contaminations shall be reduced by avoiding earth work in rainy season,		
	Solid Waste		
	(Pollution of water, air and so	il)	
Performance Indicator(s)	<ul><li>Recycling or reuse of all recyclable wa</li><li>Removed from on-site at regular inter</li></ul>		
Controls	<ul> <li>Provide adequate size bins with label e.g. metal waste, general waste, hazardous or toxic waste.</li> <li>Separate recyclable materials from waste and keep covered.</li> <li>Dispose wastes regularly and not to allow wastes overflow from bins or accumulate on-site.</li> <li>Collect concrete and wash water in concrete washout facilities.</li> <li>Choose smaller, covered containers and more frequent collection.</li> <li>Conduct visual inspections of dumpsters and recycling bins, removing contaminants and keeping containers covered.</li> </ul>	Through-out construction phase	Contractor Site Supervisor OHS Supervisor
	Traffic congestion		
(	Vehicle accidents due to traffic volume and	d higher speed)	
Performance Indicator(s)	<ul><li>Public complaint with regards to traff.</li><li>Road Accident.</li></ul>	ic congestion.	
Controls	<ul> <li>Control speed of vehicles through road safety education and fines.</li> <li>Provide adequate signage, barriers and flag persons for traffic control.</li> </ul>	Through-out construction phase	Contractor Site Supervisor



	FACTORY			
	<ul> <li>Vehicle maintenance and refuelling should be confined to areas in the site camp.</li> <li>Restriction of transport speed on roads without special covering up to 29km/hr.</li> </ul>		OHS Supervisor	
	Social Environment			
	(Interaction with Public)			
Performance Indicator(s)	<ul><li>Accident and Incident statistics.</li><li>Public complaints.</li></ul>			
Controls	Informing of public on construction activities.	Through-out construction phase	Contractor Site Supervisor OHS Supervisor	
(Ir	Occupational and Community Health	·		
Management Strategy				
Controls	<ul> <li>Placing at the site of information and warning signs and fences.</li> <li>Ensure provision of appropriate PPE for staff such as         <ul> <li>earmuffs for ear protection,</li> <li>helmets for head protection,</li> <li>dust masks for dust protection for all project works,</li> <li>goggles with good visibility for eye protection,</li> </ul> </li> </ul>	Through-out construction phase	Contractor Site Supervisor OHS Supervisor	



	<ul> <li>safety shoes for protection of the feet,</li> <li>gloves of different types according to specific works in</li> </ul>		
	relation to: puncture resistance; sharps resistance; cut resistance; flexibility; abrasion resistance; grip.		
Emergency situations	<ul> <li>Storage of inflammable and explosive substance and materials at closed warehouses or fenced sites.</li> <li>Regular territory clearing.</li> <li>Availability of necessary means for fire prevention and provision of operative access to them.</li> </ul>	Through-out construction phase	Contractor Site Supervisor OHS Supervisor



## 9.4 ENVIRONMENTAL AND SOCIAL MANAGEMENT PLAN FOR OPERATION PHASE

#### 9.4.1 WATER MANAGEMENT PLANS

Table 9.3 Water Management Plan for Operation Phase

Objective(s)  Management Strategy	<ul> <li>To control and mitigate impacts of liquid wastes and sludge from the processing</li> <li>To ensure to meet the national emission standards</li> <li>To meet the WHO Drinking water Quality Guidelines</li> <li>Provision of drainage system and it is periodically cleared so as to ensure adequate storm water flow.</li> </ul>		
Impact	Control(s)	Responsibility	Timing
Surface water contamination	<ul> <li>Factories should create a list of the materials that have the potential to come into contact with storm water and pollute it. These may include raw materials, fuels, detergents, finished products and waste materials.</li> <li>Factories should regularly inspect equipment, grounds and areas outside the factory to identify any conditions or practices that might pollute storm water and to assess if best management practices are effective in preventing pollution.</li> <li>Regular removal of debris and sediments.</li> </ul>	Plant Manager  Site Supervisor  HSE  Representative	Throughout processing phase
Sanitation waste water	<ul> <li>Reducing the volume of water used.</li> <li>All sewers should be disposed of through septic tanks.</li> <li>Discharge periodically by contacting Engineering</li> </ul>		



	Department (Water and Sanitation).  • Train employees to minimize water use and on water		
Training	conservation practices.		
Performance Indicator(s)	<ul> <li>Monitoring results of ground water quality.</li> <li>pH, Conductivity, Total Dissolved Solid, Total Hardness, Total Alkalinity, Calcium, Magnesium.</li> <li>Monitoring results of drain water Concentration of BOD, COD, TS</li> </ul>		Throughout processing period
Monitoring	Monitoring of tube well water or factory use water should be done biannually by sending the water into the laboratory.	HSE Supervisor Third party HSE firm Engage for laboratory tests	Throughout processing period
Reporting	<ul> <li>The Plant Manager or designated person shall review the monitoring results.</li> <li>The results will be evaluated during internal EHS audits and take corrective action as necessary.</li> <li>The monitoring results and corrective actions will be reported to top management</li> </ul>	Plant Manager Top Management	Throughout processing period



#### 9.4.2 AIR EMISSION AND DUST MANAGEMENT PLANS

#### Table 9.4 Air Emission and Dust Management Plan for Operation Phase

Objective(s)  Management Strategy	<ul> <li>To ensure the impacts of dust and other air born particulates and dusts on adjacent areas and the nearby community are minimised.</li> <li>To ensure to meet acceptable Air emission level of National Emission Standards. (MOECAF, 2015 December)</li> <li>Potential air emission sources and activities will be managed by mainly engineering controls and administrative controls</li> </ul>		
Impact	Control(s)	Responsibility	Timing
Control(s)	<ul> <li>Effective dust control system is provided at the furnace.</li> <li>Planting fast growth trees around the factory as a barrier to mitigate the air emission around the factory.</li> <li>Regular maintained and inspection of the furnace and control system.</li> <li>All vehicles are regularly inspected and maintained to reduce the gas emission.</li> <li>Reducing the vehicles use, and collaborated using on same route of vehicles.</li> <li>Providing proper PPE to the employee</li> </ul>	Plant Manager  Site Supervisor  HSE  Supervisor	Throughout processing phase
Performance	Concentration level of dust,		Throughout
Indicator(s)	particulate matters, PM <sub>10</sub> and PM <sub>2.5</sub> , CO <sub>2</sub> , CO, SO <sub>2</sub> , NO <sub>x</sub>		processing period
Monitoring	Monitoring and measurement of selected performance indicators of air quality at least once per six	HSE Supervisor	Throughout processing period



	month or as and when necessary	Third party	
	by third party.	HSE firm	
	• Record the emission results.		
	Define standards for air		
	emission measurement		
	comparison.		
Reporting	The Plant Manager or designated	Plant Manager	Throughout
	person shall review the	T.	processing
	monitoring results.	Тор	period
	• The results will be evaluated	Management	periou
	during internal EHS audits and		
	take corrective action as		
	necessary.		
	• The monitoring results and		
	corrective actions will be		
	reported to top management		

#### 9.4.3 NOISE MANAGEMENT PLANS

#### Table 9.5 Noise Management Plan for Operation Phase

Objective(s)  Management Strategy	<ul> <li>To minimise the impacts of environmental noise and vibration on the surrounding areas.</li> <li>To ensure to meet acceptable noise level of National Emission Standards. (MOECAF, 2015 December)</li> <li>Potential noise emission sources and activities will be managed by mainly engineering controls and administrative controls.</li> </ul>		
Impact	Control(s)	Responsibility	Timing
Control(s)	<ul> <li>Regular maintenance of the machines to reduce noise emission.</li> <li>All the personnel working in high noise generating areas will be provided with sufficient ear</li> </ul>	Plant Manager  Site Supervisor  HSE  Supervisor	Throughout processing phase



	T	T	,
	protecting devices such as ear muffs.		
Performance Indicator(s)	<ul> <li>No complaints from adjacent residential and commercial premises or community regarding noise exposure.</li> <li>Acceptable noise levels (dBA)</li> </ul>		Throughout processing period
Monitoring	• Noise monitoring should be conducted by the plant personnel or third party to ensure the predicted impacts are not exceeded as National Noise Emission Standards.	HSE Supervisor Third party HSE firm	Throughout processing period
Reporting	<ul> <li>The Plant Manager or designated person shall review the monitoring results.</li> <li>The results will be evaluated during internal EHS audits and take corrective action as necessary.</li> <li>The monitoring results and corrective actions will be reported to top management.</li> </ul>	Plant Manager Top Management	Throughout processing period



#### 9.4.4 SOLID WASTE MANAGEMENT PLANS

Table 9.6 Solid Waste Management Plan for Operation Phase

Table	le 9.6 Solid Waste Management Plan for Operation Phase			
Objective(s)	<ul> <li>Reduce waste volume, maximise recycling, reuse and recovery, prevent any process waste entering the environment.</li> </ul>			
Management Strategy	Minimise environmental impacts through proper waste management and controls.			
Impact	Control(s)	Responsibility	Timing	
Control(s) of Production waste and	<ul> <li>Provide segregated the waste type and adequate size of waste bins.</li> <li>Dispose wastes regularly and not to allow wastes overflow from bins or accumulate on-site.</li> <li>Apply 3Rs management (Reduce, Reuse and Recycle)</li> <li>Improve notice sign and awareness display board (non-smoking, no-dumping signs).</li> </ul>	Plant Manager  Site Supervisor  HSE Supervisor	Throughout processing phase	
Hazardous waste	<ul> <li>Ensure licensed contractors or YCDC are used to collect hazardous wastes.</li> <li>Train employees to store and handle hazardous waste.</li> <li>Hazardous wastes are segregated in the secured bin and disposed by the license collector or YCDC hazardous waste collection department.</li> </ul>			



Performance Indicator(s)	<ul> <li>Hazardous wastes will be appropriately disposed.</li> <li>Recycling or reuse of all recyclable wastes.</li> <li>Removed from on-site at regular intervals.</li> </ul>		Throughout processing period
Monitoring	Daily inspection of around the plant and waste bins.	Supervisor  HSE Supervisor	Throughout processing period
Reporting	<ul> <li>The Plant Manager or designated person shall review the monitoring results.</li> <li>The results will be evaluated during internal EHS audits and take corrective action as necessary.</li> <li>The monitoring results and corrective actions will be reported to top management.</li> </ul>	Plant Manager Top Management	Throughout processing period



#### 9.4.5 TRAFFIC MANAGEMENT PLANS

Table 9.7 Traffic Management Plan for Operation Phase

Objective(s)		Control and manage traffic congestion at the public roads due to delivery truck movements.		
Management Strategy	Minimize traffic congestion through proper traffic management.			
Impact	Control(s)	Responsibility	Timing	
Control(s)	<ul> <li>To schedule delivery movements outside of peak vehicle traffic times.</li> <li>Reducing the vehicles use and collaborated using on same route of venicles.</li> <li>Be sure that trucks and other vehicles are in good working order.</li> <li>Follow the established truck routes in the community.</li> <li>Driver behaviour, awareness and training should be undertaken.</li> </ul>	Plant Manager  Site Supervisor  HSE Supervisor  Truck Operators	Throughout processing phase	
Performance Indicator(s)	<ul><li>Public complaint with regards to traffic congestion.</li><li>Road Accident.</li></ul>		Throughout processing period	
Monitoring	Visual check of traffic congestion around the project area.	Supervisor HSE Supervisor	Throughout processing period	



Reporting	To report Plant Manager if there	
	is any unsolvable traffic congestion.  Top  Top  Management  processing period  period	

#### 9.5 OCCUPATIONAL AND COMMUNITY HEALTH AND SAFETY

#### 9.5.1 OCCUPATIONAL HEALTH AND SAFETY PLAN

Table 9.8 Occupational Health and Safety Plan for Operation Phase

Objective(s)	To control or mitigate significant occupational health and safety hazards and risks associated with operations.		
Management Strategy	Own employees are educated about potential OHS hazards and risks and community safety.  Provide necessary resources to control potential hazards and risks and to maintain a healthy and safe working environment.		
Impact	Control(s)	Responsibility	Timing
Control(s) of -Accidents -Drinking -Traffic safety	<ul> <li>The first aid kits and emergency medical boxes are supplied sufficiently.</li> <li>Nearest hospital phone numbers in the factory.</li> <li>Providing purified drinking water for all workers.</li> <li>Improve the driving skills and requiring licensing of drivers.</li> </ul>	Plant Manager  Site Supervisor Factory Doctor/Nurse  HSE Supervisor	Throughout processing phase



-Safety measure	<ul> <li>Fire extinguishers and facilities.</li> <li>All workers should be provided with proper Personal Protective Equipment.</li> <li>Fire drill will be conducted once</li> </ul>		
	<ul><li>per year.</li><li>Providing competency training</li></ul>		
Performance Indicator(s)	Accident and Incident statistics.		Throughout processing period
Monitoring	<ul> <li>Supervisor and HSE Supervisor should conduct daily HSE inspection to make sure a safe working environment.</li> <li>Plant Manager and Line Manager should conduct a plant inspection once per week.</li> </ul>	Supervisor HSE Supervisor	Throughout processing period
Reporting	<ul> <li>The Plant Manager or designated person shall review the monitoring results.</li> <li>The results will be evaluated during internal EHS audits and take corrective action as necessary.</li> <li>The monitoring results and corrective actions will be reported to top management.</li> </ul>	Plant Manager Top Management	Throughout processing period



#### 9.5.2 COMMUNITY HEALTH AND SAFETY PLAN

Table 9.9 Community Health and Safety Plan for Operation Phase

Table 9.	Table 9.9 Community Health and Safety Plan for Operation Phase		
Objective(s)	To control or mitigate significant of hazards and risks associated with	•	and safety
Management Strategy	Provide necessary resources to contro and to maintain a healthy and safe er	_	ds and risks
Impact	Control(s)	Responsibility	Timing
Control(s)	<ul> <li>Sludge wastes from septic tank are removed biannually.</li> <li>Reused and recycled waste.</li> <li>Traffic safety is promoted.</li> <li>The emergency response team including trained fire fighters and first aiders has developed.</li> <li>Fire drill will be conducted once per year.</li> </ul>	Plant Manager Site Supervisor  ERTeam  HSE Supervisor	Throughout processing phase
Performance Indicator(s)	Public complaints.		Throughout processing period
Monitoring	<ul> <li>Supervisor and HSE Supervisor should conduct daily HSE inspection to make sure a safe working environment.</li> <li>Plant Manager and Line Manager should conduct a plant inspection once per week.</li> </ul>	Supervisor HSE Supervisor	Throughout processing period
Reporting	<ul> <li>The Plant Manager or designated person shall review the monitoring results.</li> <li>The results will be evaluated during internal EHS audits and take corrective action as necessary.</li> </ul>	Plant Manager Top Management	Throughout processing period



The monitoring results and
corrective actions will be
reported to top management.

## 9.6 ENVIRONMENTAL AND SOCIAL MANAGEMENT PLAN FOR DECOMMISSIONING PHASE

Table 9.10 Environmental and Social Management Plan for Decommissioning
Phase

	Pnase		
Objectives	To control or mitigate significant impacts, hazards and risks associated with demolition activities during decommissioning phase.		
Management Strategy	Providing awareness about potential OHS hazards and risks and community safety for Contractors for decommissioning phase.  Provide necessary resources to control potential hazards and risks and to maintain a healthy and safe working environment.		
Impact	Control(s)	Responsibility	Timing
	Water Pollution  (Contamination of surface and underground water sources)		
Performance Indicator(s)			
Controls	Ensure sewage system is functional during demolition to prevent pollution of nearby underground and surface water sources.  Proper demolition of the sewage system to prevent pollution by contents into the environment and ground water.	Through-out decommi- ssioning phase	Contractor Site Supervisor OHS Supervisor



	Air/ Dust  (Chronic respiratory disease and eye complication)		
Performance Indicator(s)	Concentration level of dust, particulate m CO, SO <sub>2</sub> , NO <sub>x</sub>	natters, PM10 and 1	PM2.5, CO2,
Controls	<ul> <li>All vehicles used are inspected and done regular maintenance.</li> <li>Restriction of transport speed on roads.</li> <li>Installation of temporary cover.</li> <li>Set up dust barriers at strategic locations: Dust nets will be provided around the demolition area.</li> <li>Practice dust management techniques, including watering down dust.</li> <li>Provide PPE against dust (i.e. mask)</li> </ul>	Through-out decommission -ing phase	Contractor Site Supervisor OHS Supervisor
	<b>Noise</b> (Long/short term noise nuisance and he	earing loss)	
Performance Indicator(s)	, ,		cial premises
Controls	<ul> <li>Schedule noisy activities during daytime period.</li> <li>Ensure machinery is well maintained to reduce noise generating.</li> <li>Switching off installations and equipment when they are not used.</li> <li>Minimization of work during evening/night-time.</li> </ul>	Through-out decommission ing phase	Contractor Site Supervisor



	Provide PPE such as noise defenders, ear plugs and earmuffs to the workers in high noise area.		OHS Supervisor
	Solid Waste  (Pollution of water, air and so	il)	
Performance Indicator(s)	<ul> <li>Chemical wastes will be appropriately</li> <li>Recycling or reuse of all recyclable wa</li> <li>Removed from on-site at regular inter-</li> </ul>	stes.	
Controls	<ul> <li>Enforce segregation of waste at the source to encourage reuse and recycling.</li> <li>To store waste temporary in containers, in case of large dimension it is possible to store wastes with waterproof cover.</li> <li>Disposal of solid waste in compliance with local government policy</li> <li>Usable infrastructures will be hand over to the township authorities for future community use.</li> </ul>	Through-out decommission -ing phase	Contractor Site Supervisor OHS Supervisor
(	Traffic congestion (Vehicle accidents due to traffic volume and	d higher speed)	
Performance Indicator(s)	<ul><li>Public complaint with regards to traffi</li><li>Road Accident.</li></ul>	c congestion.	
Controls	<ul> <li>Control speed of vehicles through road safety education and fines.</li> <li>Provide adequate signage, barriers and flag persons for traffic control.</li> <li>Vehicle maintenance and refuelling should be confined to areas in the site camp.</li> </ul>	Through-out decommission -ing phase	Contractor Site Supervisor OHS Supervisor



Г			<u> </u>
	<ul> <li>Restriction of transport speed on roads without special covering up to 29km/hr.</li> </ul>		
	Socioeconomic Status		
(Socio	beconomic effects such as loss of jobs, low	imcome may aris	se)
In diameter (a)	<ul><li>Loss of jobs.</li><li>Family income issues</li><li>Services Terminations.</li></ul>		
	<ul> <li>Loss of jobs of the employees may occur during decommissioning phase and it may reduce by taking responsibility on gradual reducing or transferring of work force.</li> <li>By providing skill enhancement training to the employees during operation phase, it helps the employees to become qualified and proficient in finding some new jobs.</li> <li>Assist the existing staff to apply similar new work at adjacent factories.</li> <li>Factory's workforce is small, and loss of income may not even have a measurable effect on the economic situation in the local community and certainly not in the wider community.</li> <li>Skill development can be utilized elsewhere especially in Myaung Dagar Industrial Zone.</li> <li>Liaise with decommissioning contractor organizations to use local labour where practical.</li> <li>The influx of contractors may give a boost to local businesses.</li> </ul>	Through-out decommission -ing phase	HR Dept. OHS Supervisor



	<ul> <li>Positive impact for decommissioning contractors and other specialist suppliers.</li> <li>Create opportunity to fulfil an ambition to build a new business.</li> </ul>		Decommis sioning contractor
(Potentially co	Social Environment onflicting may occur because of the loss of	work and econon	nic activity)
Performance Indicator(s)	<ul><li>Personal and family stress</li><li>Accident statistics</li><li>Public complaints.</li></ul>		
Controls Interaction with Employee	<ul> <li>Plant workers can be expected to suffer from significant increases in personal and family stress following a shutdown announcement. Consequently, explain staff the decommissioning plans clearly that helps them understand it better and to avoid confusion.</li> <li>Tensions may be generated potentially leading to labour relations or other staffing problems. Accordingly, the factory will develop potential coping mechanism which is implemented by creating and taking an early opportunity to leave for other employment.</li> <li>Promote confidence to face the prospect of radical change and to find other employment.</li> <li>Create and implement an effective skill enhancement training to overcome the fear of having to retrain for unfamiliar fields of new jobs.</li> </ul>	Through-out decommission -ing phase	Site Supervisor OHS Supervisor



# Interaction with Community

- Consult the local population early once the decision has been taken to permanently shut down the factory.
- Establish good communications and cooperation exist between factory management and community representatives.
- Identify the baseline and vision for the community.
- Negotiated the closure planning with local communities and other stakeholders.
- Built up trust and understanding between the parties (staff, local community leaders or others) in dealing with the issues arising from decommissioning.

# Interaction with Zone Committee, Local Authority

- Making announcements alongside zone committee representatives can be useful in order to assuage any workforce distrust in management.
- Factory will be decommissioned according to the requirements of the local authorities and zone committee guideline.
- Collaboration management of the impact of final shutdown on the workforce and the local community can help to ameliorate the threats.

#### Occupational and Community Health and Safety

(Incidents and accidents leading to serious injury or fatalities)

#### Management Strategy

- Own employees are educated about potential OHS hazards and risks and community safety.
- Provide necessary resources to control potential hazards and risks and to maintain a healthy and safe working environment.



Controls	<ul> <li>Placing at the site of information and warning signs and fences.</li> <li>Ensure provision of appropriate PPE for staff such as         <ul> <li>earmuffs for ear protection,</li> <li>helmets for head protection,</li> <li>dust masks for dust protection for all project works,</li> <li>goggles with good visibility for eye protection,</li> <li>overalls and dust coats to protect the skin,</li> <li>safety shoes for protection of the feet,</li> <li>gloves of different types according to specific works in relation to: puncture resistance; sharps resistance; cut resistance; flexibility; abrasion resistance; grip.</li> </ul> </li> </ul>	Through-out decommissioning phase	Contractor Site Supervisor OHS Supervisor
Emergency situations	<ul> <li>Storage of inflammable and explosive substance and materials at closed warehouses or fenced sites.</li> <li>Regular territory clearing.</li> <li>Availability of necessary means for fire prevention and provision of operative access to them.</li> </ul>	Through-out decommi- ssioning phase	Contractor Site Supervisor OHS Supervisor



#### 9.7 EMERGENCY PREPAREDNESS AND RESPONSE PLAN

Myanmar is prone to various natural hazards that include earthquakes, floods, cyclones, droughts, fires, tsunamis, some of which have the potential to impact large numbers of people. During operation phase, chemical spill, machine failure, collapse of structure and malfunction of processing machine may occur in many factories.

For 999 factory, emergency situation such as fire is assessed, and the factory established "Emergency Preparedness and Response Plan".

The overall goal of the **ERP Plan** is to mitigate the impact of fire and disasters and save as many lives as possible from preventable causes.

Giant 999 Steel Manufacturing Factory has planned, designed and constructed with fixed firefighting installations systematically. Giant 999 Steel Manufacturing Factory has prepared an Emergency Preparedness and Response Plan in order to prevent consequences of natural disasters such as fire, floods and earthquakes and man-made errors (e.g. electricity shock, fire hazards).

Emergency Preparedness and Response Plan describes the requirements for planning and preparing to protect workers in the event of an emergency. Emergency and disaster response plan describes the requirements for planning and preparing to protect workers in the event of an emergency.

#### **Requirements**

- Factories must have procedures to prepare for possible emergencies such as fire, earthquakes, hurricanes, and chemical spills.
- Factories must have an emergency evacuation plan, and evacuation routes must be posted in each work area.
- Factories must hold emergency evacuation drills often enough that workers know the drill procedure and consider it routine.
- Factories must have a fire prevention plan.



#### 9.7.1 EMERGENCY RESPONSE TEAM (ERT)

Giant 999 Steel Manufacturing Factory has developed the Emergency Response Team (ERT) to fulfill the requirement of emergency and disaster response plan and to promote a safe working environment at the factory.

The team members shall have knowledge of or can be trained in responding to emergencies such as emergency plan, firefighting, precautions.

The **Emergency Response Team (ERT)** should be on call in case of safety problem that occurs during off-hours/ or Security shall contact the Township Fire Department immediately.

#### **Emergency Response Team (ERT)**

#### ERT shall comprise:

i) Ko Aung San Oo – Incident Coordinator (IC)

j) Ko Thant Zin – Deputy IC

k) Ko Moe Paing Sint – Officer-in-charge at Assembly Area (OIC-AA)

I) Ma Myat Myat Nyein – Supervisors - Wardenm) Ko Wai Phyoe Aung – Supervisors - Warden

n) Ko Kyaw Thiha - First Aiders, Fire Fighters, etc.
 o) Ko Kyar Shin - First Aiders, Fire Fighters, etc.
 p) Ko Kyaw Zin - First Aiders, Fire Fighters, etc.

### 9.7.2 ROLES AND RESPONSIBILITIES FOR EMERGENCY RESPONSE TEAM

The team members shall have knowledge of or can be trained in responding to emergencies such as emergency plan, firefighting, precautions.

The **ERT** should be on call in case of safety problem that occurs during off-hours/ or Security shall contact the Township Fire Department immediately.



Table 9.11 Roles and Responsibilities of Emergency Response Team

	Table 3.11 Roles and Responsibilities of Emergency Response Team			
Incident Controller	Commands and control the ERT to response to an emergency.			
	Communicates with authorities eg. Police/ Township Fire			
	Department in the event of an emergency.			
	• Ensure emergency plan are reviewed regularly and ERT are appropriately trained and equipped to carry out their assigned task.			
	Crowd control and monitor overall headcount at the Assembly Area.			
	• Initiate drill exercises and post exercise review with ERT on an annual basis.			
Dy- Incident	Conduct head count of all staff, consultants and workers.			
Controller	Consolidate the headcount list from wardens.			
	Report evacuation status such as any missing person to the IC .			
Member- Fire Fighters	To be trained in firefighting, and assist in firefighting at no personal risk.			
Member- Wardens	Area combing, to ensure all staff and workers leave the workplace promptly during an evacuation.			
	Direct staff and workers to the Assembly Area.			
	Conduct headcount for their workers at the Assembly Area.			
Member-	Successfully completed first aid training. To render first			
First Aiders	aid to any injured during any emergency.			
	Standby at the Assembly Area with first aid kit during a mass evacuation.			
	THE CONTROLL			

#### 9.7.3 FIRE PREVENTION PLANS

A small spark of fire may result into loss of properties and the damage by fire may produce high economic losses. This type of losses can be avoided by preventing and controlling the fire instantly for which **Emergency Response Team (ERT)** (mentioned above) is established.

The following requirements for firefighting equipment shall be taken into consideration:



- **Location** extinguishers and hoses are to be placed in readily accessible locations and in areas where risk of fire is likely.
- Access clear access is to be maintained around fire extinguishers and hoses at all times.
- **Signage** signage is to be provided at each location, indicating the type of fire extinguisher and fire types that they are suited for.
- **Mounting** fire extinguishers are to be mounted on purpose made hooks or brackets and suspended above the floor.
- **Inspection** fire extinguishers are to be inspected and serviced every six months.

#### **Hazard Assessment**

- Factories should consider all the types of emergencies that may occur at their location (e.g.fire, chemical spill, earthquake, typhoon, etc.) and include them in emergency preparedness procedures.
- Fire and explosion hazards can exist in almost any work area. Potential hazards include:
  - a) Improper operation or maintenance of gas-fired equipment.
  - b) Improper storage or use of flammable liquids.
  - c) Smoking in prohibited areas.
  - d) Accumulation of trash.
  - e) Hot Work (welding, soldering, any use of open flame or torch) operations without proper controls.

#### Rules to Follow

- Electrical lines must be checked not to leave without switching off when working hours is over or when there is blackout.
- All the fuel and diesel are to be kept and stored, away from fire prone facilities and equipped with specific fire extinguishers for emergency use.
- Flammable by-products or wastes are to be kept at a specific site.
- Smoking is strictly restricted except in a specific smoking area defined.
- Matches must not be used near the machines.
- Establish a firm rule that any repair or maintenance work on powered machines should only be down when the power is turned off and the switch is locked in the off position.



 Be certain that the electrical power can be shut off immediately in case of emergency.

#### **Emergency Contact List**

Emergency Contact List consisting contact nos. of authorities, hospital, clinic, ERT personnel shall be prepared and displayed at the factory. The list shall be reviewed at least once a year or as and when there is change in personnel or change in contact number.

The contact no. for local authorities below shall be included in the list:

- Township Fire Department fires, explosions, spills, ambulance, structure collapse
- Police local emergencies, life threatening situation
- Nearest Hospital medical emergencies
- Local clinic or on-site doctor/nurse medical emergencies

#### **Drills**

Factories should have emergency evacuation procedures that require all workers and managers to participate in drills. During a drill, workers and managers should leave the building, go to an assigned location (assembly area) and remain there until a signal is given to return to the factory. The focus should be on orderly evacuation, rather than on speed. Awareness talk for protection will be held and workers will be sent to trainings administered by Fire Bridge. The following exercise shall be conducted at least once a year for the ERT or otherwise stated:

- Fire fighting
- Evacuation Drill for all personnel at the factory

#### Fire Extinguisher

A portable fire extinguisher is a "first aid" device and is very effective when used while the fire is small. The use of a fire extinguisher that matches the class of fire, by a person who is well trained, can save both lives and property. Portable fire extinguishers should be installed in workplaces regardless of other fire-fighting measures. The successful performance of a fire extinguisher in a fire situation largely depends on its proper selection, inspection, maintenance, and distribution.



#### Classification of Fires and Selection of Extinguishers

- Extinguishers should be selected according to the potential fire hazard, the construction and occupancy of facilities, the hazard to be protected, and other factors pertinent to the situation.
- Use water from nearby tap water if the fire is caused by burning of wood, paper, plastics, textile and trash.
- Dry powder extinguisher (blue) can be used for most types of fire such as those involving burning of wood, paper, plastics, textile, trash, chemical, flammable liquid and electrical fires.
- Carbon dioxide extinguisher (black) is only suitable for flammable liquids and electrical fires only. It is not suitable for use in indoor/ enclosed environment.

The diagram below illustrates the color coding of fire extinguishers and can be used as a guideline for Fire Extinguisher selection.




Figure 9.1 Selection Guidelines for Fire Extinguishers



#### Fire Safety Inspections & Housekeeping

- Observe worksite safety and housekeeping issues and should specifically address proper storage of chemicals and supplies, unobstructed access to fire extinguishers, and emergency evacuation routes.
- Determine if an emergency evacuation plan is present in work areas and if personnel are familiar with the plan.
- Conduct monthly fire safety inspection of the facility. This includes valve inspections, flow tests of the risers, audible and visual alarm activation, emergency lighting, general order and housekeeping.
- Checking that combustible materials are removed daily, that flammable liquids are stored safely, that spill kits are intact at specific locations and that electrical equipment is in good repair.

#### **Outside Assembly Points**

- Outside assembly points will be marked and all site personnel instructed where to assemble in the event of an emergency.
- An assembly area must be assigned outside the factory so that evacuated workers can be accounted for in an emergency.

#### First Aider and First Aid Facilities

Trained first aider(s) shall be appointed for the project, and for each shift.

#### In the event of Fire & Explosion (Fire Emergency Procedures)

#### g) If you discover a fire

- Activate the nearest fire alarm (or) shout loudly.
- Otherwise, he shall evacuate and alert all personnel in the area and notify the IC/ Dy IC/ Supervisor
- The person who discover can attempt to extinguish any incipient fire with the available firefighting equipment and without personal risk.

#### h) Fight the fire ONLY if:

- The fire department has been notified of the fire, and
- The fire is small and confined to its area of origin, and
- You have a way out and can fight the fire with your back to the exit, and
- You have the proper extinguisher, in good working order, and have been trained and know how to use it.



• If you are not sure of your ability or the fire extinguisher's capacity to contain the fire, leave the area.

#### i) If you hear a fire alarm:

- Evacuate the area, and close doors as you leave.
- Leave the building and move away from exits and out of the way of emergency operations.
- Assemble in an assigned area, outside the building.
- Supervisors and Coordinators should account for all workers in their area to determine that all personnel have evacuated.
- All workers should remain outside until given the signal or announcement that it is safe to re-enter.

#### j) Evacuation Routes:

- Learn at least two escape routes and emergency exits from your area.
- Learn to activate a fire alarm.
- Learn to recognize alarm sounds.
- Take an active part in fire evacuation drills.

#### k) Evacuation

- When the alarm sounds, all personnel not assigned to emergency duties will immediately proceed to the nearest SAFE exit. Leave the building, and move directly to the nearest assembly area.
- Do not stop to pick up personal items.
- All personnel should refrain from smoking during the evacuation.
- All personnel should be at least sixty meters (60mm) or two hundred feet (200 ft) away from the building.
- Be familiar with exit routes, assembly areas, and evacuation maps.
- Report to assembly area coordinator if evacuating from other than your normally assigned location, also report to assembly area coordinator if coworker is missing.
- Treat all alarms as if there is an emergency situation. Factory will evacuate for all alarms.

#### 1) Power Failure

• In the event of a power failure, remain in your work area. Wait for instruction from your coordinator, Supervisor, or shift leader.



• Stop and park all moving equipment immediately for the duration of the power failure.



Figure 9.2 Photos of Facilities for fire prevention



Figure 9.3 Photos Record of Fire Drill at the Factory



## 9.8 COMMUNITY INVOLVEMENT AND DEVELOPMENT PROGRAM

Giant 999 Steel Manufacturing Factory intends to maximise opportunities for individuals, communities and stakeholder groups to engage in the project activities. The factory collaborates with local authorities as well as personnel of industrial zone office. Giant 999 Steel Manufacturing Factory provides an opportunity to all the stakeholders and communities in the surrounding area as well as all employees to raise issues and concerns pertaining to the factory Giant 999 Steel Manufacturing.

Factory will make necessary arrangements to reserve 2% on excepted Net Profit as CSR Fund. CSR refers to business practices involving initiatives that benefit society. Giant 999 Steel Manufacturing Factory will contribute to the plans in watching of the task which will be the least of suffering from social affairs.

And the factory will use the CSR fund for health, social and welfare program of employees.

Giant 999 Steel Manufacturing Factory is already engaged with many activities under various sectors such as educational, public health, religion, regional development as well as welfare activities, and will continue the activities with updated mechanisms.



- (၁) 2017 ခုနှစ်၊ ဩဂုတ်လ ၁၉ ရက် အခြေခံပညာ ဦးစီးဌာန၊ ရန်ကုန်တိုင်းဒေသကြီး၊ အခြေခံပညာမူလတန်းကျောင်း မြောင်းတကာစက်မှုဇုန် မှော်ဘီ၊ အခြေခံပညာ မူလတန်းကျောင်းဆောင်သစ် အတွက် အလှူငွေ ကျပ်သိန်းကိုးဆယ်တိတိ (9,000,000)
- (၂) 2017 ခုနှစ်၊ ဖေဖော်ဝါရီလ 27 ရက် အလုပ်သမား၊ လူဝင်မှုကြီးကြပ်ရေး နှင့် ပြည်သူ့အင်အားဝန်ကြီးဌာန၊ လူဝင်မှု ကြီးကြပ်ရေး နှင့် ပြည်သူ့အင်အား ဆိုင်ရာ မှော်ဘီမြို့နယ်ဦးစီးမှူးရုံး သို့ မီးအားမြှင့်စက် (၁) လုံး
- (၃) 2017 ခုနှစ်၊ ဖေဖော်ဝါရီလ (၁) ရက် အလုပ်သမား၊ လူဝင်မှုကြီးကြပ်ရေးနှင့် ပြည်သူ့အင်အားဝန်ကြီးဌာန၊ လူဝင်မှုကြီးကြပ်ရေး နှင့် ပြည်သူ့အင်အားဆိုင်ရာ မှော်ဘီမြို့နယ် ဦးစီးမှူးရုံး ပတ်ဝန်းကျင် ပြုပြင်ရေးအတွက် အလူငွေ တစ်သိန်းကျပ် (100,000)
- (၄) 2019 ခုနှစ်၊ စက်တင်ဘာလ (၂၃) ရက် ကမာဖွံ့ဖြိုးရေး ပရဟိတဂေဟာ၊ ကျောက်တန်းမြို့နယ်၊ ကမာကလုပ်စံပြကျေးရွာ သို့ အလှူငွေ နှစ်သိန်းငါးထောင်ကျပ် ( 205,000)
- (၅) 2019 ခုနှစ်၊ ဩဂုတ်လ (၂) ရက် ကရင်ပြည်နယ်၊ မွန်ပြည်နယ် ရေဘေးသင့် ပြည်သူများ အတွက် အလှူငွေ တစ်ဆယ့်ငါးသိန်းကျပ် (1,500,000)



#### 9.9 TRAINING, AWARENESS AND COMPETENCY

Operation Manager together with Environmental Management Team shall identify potential environmental, occupational health and safety risks and impacts associated with the production processes and implement training needs for the staff.

A training need is to be developed for each position to ensure all personnel receive appropriate training to enable them to competently perform their role. Competency assessment shall be conducted to all employees after training completed.

Individual roles directly associated with significant safety and health risks and environmental impact will be reviewed by respective Manager and training needs identified. Plant Manager and HSE representative are responsible for updating training in relation to newly identified safety and health risks and environmental aspects as well as quality management system.

**Table 9.12 Training Program** 


Sr.	Topic of Training	Frequency	Responsibility Party
1	Firefighting Training	Annually	Township Fire Departmt
2	Training for PPE	Monthly	HSE Representative
3	Awareness Training for Personal Hygiene	Monthly	HSE Representative
4	Training for Handling Hazardous Material	As Required	Supervisor
5	Training for Electricital Handling and Safety	Quarterly	EMT Member/Electrician
6	Capacity Building Training	As Required	Supervisor







**Figure 9.4 Photo Records of Fire Fighting Training** 







#### Safely Handling of Hazardous Material





#### Capacity Building Training



Figure 9.5 Photo Records of Training



#### 9.10 COMMITMENT

"ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံသည် ရန်ကုန်တိုင်း ဒေသကြီး၊ မှော်ဘီမြို့နယ်၊ မြောင်းတကာစက်မှုဇုန်၊ အကွက်အမှတ် (၂၀/၂၁) တွင် သံရည်ကျိုလုပ်ငန်း လုပ်ကိုင်ပြီး U Beam and Angle Bar များကိုအဓိက ထုတ်လုပ်ပါသည်။ သံရည်ကျိုလုပ်ငန်း လုပ်ကိုင်ရာတွင် ဖြစ်ပေါ်လာနိုင်သည့် သက်ရောက်မှုများကို လူမှုဝန်းကျင်အား ထိခိုက်မှု မရှိစေရေးအတွက် အစီအမံများ ချမှတ်ဆောင်ရွက်မည် ဖြစ်ပါသည်။

ပတ်ဝန်းကျင်နှင့်လူမှုဆိုင်ရာ စီမံခန့်ခွဲမှု အစီအစဥ် (EMP) ပါ အစီအစဉ်ခွဲတွင်ဖော်ပြထားသော Health and Safety Methods များနှင့် Occupational preventive measure များကို အမှန်တကယ် လိုက်နာ ဆောင်ရွက်မည် ဖြစ်ပါသည်။

ပတ်ဝန်းကျင်နှင့်လူမှုဆိုင်ရာ စီမံခန့်ခွဲမှု အစီအစဥ် (EMP) တွင် ပါရှိသည့် ပတ်ဝန်းကျင် ထိခိုက်မှု လျော့ပါးစေရေး လုပ်ငန်းများနှင့်ထိန်းချုပ်ရေးနည်းလမ်းများ၊ စောင့်ကြပ်ကြည့်ရှုခြင်း လုပ်ငန်းများကို တိကျစွာ အကောင်အထည်ဖော် ဆောင်ရွက် မည်ဖြစ်ပါကြောင်း ကတိကဝတ် ပြုအပ်ပါသည်။



#### 10.0 ENVIRONMENTAL MONITORING PLAN

#### 10.1 OBJECTIVES

The objective of environmental monitoring is to systematically collect environmental data and support information needed for evaluation of the environmental performance. The frequency and methods of data collection must ensure that the data obtained are reliable and meaningful, i.e. they will adequately reflect the project environmental performance. A proposed environmental monitoring program must be practical, relevant and cost effective.

Environmental monitoring is a very important aspect of environmental management during construction, operation and decommissions stages of the project to safeguard the environment. A chemical or process industry in general produces solid, liquid and gaseous wastes, which are discharged to the environment. The waste product may contain pollutants which may harm environment. It is the responsibility of the industries to prevent or minimize the discharges of waste products by adopting suitable control measures in the factory. The effectiveness of such measures is ascertained by systematic monitoring of discharges at factory level and at receiving level.

#### 10.2 REGULATORY REQUIREMENT

#### **Environmental Standards**

Ministry of Natural Resources and Environmental Conservation - MONREC (former Ministry of Environmental Conservation and Forestry - MOECAF) issued National Environmental Quality (Emission) Guidelines, NEQGs, in December 2015 according to the provision of Paragraph (42), Sub-paragraph (b) of the Environmental Conservation Law (2012).



#### **Governing Parameters**

Table 10.1 Environmental and Social Monitoring Parameters

Sr.	Items	Parameters				
1	Air Quality	SO <sub>2</sub> , NO <sub>2</sub> , CO, PM <sub>2.5</sub> , PM <sub>10</sub> , dusts and O <sub>3</sub>				
		concentrations of National Emission guidelines,				
		2015 December				
2	Noise	Acceptable noise levels of National Emission				
		guidelines, 2015 December				
3	Water Quality	WHO Drinking water Quality Guidelines				
		pH, Colour, Turbidity, Hardness, Iron, Chloride,				
		Conductivity, Salinity,				
		Concentration of BOD, COD				
4	Waste	Waste recycle plan, removed from on-site at regular				
		intervals.				
5	Health and Safety	Medical kit box, fire evacuation, emergency plan,				
		PPE.				
6	Socio-economic	Job availability, providing skill enhancement				
	situation	training, CSR				

#### 10.3 IMPLEMENTATION OF MONITORING AND BUDGET

Overall budget for the implementation of environmental management and monitoring activities will be kyats 11,000,000/year and described detail in the following tables.

Environmental Management Team will inform about the top management getting more budget allocation if the environmental financial arrangement is insufficient. The top management will ensure to provide necessary financial assistant for EMP.

Table 10.2 Budget Allocation for Monitoring Plan

Sr.	Description	Annually Estimated Budget (Kyats)	Remark
1	Monitoring Plan for Construction Phase	4,090,000	Section:10.5,
2	Monitoring Plan for Operation Phase	5,120,000	Section:10.6,
3	Monitoring Plan for Decommissioning Phase	1,790,000	Section:10.7,
	Total	11,000,000	



#### 10.4 REPORT TEAM AND REPORTING

The project proponent will also be responsible for the implementation of monitoring, summarization of monitoring results. The project proponent will submit the monitoring report to the Ministry of Natural Resources and Environmental Conservation (MONREC) at once per six months interval through the local Environmental Conservation Department (ECD).

Giant 999 Steel Manufacturing Factory develops the report supported team.

#### Report Supported Team (RST)

Report supported team is developed as follows:

d) A representative from EMT — Team Leader

e) A representative from Admin – Team Member

f) A representative from HR — Team Member

Table 10.3 Roles and Responsibilities of Report Supported Team

POSITION	RESPONSIBILITIES	CONTACT DETAILS
Team Leader	<ul> <li>Reporting to top management on the key performances and monitoring of environmental and social issues for review, including recommendation for improvements.</li> <li>Represent the company in reporting the environmental and safety issues to the governmental department and other agencies concerned.</li> <li>Report submission to local Environmental Conservation Department (ECD), through the company.</li> </ul>	
Team member	Record of the monitoring results in files.	



• Develop the monitoring report with related	
documents.	

# 10.5 ENVIRONMENTAL MONITORING PLAN FOR CONSTRUCTION PHASE

The environmental monitoring plan including monitoring items and locations in the Construction phases is shown in Table 10.4. Monitoring for the construction phase will be implemented by project proponent and the contractors.

Table 10.4 Proposed Environmental Monitoring Programmes – Construction Phase

Tuble 10:11110poseu	Table 10.4 Proposed Environmental Monitoring Programmes – Construction Phase						
Environmental Issues	Monitoring Location and Indicator	Monitoring and Reporting Frequency	Cost Estimate (Kyats) Per Year	Responsibility Party			
	A	Air Pollution					
Env.Standard	National Environm	ental Quality (Em	ission) Guideline fo	or Air Emission			
Parameters	SO <sub>2</sub> , NO <sub>2</sub> , CO, PM <sub>2</sub> .	5, PM10, dusts and	O <sub>3</sub>				
Ambient air quality	Suitable point on site (1 point)	On-site measurement (one time)	750,000	Project proponent/ Contractor			
Dust Situation	Project area (1 Point)	Visual check	-	Contractor			
		Noise					
Env.Standard	National Environm	ental Quality (Em	ission) Guideline				
Parameters	Acceptable noise le	vels (dB)					
Noise level	Suitable points on site [dB(A)]	On-site measurement (one time)	140,000	Project proponent/ Contractor			
Water Quality							
Env.Standard	Env.Standard WHO Drinking water Quality Guidelines						
Parameters	-pH, Colour, Turbio Dissolved Oxygen,	•		activity, Salinity, TSS,			
Water Quality	Tube well for site use	Quarterly	400,000	Project proponent/ Contractor			



Status of maintenance of septic tank	-WHO drinking water standards – 2011 (Turbidity and pH, DO, BOD, Oil & Grease, etc.) Project site	Remove As required	1,000,000	Contractor
	w	aste Disposal		
Parameters	Waste recycle plan,	removed from on	-site at regular inte	rvals.
Solid waste	Project area  Hazardous waste/ Nonhazardous waste/ Domestic waste (waste reduction plan)	Weekly -Visual check and record amount	600,000	Contractor
	Occupation	nal, Health and	l Safety	
Parameters	Statistic of accidents	s and injuries.		
OHS	Project area Record of accidents -Providing PPE	Monthly	1,200,000	Contractor



# 10.6 ENVIRONMENTAL MONITORING PLAN FOR OPERATION PHASE

The environmental monitoring plan including monitoring items and locations in the operation is shown in Table 10.5.

Table 10.5 Proposed Environmental Monitoring Programmes - Operation Phase

Environmental Issues	Monitoring Location	Point of Compliance	Monitoring and Reporting Frequency	Annual Budget (Kyats)	Responsibility Party		
	Air Pollution						
Env.Standard	National Envir	onmental Quality (	Emission) Guidel	ine for Air E	mission		
Parameters	SO2, NO2, CO,	, PM2.5, PM10, dus	ts and O3 concent	trations			
Ambient Air Quality	Near Factory Gate	14° 36' 56.3" N 98° 04' 30.2" E	Twice a year	1200000 (600000x 2) (Monito ring fees)	EMT Team  HSE Representative External Consultant firm		
		Noise					
Env.Standard	National Envir	onmental Quality (	Emission) Guidel	ine			
Parameters	Leq (dB(A))						
Noise level dB(A)	Near Factory Gate	14° 36' 56.3" N 98° 04' 30.2" E	Twice a year	100000 (50000x2)	EMT Team  HSE Representative  External Consultant firm		



	Water Quality							
Env.Standard	WHO Drinking	WHO Drinking water Quality Guidelines						
Parameters  (Underground  Water Quality)  -Temperature, pH, Colour, Conductivity, Total Dissolved Solid, Total Hardness, Total Alkalinity, Sodium, Calcium, Magnesium, Potassium, Iron, Chloride, Sulphate, Bicarbonate, Carbonate, Hydroxide,								
(Drain water Quality)		ygen, Biochemical ( d solids, Oil and Gr	, 0	, Chemical O	xygen Demand,			
Underground Water Quality	Factory Tube Well (Tap Water)	17° 10.457′N 095° 58.889′ E	Twice a year	360000 (180,000x	EMT Team  HSE  Representative			
Wastewater Quality (Drain water)	Drainage outlet	17° 10.409′ N 95° 58.969′E	Twice a year	(labora tory tests fees)	External Laboratory for water quality tests			
	Solid W	aste generation fro	m Production Pr	rocess				
Parameters		f waste, storage, rec		•	l			
Non- Hazardous Waste	- Cleanliness	The whole factory	Daily	No Extra Cost	Cleaner			
	- Inspect waste storage areas ( Visual check)	17° 10′ 27.9′′ N 95° 58′ 53.2′′E	Daily	-	Supervisor			
Remove regularly to final disposal point in Industrial Zone    Remove regularly to final disposal point in Industrial Zone   Designated disposal point in Industrial Zone   Weekly   960,000   Supervisor   Township Municipal   Municipal   Municipal   Point in Industrial   Point in Indust					•			
Hazardous Waste	-Inspect storage area	-	Weekly	No Extra Cost	HSE personnel			
(eg. Sludge waste from	(Visual check)				Supervisor			



septic tank, Spent oils)	-Disposed sludge waste from septic tank	-	Biannually	1,000,000	
		Health and	Safety		
Parameters	- Medical kit b	ox, fire evacuation,	emergency plan,	PPE, safety s	signs.
Safety Measures for Health Status	•	compliance with Health and Safety irst Aid box)	Monthly inspection for health and safety at work place	-	Supervisor
Fire Safety Measures	-Firefighting tr	aining and drill	Annually	500,000	HSE personnel EMT Team
Emergency Safety Measure	First Aid Train	ing	Annually	500,000	HSE personnel EMT Team
	Providing PPE		Monthly	500,000	



# 10.7 ENVIRONMENTAL MONITORING PLAN FOR DECOMMISSIONING PHASE

The environmental monitoring plan including monitoring items and locations in the decommissioning phases is shown in Table 10.6. Monitoring for the decommissioning phase will be implemented by project proponent and the contractors.

Table 10.6 Proposed Environmental Monitoring Programmes – Decommissioning Phase

		1 Hase					
Environmental Issues	Monitoring Location and Indicator	Monitoring and Reporting Frequency	Cost Estimate (Kyats) Per Year	Responsibility Party			
	Air Pollution						
Env.Standard	National Environm	ental Quality (Emiss	sion) Guideline for	· Air Emission			
Parameters	SO <sub>2</sub> , NO <sub>2</sub> , CO, PM <sub>2</sub>	5, PM10, dusts and O	3				
Ambient air quality	Suitable points on site	Once after the decommissioning activities	750,000	Site Engineer Contractor			
		Noise					
Env.Standard	National Environm	ental Quality (Emiss	sion) Guideline				
Parameters	Acceptable noise le	vels (dB)					
Noise level dB(A)	Sensitive spots	Monthly	140,000	Site Engineer Contractor			
	V	Vaste Disposal					
Parameters	Waste recycle plan,	removed from on-s	ite at regular inter	vals.			
Demolition debris including concrete, metal, drywall, wood, glass, adhesives, sealants and fasteners	Disposal sites	Weekly	400,000	Site Engineer Contractor			
Occupational, Health and Safety							
Parameters	Statistic of accident	s and injuries.					
OHS	Project area -Providing PPE	Weekly	500,000	Site Engineer Contractor			



#### 11.0 CONCLUSIONS

This Environmental Management Plan (EMP) was carried out for the Giant 999 Steel 999 Giant Steel Manufacturing Factory which manufactures steel products in Myaung Dagar Industrial Zone, Hmawbi Township, Yangon Region, Myanmar.

Baseline monitoring of ambient air quality, underground water quality, soil pH, noise level demonstrated that all monitoring results are within the National Emission Standards and acceptable levels.

In accordance with the assessment data in the report for the Giant 999 Steel Manufacturing Factory, a few potential environmental impacts are identified.

In accordance with the assessment data, the impacts on ambient air quality are generated from the use of furnace, using generator and exhaust gases from the trucks and cars. The furnace is equipped with the effective de-dust controller system. Generator and all vehicles are regularly inspected and maintained to reduce the exhaust gas emissions.

Most activities of the steel industry produce metal scraps and other solid wastes. Giant 999 Steel Manufacturing Factory establishes and implements comprehensive waste management plan and applies 3R management. All reusable wastes such as metal wastes are recycled or reused in the operation.

The factory identifies potential occupational health and safety hazards and risks to the workers and community. The control and mitigation measures for identified hazards and risks are provided. Workers are trained to prevent and provide awareness of potential hazards and risks associated with the operations.

During public consultation, respondents were positive on the project for the operation of factory and major concern was health care for employees.

During the Project assessment process, over 50 employees are local people. Local employment is the main socio-economic benefit that the factory can directly bring to people living in the community nearest to the factory.

The provision of effective environmental management and monitoring plans by the factory will mitigate the potential environmental and social impacts. In general,



environmental impacts from solid wastes and water and soil pollutions are considerably low as metal wates are reused and recycled. Chemicals are stored in room with MSDS.

It is recommended to make the regular maintenance and inspection of the furnace and other impact and risk control devices and equipment. Metal wastes and other wastes are regularly collected and disposed properly.

Based on the overall impact assessment of the Giant 999 Steel Manufacturing Factory operation, it can be concluded that the factory creates more positive impacts for the local employment with over 50 local employees. The negative impacts on the environment generated by the plant activities can be manageable.

The factory should therefore be licensed to operate based on implementation and adherence to the environmental management plan proposed in this report.



#### 12.0 LIST OF COMMITMENT

Project proponent is commitment to comply with the existing environmental rules and regulations and criteria laid down by the Ministry of Natural Resources and Environmental Conservation.

**Table 12.1 Project Key Commitments** 

ကတိကဝတ်၏အတိုချုပ်	အမှတ်စဥ်	ကတိကဝတ်အား ရှင်းလင်း ဖော်ပြချက်	အစီရင်ခံစၥပါ ညွှန်းချက် (အခန်း)
EMP Executive Summary	1	The project owner shall use the best available technology for potential impact such as de-dust control measures for the dust emission.	Chapter 1.0 Section 1.5.1
Legal Requirement	2	Giant 999 Steel Factory will follow strictly the applicable legislation, rules and guidelines laid down by MONREC, and the local and international relevant laws, guidelines, and procedure while implementing environmental and social management plans.	Chapter 4.0 Section 4.1
	3	The project proponent shall comply with the disciplines described in the permit and licences required.	Chapter 4.0 Section 4.3



	4	Project proponent shall comply with the law, rules and regulations which	Chapter 4.0
		related with the project activities and the regulations issued by the	Section 4.3
		Industrial Zone Management.	
Project Description	5	Factory practises reducing and recycling of waste management.	Chapter 5.0
(SOLID WASTE)			Section 5.12.1
Baseline Environmental	6	National Air Emission standards values shall be applied to ensure that	Chapter 6.0
and Social Quality		air emission conform to good practice.	Section 6.11.2
(AIR QUALITY)			
Environmental and	7	The factory management including the factory Manager shall conduct	Chapter 7.0
Social Impact		regular environmental, health and safety inspections within the factory	Section 7.7.7.2
Assessment and		to maintain and improve environmental, health and safety	
Mitigation Measures		performances.	
(OCCUPATIONAL			
HAZARDS)			
Assessment and	8	Fire drill is conducted once per year.	Chapter 7.0
Mitigation Measures		Sufficient firefighting equipment is provided within the factory	Section 7.7.8.2
(EMERGENCY		premises.	
SITUATION)			
	9	Project proponent commits to apply and implement the safety methods	Chapter 7.0
		above mentioned and to provide the safety preventive measure such	Section 7.7.8.2
		as first-aid box, fire extinguishers and PPE for employees.	



## FACTORY

Stakeholder Engagements and Information Disclosure (STAKEHOLDER ENGAGEMENT)	10	Giant 999 Steel Manufacturing Factory commit to provide an opportunity to all the stakeholders and communities in the surrounding area as well as all employees to raise issues and concerns pertaining to the factory.	Chapter 8.0 Section 8.5
Environmental and Social Management Plan (ENVIRONMENTAL MANAGEMENT TEAM)	11	Giant 999 Steel Manufacturing Factory establishes the Environmental Management Team (EMT) for implementing environmental and social management and monitoring plan for the operation phase of the project.	Chapter 9.0 Section 9.1
Environmental and Social Management Plan (EMERGENCY RESPONSE TEAM)	12	Giant 999 Steel Manufacturing Factory has developed the Emergency Response Team (ERT) to fulfill the requirement of emergency and disaster response plan and to promote a safe working environment at the factory.	Chapter 9.0 Section 9.7.1
Environmental and Social Management Plan (EMERGENCY RESPONSE TEAM)	13	"ဧရာမ သံရည်ကျိုနှင့် သံနန်းဆွဲ လုပ်ငန်း" စက်ရုံသည် ရန်ကုန်တိုင်း ဒေသကြီး၊ မှော်ဘီမြို့နယ်၊ မြောင်းတကာစက်မှုဇုန်၊ အကွက်အမှတ် (၂၀/၂၁) တွင် သံရည်ကျိုလုပ်ငန်း လုပ်ကိုင်ပြီး U Beam and Angle Bar များကိုအဓိက ထုတ်လုပ်ပါသည်။ သံရည်ကျိုလုပ်ငန်း လုပ်ကိုင်ရာတွင် ဖြစ်ပေါ်လာနိုင်သည့် သက်ရောက်မှုများကို လူမှုဝန်းကျင်အား ထိခိုက်မှု မရှိစေရေးအတွက် အစီအမံများ ချမှတ်ဆောင်ရွက်မည် ဖြစ်ပါသည်။	Chapter 9.0 Section 9.10

**FACTORY** 



		ပတ်ဝန်းကျင်နှင့်လူမှုဆိုင်ရာ စီမံခန့်ခွဲမှု အစီအစဥ် (EMP) ပါ အစီအစဉ်ခွဲတွင်ဖော်ပြထားသော Health and Safety Methods များနှင့် Occupational preventive measure များကို အမှန်တကယ် လိုက်နာ ဆောင်ရွက်မည် ဖြစ်ပါသည်။ ပတ်ဝန်းကျင်နှင့်လူမှုဆိုင်ရာ စီမံခန့်ခွဲမှု အစီအစဉ် (EMP) တွင် ပါရှိသည့် ပတ်ဝန်းကျင် ထိခိုက်မှု လျော့ပါးစေရေး လုပ်ငန်းများနှင့်ထိန်းချုပ်ရေးနည်းလမ်းများ၊ စောင့်ကြပ်ကြည့်ရှုခြင်း လုပ်ငန်းများကို တိကျစွာ အကောင်အထည်ဖော် ဆောင်ရွက် မည်ဖြစ်ပါကြောင်း ကတိကဝတ် ပြုအပ်ပါသည်။	
Environmental Monitoring Plan (MONITORING REPORT)	14	The project proponent will submit the monitoring report to the Ministry of Natural Resources and Environmental Conservation (MONREC) at once per six months interval through the local Environmental Conservation Department (ECD).	Chapter 10.0 Section 10.4
Community Involvement and Development Program (CSR Fund)	15	Factory will make necessary arrangements to reserve 2% on excepted Net Profit as CSR Fund.	Chapter 9.0 Section 9.8
Training, Awareness and Competency (Implementing Training)	16	Operation Manager together with Environmental Management Team shall identify potential environmental, occupational health and safety risks and impacts associated with the production processes and implement training needs for the staff.	Chapter 9.0 Section 9.9

## **Environmental Management Plan Report**



# GIANT 999 STEEL MANUFACTURING FACTORY

Conclusion	17	The factory identifies potential occupational health and safety hazards and risks to the workers and community.	Chapter 11.0
Conclusion	18	The control and mitigation measures for identified hazards and risks are provided.	Chapter 11.0




## APPENDIX (A) PERMIT AND LICENSE

ရန်ကုန် ရန်ကုန်တိုင်းဒေသ (ရန်ကုန်တိုင်းဒေသ မော်ဘီမြို့	ညာမွတမြန်မာနိုင်ငံတော်အစိုးရ တိုင်းဒေသကြီးအစိုးရအဖွဲ့ ပင်္ကြီးစည်ပင်သာယာရေးဝန်ကြီးဌာန သေကြီးစည်ပင်သာယာရေးအဖွဲ့) နယ်စည်ပင်သာယာရေးအဖွဲ့ ရူးနှစ် တေးလန္တကုလာ လုပ်ငန်းလိုင်ခင်
၁။ လုပ်ငန်းပိုင်ရှင်အမည်	લ્કાર્જી મુજા જેટ દું
၂။ နိုင်ငံသားမှတ်ပုံတင်အမှတ်	1 1 mt 0, C/2 5 0 of 2013 0.
၃။ လုပ်ငန်းတည်ရှိသည့်နေရာ	
၄။ လုပ်ကိုင်ခွင့်ပြုသည့်လုပ်ငန်းအမျိုးအစား	
၅။ နှစ်စဉ်လိုင်စင်ကြေးငွေ	<u> </u>
၆။ ငွေပေးသွင်းသည့်ရက်စွဲ	
၇။ လိုင်စင်သက်တမ်းကုန်ဆုံးသည့်နေ့	<u> ಕರ್.೬. ಇರ್ರ್ಗ ರಾತಿಶ್ರಶಾ</u>
လိုက်နာ	ရန် စည်းကမ်းချက်များ
အလုပ်အကိုင်နှင့်ကူးသန်းရောင်းဝယ်ခြင်း ရောင်းချခြင်းဆိုင်ရာ စည်းကမ်း(Bye-Law များကို တိကျစွာ လိုက်နာရမည်။ ၃။ လိုင်စင်ရရှိသူသည် လုပ်ငန်းခွင်ဘေးအန္တရာ တိကျစွာ လိုက်နာရမည်။ ၄။ လိုင်စင်ရရှိသူသည် မိမိလုပ်ငန်းမှထွက်ရှိသ အမှိုက်ကင်းမဲ့ဇုံ စီမံချက်နှင့်အညီ စနစ်တင စီးပွားရေးအမှိုက်ခွန်ပေးသွင်း၍ အမှိုက်သိ ၅။ လိုင်စင်တွင် ရောင်းချဒွင့်ပြုထားသည့် ကုန် များက တားမြစ်သည့် ကုန်ပစ္စည်းများကို ဧ ပေးဆောင်ရမည်။ ၇။ လုပ်ငန်းရှင်များသည် ရှေ့လာမည့်ဘဏ္ဍာေ ကြိုတင်လျှောက်ထားရမည်။	ခြင်း၊ ပေးတမ်းခြင်း လုံးဝမပြုလုပ်ရ။ ဂးအန္တရာယ်ဖြစ်စေသည့် သို့မဟုတ် စက်ဆုပ်ရွံရှာဖွယ်ဖြစ်စေသည့် လုပ်ငန်းများ၊ စားသောက်ဖွယ်ရာများထုတ်လုပ်ခြင်း၊ တည်ခင်း လှပ်ငန်းများ၊ စားသောက်ဖွယ်ရာများထုတ်လုပ်ခြင်း၊ တည်ခင်း လှပ်များနှင့် အခါအားလျော်စွာ ထုတ်ပြန်သည့်အမိန့် ညွှန်ကြားချက် ယ်ကင်းရှင်းစေရန်နှင့် မီးဘေးကြံတင်ကာကွယ်ရေးအတွက် ကြံကင် ပည့် အမှိုက်သရိုက်၊ အညစ်အကြေးနှင့်ဓါတုဗေဒပစ္စည်းများအား ကျငွန့်ပစ်ရမည်။ လိုအပ်ပါက မြိုနယ်စည်ပင်သာယာရေးအဖွဲ့တွင် မီးယာဉ်အကူအညီ တောင်းခံရည်။ လစ္စည်းများကိုသာ ရောင်းချခွင့်ပြုသည်။ သက်ဆိုင်ရာအာဏာပိုင် ရောင်းချခြင်းမပြုရ။ လုပ်ငန်းအမျိုးအစားအလိုက် သတ်မှတ်သည့်နှုန်းထားအတိုင်း ရာနှစ်တွင် မိမိလုပ်ငန်းအား ဆက်လက်လုပ်ကိုင်လိုပါက အဖွဲ့ရုံးသို့ ကိုသိမ်းသည့်အခါ အဖွဲ့ရုံးသို့ ကြိုတင်အကြောင်းကြားရမည်။ ခြင်းမရှိပါက လိုင်စင်ကို ပြန်လည်ရုပ်သိမ်း၍ စည်ပင်သာယာရေး











### APPENDIX (B) WATER QUALITY



## Myanmar Water Engineering and Products Co., Ltd.

Tel +95 1 571694, +95 1 8564547 Ernail: <u>mwepmyanmar@gmail.com</u> www.facebook.com/mwep.myanmar

No. 15, Thu Mingalar Lane (1), Thu Mingalar Housing Estate, Thingangyun Township, Yangon.

#### WATER ANALYSIS RESULT FORM

Analysis Ref. No

: WR-081119

Source of Water

: Tubewell

Client

: Green EHSS

Receiving Date

: 04.11.2019

Address

: Giant 999 Steel Manufacturing

Analysis Date

: 06.11.2019

S/N	Parameters	Sample Result	WHO Standard	Unit
1	pH	7	6.5 - 8.5	S.U.a
2	Color	Clear	Clear	-
3	Conductivity (EC)	78.13	-	micro S/ cm
4	Total Dissolved Solid (TDS)	50	<250	mg/ L
5	Total Hardness (TH)	16	<16	mg/ L as CaCo <sub>3</sub>
6	Total Alkalinity (TA)	38	<250	mg/ L as CaCo <sub>3</sub>
7	Calcium (Ca <sup>++</sup> )	4.01	<8	mg/Las CaCo <sub>3</sub>
8	Magnesium (Mg <sup>++</sup> )	1.44	<8	mg/ L as CaCo <sub>3</sub>
9	Iron (Fe <sup>++</sup> )	0.02	<0.3	mg/ L
10	Chloride (Cl <sup>-</sup> )	17	<250	mg/ L
11	Bicarbonate (HCO <sub>3</sub> -)	38	<250	mg/ L as CaCo <sub>3</sub>
12	Carbonate (CO3 <sup>=</sup> )	ND	<250	mg/ L
	Remarks		Chemically Potable	

Analysis By : Thiri Nyi Nyi

Approved By : Win Kalaya

## **Environmental Management Plan Report**

## **GIANT 999 STEEL MANUFACTURING FACTORY**





#### Advanced Medical & Diagnostics Trading Ltd.

Yangon Office: Phone: Mandalay Office:

No. 20-A Ywar Lae Lane, Za-North Ward, Thingangyun Tsp, Yangon 01 571656, 01 565797, 09 73176248, 09 73112672

No. MA 28, 59th street, Bt. 41st and 42nd street, Ye' Mon Taung Ward, Ma Har Aung Myay Tsp, Mandalay

02-2848201, 2848202, 2848203, 2848204 www.amdmyanmar.com & amd@amdmyanmar.com Website & Email:



#### **WATER & WASTE WATER TREATMENT DIVISION**

GREEN EHSS Consultancy Co., Ltd.

Attention To

No.172, Building C-2 A, 11th Floor, Room (A/1112)

Botahtaung Township, Yangon.

Source of Water

: Giant 999 Steel

Analysis

: Drain Water Test

Date Attended to Lab : 4.11.2019 ed

Sr.	Item	Drainage Waste Water	YCDC Target range
1.	Dissolved Oxygen (DO)	3.6	> 1 ppm
2.	Biochemical Oxygen Demand (BOD <sub>5</sub> ) (5days at 20°C) (mg/L)	31.8	20-60 ppm
3.	Chemical Oxygen Demand (COD) (Adaptation of the USEPA 410.4 approved method) (mg/L)	54	< 200 ppm
4.	pH effluent water	6.97	6 <ph<9.6< td=""></ph<9.6<>
5.	Suspended solids (SS)	16	< 500 ppm
6.	Nitrate ( NO <sub>3</sub> N )	1.3	N/A

Remarks:

: Results valid for the received sample only.

Win Pyae Pyae Aung Laboratory In-Charge Water Treatment Division \*

Amd Trading Co.,Ltd



#### APPENDIX (C) MATERIAL SAFETY DATA SHEET

#### కింట్ MSDS

၁ အချက် - ဓါတုပစ္စည်းအကျဉ်းချုပ် မြန်မာအခေါ် အဝေါ် కియవి အင်္ဂလိပ်အခေါ် အဝေါ် Diesel fuel အဓိပ္ပါယ်တူ အင်္ဂလိဝ်စာလုံးများ Diesel Fuel Diesel Oil ၂ အချက် - ပါဝင်သည့်အရာများ အန္တာရာယ်ရှိ ဓါတုလျှပ်စစ်ပစ္စည်း သံလိုက်စွမ်းအား ပါဝင်မှုအနည်းငယ် Cas No : 68334-30-5 ၃ အချက် - အန္တာရာယ်ရှိနိုင်သည့် အကြောင်းအရင်း

ကျန်းမာရေးထိခိုက်နိုင်ခြင်း

အဓိကအားဖြင့် အရေပြားမှ တိုက်ရိုက်ထိတွေ့ပြီး ဒီဇယ်အား ဆုပ်ယူနိုင်သောကြောင့် ကျောက်ကပ် အသည်းအသန် ဖြစ်၍ ပျက်စီးသည်။ ထို့ အပြင် ဒီဇယ်ကြောင့် အရေပြားရောဂါ၊ အဆီအကျိတ်ပေါက်ခြင်း ဖြစ်နိုင်သည်။ ဓါတ်ငွေ့ နှင့် အရည်ကို ဖိအားပေးသွင်း ထားသောဘူး စသည်မှပန်းထွတ်လာသော အမှုန်အမွှားမှားကို ရှုသွင်းမိပါက အသည်းရောင်အသားဝါ ဖြစ်တတ်သည်။ မိခင်ဗိုက်အချင်းမှ တစ်ဆင့် သန္ဓေသား၏ သွေးထဲသို့ ဝင်ရောက်နိုင်သည်။ ထို့ပြင်လည်း ဒီဇယ်အငွေ့ အသက်သည် လူနှင့်ထိတွေ့ခဲ့ပါက မျက်လုံး၊ နှာခေါင်း စူးခြင်းနှင့် ခေါင်းမှုး ခေါင်း ကိုက်ခြင်း ဖြစ်စာတိပါသည်။

ပတ်ဝန်းကျင်ထိခိုက်မှု သဘာဝပတ်ဝန်းကျင်ကို အန္တာရာယ်ဖြစ်စေသည့်၊ ရေနှင့်လေထုသည် ညစ်ညမ်းမှုကို ဖြစ်ပေါ် စေသည်။ ပေါက်ကွဲမှုဘေးအန္တာရာယ် လောင်ကျွမ်း ပေါက်ကွဲလွယ်သော ပစ္စည်းဖြစ်သည်။ စူးရှပြင်းထန်မှု ရှိသည်။

၄ အချက် - အရေးပေါ် ကယ်ဆယ်မှု

အရေပြားနှင့်ထိသောအခါ ဒီဇယ်အစွန်းအထင်း ထိမိသော အထည်အား ချက်ခြင်းချွတ်ပစ်ရမည်၊ ဆပ်ပြာရည် (သို့မဟုတ်) ရေသန့်ဖြင့် ဒီဇယ်ထိတွေ့ မိသောအရေပြားအား စင်ကြယ်စွာဆေးကြောပါ။ လိုအပ်လျှင် ဆရာဝန်နှင့် ပြပါ။ မျက်လုံးထဲသို့ ဝင်သောအခါ

ဒီဇယ်ဝင်သော မျက်လုံး၏ မျက်ခွဲအား အပေါ်သို့ ဆွဲတင်ပါ။ ရေသန့် (သို့မဟုတ်) ဓာတ်ဆားနှင့် လောင်းဆေးပေးပါရန်။ လိုအပ်ပါက ဆရာဝန်နှင့်ပြပါ။ နှာခေါင်းထဲသို့ ရှုသွင်းမိသောအခါ

လေကောင်းလေသန့် ရှိရာသို့ လျှင်မြန်စွာသွားပါ။ အသက်ရှုလမ်းကြောင်း မပိတ်မိစေရန် နေထိုင်ပါ။



8

ဥပမာ အသက်ရှုကျပ်လျှင် အောက်စီဂျင်သွင်းပေးပါ။ အကယ်၍ လိုအပ်ပါက ဆရာဝန်နှင့် ပြပါ။ သောက်သုံးမိသောအခါ တတ်နိုင်သ၍ အမြန်ဆုံးအစာအိမ်ကို ဆေးကြောပစ်ရမည်။ ဆရာဝန်ထံပြသရမည်။ ၅ အချက် – မီးသတ်ရန်ပြင်ဆင်မှု အန္တာရာယ်ထူးခြားချက်

မီးတောက်မီးလျှံများသည် မြင့်မားသောအပူချိန် (သို့မဟုတ်) အောက်စီဂျင်နှင့်ထိတွေ့ခဲ့ပါက ပိုမိုလောင် ကျွန်းပေါက်ကွဲရန် လွယ်ကူပါသည်။ အကယ်၍မြင့်မားသော အပူချိန်နှင့်ထိတွေ့ခဲ့သောအခါ၊ အတွင်းအပူရှိန် ဖိအားများလာသောအခါ များတွင် ပေါက်ကွဲလောင်ကျွမ်းသည့် အန္တာရာယ်ရှိပါသည်။

အန္တာရာယ်ရှိလောင်ကျွမ်းပစ္စည်း

CO

ကာဗွန်ဒိုင်အောက်ဆိုဒ်

Carbon monoxide Carbon dioxide

Con

မီးငြိမ်းသတ်ရန်နည်းလမ်း

မီးသတ်သမားသည် အဆိပ်ကာမျက်နှာဖုံး တစ်ဆင်ရမည်။ တစ်ကိုယ်လုံး မီးသတ်ဝတ်စုံ ဆင်ယင်ထားပြီး မီးကိုကျွမ်းကျင်စွာငြိမ်းသတ်နိုင်ရမည်။ တတ်နိုင်သမျှ မီးလောင်လွယ်သည့် ပစ္စည်းများအား မီးလောင်ကျွမ်း ရာနေရာမှ ဖိအားရှိပစ္စည်းများ အရောင်ပြောင်းလဲလာလျှင် (သို့မဟုတ်) ဖိအားဖုံးမှ အသံထွက်ပေါ် လာသည့် အခါ ချက်ခြင်းနောက်ဆုတ် ထွက်ခွာရမည်။ မီးသတ်ဆေးဖျန်းသုံးရသည့် စပရေးအရည်၊ အမြုပ်၊ ခြောက်သွေ့သောအမှုန့်၊ ကာဗွန်ဒိုင်အောက်ဆိုဒ်နှင့် သဲမှုန့်။

၆ အချက် – အရေးပေါ် ဖြေရှင်းနည်းများ

အရေးပေါ် ဖြေရှင်းနည်း ဒုက္ခသည်များအား အမြန်ဆုံးလုံခြုံသည့် နေရာသို့ ရွှေ့ပြောင်းပေးပြီး လောင်ကျွမ်းရာနေရာသို့ ပြန်မ ဝင်မိ စေရန် ဒုက္ခသည်များအား သီးခြားစွာထားရှိပေးပါရန်။ အဓိက မီးလောင်ရာနေရာကို အပြီးပြိမ်း သတ်ပါ။ အရေးပေါ် ကယ်ဆယ်ရေးသမားများအား ကိုယ်၌အောက်စီဂျင်ပုံး တပ်ဆင်ပြီး စွပ်ထားပါရန်နှင့် မီးသတ် ဝတ်စုံဝတ်ဆင်ရန် အကြံပြုအပ်ပါသည်။ တတ်နိုင်သမျှ ကျွန်ရှိသေးသည့် မီးစများအား ပြိမ်းသတ် စေ လိုပါသည်။ ပိုလျှံနေသော ဒီဇယ်နှင့် ကျန်ရှိသေးသည့် မီးစများအတူတကွ ပိုက်လိုင်းများထဲသို့ စီးဝင်ခဲ့ပါက အန္တာရာယ်ပိုမို ကြီးမားသွားနိုင်သူဖြင့် ထိုသို့ မြေစ်စေရန် ပိုက်လိုင်းများကို ပိတ်ဆို့ထားရမည်။ အနည်းငယ် ယိုစိမ့်မှု

အယ်တစ်ဗိတ်ကာဗွန် (သို့ မဟုတ်) အခြားကြုံရာဝတ္ထု တစ်ခုခုဖြင့် စုပ်ယူရန်စွန့်ပစ်နိုင်ပါသည်။

ကြီးမားသော ယိုစီးမှု တိုင်ကီတစ်ခုတည်ဆောက်ပါ (သို့ မဟုတ်) မြေအောက်တွင် ကန်တစ်ခုတူး၍ သို လှောင်ပါရန်။ ပန် ဖြင့်သွယ်တန်း၍ လော်ရီကားထဲသို့ ရွှေ့ပြောင်းပြီး လုံခြုံရာသို့ ပို့ဆောင် သိမ်းသွင်းပြီး ပြန် လည်ဝယ်ယူ သိမ်းဆည်းသည့်ဌာန(သို့ မဟုတ်) အမှိုက်များရှို့ရန်နေရာသို့ သွားရောက်အသုံးဖြုပါ။

၇ အချက် - ထားသိုရန်နည်းလမ်းများ

ထားသိုရာတွင် ဂရုစိုက်ရမည့်အချက်များ စီမံရာတွင် အလုံပိတ်ပါ လေဝင်လေထွက် ဂရုစိုက်ပါ။ ဆောင်ရွက်သူသည် ကျွမ်းကျင်သင်တန်း ဆင်းထား သူ ဖြစ်ရပြီး ကျွမ်းကျင်စွာဖြင့် စနစ်တကျ ဆောင်ရွက်တတ်သူ ဖြစ်ရမည်။ လုပ်ငန်းဆောင်ရွက် သူများ အဆိပ် ကာမျက်နှာဖုံးစွပ်ရန် အကြံပြုသည်။ သိပ္ပံနည်းကျ တီထွင်ထားသော မျက်လုံးကာကွယ် နိုင်သည့် မျက်မှန် တပ်ဆင်ရမည်။ ဆီများကို ကာကွယ်နိုင်သည့် ရာဘာလက်အိတ်များစွတ်ပါ။ မီးစ၊ မီးပွား၊ များကိုဝေးဝေး ရှောင်ပါ။ လုပ်ငန်းခွင်အတွင်း ဆေးလိပ်မသောက်ကြပါရန်။ ပေါက်ကွဲမှုကို ကာကွယ်နိုင်သည့်



2

စက်ပစ္စည်းမွားသာ သုံးပါ။ လေဝင်လေထွက် ကောင်းမွန်အောင် ထိန်းသိမ်းပါ။ အပူငွေ့များ လုဝ်ငန်းခွင် လေထုထဲသို့ မပြန့်ပွားအောင် ထိန်းသိမ်းကာကွယ်ပါ။ အောက်စိတန့် ခါတ်များနှင့် ထိတွေ့ စေခြင်းမှ ရှောင်ကျဉ်ပါ။ ပုံးထဲသို့ဖြည့်စွတ် သိမ်းဆည်းရာတွင် အရှိန်ကိုဂရုစိုက်ရမည်။ လျှစ်စစ်ခါတ်ငြိမ်များ စုစည်းမှ မြေစိရန်လည်း ကာကွယ်ရမည်။ ရွှေပြောင်းရာတွင် ညင်သာစွာမပြီး ဖြည်းညင်းစွာချပါ။ ပါကင်ပုံးများ ပျေက်စီးအောင်လည်း ကာကွယ်ရမည်။ အနီးတဝိုက်တွင် သင့်လျှော်သည့် မီးသတ်ဆေးပူးများ အရေအတွက် မှန်ကန်စွာ ထားရှိပေးထားသင့်သည်။ ဒီဇယ်ပုံးအလွတ်များတွင်လည်း အန္တာရာယ်ကျန်ရှိ ပစ္စည်းများ ကျန်ရှိ နိုင်ခြေ ရှိသည်။

သိုလှောင်စုဆောင်းရာတွင် ဂရုစိုက်ရမည့်အချက်များ

လေဝင်လေထွက်ကောင်းမွန်ပြီး အေးမြသောနေရာတွင် ထားပါ။ ဖီးပွား၊ ဖီးစများနှင့်ဝေးကွာသော နေရာ တွင်ထားပါ။ အောက်စိတန့် ဝါတ်နှင့် ဟယ်လိုဂျင်ဓာတ်နှစ်မျိုးအား ခွဲခြားသိုလှောင်ရမည် ရေယှက်သိုလှောင် ခြင်းမပြုရပါ။ နေရောင်ခြည်နှင့်ဝေးရာတွင် ထားရှိရမည်။ အနီးတစ်ဝိုက်တွင် ဖီးမှုန်မီးပွားများ ထတတ်သည့် ကိရိယာများ အသုံးမပြုရပါ။ ထားသိုရာတွင် အရေးပေါ် အသုံးပြုနိုင်ရန် ပစ္စည်းထားရှိသင့်ပြီး စတိုခန်း တည်ဆောက်ရာတွင် လောင်ကျွမ်းလွယ်သော ကုန်တြမ်းများအသုံးပြုခြင်းမှ ရှောင်ကြဉ်သင့်သည်။

၈ အချက် – ထိတွေ့ ရသူများအတွက် ကာကွယ်ချက် လုပ်ငန်းကာကွယ်မှု အလုံပိတ်ထားရှိရန်နှင့် လေဟာခြင်းဂရုပြုရန်။ အသတ်ရှုလမ်းကြောင်း ကာကွယ်မှု လေထုထဲမှ ဓာတ်ငွေ့ ထူထပ်မှု စံနှုန်းကျော်လွန်လာသောအခါ အဆိပ်ကာမျက်နှာဖုံးစွပ်ရန် အကြံ ပြုသည်။ အနေပေါ် ထွက်ခွာလျှင် (သို့ မဟုတ်) အရေပေါ် ကယ်ဆယ်သောအခါတွင် အောက်ဆီဂျင် မျက်လုံးအပေါ် တာကွယ်မှု သိပ္ပံနည်းကျ တီထွင်ထားသော မျက်လုံးကာမျက်မှန်တပ်ဆင်ရမည်။ ကိုယ်ခန္ဓာ ကာကွယ်မှု မီးကာကွယ်ရေးဝတ်စုံ ဝတ်ရန်။ လက်အတွက် ကာကွယ်မှု ဆီကာကွယ်နိုင်သည့် ရာဘာလက်အိတ် အထွေထွေ ကာကွယ်မှု လုပ်ငန်းခွင်တွင် ဆေးလိပ်မသောက်ရန်နှင့် အထပ်အထပ်အခါခါ ဆီနှင့် ထိတွေ့ခြင်းမှ ရှောင်ကျဉ်ရန်။ ၉ အချက် – ဓါတုဗေဒပစ္စည်း၏ ထူးခြားချက် ၄င်း၏အပြင်ပန်းပုံစံ အနဲငယ်စီးကဝ်ကဝ်ဖြစ်ပြီး ကော်ဖီရောင်အနဲငယ်သန်းခြင်း။ ပျော်ကျသည့် ဒီဂရီယူနစ် ၁၈ဒီဂရီ ပွက်ပွက်ဆူသည့် ဒီဂရီယူနစ် ၂၈၂-၃၃၈ ဒီဂရီ ထူဖျစ်မှုယူနစ်(ရေ = ၁) ၀. ၈၇-၀. ၉ လင်းလက်မှုဒီဂရိယူနစ်



4 လောင်ကျွမ်းစေသည့် ဒီဂရိယူနစ် အဓိကအသုံးပြုရန်နေရာ ဒီဇယ်သုံးစက်တွင် လောင်စာဆီအဖြစ် အသုံးပြုသည်။ ၁၀ အချက် - တည်ငြိမ်မှုနှင့် ၄င်း၏ပုန်ကန်မှု တွဲဖက်ထား၍မရသည့် အရာများ အင်တီအောက်စိတန့် ဓာတ်နှင့် ဟယ်လိုဂျင်ခြပ်ပေါင်း ၁၁ အချက် - ပြင်းထန်သောအဆိပ်ဓါတ် LD 50 : အချက်အလက်မရှိသေး LC 50: အချက်အလက်မရှိသေး ၁၂ အချက် - ဂေဟဗေဒပညာအချက်အလက် အခြားအန္တာရာယ်ရှိသောအပိုင်း ၄င်းပစ္စည်းများသည် ပတ်ဝန်းကျင်ကို ထိခိုက်နိုင်သည့်အတွက် မြေကြီးထဲသို့ တိုက်ရိုက်မသွန်ပစ်ရန် အကြံပြုအပ်ပါသည်။ ရေနှင့်အိုဇုန်းလွှာများကိုလည်း ထိခိုက်စေရုံသာမက ရေနေသတ္တဝါများကိုလည်း ထိ ခိုက်ပျက်စီးစေပါသည်။ အထူးသဖြင့် ရေညှိများအပေါ် အထူးဂရုပြုသင့်သည်။ ၁၃ အချက် - စွန့်ပစ်ရန်စနစ် စွန့် ပစ်ရန်နည်းလမ်း စွန့်မပစ်မှီ နိုင်ငံတော်မှ လောင်စာများအပေါ် ချမှတ်ထားသောဥပဒေအား ရှေးဦစွာလေ့လာထားသင့် သည်။ ဖျက်ဆီးမည်ဆိုပါက လောင်ကျွမ်းဖျက်စီးသည့်နည်းကို အသုံးပြုရန် အကြံပြုသည်။ ၁၄ အချက် - သယ်ယူပို့ဆောင်ရန်အချက်အလက် အန္တာရာယ်ရှိပစ္စည်းအမှတ်စဉ် အချက်အလက်မရှိ ပါကင်အမျိုးအစား **ZO1** ပါကင်ထုပ်နည်း အချက်အလက်မရှိ သယ်ယူပို့ဆောင်ရာတွင် ဂရုပြုရမည့်အချက်များ မပို့ဆောင်မှီပါကင်နှင့် ၎င်းအတွင်းရှိပစ္စည်းများအား သေချာစစ်ဆေးပါ။ အလုံပိတ်ပါ။ သယ်ယူပို့ဆောင်ရာတွင် ယိုဆိမ့်မှုမရှိခြင်း၊ ဘေးမကျခြင်း၊ မပြုကျခြင်း၊ မပျက်စီးခြင်း စသည့်အချက်အလက် များကိုအာမခံရမည်။ သယ်ယူပို့ဆောင်ရာတွင် အသုံးပြုသည့်ကားသည် ၄င်းလောင်စာအမျိုးအစားနှင့် တင် နိုင်သည့် ကားဖြစ်ပြီး မီးသတ်ဆေးဗူးများ ကားပေါ် တွင် အသင့်ရှိနေရမည်။ နွေရာသီတွင် ညကားဖြင့် သယ်ယူပို့ဆောင်ပါက အကောင်းဆုံးဖြစ်ပါသည်။ ညတွင်သယ်ယူပို့ဆောင်ရာတွင် ကရိန်းကားနှင့် ပန့်များ ဖြင့် သေချာစွာ လုဝ်ဆောင်ပါ ခံပြားများဖြင့် သေချာဆက်နွယ်ကြားခံထားမှသာလျှင် တုန်ခါမှုကို လျော့ချနိုင် ပြီး လျှပ်စစ်ငြိမ်ဖြစ်ပေါ် မှုကို လျော့ချနိုင်မည် ဖြစ်သည်။ အောက်စီတန့် ဓါတ်နှင့် ဟိယ်လိုဂျင်ဓါတ်ပေါင်းကဲ့သို့ သော ဓါတ္ပပစ္စည်းရောစပိမှုများ မဖြစ်စေရန် ဂရုပြုရမည်။ သယ်ယူပို့ဆောင် ကာလအတွင်း ဒီဇယ်များအား နေပူလှမ်းခြင်း၊ မိုးရေစိုခြင်း၊ အပူထီခြင်းများမှ ကာကွယ်ရမည်။ လမ်ခရီးတစ်ဝက်တွင် အနားယူမည် ဆိုလျှင် လည်း မီးပွားမီးစနှင့် အပူရှိန်မြင့်ဧရိယာနှင့် ကင်းဝေးနေရမည်။ ၄င်းလောင်စာများ၏ အိတ်ဇောပိုက်များတွင်



#### MATERIAL SAFETY DATA SHEET

အမည် Trade Name : Engine Oil စက်ဆီ

အန္တရာယ်သင့်စေသည့်အကြောင်း Hazard Rating: ကျမ်းမာရေးနှင့် မသင့်လျော် Health

အမျိုးအစား Form : အရည် Liquid

ထင်ရှားသည့် အသွင်အပြင်/အရောင် Appearance/Colour: အဝါနုရောင် Light Yellow CLEAR

အနံ Odor: အနံမရှိ Odorless

မီးငြိမ်းသတ်ရမည့် ပစ္စည်း Extinguishing Media: မီးသတ်ဆေးဗူး Dry chemical

- အရည်ပြားထိခိုက်နိုင်မှု Skin contact: အရည်ပြားနှင့် အချိန်ကြာကြာ ထိတွေ့မိပါက ပူ လောင်ယားယ့နိုင်ပါသည်။ Prolonged or repeated contact can cause moderate irritation, defatting, and dermatitis.
- မျက်လုံးထဲဝင်ပါက Eye contact: မျက်လုံးယားယံခြင်း၊ ပူလောင်ခြင်း၊ နီခြင်း၊ အမြင်အာရုံ မှုန်ဝါးခြင်း can cause severe irritation, redness, tearing, and blurred vision.
- ခန္တာကိုယ်အတွင်းဝင်ပါက Ingestion : အစာအိမ်နှင့် အူလမ်းကြောင်းထိခိုက်နိုင်ခြင်း ဖြစ်ပွားနိုင်ပါသည်။ can cause gastrointestinal irritation, nausea, vomiting, and the lungs can cause chemical pneumonitis which can be fatal.
- အရေးပေါ်နှင့် ရှေးဦးသူနာပြုဆိုင်ရာ လုပ်ထုံးလုပ်နည်းများ Emergency and first aid procedures: မျက်လုံးထဲဝင်ပါက ၁၅ မိနစ်ကြာသည်အထိ ရေနှင့် ဆက်တိုက် ဖြန်း ပေးရမည်။ eyes flush thoroughly with running water for 15 minutes, including under eyelids. Get medical attention.
- အရည်ပြားထိခိုက်မိပါက Skin: အရည်ပြားထိခိုက်မိပါက ရေဖြင့်ဆေးပါ ဆေးကုသမှုခံယူပါ။ promptly remove contaminated clothing and wash affected areas thoroughly with soap and water. If irritation occurs get medical attention. Wash contaminated clothing thoroughly before re-use.
- ရှရှိုက်မိပါက Inhalation: အနံ့ရှိသောနေရာမှ ချက်ခြင်းဖယ်ရှားပြီး လေဝင်လေထွက် ကောင်းမွန်သော နေရာသို့ ခေါ်ဆောင်၍ နွေးထွေးအောင်ထားပြီးဆေးကုသမှုခံယူပါ။



## အန္တရာယ်ကင်းရှင်းမှု အဆင့်မှတ်တမ်း/ MSDS

## **Ferrosilicon**

စာမျက်နှာ 1/5

#### ၁. ထုတ်ကုန်ပစ္စည်းအမျိုးအမည် နှင့် ပေးသွင်းသူ၏ အချက်အလက်ဖော်ပြချက်

ထုတ်ကုန်အမည် Ferrosilicon ဓာတုမိသားစု သတ္တု၊ အလ္ဂိုင်း

အဓိပ္ပါယ်တူ/ကုန်သွယ်မှုအမည်များ Ferro Silicon၊ Fesi (Fesi %75)

UN Number: 1408 CAS နံပါတ်: 8049-17-0

ထုတ်ကုန်အသုံးပြုမှု သံမဏိအတွက် ၊ သံမဏိနှင့် သံရည်ကျိုပစ္စည်းများအတွက်

ပေါင်းထည့်ခြင်း

လိပ်စာ/ဖုန်းနံပါတ် Iran Ferroalloy Industries (IFI), P.O. အကွက် ၁၅၁၇၈/၃၁၆၉

φδ: (+98 21) 88 77 93 30 – 88 78 70 33-88 77 42 71, Fax:

(+98 21) 88 88 20 43, <u>www.Iranferroalloys.com</u>

ဆက်သွယ်ရန်ပုဂ္ဂိုလ် Alaleh Shahani၊ အီးမေးလ်- shahani@iranferroallovs.com

#### ၂. ပါဝင်သောပစ္စည်းများ

<u> ဒြ</u> ပ်စင်	သင်္ကေတ	CAS နံပါတ်	အလေးချိန် %
Silicon	Si	7440-21-3	72-80
ကာဗွန်	С	7440-44-0	<0.20
ဆာလဖာ	S	7704-34-9	<0.04
Phosphorus	Р	7723-14-0	<0.05
အလူမီနီယမ်	အယ်လ်	7429-90-5	0-3
Calcium	Ca	7440-70-2	<0.08
မန်းဂနိစ်	Mn	7439-96-5	<0.50
Chromium	Cr	7440-47-3	<0.30
တိုက်တေနီယမ်	Tí	7440-32-6	<0.20
Iron	Fe	7439-89-6	လက်ကျန်

#### ၃. ဘေးအန္တရာယ်ဖော်ပြချက်

အမျိုးအစားခွဲခြားခြင်း

ရုပ်ပိုင်းဆိုင်ရာအန္တရာယ် - ရေနှင့်ထိတွေ

- ရေနှင့်ထိတွေ့သည့်အရာများသည် မီးလောင်လွယ်သော ဓာတ်ငွေ့

အမျိုးအစား 3 ကိုထုတ်လွှတ်သည်။

ကျန်းမာရေးအန္တရာယ် - အဆိပ်သင့်မှု အမျိုးအစား 3 (ပါးစပ်၊ ရှူရှိုက်မိခြင်း) Label Elements သင်္ကေတ







စာမျက်နာ: 2/5

အချက်ပြစာတန်း - **အန္တရာယ်ရှိသည်** 

အန္တရာယ်အကြောင်းဖော်ပြချက်

H231 ရေနှင့်ထိတွေ့ရာတွင် မီးလောင်လွယ်သောဓာတ်ငွေ့ကို ထုတ်လွှတ်သည်။

H301 မျိုလျှင် အဆိပ်သင့်ခြင်း။ H331 ရှူမိပါက အဆိပ်သင့်ခြင်း။

ကြိုတင်သတိထားရမည့်ဖော်ပြချက်(များ)

P232 အစိုဓာတ်ကိုကာကွယ်ပါ။

P261 ဖုန်/အငွေ့ /ဓာတ်ငွေ့ ရှူရှိုက်ခြင်း မှရောင်ရှားရန်။ P264 ကိုင်တွယ်ပြီးနောက် လက်ကို သေချာဆေးကြောပါ။

P270 ဤထုတ်ကုန်ကိုအသုံးပြုသည့်အခါ အစာစားခြင်း၊ သောက်ခြင်း သို့မဟုတ်

ဆေးလိပ်မသောက်ပါနှင့်။

P271 လေဝင်လေထွက်ကောင်းသောနေရာတွင်သာ အသုံးပြုပါ။

P280 မျက်လုံးအကာအကွယ်/ မျက်နှာကို အကာအကွယ်လက်အိတ်များ ဝတ်ဆင်ပါ။

P301+P330+P331 မျိုချမိပါက - ပါးစပ်ကို ဆေးကြောပါ။ အော့အန်ခြင်းကို မဖြစ်စေရ။

P304+P340 ရှူရိုက်မိပါက - ထိုသူအား လေကောင်းလေသန့်သို့ရွှေ့စေပြီး အသက်ရှူရအဆင်ပြေသည့်

အနေအထားတွင် အနားယူပါ။

P310 အဆိပ်သင့်စင်တာ သို့မဟုတ် ဆရာဝန်ကို ချက်ချင်းခေါ်ပါ။

P370+P378 မီးလောင်သောအခါ - ပုံမှန်ခြောက်သွေ့သောဓာတုဗေဒ၊ ကာဗွန်ဒိုင်အောက်ဆိုဒ်၊ ဆိုဒါပြာ၊ ထုံး

သို့မဟုတ် သဲကို မီးငြိမ်းရန်အသုံးပြုပါ။

P402+P404 ခြောက်သွေ့သောနေရာတွင် သိမ်းဆည်းပါ။ အလုံပိတ် ကွန်တိန်နာ တွင်

သိမ်းဆည်းပါ။

P405 စတိုးကို သော့ခတ်ထားသည်။

P501 ဗဟို၊ ပြည်နယ်နှင့်ဒေသဆိုင်ရာစည်းမျဉ်းများနှင့်အညီ ပါဝင်ပစ္စည်းများကို စွန့်ပစ်ပါ။

အန္တရာယ်မဟုတ်ဟု ခွဲခြားသတ်မှတ်ထားခြင်း- မသက်ဆိုင်ပါ။

အမည်မသိ ပြင်းထန်သော အဆိပ်သင့်မှုရှိသော ပါဝင်ပစ္စည်းများ။ မသက်ဆိုင်ပါ။

#### ၄. ရှေးဦးသူနာပြုဆောင်ရွက်ရန် နည်းလမ်းများ

**ရှုရှိုက်မိပါက** အနံ့ရှိသောနေရာမှ ချက်ခြင်းဖယ်ရှားပြီး လေဝင်လေထွက် ကောင်းမွန်သော နေရာသို့

ခေါ်ဆောင်၍ နွေးထွေးအောင်ထားပြီးဆေးကုသမှုခံယူပါ။

**အရည်ပြားထိခိုက်မိပါက**အရေပြားကို ရေနှင့်/သို့မဟုတ် အပျော့စား ဆပ်ပြာဖြင့် ဆေးကြောပါ။

မျက်လုံးထဲဝင်ပါက မျက်လုံးကို ရေ/ဆားရည်ဖြင့် ဆေးကြောပါ။ မသက်မသာခံစားရခြင်းများကို

သမားတော်နှင့် ပြသပါ။

**စားသုံးခြင်း/ခန္ထာကိုယ်အတွင်းဝင်ပါက** ဖုန်မှုန့်များ ထိတွေ့သောနေရာမှ ထိခိုက်ခံရသူကို ဖယ်ရှားပါ။

#### ၅. မီးငြိမ်းသတ်ရန်နည်းလမ်းများ

မီးလောင်ခြင်းနှင့်ပေါက်ကွဲခြင်းအန္တရာယ်များ- ဖုန်မှုန့်/လေထုအရောအနှောများသည် မီးလောင်ကျွမ်းခြင်း သို့မဟုတ်

ပေါက်ကွဲနိုင်သည်။ Ferrosilicon သည်အစိုဓာတ် သို့မဟုတ် ရေနှင့် ဓာတ်ပြု၍မီးလောင်လွယ်သော နှင့်/သို့မဟုတ် အဆိပ်ဓာတ်ငွေ့များကို

ထုတ်လွှတ်သည်။

မီးငြိမ်းသတ်ရမည့် ပစ္စည်း - သဲခြောက်၊ CO2 သို့မဟုတ် အခြောက်မှုန့်

ခြောက်သွေ့သော Fesi သည် lump ဖများ သို့မဟုတ် granules ပုံစံဖြင့် လောင်ကျွမ်း၍မရပါ။



စာမျက်နာ- 3/5

လေထဲတွင် ဆိုင်းငံ့ထားသည့် FeSi ဖုန်မှုန့်များသည် အချို့သော အခြေအနေများတွင် ဖုန်မှုန့်များ ပေါက်ကွဲခြင်းကို ဖြစ်စေနိုင်သည် (အပိုင်း 10 ကို ကြည့်ပါ)။

#### ၆. မတော်တဆဖြစ်လျှင်ဆောင်ရွက်ရန် နည်းလမ်းများ

ဖုန်မှုန့်ပုံစံရှိသော ပစ္စည်းကို သင့်လျော်သော ကွန်တိန်နာများတွင် စုဆောင်းသင့်သည်။ စိုစွတ်သောပစ္စည်းကို ခြောက်သွေ့ခြင်းမှ ဝေးဝေးတွင် ထားရမည်ဖြစ်ပြီး ပိတ်ထားသော ကွန်တိန်နာများတွင် စုဆောင်းခြင်းမပြုရ မသိမ်းဆည်းရပါ။

ခြောက်သွေ့သော ဖုန်မှုန့်များကို vacuum ဖြင့်သန့်ရှင်းနိုင်သည် (သို့) လှည်းကျင်းသန့်ရှင်းနိုင်သည်။

#### ၇. ကိုင်တွယ်ပုံနှင့် သိမ်းဆည်းနည်းစနစ်

ကို**င်တွယ်ခြင်း** - ဖုန်မှုန့်များကို ဖြစ်ပေါ်စေသော ကိုင်တွယ်ခြင်းကို ရှောင်ကြဉ်ပါ။ ဖုန်မှုန့်များကို ရှူရိုက်ခြင်းမှ ရှောင်ကြဉ်ပါ (အခန်း ၈ ကိုကြည့်ပါ)။ ဖုန်မှုန့်ပါဝင်မှု မြင့်မားသောနေရာများတွင် မီးလောင်ရာနေရာများ (ဥပမာ ဂဟေဆော်ခြင်း) ကို ရှောင်ကြဉ်ပါ။ သွန်းသောသတ္တုထဲသို့ စိုစွတ်သောပစ္စည်းကို ပေါင်းထည့်ခြင်းသည် ပေါက်ကွဲမှုဖြစ်စေနိုင်သည်။ အပိုင်း ၁၀ ကို ကြည့်ပါ။

သိမ်းဆည်းထားသိုခြင်း - FeSi ကို ခြောက်သွေ့ပြီး လေဝင်လေထွက်ကောင်းသည့်နေရာတွင် ထားရှိကာ အက်ဆစ်နှင့် ဘေ့စ်များနှင့် ဝေးဝေးတွင် ထားရှိရမည်။

#### ၈. ထိတွေ့မှုမရှိစေရန် ထိန်းချုပ်ခြင်းနှင့် ကာကွယ်ခြင်း

မျက်လုံးကို အကာအကွယ်ပေးခြင်း၊ မျက်လုံးဆေးကြောခြင်း ကိရိယာများနှင့် အကာအကွယ်လက်အိတ်များ။ လေဝင်လေထွက်ကောင်းရန် သေချာပါစေ။ 29CFR1910.134 သို့မဟုတ် CSA Z94.4-M1982 အရ လေဝင် လေထွက် မလုံလောက်သောနေရာများတွင် အမှုန်အမွှားကာအသက်ရှူကိရိယာကို ဝတ်ဆင်ပါ။ ဖော့စဖင်းနှင့် အာဆင်းန်တို့ကို ထိတွေ့မိသည်ဟု သံသယရှိပါက (အခန်း 10 ကိုကြည့်ပါ) လေဝင်လေထွက်မကောင်းသောနေရာများ (ဥပမာ- သိုလှောင်ခန်းများ၊ ကတုတ်ကျင်းများ စသည်ဖြင့်)၊ ကိုယ်တိုင်ပါ ရှိသော အသက်ရှုကိရိယာ သို့မဟုတ် လေဝင်လေထွက်ရှိသော အသက်ရှူကိရိယာကို ဝတ်ဆင်သင့်သည်။ အလုပ်ခွင် ထိတွေ့မှုကန့်သတ်ချက်များ (HSE၊ EH40/2005)

ပစ္စည်းများ	2-6-1-5	8 နာရီ TWA		15 မိန	စ် STEL
•= •	CAS နံပါတ်	ppm	Mg/m <sup>3</sup>	ppm	Mg/m <sup>3</sup>
ရှူရှိုက်နိုင်သော ဖုန်မှုန့်		-	10	-	-
အနံ့အသက်ရှူနိုင်သော ဖုန်မှုန့်	-	-	4	(*)	1943
ဖော့စဖင်းဓာတ်ငွေ့ (PH3)	7803-51-2	0.1	0.14	0.2	0.28
အာစင်ဓာတ်ငွေ့ (AsH3)	7784-42-1	0.05	0.16	-	-

EU OEL- ကော်မရှင် ညွှန်ကြားချက် ၂ဝဝ၆/၁၅/EC

ဓာတ်	CAS နှံပါတ်	၈ နာရီ		၁၅ မိနစ်	
6303	CA3 &0103	ppm	Mg/m3	ppm	Mg/m3
Phosphine	7803-51-2	0.1	0.14	0.2	0.28

DNEL (ဆင်းသက်သောအကျိုးသက်ရောက်မှုအဆင့်)-

4mg/m3 ရှူသွင်းနိုင်သော FeSi အမှုန်များအတွက် အဆိုပြုချက် (Si အဖြစ်သတ်မှတ်သည်)။ 0.3 mg/m3 အသက်ရှူနိုင်သော FeSi အမှုန်များအတွက် အဆိုပြုချက် (Si အဖြစ်သတ်မှတ်သည်)။



စာမျက်နှာ- 4/5

#### ၉. ရုပ်ဂုဏ်သတ္တိနှင့် ဓာတ်ဂုဏ်သတ္တိများ

ထင်ရှားသည့် အသွင်အပြင်

- ငွေရောင် မီးခိုးရောင် အရောင်

အမျိုးအစား - ဆန်ခါအပိုင်းအစများ၊ ကောင်းသော။

အစုလိုက်သိပ်သည်းဆ- 1.6 g/cm3

တိကျသောဆွဲငင်အား (water=1) ခန့်မှန်းခြေ- 3.2

အရည်ပျော်အမှတ် (°C): 1240 -1350

#### ၁၀. တည်ငြိမ်မှုနှင့် ဓာတ်ပြုမှု

<mark>ရောင်ရန်အခြေအနေများ</mark> : ဖုန်မှုန့်ပါဝင်မှုမြင့်မားသောနေရာများတွင် မီးပွားများနှင့် အခြားမီးပွားအရင်းအမြစ်များ (ဥပမာ ဂဟေ ဆော် ခြင်း) ကို ရောင်ကြဉ်ပါ။ လေထုထဲတွင် FeSi ပါဝင်မှုများသည် 100-300 g/m3 ထက်ပိုများပါက ဖုန်မှုန့် ပေါက်ကွဲခြင်း ကို ဖြစ်စေနိုင်သည်။ပေးထားသော အမှုန်အမွှားအရွယ်အစားအတွက်၊ Si/Fe ပါဝင်မှုအချိုးကိုလျှော့ချခြင်းဖြင့်မီးလောင်ကျမ်းမှု ခံနိုင်မှုနှင့်ပေါက်ကွဲမှု၏ပြင်းထန်မှုနှုန်းတို့လျော့နည်း သွား သည်။ သွန်းသောသတ္တုထဲသို့ စိုစွတ်သောပစ္စည်းကို ပေါင်းထည့်ခြင်းသည် ပေါက်ကွဲမှုဖြစ်စေနိုင်သည်။

ရောင်ရန်ပစ္စည်းများ: ရေ/စိုထိုင်းဆ၊ အက်ဆစ်နှင့် ဘေ့စ်များ။

#### အန္တရာယ်ရှိသော ဓာတ်ပြိုကွဲသည့်ထုတ်ကုန်များ

မီးလောင်လွယ်သော ဟိုက်ဒရိုဂျင်ဓာတ်ငွေ့ (H2) နှင့် မီးလောင်လွယ်ပြီး အလွန်ပြင်းထန်သော အဆိပ် ဓာတ်ငွေ့များ ဖော့စဖင်း (PH3) နှင့် အာဆင်း (AsH3) (ကြက်သွန်ဖြူကဲ့သို့ အနံ့) များ FeSi သည် အစိုဓာတ်၊ အက်ဆစ် သို့မဟုတ် အောက်ခံများနှင့် ထိတွေ့မိပါက ဖြစ်ပေါ် လာနိုင်သည်။

ဟိုက်ဒြိုရစ်အက်ဆစ်(HF)သို့မဟုတ်နိုက်ထရစ်အက်ဆစ်(HNO3) နှင့်တုံ့ပြန်မှုသည် ဆီလီကွန်တက်ထရာ ဖလို ရိုက် (SiF4) သို့မဟုတ် နိုက်ထရပ်ဓာတ်ငွေ့များ (NOx) ကဲ့သို့သော အဆိပ်ဓာတ်ငွေ့များ ဖြစ်ပေါ် စေသည်။ စိုစွတ်သောထုတ်ကုန်သည် ရေ၏ပြိုကွဲမှုကြောင့် သွန်းသောသတ္တုထဲသို့ ပေါင်းထည့်ပါက မီးလောင်လွယ်သော ဟိုက်ဒရိုဂျင်ဓာတ်ငွေ့ ကို ဖြစ်ပေါ် စေလိမ့်မည်။

#### ၁၁. အဆိပ်အတောက်ဆိုင်ရာ သတင်းအချက်အလက်

#### ပြင်းထန်သောသက်ရောက်မှုများ-

**ရူရိုက်ခြင်း-** သေးငယ်သော အမှုန်အမွှားများသည်အကျိအချွဲအမြှေးပါးများကို ယားယံစေပြီး ရေဓာတ်ခန်း ခြောက် စေပါသည်။ ဖော့စဖင်း/အာဆင်းန်သည် အကျိအချွဲအမြှေးပါးများပေါ်ရှိ ဖုန်မှုန့်များမှ စုပ်ယူနိုင်သည်။ ကွန်တိန်နာများ, ဖော့စဖင်း/အာဆင်းန်ကို အတွင်းပိုင်း ရှူသွင်းပြီး အသစ်ဖွင့်ထားသော လေဝင်လေထွက် မ လုံလောက်သော ကွန်တိန်နာများသို့ ပိတ်နိုင်သည်။ ဖော့စဖင်းသည် ထိတွေ့နေသော အကျိအမြှေးပါးများ ကို ယားယံစေကာ ဗဟိုအာရုံကြောစနစ် (CNS) ကို စိတ် ဓာတ်ကျစေပြီး အဆုတ်ရောင်ခြင်းကို ဖြစ်စေနိုင် သည်။ ဖော့စဖင်းပါသော ပြင်းထန်သော၊ သန္ဓေသား မဟုတ် သော အဆိပ်သင့်မှုသည် ခေါင်းကိုက်ခြင်း၊ မအီ မသာ ဖြစ်ခြင်း၊ အော့အန်ခြင်း၊ ဗိုက်နာခြင်း၊ ချောင်းဆိုး ခြင်း နှင့် အသက်ရူရခက်ခဲခြင်းတို့တွင် ယာယီအကျိုးသက် ရောက်မှုကိုပေးသည်။

အရေပြားထိတွေ့ခြင်း- ဖုန်မှုန့်များသည် အရေပြားကို ယားယံစေနိုင်သည်။ မျက်လုံးနှင့် ထိတွေ့ခြင်း- ဖုန်မှုန့်များသည် ယားယံစေပြီး ခြောက်သွေ့မှုကို ဖြစ်စေနိုင်သည်။

နာတာရှည်သက်ရောက်မှုများ

လက်တွေ့အတွေ့အကြုံနှင့် ရရှိနိုင်သော သိပ္ပံနည်းကျစာပေများကို ပြန်လည်သုံးသပ်ခြင်းအပေါ် အခြေခံ၍ ဤထုတ်ကုန်၏ နောက်ဆက်တွဲဆိုးကျိုးများ မျှော်မုန်းထားခြင်းမရှိပါ။ Norwegian ferro-alloy လုပ်ငန်းရှိ အလုပ်သမား အစုအဝေးများကို လွှမ်းခြုံထားသော သမိုင်းဝင်၊ ကူးစက်ရောဂါဆိုင်ရာ လေ့လာမှုများကို ရည်ညွှန်းစာပေများစာရင်းတွင် သရုပ်ပြခဲ့ပြီး၊ ဤထုတ်ကုန်မှ ကင်ဆာအန္တရာယ်မရှိကြောင်း ပြသခဲ့သည်။



စာမျက်နှာ- 5/5

#### ၁၂. ဂေဟစနစ်ဆိုင်ရာ သတင်းအချက်အလက်

ထုတ်ကုန်သည် ပတ်ဝန်းကျင်အတွက် အန္တရာယ်ရှိသည်ဟု လက္ခဏာမပြပါ။

#### ၁၃. စွန့်ပစ်မှုဆိုင်ရာနည်းလမ်းများ

တတ်နိုင်သမျှ ပြန်လည်အသုံးပြုရန်အတွက် ပစ္စည်းကို ပြန်လည်သိမ်းဆည်းသင့်ပါသည်။ ကော်မရှင် ဆုံးဖြတ်ချက်များ 2000/532/EC နှင့် 2001/118/EC အရ ထုတ်ကုန်မှ စွန့်ပစ်ပစ္စည်းများကို အန္တရာယ်ရှိသော စွန့်ပစ်ပစ္စည်းများအဖြစ် မသတ်မှတ်ပါ။ ဤပစ္စည်းအမြောက်အမြားကို စွန့်ပစ်ခြင်းမပြုမီ၊ အနီးဆုံးပတ်ဝန်းကျင်အေဂျင်စီထံမှ အကြံဉာဏ် တောင်းခံ သင့်ပါသည်။

#### ၁၄. သယ်ယူပို့ဆောင်ရေးဆိုင်ရာ သတင်းအချက်အလက်

DOT (သယ်ယူပို့ဆောင်ရေးဌာန)-ကုလသမဂ္ဂ နံပါတ် : ၁၄၀၈

သင်္ဘောအမည်- Ferrosilicon

Hazard အမျိုးအစား- 4.3၊ စိုစွတ်ချိန်တွင် အန္တရာယ်ရှိသော၊ လုပ်ငန်းခွဲအန္တရာယ်၊ 6.1၊ အဆိပ်သင့်မှု

I.D. နံပါတ် - စည်းကမ်းမထားပါ။

ထုပ်ပိုးမှုအုပ်စု - အုပ်စု III

အညွှန်း(များ) - စည်းကမ်းမထားပါ။

#### ၁၅. စည်းမျဉ်းစည်းကမ်းဆိုင်ရာ သတင်းအချက်အလက်

OSHA (လုပ်ငန်းခွင် ဘေးကင်းလုံခြုံပြီး ကျန်းမာရေး စီမံခန့်ခွဲမှု)

hazardous communication စံသတ်မှတ်ချက် (29 CFR 1910 1200) အရ အန္တရာယ်ရှိသည်။

TSCA (အဆိပ်အတောက်ထိန်းချုပ်ရေးဥပဒေ)။

ဤထုတ်ကုန်၏ပါဝင်မှုများကို TSCA Inventory တွင်ဖော်ပြထားသည်။

CERCLA (ပြည့်စုံသော တုံ့ပြန်မှု လျော်ကြေးငွေနှင့် တာဝန်ယူမှု ဥပဒေ)-

ဆီလီကွန်မန်ဂနိစ်အလွိုင်းကို "အန္တရာယ်ရှိသောပစ္စည်းစာရင်းနှင့် အစီရင်ခံနိုင်သောပမာဏ" (40 CFR 302.4) "မန်ဂနိစ်နှင့် ဒြပ်ပေါင်းများ" ၏ ယေဘူယျ သို့မဟုတ် ကျယ်ပြန့်သောအတန်းအတွက် RQ ကို သတ်မှတ်မထားပါ။

RCRA (သယံဇာတ ထိန်းသိမ်းရေး/ ပြန်လည်ရယူရေး ဥပဒေ)-

Silicomanganese သတ္တုစပ်သည် စာရင်းဝင်သော အန္တရာယ်ရှိသော စွန့်ပစ်ပစ္စည်းမဟုတ်ပါ။

#### ၁၆. အဆိပ်အတောက်ဆိုင်ရာ သတင်းအချက်အလက်

ဤ Material Safely Data Sheet တွင်ဖော်ပြထားသောအချက်အလက်များသည် ဤတိကျသော ပစ္စည်းနှင့် သက်ဆိုင် ပါသည်။ အခြားပစ္စည်းများနှင့် ပေါင်းစပ်အသုံးပြုပါက သို့မဟုတ် မည်သည့်လုပ်ငန်းစဉ်တွင်မဆို ဤ ပစ္စည်းအတွက် အကျုံးဝင်မည်မဟုတ်ပါ။ ရည်ရွယ်ထားသည့် အသုံးပြုမှုအတွက် ဤအချက်အလက်၏ သင့် လျော် မှုနှင့် ပြည့်စုံမှုကို စစ်ဆေးရန် သုံးစွဲသူ၏ တာဝန်ဖြစ်သည်။



## ပစ္စည်းလုံခြုံရေးဒေတာစာရွက် (MSDS)

စာမျက်နှာ 1/5

#### ၁. ထုတ်ကုန်အမည်နှင့် ကုမ္ပဏီအချက်အလက်

ကုန်ပစ္စည်းအမည် Sintered Neodymium Iron Boron (NdFeB) Magnet ထုတ်လုပ်သူ/ရောင်းချသူ အချက်အလက် ChengDU ကောင်းကင်ဘုံနှင့်ကြီးမားသောနည်းပညာ CO,LTD 146 Hongqi လမ်း၊ Pidu ခရိုင်၊ Chengdu 611730၊ တရုတ်နိုင်ငံ

ပ၂၈ ၆၉၉၁၄၈၃၆ ၈၆

www.advancedmagnets.com

### ၂. ဘေးအန္တရာယ် ခွဲခြားသတ်မှတ်ခြင်း။

သေဆုံးခြင်း: သံလိုက်များအတွက် N/A အနုမှုန့် သို့မဟုတ် ဖုန်မှုန့်များသည် မီးလောင်လွယ်သည်။ ကျန်းမာရေးအန္တရာယ်: အရေပြားကို ကြာရှည်ထိတွေ့ပါက ယားယံခြင်း သို့မဟုတ် ဓာတ်မတည့်သော အရေပြားရောင်ရမ်းခြင်းကို ဖြစ်စေနိုင်သည်။

ဓာတုအန္တရာယ်: ရေနှင့် အက်ဆစ်တွင် ကြာရှည်စွာ နှစ်မြှုပ်ခြင်းသည် ဟိုက်ဒရိုဂျင်ကို ဖန်တီးနိုင်သည်။ Physical Hazard: Magnet များသည် အခြားသံလိုက်များကို ဆွဲဆောင်နိုင်သော သံလိုက်စွမ်းအားများ ပါရှိသည်။ သံလိုက် နှင့် သံ သို့မဟုတ် သံမဏိကဲ့သို့သော အခြား ferromagnetic ပစ္စည်းများ ဤအရာသည် ကိုင်တွယ်စဉ်အတွင်း ထိခိုက်ဒဏ်ရာရခြင်း ဖြစ်နိုင်သည်။

#### ၃. ပါဝင်ပစ္စည်းများဆိုင်ရာ ပေါင်းစပ်ဖွဲ့ စည်းမှု/အချက်အလက်

ပါဝင်ပစ္စည်းများ

Element Name	Molecular Formula	Weight %	CAS No	EINECS No.
Neodymaum *	Nd	20-33	7440-00-8	231-109-3
Praseodymium *	Pr	0-8	7440-10-0	231-120-3
Dysprosium *	Dy	0-6	7429-91-6	231-073-9
Terbium *	Тъ	0-3	7440-27-9	231-137-6
Iron	Fe	62-70	7439-89-6	231-096-4
Boron	В	09-13	7440-42-8	231-151-2
Cobalt	Со	0-5	7440-48-4	231-158-0
Copper	Cu	0 01-0 5	7440-50-8	231-159-6
Aluminum	Al	0.01-0.8	7429-90-5	231-072-3
Nickel **	Ni	0-04	7440-02-0	231-111-4
Zinc **	Zn	0-0.2	7440-66-6	231-175-3

#### Note

1

<sup>\*</sup> The total content of rare earth elements is 28-35 wt%

<sup>\*\*</sup> These elements are contained in surface coatings



### ၄. ရှေးဦးသူနာပြုနည်း

**ရှူရှိုက်မိခြင်း** သံလိုက်များအတွက် မရှိပါ။ အမှုန့်များ သို့မဟုတ် ဖုန်မှုန့်များကို ရှူရှိုက်သည့်

အခါ လတ်ဆတ်သော အသက်ရှုရန် အပြင်ထွက်ပါ။ လေထဲတွင် ရောဂါ

လက္ခဏာများ ဖြစ်ပေါ်ပြီး/သို့မဟုတ် ဆက်လက်ရှိနေပါက ဆရာဝန်ထံ သွားပါ။

အရေပြား: ဆပ်ပြာနှင့်ရေဖြင့် သေချာစွာဆေးကြောပါ။ လက္ခဏာတစ်ခုခု ဖြစ်ပေါ်လာပါက

ဆက်နေ /သို့မဟုတ် ဆရာဝန်ထံ သွားပါ။

မျက်လုံးနှင့် ထိတွေ့ခြင်း - လက္ခဏာများ ဖြစ်ပေါ် လာပါက ကြည်လင်လာသည်အထိ ရေဖြင့်

ဆေးကြောပါ ဆရာဝန်ထံ သွားပါ။

မျိုချပြီး: ရေနွေးနွေးကို လုံလုံလောက်လောက်သောက်ပြီး အော့အန်ခြင်းကို သက်သာ

စေပါတယ်။ အားထားရာတစ်ခုခုရှိရင် ဆရာဝန်ဆီ ချက်ချင်းသွားပါ။ သို့မဟုတ်

အစိတ်စိတ်အမွှာမွှာ ခန္ဓာကိုယ်မှ မထွက်နိုင်ဘဲ သို့မဟုတ် မည်သည့် ရောဂါလက္ခဏာများ ဖြစ်ပေါ်ပြီး/သို့မဟုတ် ဆက်လက်တည်ရှိနေမည်နည်း။

#### ၅. မီးငြိမ်းသတ်ရန်နည်းလမ်းများ

အန္တရာယ်ရှိသော လောင်ကျွမ်းခြင်းဆိုင်ရာ ထုတ်ကုန်များ - N/A

မီးသတ်ဆေးဘူး: - အောက်ဆီဂျင်ဓာတ် မပါဘဲခြောက်သွေ့သောဓာတုပစ္စည်းများ သို့မဟုတ်

သဲများ ။

**အထူးမီးငြှိမ်းသတ်ရေးလုပ်ထုံးလုပ်နည်းများ** မီးလောင်နေသောအမှုန့်များကို သီးခြားခွဲထုတ်ခြင်း။ Halon သို့မဟုတ်

ရေကို အသုံးမပြုပါနှင့်

**ပုံမှန်မဟုတ်သော မီးလောင်ကျွမ်းမှုနှင့် ပေါက်ကွဲခြင်းအန္တရာယ်များ**- အနုမှုန့်များသည် ဓာတ်ပြုခြင်း၊ လောင်ကျွမ်း

စေ ကာ လေ သို့မဟုတ် အောက်ဆီဂျင်ပါဝင်ပါကလျင်မြန်စွာ

လောင်ကျွမ်းစေပါသည်။။ သံလိုက်များသည် သက်ရောက်မှုရှိနိုင်ပါသည်။

#### ၆ မတော်တဆ စွန့်ထုတ်မှု အတိုင်းအတာ

သံလိုက် : N/A

အမှုန့်/ဖုန်မှုန့်များ: အမှုန် သို့မဟုတ် ဖုန်မှုန့်များကို စုပ်ခွက် သို့မဟုတ် တံမြက်စည်းဖြင့် သုတ်သင်ပြီး ရေတွင်

သိုလှောင်ပါ သို့မဟုတ် အလုံပိတ်ကွန်တိန်နာများ။ ဖုန်စုပ်စက်ဖြင့် အမှုန့်

သို့မဟုတ် ဖုန်မှုန့်များကို မစုဆောင်းပါနှင့်.

#### ၇. ကိုင်တွယ်ခြင်းနှင့် သိုလှောင်ခြင်း။

ကိုင်တွယ်ခြင်း-

အချိန်ကြာမြင့်စွာ ကိုင်တွယ်ရာတွင် လက်အိတ်များ ဝတ်ဆင်ပါ။

သံလိုက်များသည် သံ သို့မဟုတ် သံလိုက်ကဲ့သို့ အခြားသော သံလိုက်ဓာတ်များကို ဆွဲဆောင်နိုင်စေသည့် အလွန်အားကောင်းသော သံလိုက်စွမ်းအားများ ပါဝင်ပြီး လက် သို့မဟုတ် ခန္ဓာကိုယ် ထိခိုက်မှုကို အာရုံစိုက်ပါ။

Magnet ကို floopy disk, သံလိုက်များ သို့မဟုတ် သံလိုက်ကတ် သို့မဟုတ် အီလက်ထရွန်းနစ်နာရီများနှင့် ဝေးဝေးတွင် ထားပါ။

2

## **Environmental Management Plan Report**

## **GIANT 999 STEEL MANUFACTURING FACTORY**



သိုလှောင်ခြင်း

အေးမြုပြီး လေဝင်လေထွက်ရှိသော ဂိုဒေါင်ထဲတွင် သံလိုက်များကို သိမ်းဆည်းပါ သံလိုက်များကို စိုစွတ်ပြီး အဆိပ်သင့်သော ပတ်ဝန်းကျင်များမှ ဝေးဝေးတွင်ထားပါ။ သံလိုက်ဖြင့်ပြုလုပ်ထားသော ထုတ်ကုန်များကို တံဆိပ်ပါသော အပိတ်ကွန်တိန်နာတွင် သိမ်းဆည်းပါ။

ထပ်လောင်းအချက်အလက်များ

သံလိုက်၏အပေါ် ယံပိုင်းကို မခွာပါနှင့်၊ သို့မဟုတ်ပါက သံချေးတက်ခြင်း သို့မဟုတ် သံချေးတက်ခြင်းတို့ကို ဖြစ်စေသည်။

စက်အသုံးပြုနေစဉ်အတွင်းအမှုန့်များ သို့မဟုတ် ဖုန်မှုန့်များသည် မီးလောင်ကျွမ်းစေ သောကြောင့်ဂရုပြုပါ ။

၈. ထိတွေ့မှု ထိန်းချုပ်မှု / ပုဂ္ဂိုလ်ရေးဆိုင်ရာ အကာအကွယ်များ

MAC: N / A

Engineering Controls: စိုစွတ်သော စက်ပိုင်းဆိုင်ရာ လုပ်ငန်းစဉ်များနှင့် ထုတ်လုပ်နေစဉ်အတွင်း

လေဝင်လေထွက်စက်ကို အသုံးပြုပါ။

အသက်ရူလမ်းကြောင်းဆိုင်ရာ အကာအကွယ်- ကိုင်တွယ်ခြင်းနှင့်/သို့မဟုတ် စက်ပြုလုပ်နေစဉ်အတွင်း

နှာခေါင်းစည်း သို့မဟုတ် အသက်ရူကိရိယာကို ဝတ်ဆင်ပါ။

အရေပြားအကာအကွယ်- လက်အိတ်ဝတ်ဆင်ပါ။

မျက်စီအကာအကွယ် ကိုင်တွယ်ခြင်းနှင့်/သို့မဟုတ် ပြုပြင်နေစဉ်အတွင်း ဘေးကင်းသောမျက်မှန် သို့မဟုတ်

မျက်မှန်များဝတ်ဆင်ပါ

**နောက်ဆက်တွဲသတိထားချက်များ** လုပ်ငန်းခွင်အတွင်း ဆေးလိပ်သောက်ခြင်း၊ စားသောက်ခြင်းကို တားမြစ်

#### ၉. ရုပ်ဂုဏ်သတ္တိနှင့် ဓာတ်ဂုဏ်သတ္တိများ

ရုပ်ထွက်ပစ္စည်းပုံစံ အစိုင်အခဲအခြေအနေ

ပုံပန်းသဏ္ဌာန်

သတ္တု

အရည်ပျော်ပွိုင့် : ခန့်မှန်းခြေ 1200°C

Boiling Point: N/Aအငွေ့ဖိအား N/A Vapor Density N/A

N/A တို့သည် သံလိုက်များအတွက် ဖြစ်သည်။ အမှုန့် သို့မဟုတ် ဖုန်မှုန့်များသည် Explosion

ပေါက်ကွဲထွက်နိုင်သည်။

74-7.7 Specific Gravity Evaporation Rate N/A အနံ့ အနံ့မရှိ

ရေတွင် မပျော်ဝင်နိုင်၊ အက်ဆစ်တွင် ပျော်ဝင်နိုင် ပျော်ဝင်နိုင်မှု

## ၁၀. တည်ငြိမ်မှုနှင့် ဓာတ်ပြုမှု

လေထဲတွင် တည်ငြိမ်မှု တည်ငြိမ်မှု

မလိုက်ဖက်နိုင်သော တည်ငြိမ်မှု ( ရှောင်ရန်ပစ္စည်းများ ) : အက်ဆစ် ၊ အလွန်တက်ကြွသော ဓာတ်တိုး ဆန့်ကျင် ပစ္စည်းများ

ရောင်ရှားရန် အခြေအနေများ အပူချိန် မြင့်မားသော အပူရှိန် ၊ မီးတောက်ခြင်းများကို နှင့် အဆိပ်သင့် သော

ပတ်ဝန်းကျင်များ။

3

09 5026245, 09 965026245, 09 425353553



#### ၁၁. အဆိပ်အတောက်ဆိုင်ရာ သတင်းအချက်အလက်

ယားယံခြင်း : ကြာရှည်စွာ အရေပြား ထိတွေ့ခြင်းသည် ယားယံခြင်း သို့မဟုတ် ဓာတ်မတည့်သော

အရေပြားရောင်ရမ်းခြင်းကို ဖြစ်စေနိုင်သည်။

ကင်ဆာဖြစ်စေနိုင်မှု : N / A

နာတာရှည် အဆိပ်သင့်မှု : မှတ်တမ်းမရှိပါ။

### ၁၂. ဂေဟစနစ်ဆိုင်ရာ သတင်းအချက်အလက်

Ecotoxicity : မှတ်တမ်းမရှိပါ။ ခံနိုင်ရည်ရှိမှုနှင့် ပျက်စီးနိုင်မှု - မှတ်တမ်းမရှိပါ။ ဇီဝစုဆောင်းခြင်း - မှတ်တမ်းမရှိပါ။ မြေဆီလွှာအတွင်း ရွေ့လျားနိုင်မှု - မှတ်တမ်းမရှိပါ။

#### ၁၃. စွန့်ပစ်မှုဆိုင်ရာနည်းလမ်းများ

စွန့်ပစ်ခြင်းနည်းလမ်း း ဒေသဆိုင်ကှသတ်မှတ်ချက်များအတိုင်း လိုက်နာ စွန့်ပစ်ရန်။

#### ၁၄. သယ်ယူပို့ဆောင်ရေးဆိုင်ရာ သတင်းအချက်အလက်

သယ်ယူပို့ဆောင်ရေး စည်းမျဉ်းများ လေကြောင်းပို့ဆောင်ရေးမှ သံလိုက်များသည် IATA စည်းမျဉ်းများနှင့်အညီ ဖြစ်ရမည်။ အတွင်းမှ သံလိုက်သံလိုက်ပါသော ထုပ်ပိုးမှု သို့မဟုတ် ကွန်တိန်နာများသည် ကုန်ပစ္စည်းများ လုံခြုံစွာ ပို့ဆောင်ခြင်းအတွက် လက်မှတ်ရရှိရန် စမ်းသပ်စစ်ဆေးပြီး သယ်ယူပို့ဆောင်ရေးဆိုင်ရာ ထည့်သွင်း စဉ်းစား မှုများ သင်္ဘောမတင်မီ ထုပ်ပိုးခြင်း သို့မဟုတ် ကွန်တိန်နာများ ပြီးပြည့်စုံမှုနှင့် တံဆိပ်ခတ်ခြင်းတို့ကို စစ်ဆေးခြင်း၊ ယိုစိမ့်ခြင်း ၊ ပြိုကျခြင်း၊ ပြုတ်ကျခြင်းနှင့် ပျက်စီးခြင်းတို့ကို ကင်းဝေးစေခြင်း ၊ မိုးရွာခြင်း၊ အပူချိန် မြင့်မားခြင်း၊ ထိခိုက်မှုနှင့် ပွတ်တိုက်မှု အက်ဆစ်နှင့် ဓာတ်တိုးဆန့်ကျင်ပစ္စည်းများ အမျိုးမျိုးဖြင့် ထုပ်ပိုးခြင်းကို ရှောင်ကြဉ်ပါ ထုပ်ပိုးခြင်း သို့မဟုတ် ကွန်တိန်နာများ ပျက်စီးခြင်းမှ ကာကွယ်ရန် ဂရုတစိုက် ကိုင်တွယ်ပါ

#### ၁၅. စည်းမျဉ်းစည်းကမ်းဆိုင်ရာ သတင်းအချက်အလက်

ဒေသဆိုင်ရာ စည်းမျဉ်းများနှင့်အညီ လိုက်နာပါ

4



### APPENDIX (D) ECD COMMENT RESPONSE TABLE

Giant 999 Iron Mill ၏ သံရည်ကျိုသံမဏိလုပ်ငန်းအတွက် တင်ပြလာသည့် ပတ်ဝန်းကျင်စီမံခန့်ခွဲမှုအစီအစဥ် (EMP) အပေါ် ECD မှသုံးသပ်အကြံပြုချက်များကို ဖြေရှင်းချက်

စဉ်	ပြန်လည်ပြင်ဆင်ဖြည့်စွက်တင်ပြရန်အချက်များ	ပြန်ကြားချက်
OII	အတိုကောက်စာလုံးများ၊ အဓိပ္ပါယ်ဖွင့်ဆိုချက်များ နှင့်	
	အစီရင်ခံစာတွင် အသုံးပြုထားသော အတိုကောက်စကားလုံး များကို ပြည့်စုံစွာ ဖော်ပြပေးရန် လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၂.၂ စာမျက်နှာ ၈၇ တွင်ဖော်ပြထားပါသည်။
اال	အစီရင်ခံစာအကျဉ်းချုပ်	
	• ထုတ်လုပ်မှုဆိုင်ရာ အဆောက်အဦးများ နှင့် ဆက်စပ် အဆောက်အဦး များ အား ဖော်ပြသည့် ဇယားနေရာပြပုံမှာ ကိုက်ညီမှုမရှိပါသဖြင့် ပြန်လည် ဆန်းစစ်ဖော်ပြပေးရန် လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၃. စာမျက်နှာ ၅၃ - ၅၄ တွင်ဖော်ပြ ထားပါသည်။
	• ဥပဒေအကြောင်းဆိုင်ရာ လိုအပ်ချက်များ ဖော်ပြရာတွင် သဘာဝ ပတ်ဝန်း ကျင် ထိန်းသိမ်းရေး ဥပဒေ (၂၀၁၂) နှင့် စည်းမျဉ်းဥပဒေများ (၂၀၁၄) ဟု ဖော်ပြချက်နှင့် ပက်သက်၍ ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး ဥပဒေ (၂၀၁၂) နှင့် ပတ်ဝန်းကျင် ထိန်းသိမ်းရေး နည်းဥပဒေများ (၂၀၁၄)ဟု ပြန်လည် ဆန်းစစ် ဖော်ပြပေးရန် လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၂ စာမျက်နှာ ၅၀ တွင်ဖော်ပြ ထားပါသည်။



စက်ရုံအတွင်းတူးဖော်ထားသည့် အဝီစိတွင်း အရေအတွက် နှင့် ရေရယူ သုံးစွဲမှု အခြေအနေအား ဖော်ပြထားသော်လည်း ရယူ သုံးစွဲသည့် ရေတွင်း ၏ တည်နေရာ ၊ အနက် နှင့် အရွယ်အစားတို့အား ဖော်ပြရန်	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၉. စာမျက်နှာ ၅၈ တွင်ဖော်ပြ ထားပါသည်။
• စီမံကိန်းကာလအား ဖော်ပြပေးရန်လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၂. စာမျက်နှာ ၅၃ တွင်ဖော်ပြ ထားပါသည်။
• ကုန်ကြမ်းပစ္စည်းများ မည်သို့သိုလှောင်ထားကြောင်းကို အကျဥ်းချုပ် ဖော်ပြရန်လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၄. စာမျက်နှာ ၅၄-၅၅ တွင်ဖော်ပြ ထားပါသည်။
• ကရိန်းနှင့် အခြားစက်ယန္တရားများ လုပ်ငန်းလည်ပတ်စဥ် အသုံးပြုသည့် စက်ယာဥ်ယန္တရား အမျိုးအမည် နှင့် အရေအတွက် အားေဖာ်ပြ ရန် လိုအပ် ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၆ စာမျက်နှာ ၅၇ <b>ဧယား ၁.၃</b> တွင်ဖော်ပြ ထားပါသည်။
• တစ်ရက်အလုပ်လုပ်ချိန်အား အကျဥ်းချုပ် အစီရင်ခံစာ တွင်ထည့်သွင်း ရေးသားရန် လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၈ စာမျက်နှာ ၅၆ တွင်ဖော်ပြ ထားပါသည်။
အရန်ဓာတ်အားအဖြစ်ထားရှိသည့် မီးစက်များအတွက် လိုအပ်သော ဒီဇယ် တစ်နှစ်စာ (၁၉၀၀)ဂါလံ ဟု ဖော်ပြထားပါသည်။ ထိုသုံးစွဲသော ဒီဇယ်အား မည်သည့် အရင်းအမြစ်တွင် ရယူ၍ လုပ်ငန်းခွင် တွင် ဖိတ်စင်မှု မရှိအောင် မည်သို့ထားသို သိမ်းဆည်း ကြောင်း ကို အကျဥ်းချုပ် ဖော်ပြရန် လိုအပ် ပါကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၈ စာမျက်နှာ ၅၈ တွင်ဖော်ပြ ထားပါသည်။



	• စက်ရုံအတွင်းနှင့် ဝန်ထမ်းအိမ်ယာမှ အဆင့်ဆင့် ပြန်လည် အသုံးပြု၍ နောက်ဆုံးအဆင့် ထွက်ရှိလာသော အမှိုက်များ အား မည်သည့် နေရာတွင် စွန့်ပစ်လေ့ရှိကြောင်းထည့်သွင်းရေးသားရန် လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၁၁ စာမျက်နှာ ၆၀ တွင်ဖော်ပြ ထားပါ သည်။
	• ကဏ္ဍများအနက် မည်သည့် လုပ်ငန်းသို့ အသုံးပြုရန် ရောင်းချလေ့ရှိ ကြောင်း ဖော်ပြပေးရန် လိုအပ်ကြောင်း။	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၃.၁၁ စာမျက်နှာ ၆၀ တွင်ဖော်ပြ ထားပါ သည်။
	• အဆိုပြုလုပ်ငန်း၏ တည်ဆောက်ဆဲကာလသည် အချိန်ကာလ ကြာ မြင့် နေပြီဖြစ်သောကြောင့် သက်ရောက်နိုင်သော ပမာဏ နည်း သည် များသည် ကို ထည့်သွင်းမစဦးစားတော့ပါကြောင်း နှင့် ရေ ရှည် တွင် အကျိုးသက်ရောက်မည့် ပမာဏများနှင့် လျော့နည်းမည့် နည်းလမ်း များကို သာဖော်ပြပေးရန်လိုအပ်ကြောင်း	• အခန်း (၁) ခေါင်းစဥ်ခွဲ ၁.၅.၂. စာမျက်နှာ ၇၀ တွင်ဖော်ပြ ထားပါသည်။
<b>2</b> II	နိဒါန်း	
	• လုပ်ငန်း၏ နောက်ခံအကြောင်းအရာဖော်ပြချက်တွင် မှော်ဘီမြို့နယ် စည်ပင်သာယာ ရေးအဖွဲ့၏ လုပ်ငန်းလိုင်စင် ထုတ်ပေးသည့် ရက်စွဲကို ပြန်လည် ဆန်းစစ်ဖော်ပြရန်လိုအပ်ကြောင်း	• ခေါင်းစဥ်ခွဲ ၂.၁ စာမျက်နှာ ၈၇ တွင်ဖော်ပြထားပါသည်။
	• လက်ရှိလည်ပတ်ဆောင်ရွက်နေသည့် နည်းပညာ လက်ရှိလုပ်ငန်း လည်ပတ်ခြင်း ကြောင့် စီးပွားရေး၊ ပတ်ဝန်းကျင်လူမှုရေးဆိုင်ရာ လေ့လာမှု များမှ အဓိကတွေ့ရှိချက် များနှင့် ပက်သက်၍ ထည့်သွင်း ဖော်ပြရန် လိုအပ် ကြောင်း	• ခေါင်းစဥ်ခွဲ ၂.၄ စာမျက်နှာ ၉၀-၉၁ တွင်ဖော်ပြထားပါသည်။



(က)	• လုပ်ငန်းလုပ်ကိုင်သူ ပုဂ္ဂိုလ်/ အဖွဲ့အစည်း၏ အချက် အလက်များ ထည့်သွင်း ဖော်ပြရန်၏	• ခေါင်းစဥ်ခွဲ ၂.၅ စာမျက်နှာ ၉၁-၉၂ တွင်ဖော်ပြထားပါသည်။
911	ကတိကဝတ်များ	
	<ul> <li>စီမံကိန်း ပိုင်ရှင် နှင့် အစီရင်ခံစာပြုစုရေးသားသူ တတိယ အဖွဲ့ အစည်း ဖြစ်သည့် Green Environmental, Health, Safety and Social Consultancy Company Limited တို့အနေဖြင့် ကတိ ကဝတ် အား မူရင်း လက်မှတ်ဖြင့် ရေးထိုး တင်ပြရန် လိုအပ် ကြောင်း</li> <li>ကတိကဝတ်များကို လက်မှတ်ရေးထိုးဖော်ပြရာတွင် စီမံကိန်း အဆိုပြုသူမှ အောက်ပါ အချက်များကိုအမှန်တကယ် တိကျစွာ လိုက်နာမည်ဖြစ် ကြောင်း လက်မှတ် ရေးထိုးဖော်ပြရန်</li> <li>ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဥ်သည် တိကျခိုင်မာ ကြောင်းနှင့် ပြည့်စုံ ကြောင်း ပတ်ဝန်းကျင် ထိခိုက်မှု ဆန်းစစ်ခြင်းဆိုင်ရာ လုပ်ထုံးလုပ်နည်း အပါအဝင် သက်ဆိုင်ရာ ဥပဒေများကို တိကျစွာ လိုက်နာ၍ ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဥ်ကို ရေးဆွဲကြောင်း</li> <li>စီမံကိန်းသည် ပတ်ဝန်းကျင် စီမံခန့်ခွဲမှု အစီအစဥ်ကို ရေးဆွဲကြောင်း တိဝ်ဝန်းကျင် ထိခိုက်မှု လျော့ချရေးလုပ်ငန်းများ နှင့် အစီအစဥ်များ ကို အပြည့်အဝ အစဥ်အမြဲ လိုက်နာ ဆောင်ရွက် မည်ဖြစ်ကြောင်း</li> <li>အစီရင်ခံစာရေးသားသူမှ အစီရင်ခံစာပါ အကြောင်းအရာများသည် တိကျ မှန်ကန်ကြောင်းနှင့် ပြည့်စုံကြောင်း သက်ဆိုင်ရာ ဥပဒေ၊</li> </ul>	



	နည်းဥပဒေ များ လုပ်ထုံးလုပ်နည်းများနှင့်အညီ ရေးသား ထား ကြောင်း ကတိကဝတ် ပြုလတ်မှတ် ရေးထိုးရန်လိုပါကြောင်း • လက်မှတ်ရေးထိုးဖော်ပြရာတွင် အမည်၊ သက်ဆိုင်ရာ တံဆိပ်တုံး နှင့် လက်မှတ်တို့ ရေးထိုးဖော်ပြရန်လိုအပ်ပါကြောင်း	
၅။	မူဝါဒ ဥပဒေနှင့် မူဘောင်များနှင့် ဖွဲ့စည်းမှုဆိုင်ရာများ	
(m)	<ul> <li>မူဝါဒ ဥပဒေနှင့် မူဘောင်များနှင့် ဖွဲ့စည်းမှုဆိုင်ရာများ နှင့်ပက်သက်၍ အောက်ပါတို့ကို ဖြည့်စွက်ရန်လိုအပ်ကြောင်း</li> <li>အမျိုးသားပတ်ဝန်းကျင်ရေးရာမူဝါဒ (၂၀၁၉)</li> <li>ရန်ကုန်မြို့တော်စည်ပင်သာယာရေးဥပဒေ (၂၀၁၈)</li> <li>အဆိုပြုစီမံကိန်းမှ လိုက်နာသွားမည့် သက်ဆိုင်ရာဥပေဒများမှ ကောက်နုတ် ချက်များကို ဖော်ပြရာတွင် အမှန်တကယ် လိုက်နာ ဆောင်ရွက် သွားမည့် အပိုဒ်များကို ဖော်ပြရာန်</li> <li>အောက်ပါဥပဒေများ ထပ်မံဖြည့်သွင်းရန် လိုအပ်လျက်ရှိကြောင်း</li> <li>အမျိုးသားပတ်ဝန်းကျင်ရေးရာမူဝါဒ (၂၀၁၉)</li> <li>မြေအသုံးချမှုဥပဒေ (၂၀၁၉)</li> <li>လူမူဖူလုံရေး နည်းဥပဒေများ (၂၀၁၄)</li> <li>အလုပ်သမားအဖွဲ့အစည်း ဥပဒေ(၂၀၁၁)</li> <li>အလုပ်သမားအဖွဲ့အစည်း နည်းဥပဒေများ (၂၀၁၂)</li> <li>အနည်းဆုံး အကြေးငွေဥပဒေများကို ပြင်ဆင်သည့် နည်းဥပဒေများ (၂၀၁၅)</li> <li>ခွင့်နှင့် ပိတ်ရက်အက်ဥပဒေများ (၁၉၅၁)</li> </ul>	• ခေါင်းစဥ်ခွဲ ၄.၁ စာမျက်နှာ ၉၅ မှ ၉၇တို့တွင် ဖော်ပြ ထားပါ သည်။

#### **Environmental Management Plan Report**

### GIANT 999 STEEL MANUFACTURING FACTORY



- အလုပ်ရုံအက်ဥပဒေများ( ၁၉၅၁)
- အလုပ်ရုံအက် ဥပဒေများ ကိုပြင်ဆင်သည့် ဥပဒေ (၂၀၁၆)
- အခကြေးငွေပေးချေရေး ဥပဒေ (၂၀၁၆)
- အလုပ်သမား အငြင်းပွားမှု ဖြေရှင်းရေး ဥပဒေကို ဒုတိယအကြိမ် ပြင်ဆင် သည့်ဥပဒေ (၂၀၁၉)
- အလုပ်သမား အငြင်းပွားမှု ဖြေရှင်းရေး နည်းဥပဒေများ (၂၀၁၂)
- လုပ်ငန်းခွင် ဘေးအန္တရာယ်ကင်းရှင်းရေးနှင့် ကျမ်းမာရေးဆိုင်ရာ ဥပဒေ (၂၀၁၉)
- မြန်မာနိုင်ငံမီးသတ်တပ်ဖွဲ့ နည်းဥပဒေ(၂၀၁၅)
- ဓာတုပစ္စည်းနှင့် ဆက်စပ်ပစ္စည်းများ အန္တရာယ်မှတားဆီး ကာကွယ်ရေး ဥပဒေ (၂၀၁၃)
- ဓာတုပစ္စည်းနှင့် ဆက်စပ်ပစ္စည်းများ အန္တရာယ်မှတားဆီး ကာကွယ်ရေး နည်းဥပဒေ (၂၀၁၆)
- မြန်မာရင်းနှီးမြုပ်နှံမှု ဥပဒေကို ပြင်ဆင်သည့် ဥပဒေများ (၂၀၁၉)
- မြန်မာရင်းနှီးမြုပ်နှံမှု နည်းဥပဒေကို ပြင်ဆင်သည့် နည်းဥပဒေများ
   (၂၀၁၈)
- ဖွဲ့စည်းပုံအခြေခံ ဥပဒေ (၂၀၁၈)
- မြေအောက်ရေ ကြီးကြပ်မှုအက်ဥပဒေ (၁၉၃၀)
- အလုပ်သမားလျော်ကြေးငွေ အက်ဥပဒေ (၁၉၅၁)
- ကုန်သွယ်လုပ်ငန်းခွန်ဥပဒေ(၂၀၁၅)
- ပြည်ထောင်စု၏ အခွန်အကောက်ဥပဒေ (၂၀၁၈)
- မြန်မာနိုင်ငံကုမ္ပဏီများ ဥပဒေ (၂၀၁၇)



	• စီမံကိန်းကြောင့် ဖြစ်ပေါ်နိုင်သည့် သက်ရောက်မှု အပေါ် အခြေခံ၍ စီမံကိန်းပိုင်ရှင်မှ လိုက်နာရမည့် စက်မှုလုပ်ငန်းကဏ္ဍ အတွက် NEQEG ပါ ပြဋ္ဌါန်းချက်များမှ လုပ်ငန်းနှင့် သက်ဆိုင်သည့် parameter များ၏ အရည် အသွေးဆိုင်ရာ စံချိန်စံညွှန်း လမ်းညွှန်တန်ဖိုး ( Guideline value) များကို ဖော်ပြရန် နှင့် NEQEG တွင် ဖော်ပြထားခြင်းမရှိသည့် parameter များ အတွက် ပြည်ပမှ လက်ခံထားသည့် Guideline value များဖြင့် ထည့်သွင်း ဖော်ပြရန် လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၄.၂ စာမျက်နှာ ၉၇ မှ ၁၀၁ တွင်ဖော်ပြထားပါ သည်။
GII	စီမံကိန်းအကြောင်းအရာဖော်ပြချက်	
	• ထုတ်လုပ်မှုလုပ်ငန်းစ၌ အဆင့်ဆင့် ဖော်ပြရာတွင် လုပ်ငန်းစ၌ တစ်ဆင့် ချင်းစီအား အသေးစိတ် ရှင်းလင်းဖော်ပြ ပေးရန်၊ ကုန်ကြမ်း အဖြစ် သံတိုသံစ များ Silicon နှင့်Magnet ကို အသုံးပြု မည်ဖြစ်ကြောင်း ဖော်ပြထား သည့် အတိုင်း သံတိုသံစများ Silicon နှင့် Magnet တို့ကို ထုတ်လုပ်မှုလုပ်ငန်း စဉ့်၏မည်သည့် အဆင့်တွင် ထည့် သွင်း အသုံးပြုမည် ကိုဖော်ပြရန် နှင့်	• ခေါင်းစဥ်ခွဲ ၅.၇ စာမျက်နှာ ၁၁၈ တွင်ဖော်ပြထားပါသည်။
	ကုန်ကြမ်း/ကုန်ချော သယ်ယူ ပို့ဆောင်ခြင်း နှင့် လုပ်သား ကြိုပို့ ဆောင်ရွက် မှုများနှင့် လမ်းပန်းဆက်သွယ်ရေး/ သယ်ယူပို့ဆောင်ရေး အခြေအနေ များကို ထည့်သွင်း ဖော်ပြရန်လိုအပ်ကြောင်း	• ခေါင်းစဥ်ခွဲ ၅.၁၄ စာမျက်နှာ ၁၃၉ တွင်ဖော်ပြထားပါသည်။
	• စီမံကိန်းလည်ပတ်မည့် ကာလအားပြည့်စုံစွာ ဖော်ပြရန်။	• ခေါင်းစဥ်ခွဲ ၅.၃ စာမျက်နှာ ၁၀၉ တွင်ဖော်ပြထားပါသည်။



• ဓာတုပစ္စည်းသိုလှောင်ထားမှု အခြေအနေတို့ကို စီမံကိန်း အကြောင်း အရာ ဖော်ပြချက် ခေါင်းစဥ်အောက်တွင် ဖော်ပြရန်။	• ခေါင်းစဥ်ခွဲ ၅.၅.၁ စာမျက်နှာ ၁၁၄ မှ ၁၁၅ ထိ ဖော်ပြထား ပါသည်။
• ရေသိုလှောင်ထားရှိမှုအခြေအနေကို စီမံကိန်း အကြောင်း အရာ ဖော် ပြချက် ခေါင်းစဥ် အောက်တွင်ဖော်ပြရန်	• ခေါင်းစဥ်ခွဲ ၅.၁၀ စာမျက်နှာ ၁၂၈ တွင်ဖော်ပြထားပါသည်။
• စက်ပစ္စည်းယန္တရားများအတွက် အသုံးပြုသည့် လောင်စာ ဆီ ပမာဏ နှင့် မည်သို့သိုလှောင် ထားရှိသည် ကို ရှင်းလင်း တိကျ စွာ ဖော်ပြရန် လိုအပ် ကြောင်း	
• Production Activity တွင် siliconနှင့် magnet ကို သံရည်ကျို ရာ၌ မည်သည့် အဆင့်တွင် ထည့်သွင်း အသုံးပြု ကြောင်း သံရည်ကျို ရာတွင် မည်သည့် အပူချိန် လိုအပ်၍ မည်သည့် လောင်စာအား အသုံးပြုထား ကြောင်း ဖော်ပြရန် လိုအပ်ကြောင်း။	
• Effluent wastewater (စွန့်ထုတ်ရေအရည်အသွေး) နှင့် ပက်သက်၍ စက်ရုံမှ သံပူထုတ်ကုန်အား ရေဖြန်းသည်ဟု ဖော်ပြထားပါသည်။ ထိုရေဖြန်း ရာမှ ထွက်လာသော စွန့်ပစ်ရေအား မည်သို့ စီမံခန့်ခွဲ ကြောင်း ဖော်ပြ ပေးပါရန်၊	ပါသည်။



• စက်ရုံတွင် ကုန်ကြမ်း နှင့် ကုန်ချော သယ်ယူပို့ဆောင်သည့် ယာဥ်များ မှ မတော်တဆ ဓာတ်ဆီ နှင့် အင်ဂျင်ဝိုင် ဖိတ်စင်ရာမှ ထွက်ရှိလာ သော စွန့်ပစ်အရည်များ အားစီမံခန့်ခွဲ မှုအားဖော်ပြပေးပါရန်	• ခေါင်းစဥ်ခွဲ ၅.၁၂.၂ စာမျက်နှာ ၁၃၅ တွင်ဖော်ပြထား ပါသည်။
• သုံးစွဲမည့် ဓာတုပစ္စည်းများ၏ တစ်လ အသုံးပြုသည့် ပျှမ်းမျှ ခန့်မှန်း ပမာဏ အားထည့်သွင်းဖော်ပြရန်	• ခေါင်းစဥ်ခွဲ ၅.၅.၁ စာမျက်နှာ ၁၁၄ မှ Table 5.3 တွင်ဖော်ပြ ထားပါသည်။
• Hazardous waste နှင့် ပက်သက်၍ ကုန်ကြမ်းပစ္စည်းဖြစ်သည့် Silicon နှင့် Magnet မတော်တဆ ဖိတ်စင်ရာမှလည်း အဆိပ် အတောက် ဖြစ်စေ နိုင်သော Hazardous waste များ ထွက်ရှိနိုင် ပါသည်။ ထို့ကြောင့် အန္တရာယ် ရှိ ပစ္စည်းများ ကိုင်တွယ်သိုလှောင်ပုံ နှင့် စွန့်ပစ်ပစ္စည်း စီမံခန့်ခွဲမှုအား ဖော်ပြ ပေးပါရန်	• ခေါင်းစဥ်ခွဲ ၅.၅.၁ စာမျက်နှာ ၁၁၄ မှ ၁၁၅ Figure 5.12, Figure 5.13, တွင်ဖော်ပြ ထားပါသည်။
• စက်ရုံဝင်းအတွင်း ဆောက်လုပ်ထားပြီးဖြစ်သည့် အဆောက်အဦး အမျိုး အစား နှင့် အတိုင်းအတာ များအားဖော်ပြရန်	• ခေါင်းစဥ်ခွဲ ၅.၄ စာမျက်နှာ ၁၀၉ မှ ၁၁၂တွင်ဖော်ပြထား ပါသည်။
• လုပ်ငန်းလည်ပတ်ခြင်း အဆင့်ဆင့်တွင် လုပ်ငန်းဆောင်ရွက်ပုံ အဆင့် ဆင့် ကို စာသားဖြင့်သာမက Flow Chart ဖြင့်ပါ သီးသန့် ခေါင်းစဥ် ခွဲများဖြင့် ဖော်ပြ ပေးပါရန်	• ခေါင်းစဥ်ခွဲ ၅.ဂု.၁ စာမျက်နှာ ၁၁ဂု Figure 5.15, Figure 5.16 တွင်ဖော်ပြ ထားပါ သည်။



	• Iron Powder Fume Dust Collecting System နှင့် ပက်သက်၍ အသေးစိတ် ထပ်မံ ဖော်ပြပေးရန် လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၅.၁၂.၃.၁ စာမျက်နှာ ၁၃၄ မှ ၁၂၆ တွင်ဖော်ပြ ထားပါသည်။
၇။	လက်ရှိပတ်ဝန်းကျင်အခြေအနေနှင့် လူမှုပတ်ဝန်းကျင် အကြောင်းအရာ မေ	ဖော်ပြချက်
	• စီမံကိန်း တည်ရှိရာမြို့နယ်၏ နောက်ခံသမိုင်းကြောင်း ဖော်ပြရာတွင် မြို့နယ် အမည် ပြန်လည် ဆန်းစစ်ဖော်ပြပေးရန် လိုအပ်ကြောင်း	• ခေါင်းစဥ်ခွဲ ၆.၂ စာမျက်နှာ ၁၄၁ တွင်ပြင်ဆင်ပြီး
	• ရာသီဥတုဆိုင်ရာ အချက်အလက်များကို ဖော်ပြရာတွင် အပူချိန် မိုးရေချိန် စိုထိုင်းစ လေတိုက်ခတ်သည့် လမ်းကြောင်း နှင့် လေ တိုက်နှုန်း တို့ကို မည်သည့် ခုနှစ်၏ တိုင်းတာချက်များ ဖြစ်သည်ကို ဖော်ပြရန်လိုအပ်ကြောင်း	• ခေါင်းစဥ်ခွဲ ၆.၅ စာမျက်နှာ ၁၄၄ တွင်ဖော်ပြထားပါသည်။
	• စီမံကိန်းတည်ရှိရာ မှော်ဘီမြို့နယ် အတွင်း သဘာဝပေါက်ပင်နှင့် တောရိုင်း တိရစ္ဆာန်များမရှိဟု ဖော်ပြချက်အတွက် သတင်း အချက်အလက် ရယူသော ရင်းမြစ်ကို ဖော်ပြပေးရန်လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၆.၆ စာမျက်နှာ ၁၄၇ တွင်ဖော်ပြထားပါသည်။
	• စီမံကိန်းတည်ရှိရာ မြို့နယ်၏ မြေအသုံးချမှုနှင့် ပက်သက်၍ ပြန်လည် ဆန်း စစ် ဖော်ပြပေးရန် နှင့် သတင်းအချက်အလက် ရယူသော အရင်းအမြစ် ကို ဖော်ပြ ပေးရန် လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၆.၈ စာမျက်နှာ ၁၅၀, ၁၅၂, Table 6.6 တွင်ဖော်ပြ ထား ပါသည်။



	• တိုင်းတာရရှိသည့် အချက်အလက်များအား အမျိုးသား ပတ်ဝန်းကျင် ဆိုင်ရာ အရည်အသွေး (ထုတ်လွှတ်မှု) လမ်းညွှန်ချက်ပါ စံချိန် စံညွှန်း များနှင့် နှိုင်းယှဥ် ဖော်ပြရန် တိုင်းတာသည့် ရလာဒ်များကို ပူးတွဲ တင်ပြရန် လိုအပ်ကြောင်း	<ul> <li>ခေါင်းစဥ်ခွဲ ၆.၁၁.၂ စာမျက်နှာ ၁၆၁, Table 6.13 တွင် guideline value ကိုဖော်ပြထားပါသည်။</li> <li>ခေါင်းစဥ်ခွဲ ၆.၁၁.၄ စာမျက်နှာ ၁၆၄, Table 6.16 တွင် တိုင်းတာသည့် ရလာဒ်များကိုဖော်ပြထားပါသည်။</li> <li>ခေါင်းစဥ်ခွဲ ၆.၁၁.၄ စာမျက်နှာ ၁၆၇ နှင့် ၁၆၈, Table 6.19, Table 6.20 တွင် စံချိန် စံညွှန်း များနှင့် တိုင်းတာသည့် ရလာဒ် များကို နှိုင်းယှဥ် ဖော်ပြထားပါသည်။</li> </ul>
	• Air quality ကို တိုင်းတာရာမှ ထွက်ရှိလာသော result များသည် မည် သည့် စက်ဖြင့် တိုင်းတာခြင်း မှ ရရှိကြောင်း အထောက်အထား ဖြင့် ဖော်ပြရန် လိုအပ်ပါကြောင်း ထို့ပြင် ထိုလေတိုင်းတာခြင်းအား မည်သည့်အချိန် အ တွင်း တိုင်းတာသည့် data များဖြစ်ကြောင်း စသည်ဖြင့် အထောက် အထားဖြင့် ဖော်ပြရန်လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၆.၁၁.၁ စာမျက်နှာ ၁၆၀ နှင့် ၁၆၂-၁၆၃, Figure 6.17, Figure 6.20. ဖော်ပြထားပါသည်။
	• ဆူညံသံနှင့် တုန်ခါမှု တိုင်းတာခြင်း တွင် ဆူညံသံကို လုပ်ငန်း လည်ပတ် စဥ်တွင် တိုင်းတာထားကြောင်း dBA result များအား အထောက်အထား ဖြင့် ဖော်ပြရန် စက်ရုံ ဝန်းကျင် လေထု အတွင် သက်ရောက်နေသော ဆူညံသံ နှင့် တုန်ခါမှုများကိုပါ coordinates points များသတ်မှတ်၍ ဖော်ပြပေးရန် လိုအပ်ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၆.၁၂. စာမျက်နှာ ၁၆၈ မှ ၁၇၄ အထိ တွင်, Table 6.22 , Table 6.23, Table 6.24, Table 6.25, Table 6.26, Figure 6.22 တို့ဖြင့်ဖော်ပြထားပါသည်။
ଗା	ထိခိုက်မှုနှင့် ဘေးအန္တရာယ် ဖြစ်နိုင်ခြေဆန်းစစ်ခြင်းနှင့် လျော့နည်းစေရေး	းလုပ်ငန်းများ
	• ဒေသတွင်း အလုပ်အကိုင် အခွင့်အလမ်း ဖန်တီးပေးနိုင်ရန် အလို့ငှာ နောက်ထပ် စက်ရုံဝန်ထမ်း ၁၅၀၀ ဦးအား ခန့်ထားရန် လျာထားချက်	• ခေါင်းစဥ်ခွဲ ဂု.၃ Table 7.7 စာမျက်နှာ ၂၀၁ တွင် ဖော်ပြထား ပါသည်။

# **Environmental Management Plan Report**



## **GIANT 999 STEEL MANUFACTURING FACTORY**

နှင့် ပက်သက်၍ population influx သက်ရောက်မှုများကိုပါ ထည့်သွင်း တွက်ချက် ပေးရန်လိုအပ်ပါကြောင်း • သက်ရောက်နိုင်မှုပမာဏအား ပြန်လည် ထည့်သွင်းစဥ်းစားပေးရန် လိုအပ် ပါကြောင်း	• ခေါင်းစဥ်ခွဲ ၇.၃ Table 7.7 စာမျက်နှာ ၁၉၂ တွင် ဖော်ပြထား ပါသည်။
<ul> <li>လုပ်ငန်းလည်ပတ်ဆဲကာလတွင် စက်ရုံလည်ပတ်ခြင်းကြောင့် ဖြစ်နိုင်ခြေ ရှိသော အောက်ပါသဘာဝဘေးအန္တရာယ် နှင့် စက်မှုဆိုင် ရာ အန္တရာယ် များ ဖြစ်နိုင် ခြေရှိပါက ဆန်းစစ်ဖော်ပြရန်</li> <li>မီးဘေး</li> <li>မုန်တိုင်းနှင့် ရေကြီးခြင်း</li> <li>ပေါက်ကွဲခြင်း</li> <li>ဓာတုပစ္စည်းယိုဖိတ်ခြင်း</li> <li>စက်ပစ္စည်း ကိရိယာ ချွတ်ယွင်းခြင်း</li> <li>စက်ပစ္စည်း ကိရိယာ ချွတ်ယွင်းခြင်း</li> <li>စက်ပိုင်းဆိုင်ရာနှင့် တည်ဆောက်ပုံဆိုင်ရာ ချွတ်ယွင်းမှုများ</li> </ul>	• ခေါင်းစဥ်ခွဲ ဂု.ဂု.၈.၁, ဂု.ဂု.၈.၂ စာမျက်နှာ ၂၂၈ မှ ၂၂၉ တွင် ဖော်ပြထား ပါသည်။
• ရေမြောင်းစွန့်ပစ်ရေစီမံခန့်ခွဲမှု နှင့် ပက်သက်၍ ဖော်ပြပေးရန် လိုအပ် ကြောင်း	• ခေါင်းစဥ်ခွဲ ဂု.ဂု.၁.၁, ဂု.ဂု.၁.၂ စာမျက်နှာ ၂၀၈-၂၀၉ တွင် ဖော်ပြထား ပါသည်။
• Safety Methodsများအား အမှန်တကယ်လိုက်နာ ဆောင်ရွက် ရန်နှင့် မတော်တဆ ထိခိုက်မှုများကို ကယ်ဆယ်မည့် အရေးပေါ် ဆေးသတ္တာ နှင့် ကယ်ဆယ်ရေးနည်းလမ်းများကို ပါ ဖော်ပြပေးရန် လိုအပ်ပါ ကြောင်း	• ခေါင်းစဥ်ခွဲ ၇.၇.၇.၂ စာမျက်နှာ ၂၂၃-၂၂၇ တွင် ဖော်ပြထား ပါသည်။



- နည်းလမ်းများကို အမှန်တကယ် လိုက်နာမည် ဖြစ်ကြောင်း ဝန်ခံ ခေါင်းစဥ်ခွဲ ၇.၄ Table 7.8 စာမျက်နှာ ၂၀၃ ကတိပြုရန် အထူးသဖြင့်လုပ်ငန်းပိတ်သိမ်းစဥ့်ကာလ၊ လုပ်ငန်း လည်ပတ်ဆဲကာလများ တွင် ဖြစ်ပေါ်နိုင်သော သဘာဝ ဘေးအန္တ ရာယ် နှင့် မတော်တဆမှုများ သက် ရောက်နိုင်မှု ပမာဏ နှင့် လျော့ပါး 🔸 ခေါင်းစဉ်ခွဲ ၇.၉.၆ စာမျက်နှာ ၂၃၃ တွင် လျော့ပါးစေရေး စေရေး နည်းလမ်းများ အား တွက်ချက် ဖော်ပြပေးရန် လိုအပ်ပါ ကြောင်း
  - လုပ်ငန်းပိတ်သိမ်းကာလ အတွက် တွက်ချက်ဖော်ပြထား ပါသည်။
  - နည်းလမ်းများ အား ဖော်ပြထား ပါသည်။
  - (လည်ပတ်ဆဲကာလ)
  - ခေါင်းစဥ်ခွဲ ၇.၄ Table 7.8 စာမျက်နှာ ၂၀၃ တွင် တွက်ချက်ဖော်ပြထား ပါသည်။
  - ခေါင်းစဉ့်ခွဲ ၇.၉.၆ စာမျက်နှာ ၂၃၃ တွင် လျော့ပါးစေရေး နည်းလမ်းများ အား ဖော်ပြထား ပါသည်။

#### ဒေသခံပြည်သူများနှင့် တိုင်ပင်ဆွေးနွေးခြင်း ଖା

• ဒေသခံပြည်သူများ နှင့် တွေ့ဆုံဆွေးနွေးရာတွင် အရေအတွက် စုစုပေါင်း ၁၇ ဦးသာရှိပြီး ကုလားကုန်းကျေးရွာသည် | အကိုင် အခွင့်အလမ်း များရှိပါက ကျေးရွာနေသူ များကို ခန့်ထား အိမ်ခြေ (၁၆၇၆) အိမ်ရှိသည်ဟု ၂၀၁၄ ခုနှစ် ပြည်လုံးကျွတ် သန်းခေါင်စာရင်းအရ တွေ့ရှိရ ပါသည်။ လူဦးရေ စုစုပေါင်း ၇,၈၇၄ ရှိသည့် အနက်မှ ၁၇ ဦး ဖြစ်သည့် ရပ်မိ ရပ်ဖများသာ တက် ရောက်ထားသော Public Consultation အစည်းအဝေး ဖြစ်သည်ကို စိစစ်တွေ့ရှိရပါသည်။ ထို့ပြင် ဆွေးနွေးထားသော အကြံပြုချက် များ မှာ CSR နှင့် ပက်သက်၍ အကြံပြုချက်များ မပါရှိကြောင်း စိစစ်တွေ့ရှိ ရပါသည်။ ထို့ကြောင့် Public Consultation တွင် CSR နှင့်

လူဦးရေ | CSR နှင့် ပက်သက်၍ သီးခြားအကြံပြုချက်များ မပါရှိပါ။ အလုပ် ပေးရန် တင်ပြကြပါသည်။ ခေါင်းစဥ်ခွဲ ၈.၃ စာမျက်နှာ ၂၄၁ တွင် ဖော်ပြထားပါသည်။



	ပက်သက်၍ မည် သည့် အကြံပြုချက် မှ တင်ပြဆွေးနွေး ခြင်းမရှိ ကြောင်း သုံးသပ်ရပါသည်။
OOII	ပတ်ဝန်းကျင်နှင့် လူမူရေးဆိုင်ရာ စီမံခန့်ခွဲမှုအစီအစဥ်များ ( Environmental and Social Management Sub-plans)
	• ဖျက်သိမ်းခြင်းကာလတွင် ဖြစ်ပေါ်လာနိုင်သည့် လူမူစီးပွားရေး အခြေ အနေ၊ လူမှုရေးပဋိပက္ခများနှင့် ပက်သက်၍ စီမံခန့်ခွဲမှု အစီအစဥ်များ အား ဖော်ပြရန် လိုအပ်ကြောင်း
	ပတ်ဝန်းကျင်နှင့် လူမှုဆိုင်ရာ စီမံခန့်ခွဲမှု အစီအစဥ်ခွဲများတွင် ဖော်ပြထား သော Health and Safety Methods များနှင့် လုပ်ဆောင်မည့် လျော့ပါး စေ ရေးနှင့် ထိန်းချုပ်ရေးနည်းလမ်း များကို အမှန်တကယ် လိုက်နာ ဆောင်ရွက် သွားမည်ဟု ကတိဝန်ခံချက် နှင့် ကတိကဝတ် ဖေသားတွင် ထည့်သွင်း ရေး သားရန်
SOII	စောင့်ကြပ်ကြည့်ရှုမည့် အစီအစဥ်
	• စောင့်ကြပ်ကြည့်ရှုမည့် လေအရည်အသွေး၊ ဆူညံသံ၊ စွန့်ထုတ်အရည် နှင့် စွန့်ပစ်ရည်စီမံခန့်ခွဲမှုအစီအစဥ်၊ စွန့်ပစ်ပစ္စည်းစီမံခန့်ခွဲမှု အစီအစဥ် စသည်ဖြင့် စောင့်ကြပ်ကြည့်ရှုရန် လျာထားသည့် နေရာ point of compliance (လိုက်နာမှတ်) နှင့် parameters များကို ဖော်ပြရန်



၁၂။	ကတိကဝတ်ပြုချက်ဖယား (list of commitment)							
		ပါ ကတ် တ်၏	ပြုသူမှ အစီရင်ခံစ ဂိကဝတ် ပြုချက်ဧ အမှတ်စဥ်	•			အခန်း ၁၂ စာမျက်နှာ ၃၀၁ - ၃၀၃ ရှိ Table 12.1 တွင် ဖော်ပြထား ပါသည်။	
၁၃။	နိဂုံးသုံး၁	သပ်ချက်	5			·		
	• နိဂုံးသုံးသပ်ချက် အနေဖြင့် စုစုပေါင်းဝန်ထမ်း ၆၅ ယောက်တွင် နိုင်ငံခြား သား(၁၅)ဦး ပြည်တွင်းဒေသခံ (၅၀)ဦး ဖြင့် ၁၀၀% မြန်မာနိုင်ငံသား ရင်းနှီး မြုပ်နှံမှုဖြစ်ကြောင်း ဖော်ပြထားပါသည်။ သို့ရာတွင် safety signs များ နှင့် MSDS procuct safety information များကို English ဘာသာဖြင့် အဓိက ထား ဖော်ပြထားသည်ကို စိစစ်တွေ့ရှိရပါသည်။ နှစ်ဦးနှစ်ဖက် အဆင်ပြေ စေရန် နှင့် လုပ်ငန်းလွယ်ကူ ချောမွေ့စေရန် အများပြည်သူ ဖတ်၍ မှတ်သား လွယ်ကူစေရန် အင်္ဂလိပ်နှင့် မြန်မာ နှစ်ဘာသာဖြင့် ဖော်ပြနိုင်လျင် ပို၍ ကောင်းမွန်မည်ဟု အကြံပြုပါသည်။					% !!! !! !! !! !! !!	Appendix (C) စာမျက်နှာ ၃၁၄ မှ ၃၂၂ တွင် မြန်မာဘာသာ ဖြင့် ဖော်ပြထားပါသည်။	



#### REFERENCES

- 1. Ahmad, Nafis. 1970. *Planning the Economic Development of the Resources of Burma*. The Oriental Geographer, January, pp.1-34.
- 2. Asia Development Bank. (2003) Environment Assessment Guideline.
- 3. Bibby, C., Jones, M. and Marsden, S. 1998. Bird Surveys. In: Expedition Field Techniques. Published by the Expedition Advisory Center. Royal Geographical Society. Kensington. Gore. London.
- 4. Byron, H. 2000. *Biodiversity and Environmental Impact Assessment*: A Good Practice Guide for Road Schemes. The RSPB, WWF-UK, English Nature and the Wildlife Trusts, Sandy.
- 5. Canadian Environmental Assessment Agency, Reference Guide. 1994. Addressing Cumulative Environmental Effects.
- 6. Department of Chemical and Environmental Engineering. (2000) *Environmental Impact Assessment*, Master of Environmental Engineering Course, Faculty of Engineering of National University of Singapore.
- 7. Fellmnn, Jerome at. Al. 1990. Landscape of Human Activities.
- 8. Hla Tun Aung. 1995." Myanmar: The Study of Processes and Patterns". National Centre for Human Resources Development." Ministry of Education, Union of Myanmar.
- 9. International Finance Corporation. 2007. Environmental, Health, and Safety Guidelines, General EHS Guidelines: Environmental, Air Emissions and Ambient Air Quality.
- 10. Imre, Kiss. June 2019. A Case Study: Cast iron rolls: an overview on the proper hardness assured by the manufacturing process.
- 11. Foreign Imports of Cast Iron and Steel Rolling Mill Rolls.



- 12. Schröder, Dr. Karl Heinrich. 2003. Clothing factory in Sri Lanka. "A Basic Understanding of The Mechanics Of Rolling Mill Rolls".
- 13. UNITED NATIONS INDUSTRIAL DEVELOPMENT ORGANIZATION. 1991. Workshop on Steel Plant and Rolling Mill Rehabilitation.
- 14. Spuzic, Sead. 1994. Wear of hot rolling mill rolls.
- 15. Karlsruhe, March 1999. Ferrous Metals Processing Industry. Report on Best Available Techniques (BAT) in the German.
- 16. Integrated Pollution Prevention and Control (IPPC) (December 2001) Best Available Techniques in the Ferrous Metals Processing Industry
- 17. Michael, D. Fenton. 2005–1254. U.S. Department of the Interior, Mineral Commodity Profiles—Iron and Steel.